

ASS. REC. BY

REF

CS/MSG19001958/Dvd30

Official Instruction

Surveyor

Brylin

ASSIGNMENT (Office)

Merimen

From (Person)

Elaine Ngu

of

MSIG

Date/Time

30/1/19 @ 9.46am

Estimated Cost

Bill to:

OD (TP) WS/TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No:

3HC 8919L

Insured:

SFH 9090S

at Workshop m/s

Soon Hock Automotive

Tel:

65425119

of

BLK 10, AMK Ind. Park 2A #01-06

Policy No:

p28939017DMA

Claim No:

583669

Sum Insured:

Excess:

Make of Veh:

(Client's Record)

D.O.A.

26/1/19

CA / REV / REP. / REV 24 HRS

lwp

H.O.D. Endorsement:

Date/Time:

10:11am @ 30/1/19

Person Contacted:

Lynn

Vehicle

IN OUT

Date/Time	Action/Instruction (✓) Estimate
	3HC 8919L - CS/CTI 18020522/Dvbnd 20A:11/11/18
	SFH 9090S - x
31/1/19	Email preh revised via merimen

REF:

ASSIGNMENT

8919

COE April 2024

From
Estimated Cost

Date:

Veh No:

SHC 8919 L

V. Regn:

2016 April

Type: M/Car / M/Cycle / Bus / Van / Lorry / ☒ Prime Mover /

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To inspect Vehicle No

at Workshop m/s

at

Insured

Policy No.

Claims No.

Sum Insured:

Excess:

(Client's Record)

Make of Veh:

(Policy Condition)

Remark: The veh had commenced its
repair at the time of inspection.

Bal. or Market Value:

IDAC Accident Rpt:

Consistent? : Yes or No

GIA / PR Seen:

Consistent? : Yes or No

Est. Repairs:

13

days

Res.: Yes or No

Lump Sum

20

%

3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Date:

Person Contacted:

Vehicle: IN / OUT

Truck / Trailer or

Make:

Hyundai I40

cc 1685

Colour:

Blue

A/C

Insured / SM / NI / NA

Sp. Reading

494986

T/Radio

Insured / Std / NI / NA

Eng/No:

D4FDGU613578

C/No:

KMHLB41UMGU087814

Gen. Cond: ☒ Good / Fair / Poor / BurntSteering: ☒ In order / Jammed / Leaked / Burnt orBrake: ☒ In order / Jammed / Leaked / Burnt orModi: ☒ S/Rim / STD A/Rim or

Tyre Size:

F:

205/60 R16

R:

- 11 -

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

Wastake

Front

Rear

R/Bal:

S

mm

R/Bal:

S

mm

L/Bal:

S

mm

L/Bal:

S

mm

D.O.A:

26/01/2019

D.O.I:

29/01/2019

Survey held at

Chunni AMK

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

Front & Rear

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time

Action / Instruction

MSG SFH 90908

01/03/19 Jmnp 2/5 19000/- with 13 days. g m (Recd 21, 174.8), 53b

RECEIVED 01 MAR 2019

Date/Time, File Pass to?

☐

: Prel. Report

1)

☐

: Final Report

Date/Time, File Return to?

Days Of Repair:

13

Resurvey No. of Trip:

2

Survey Fee:

Transportation

1) 1 + 100 50

1) Photos

1) Other:

1)

TOTAL

Add Fee:

☐

Site Insp 1\$

☐

Interview 1\$

☐

Tech Insp 1\$

☐

Weekend 1\$

(2) 1/3 - typst

Report Format:

merimen

Lump Sum / I.B.I: 1\$

19,000p

290

10

260

...CLAIM SUBFOLDER...(New Assignment)

CLAIM SUBFOLDER TRACKING

Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'd	Status
Main	28 Jan 2019		30 Jan 2019 09:46 Assign				New Assignment Cancel Case

Main	Reference	Claim Details	Documents	Show All
------	-----------	---------------	-----------	--------------------------

CLAIM SUBFOLDER DETAILS [Created by insurer]

Insured:	HO WAN SING, ID: S1301150H			
Main Claimant:	COMFORT TRANSPORTATION PTE LTD, Co. Reg. No.: 199303821R			
Vehicle Reg. No.:	SHC8919L	Date of Loss:	26/01/2019 15:00 - :59 [93 Months and 5 Days From LTA Reg Date (Man Yr)]	
Claim Type:	TP / 583669	Policy/Cover Note No.:	P28959017DMA (Comprehensive) Coverage: 26/05/2018 - 25/05/2019	
Vehicle Reg. No. (Insured):	SFH9090S	Policy No. (Claimant):	D-18088936MFSH	
		Excess:	\$1,500.00	
Repairer:	Soon Hock Automotive (HQ) BLK 10 ANG MO KIO INDUSTRIAL PARK 2A AUTOPOINT #01-06 S(568047), 568047 Ang Mo Kio - Tel:			
Handling Insurer:	MSIG Insurance (Singapore) Pte. Ltd. (HQ) - Tel: +65 6827 7888 ... [Handled by Elaine Ngu Siau Mei - 6594 2540]			
Claimant's Insurer:	MS First Capital Insurance Ltd (HQ) - Tel: 62222311			
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Imm.Advice due 31/01/2019]			
Adj Asg. Remarks:	on WP. liability 100% on OI Assign LKK Consultant contact 65425119 or 65427162			

ASSOCIATED MAIL RECEIVED [View All](#) [Compose Case Mail](#)

There are no mail for this case.

ALL ASSOCIATED TASKS [View All](#) [Search Tasks](#) [Create New Task](#) [Complete](#)

Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

To: MSIG Insurance (Singapore) Pte. Ltd.
4 Shenton Way
#21-01 SGX Centre 2
Singapore 068807

From: LKK Auto Consultants Pte Ltd
51 Ubi Ave 1 #01-25
Paya Ubi Industrial Park
Singapore 408933

Attn: Elaine Ngu Siau Mei

Date: 31 Jan 2019

Preliminary Advice

Insured Vehicle No	: SFH9090S		
TP Vehicle No	: SHC8919L	Accident Date	: 26/01/2019
Make	: HYUNDAI I40	Assignment Date	: 30/01/2019
Date of Inspection	: 29/01/2019	Est. Duration of Repair	: 12.00
Inspection At	: SOON HOCK AUTOMOTIVE (HQ) BLK 10 ANG MO KIO INDUSTRIAL PARK 2A AUTOPOINT #01-06 S(568047) SINGAPORE 568047		

Point of Impact / General Description of Damages

The vehicle sustained impact / damages front and rear portion and parts claimed are consistent to the accident.

Repairer's Estimate (Gross)	:S\$	39,976.42
Revised Amount	:S\$	23,924.10
Check Items (Estimated)	:S\$	0.00
Total	:S\$	23,924.10

Lump Sum Repair	:S\$	
-----------------	------	--

Total Loss Consideration

New for Old Value	:S\$	
Pre-Accident Value	:S\$	
COE / PARF Rebate	:S\$	
Salvage Value	:S\$	
Margin for Repair	:S\$	

Remarks

() The vehicle is economical/not economical for repair.

(X) The above survey was conducted on a 'without prejudice' basis.

MCD619012773 / ComfortDelGro Engineering Pte Ltd - Luyang
 ENTRY DATE & TIME: 28/01/2019 10:48
 SUBMITTED BY: Janet Lim Siang Gek

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any willful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT	
Date Of Report	28/01/2019 10:46
Date Of Accident	26/01/2019 15:20
Exact Location Of Accident	CTE TWDS SLE NEAR ANG MO KIO AVE 1 EXIT
Country/State of Loss	SINGAPORE
DETAILS OF OWN VEHICLE	
Vehicle Registration Number	SHC8919L
Insured/Policyholder	
Name Of Registered Owner	COMFORT TRANSPORTATION PTE LTD
Co Reg No	199303821R
Email Address	FLEETSAFETY@CDGTAXI.COM.SG
Mobile Phone No	
Alternative Phone No	OFFICE-65508768
Vehicle Particulars	
Manufacturer	HYUNDAI
Model	I40
Exact Purpose for which vehicle was being used at time of accident	
Are you claiming under your own insurance policy for repair to your vehicle?	NO
If No, Please state action to be taken	THIRD PARTY
Vehicle Category	TAXI
Insurance Company	
Name of Insurance Company	MS FIRST CAPITAL INSURANCE LTD
Type Of Coverage	THIRD PARTY FIRE AND/OR THEFT
Fleet Policy	YES
Policy Number	D-18088936MFSH
Cover Note Number	
Driver	
Name of Driver	TAN CHIA WEI (CHEN JIAWEI)
NRIC No	S8515623C
Date Of Birth	08/06/1985
Occupation	OUTDOOR
Date Of Driving Pass	25/03/2011
Driving Experience	7 YEARS AND 10 MONTHS
Gender	MALE
Mobile Number	(LOCAL) +65-98510628
Fax Number	
Contact Number	
Email Address	MACAVYN@YAHOO.COM.SG

Address	BLK 911 TAMPINES STREET 91 #11-97
Postcode	520911
Was driver an employee of the Insured's Company	NO
If No, Relationship of the Driver with the Insured	OTHER - TAXI DRIVER
Vehicle Registration Number of Driver's Own Vehicle	-
Insurance Company of Driver's Own Vehicle	-

General Information of the Accident

Type Of Accident	CHAIN COLLISION
Weather Conditions	CLEAR
Road Surface	DRY

Other Information

Was any foreign vehicle involved in this accident?	NO
Number of vehicles (including own vehicle) Involved in the accident	4
Was any body injured in the Accident?	NO
Was any injured conveyed to hospital by ambulance?	NO
Was any other material or property damaged?	YES
I have been approached by unknown person(s) soliciting/offering accident claims assistance.	NO
Number of Passengers (Including Driver)	2
Passenger 1	

NAME: : -
GENDER: : FEMALE

Details of Police Action

Was the accident reported to the police?	YES
If Yes, Please state which Police Station	
Police Station Name	CHANGI NEIGHBOURHOOD POLICE CENTRE
Police Station Address	ROAD: 9 SIMEI STREET 2 , POSTCODE: 529914 , COUNTRY: SINGAPORE
Police Station Contact	TEL NO: 1800-5872999 - FAX NO: 65872900
Was notice of intended Prosecution given?	NO
If Yes, against whom?	

Circumstances of Accident

REFER POLICE REPORT NO: T/20190126/2144

Attachment(s)

Are accident photos available for attachment?	YES
Was there any video captured by Car Camera?	NO
Was there any audio recorded?	NO

DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number	SFH9090S
Vehicle Make/Model/Colour	MERCEDES
Details Of Properties	
Vehicle Category	PRIVATE CAR
Name of Driver	HO SHEN AN CHRISTOPHER
NRIC/Passport Number	S9490463C
Contact Number	98163867

Address

Postcode

Insurance Company Name

Nature Of Damage FRONT AND REAR

No. Of Passenger (Including Driver)

DETAILS OF OTHER VEHICLE PROPERTY 2

Vehicle Registration Number SKD6724D
Vehicle Make/Model/Colour TOYOTA
Details Of Properties
Vehicle Category PRIVATE CAR
Name of Driver LIM ZHAN KANG
NRIC/Passport Number S9422751H
Contact Number
Address
Postcode
Insurance Company Name
Nature Of Damage REAR
No. Of Passenger (Including Driver)

DETAILS OF OTHER VEHICLE PROPERTY 3

Vehicle Registration Number SLM4539B
Vehicle Make/Model/Colour TOYOTA
Details Of Properties
Vehicle Category PRIVATE CAR
Name of Driver CHUA MENG LEE (CAI MINGLI)
NRIC/Passport Number S7215489D
Contact Number
Address
Postcode
Insurance Company Name
Nature Of Damage FRONT
No. Of Passenger (Including Driver)

SKETCH PLAN**IMPORTANT NOTICE**


1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by Insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. The report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgment of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.
8. **Consent under the Personal Data Protection Act (PDPA)**


I understand, acknowledge, agree and consent that:

- (a) My Insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this [form] and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the Insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of:
 - (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
 - (ii) investigating the accident and/or my claims;
 - (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
 - (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
 - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims.(collectively the "Purposes")
- (b) all Insurer(s) who have insured vehicle(s) involved in this accident and the Insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
- (c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third party service providers or agents(including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.
- (d) my Personal Information will also be collected and used to compile claims history for the purpose of fraud detection, investigation and management in present and all future claims.
- (e) the information so collected under (d) above may be shared / disclosed:
 - (i) to all insurers and/or any other third parties that assist in evaluating, investigating, controlling or managing fraud, regulators, law enforcement and government agencies as reasonably required for the purposes stated, or
 - (ii) for complying with requirements under any regulations, laws or court orders.


COMFORT TRANSPORTATION PTE LTD
CO. REG. NO. 199303821R

Policyholder's Signature
Date & Time:


Driver's Signature
(If driver is not the policyholder)
Date & Time: 28.01.2019@0930HRS


Reporting Centre Personnel's Signature
Name:
NRIC/FIN No.: June Tan

SKETCH PLAN



DESCRIBE CIRCUMSTANCES OF THE ACCIDENT

Refer to attachment: T/20190126/2144

DECLARATION

I/We declare the foregoing particulars are true in every respect.

COMFORT TRANSPORTATION PTE LTD
CO. REG. NO. 199303821R

Policyholder's Signature
Date & Time:

Driver's Signature
(If driver is not the policyholder)
Date & Time: 28.01.2019@0930HRS

Reporting Centre Personnel's Signature
Name:
NRIC/FIN No.: June Tan



SINGAPORE POLICE FORCE



T/20190128/2032

1 of 3

Report No. T/20190128/2032

Police Station Of Origin:
Changi N.P.C
9 Simei Street 2 SINGAPORE 529914
Tel No: 1800-5872999

REPORT OF A TRAFFIC ACCIDENT

Date/Time Report Made: 28/01/2019 12:24		Vide Report No.: T/20190126/2144		Station Diary No.: 29	
Informant's Particulars					
Name of Informant: TAN CHIA WEI			Address: APT BLK 911 TAMPINES STREET 91 #11-97 SINGAPORE 520911		
ID Type / ID No.: NRIC NO / S8515623C			Contact No.: Home/Office: Mobile: 98510628		
Nationality: SINGAPORE CITIZEN			Email:		
Sex: Male	Age: 33	Date of Birth: 08/06/1985	Type of Informant: Driver		
Race: Chinese			Language: English		Institution / School Name:
Occupation: Taxi Driver			Driving Licence Information: Class: 3		Date of Expiry:

General Information of the Accident

Type of Accident:	Injury Conveyed By Ambulance	Drink Drive: No	Date/Time of Accident: 26/01/2019 15:20	Type of Location: Straight Road
Location: Along Road 1 CENTRAL EXPRESSWAY Going towards Ang Mo Kio Ave 1, near exit 10.8km				
Weather: Clear		Road Surface: Dry		Road Speed Limit:
Traffic Flow: One Way		Traffic Control: Not Controlled		Traffic Volume: Moderate
Type of Collision: Between Moving Vehicles - Head To Rear				Anyone conveyed by ambulance: Yes

Details of Vehicle Involved

Vehicle No.	Type	Make	Model	Color	Condition	No. of Passenger
SFH9090S	Car				Seriously Damaged	0
SHC8919L	Car				Seriously Damaged	1
SKD6724D	Car				Slightly Damaged	0
SLM4539B	Car				Seriously Damaged	0



**SINGAPORE
POLICE FORCE**



T/20190128/2032

2 of 3

Report No. T/20190128/2032

Police Station Of Origin:
Changi N.P.C
9 Simei Street 2 SINGAPORE 529914
Tel No: 1800-5872999

CONTINUATION OF REPORT

Details of Person Involved			
Any Pedestrian Involved: No			
No. of Pedestrians Injured: NIL		Use of Pedestrian Crossing: NA	
Driver			
Name	TAN CHIA WEI	ID No.	S8515623C
Related Vehicle	NIL SHC8919L (car) <i>on right of</i>	Contact No.	98510628
Hospital/Clinic	NIL	Class of Driving Licence & Expiry Date	Class: 3 Date of Expiry: NIL
Date Treatment	NIL	Date Discharge	NIL
No. of Days granted Medical Leave	NIL	Degree of Injury	NIL

Brief Details.

On 26/01/2019 at about 1521hrs, I was driving my vehicle(SHC8919D) together with one passenger along Central Expressway towards Ang Mo Kio. I was driving along the most right lane of the road. There were 5 lanes on the road.

As I was driving, suddenly the vehicle in front of me(SKD6724D) made a sudden brake. I made a hard brake as well, however the vehicle(SFH9090S) which was behind could not brake in time and hit onto the back of my vehicle. The vehicle behind of (SFH9090S) which was (SLM4539B) had also hit onto the back of his vehicle. There were a total of 4 cars involving in the accident. The impact had made the 3rd and 4th car to move one lane to the left. I then came out of my vehicle to make a check. The back of my vehicle was seriously damaged and could not be driven anymore. I had called my company's towing crew to tow my vehicle. Police and ambulance came and also conveyed one of the driver to the hospital.

I had also took photos of the incident. I have an in-car camera installed in my vehicle. Traffic Police had seized my SD card of my in-car camera and had informed me to make a police report and to report to him at TP HQ on Monday at 11am.

**SINGAPORE
POLICE FORCE**

T/20190128/2032

Police Station Of Origin:
Changi N.P.C
9 Simei Street 2 SINGAPORE 529914
Tel No: 1800-5872999

3 of 3

Report No. T/20190128/2032

CONTINUATION OF REPORT

Sketch Plan

Informant is not able to provide sketch plan

IMPORTANT: Please attach a copy of your vehicle's Insurance Certificate to this report. If you don't have the certificate with you now, please fax a copy to 65474885 stating the report number as reference.

Signature Of Officer Recording The Report:

G /
Sgt 2 MUHAMMAD SAIFUL BAKHRI BIN
RAZALI

Signature Of Interpreter:

Not applicable

Officer In Charge Of Case:

TP / GIT /
SI YEO CHUN JIAN
Contact No.: 65476213

Authentication Stamp

NP188

Signature Of Informant:

Date/Time:

28/01/2019 12:24

Classification Of Case:

CHUNNI MOTOR WORK PTE LTD**REPAIR ESTIMATE***

VEHICLE NO : SHC 8919L

DATE : 28.01.2019

MAKE :

TEL : 6542 5119

MODEL : HYUNDAI i40

FAX : 6542 6039

m116

Qty	Parts Description/ Labour	Type	Unit Price	Amount	
	Radiator Grille <i>crack</i>			\$ 1,110.10	✓
	Radiator Grille H Emblem <i>new</i>			\$ 120.30	✓
	Front Bumper Cover <i>mainly crack / distorted</i>			\$ 1,052.20	✓
	Front Bumper Sponge <i>new</i>			\$ 99.20	✓
	Front Bumper Reinforcement <i>new</i>			\$ 402.10	✓
	Front Bumper Bracket Top (LH/RH) <i>new</i>	\$	22.40	\$ 44.80	X
	Front Bumper Bracket (LH/RH) <i>new</i>	\$	24.60	\$ 49.20	X
	Headlamp Support Top Cover <i>new</i>			\$ 222.60	X
	Headlamp Support Panel Assy <i>new</i>			\$ 907.40	✓
	Headlamp (LH/RH) <i>mainly broken</i>	\$	1,388.00	\$ 2,776.00	✓
	Radiator <i>new</i>			\$ 698.30	✓
	Radiator Fan Blade, Cowling, Motor Assy <i>new</i>			\$ 792.95	X
	Radiator Bracket (RH/LH) <i>new</i>	\$	6.50	\$ 13.00	X
	Radiator Guard <i>broken</i>	\$	20.00	\$ 40.00	✓
	Horn Unit (LH/RH) <i>broken</i>	\$	73.80	\$ 147.60	✓
	Aircon Condenser <i>new</i>			\$ 927.50	✓
	Inter Cooler <i>new</i>			\$ 1,032.50	✓
	Inter Cooler Mounting (2 PCS) <i>new</i>			\$ 25.90	X
			9313.20		
			7450.56		
	SUB TOTAL			\$ 10,461.65	
	LESS 20%			\$ 2,092.33	
	DISCOUNTED TOTAL			\$ 8,369.32	
	Front Number Plate <i>crack</i>			\$ 25.00	Nett ✓
	Front No Plate Trim Cover <i>new</i>			\$ 30.00	Nett X
			25.00		
				\$ 55.00	
	Labour Charge				
	Panel Beating			\$ 1,000.00	500/-
	Spray Painting Charge			\$ 250.00	250/-
	Wiring Charge			\$ 50.00	30/-
	Towing Charge			\$ 50.00	new
	Remove/Refix Aircon & Refill Gas			\$ 150.00	780/-
	Diagnostic & Resetting To Erase Fault Code			\$ 480.00	new
			810.00		
	TOTAL LABOUR			\$ 1,980.00	

SHC 8919L

Qty	Parts Description/ Labour	Type	Unit Price	Amount	
	Boot Lid <i>h/c</i>			\$ 2,174.90	✓
	Boot Lid Rubber <i>defunct</i>			\$ 96.50	✓
	Boot Lid Hinge (LH/RH) <i>regr</i>		\$ 142.30	\$ 284.60	X
	Boot Lid Lock Upper <i>u/t</i>			\$ 102.60	✓
	Boot Lid Lock Lower <i>u/t</i>			\$ 31.70	✓
	Boot Lid Catch Handle <i>h/c</i>			\$ 198.00	X
	Boot Lid 'H' Emblem <i>h/c</i>			\$ 28.70	✓
	Boot Lid CRDI Plate <i>h/c</i>			\$ 27.90	✓
	Boot Lid Lamp (LH/RH) <i>crack / broken</i>		\$ 565.60	\$ 1,131.20	✓
	Licence Lamp (LH/RH) <i>svc</i>		\$ 33.95	\$ 67.90	X
	Boot Lid Trimboard <i>turn</i>			\$ 116.40	✓
	Boot Lid Trimboard Clips (10pcs) <i>h/c</i>			\$ 11.00	✓
	Bootlid Moulding <i>dislodged</i>			\$ 85.00	✓
	Bootlid i40 Emblem <i>h/c</i>			\$ 27.90	✓
	Bootlid Lower Garnish <i>broken</i>			\$ 227.90	✓
	Rear Bumper <i>broken</i>			\$ 553.00	✓
	Rear Bumper Reinforcement <i>broken</i>			\$ 428.40	✓
	Rear Bumper Reinforcement Bracket (LH/RH) <i>dent</i>		\$ 80.30	\$ 160.60	✓
	Rear Bumper Clip 10 pcs <i>h/c</i>			\$ 22.00	✓
	Rear Bumper Bracket <i>h/s broken o/s svc</i>		\$ 35.60	\$ 71.20	✓
	Rear Bumper Sponge <i>turn</i>			\$ 118.40	✓
	Rear Bumper Under Cover <i>dislodged</i>			\$ 228.00	✓
	Rear Bumper Reflector Lamp (LH/RH) <i>crack / broken</i>		\$ 30.60	\$ 61.20	✓
	Tail Lamp (LH/RH) <i>broken / crack</i>		\$ 697.80	\$ 1,395.60	✓
	Tail Lamp Quarter Panel (LH/RH) <i>dent</i>		\$ 226.50	\$ 453.00	✓
	Rear Panel <i>h/c</i>			\$ 526.70	✓
	Rear Panel Garnish <i>defunct mounting</i>			\$ 57.70	✓
	Rear Panel Lower Panel <i>dent</i>			\$ 495.50	✓
	Spare Tyre Holder <i>h/c</i>			\$ 248.00	X
	Tail Lamp Panel Top (LH/RH) <i>h/c</i>		\$ 545.90	\$ 1,091.80	X
	Spare Tyre Panel <i>dent</i>			\$ 852.80	✓
	Spare Tyre Panel Cushion <i>svc</i>			\$ 209.05	X
	Rear Towing Hook <i>h/c</i>			\$ 94.60	X
	Member Assy- Rear Floor Centre <i>h/c</i>			\$ 570.40	X
	Panel Assy-Rear Floor Side (LH/RH) <i>regr</i>		\$ 90.10	\$ 180.20	X
	Rear Floor Chassis Member <i>regr</i>			\$ 3,636.20	X
	Exhaust Pipe Insulator <i>h/c</i>		\$ 58.55	\$ 117.10	X
	Exhaust Silencer <i>u/t</i>		\$ 967.70	\$ 1,935.40	✓
	Exhaust Pipe Hanger <i>h/c</i>		\$ 58.55	\$ 117.10	X
	Exhaust Pipe Centre <i>h/c</i>		2020.00	\$ 730.10	X
	Rear Fender With Housing (LH/RH) <i>dent</i>		\$ 4,236.80	\$ 9,473.60	✓ 4040-bc
	Rear Fender Inner Lining (LH/RH) <i>h/c</i>		\$ 169.30	\$ 338.60	X
	Rear Fender Air-Duct <i>h/c</i>			\$ 51.60	X
	Rear Fender Trim Board (LH/RH) <i>u/t</i>		\$ 188.75	\$ 377.50	✓
	Rear Windscreen Moulding <i>h/c</i>			\$ 28.30	✓
	Fuel Lid Cover <i>dislodged</i>			\$ 70.90	✓
			15902.30		
			12721.84		
	SUB TOTAL			\$ 29,306.75	
	LESS 20%			\$ 5,861.35	
	DISCOUNTED TOTAL			\$ 23,445.40	

SHC 8919L

Qty	Parts Description/ Labour	Type	Unit Price	Amount
	Boot Lid Comfort Logo & Tel No. Sticker Hec			\$ 30.00
	Rear No.Plake chuk			\$ 25.00
	Rear Bumper Reverse Sensor Dem			\$ 135.70
	Rear Windscreen Sealant Hec			\$ 46.00
			236.70	\$ 236.70
	Labour Charge			
	Panel Beating			\$ 2,600.00
	Spray Painting Charge			\$ 1,800.00
	Wiring Charge			\$ 100.00
	Tuff Kote			\$ 150.00
	Rear Chassis Alignment Charge			\$ 400.00
	Remove/Refix Cushion & Upholstery Rear			\$ 150.00
	Remove/Refix Rear Windscreen Glass			\$ 120.00
	Remove/Refix Reverse Sensor			\$ 120.00
	Remove/Refix Fuel Tank			\$ 150.00
	Remove/Refix Exhaust Pipe			\$ 300.00
			2680.00	
	TOTAL LABOUR			\$ 5,890.00
	ESTIMATE TOTAL		40,174.82	\$ 39,976.42
	29/01/2019 e 1630hrs HWA Andrew 2/5m 13 days. <u>Ryan</u> LKK Auto			23924.10
			sup? 24122. 198.40	24122.50
			L/S 19000/-	
				10134.82

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
Signature:
Date:

This is an initial estimate based on a visual inspection of the above vehicle. The final repair quantum will be prepared after the vehicle is surveyed by a motor Surveyor appointed by the insurance company.

CHUNNI MOTOR WORK FIELD LTD



REPAIR ESTIMATE*

VEHICLE NO : SHC 8919L (Supplementary)

DATE : 11.02.2019

MAKE :

MODEL : HYUNDAI i40

Qty	Parts Description/ Labour	Type	Unit Price	Amount
	Rear Spare Tyre Bracket BH			\$ 248.00
	SUB TOTAL			\$ 248.00
	LESS 20%			\$ 49.60
	DISCOUNTED TOTAL			\$ 198.40
	 LKK Auto 			
This is an initial estimate based on a visual inspection of the above vehicle. The final repair quantum will be prepared after the vehicle is surveyed by a motor Surveyor appointed by the insurance company.				

...CLAIM SUBFOLDER...(Pending for Survey Report)

CLAIM SUBFOLDER TRACKING

Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'd	Status
Main	28 Jan 2019		30 Jan 2019 09:46 Edit Adj Rpt	S\$19,000.00 Edit Estimates	S\$19,000.00 View Rpt		Pending for Survey Report Cancel Case

Main	Reference	Claim Details	Documents	Show All					
CLAIM SUBFOLDER DETAILS		[Created by insurer]							
Insured:	HO WAN SING , ID: S1301150H								
Main Claimant:	COMFORT TRANSPORTATION PTE LTD , Co. Reg. No.: 199303821R								
Vehicle Reg. No.:	SHC8919L	Date of Loss:	26/01/2019 15:00 - :59 [33 Months and 5 Days From LTA Reg Date (Man Yr)]						
Claim Type:	TP / 583669	Policy/Cover Note No.:	P28959017DMA (Comprehensive) Coverage: 26/05/2018 - 25/05/2019						
Vehicle Reg. No. (Insured):	SFH9090S	Policy No. (Claimant):	D-18088936MFSH						
		Excess:	S\$1,500.00						
Repairer:	Soon Hock Automotive (HQ) BLK 10 ANG MO KIO INDUSTRIAL PARK 2A AUTOPOINT #01-06 S(568047), 568047 Ang Mo Kio - Tel:								
Handling Insurer:	MSIG Insurance (Singapore) Pte. Ltd. (HQ) - Tel: +65 6827 7888 ... [Handled by Elaine Ngu Siau Mei - 6594 2540]								
Claimant's Insurer:	MS First Capital Insurance Ltd (HQ) - Tel: 62222311								
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Handled by BRYAN TANI] ... [Final Rpt due 01/03/2019]								
Adj Asg. Remarks:	on WP. liability 100% on OI Assign LKK Consultant contact 65425119 or 65427162								
ASSOCIATED MAIL RECEIVED		View All Compose Case Mail							
There are no mail for this case.									
ALL ASSOCIATED TASKS		View All Search Tasks Create New Task Complete							
Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									



















































Claim Documents



















































*SHC8919L (583669)
[SFH9090S]
TP
COMFORT TRANSPORTATION PTE LTD
Jan 26 2019 3:00PM
[HO WAN SING]
Soon Hock Automotive














































Upload Documents | Upload Photos | Compose New Letter

View View in Browser

Assessment Reports				1 per page	
No	Finalized On	MSIG Insurance (Singapore) Pte. Ltd. (HQ)		Thumbnail	Print
1	29/01/19 16:38	Accident Statement From: SC - Rep. No: SFH9090S, Claimant: HO WAN SING	1	Load HTM	
No	Finalized On	ComfortDelGro Engineering Pte Ltd (Loyang)		Thumbnail	Print
1	28/01/19 11:43	Accident Statement	1	Load HTM	
No	Finalized On	LKK Auto Consultants Pte Ltd (HQ)		Thumbnail	Print
1	31/01/19 13:43	Adjuster Immediate Advice	1	Load HTM	
Photos/Images				3 per page	
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)		Thumbnail	Print
1	23/02/19 12:21	Front View Left	1	Load JPG	✓
2	23/02/19 12:21	Front View Right	1	Load JPG	✓
3	23/02/19 12:21	General View	1	Load JPG	✓
4	23/02/19 12:21	General View	1	Load JPG	✓
5	23/02/19 12:21	General View	1	Load JPG	✓
6	23/02/19 12:21	General View	1	Load JPG	✓
7	23/02/19 12:21	General View	1	Load JPG	✓
8	23/02/19 12:21	General View	1	Load JPG	✓
9	23/02/19 12:21	General View	1	Load JPG	✓
10	23/02/19 12:21	General View	1	Load JPG	✓
11	23/02/19 12:21	General View	1	Load JPG	✓
12	23/02/19 12:21	General View	1	Load JPG	✓
13	23/02/19 12:21	General View	1	Load JPG	✓
14	23/02/19 12:22	General View	1	Load JPG	✓
15	23/02/19 12:22	General View	1	Load JPG	✓
16	23/02/19 12:22	General View	1	Load JPG	✓
17	23/02/19 12:22	General View	1	Load JPG	✓
18	23/02/19 12:22	General View	1	Load JPG	✓
19	23/02/19 12:22	General View	1	Load JPG	✓
20	23/02/19 12:22	General View	1	Load JPG	✓
21	23/02/19 12:22	General View	1	Load JPG	✓
22	23/02/19 12:22	General View	1	Load JPG	✓
23	23/02/19 12:22	General View	1	Load JPG	✓
24	23/02/19 12:22	General View	1	Load JPG	✓
25	23/02/19 12:22	General View	1	Load JPG	✓
26	23/02/19 12:22	General View	1	Load JPG	✓
27	23/02/19 12:22	General View	1	Load JPG	✓
28	23/02/19 12:22	General View	1	Load JPG	✓
29	23/02/19 12:22	General View	1	Load JPG	✓
30	23/02/19 12:22	General View	1	Load JPG	✓





























Assessment Reports			1 per page	<input checked="" type="checkbox"/>
No	Finalized On	MSIG Insurance (Singapore) Pte. Ltd. (HQ)	Thumbnail	Print
31	23/02/19 12:22	General View	 Load JPG	<input checked="" type="checkbox"/>
32	23/02/19 12:22	General View	 Load JPG	<input checked="" type="checkbox"/>
33	23/02/19 12:22	General View	 Load JPG	<input checked="" type="checkbox"/>
34	23/02/19 12:22	General View	 Load JPG	<input checked="" type="checkbox"/>
35	23/02/19 12:22	General View	 Load JPG	<input checked="" type="checkbox"/>
36	23/02/19 12:22	General View	 Load JPG	<input checked="" type="checkbox"/>
37	23/02/19 12:22	General View	 Load JPG	<input checked="" type="checkbox"/>
38	23/02/19 12:22	General View	 Load JPG	<input checked="" type="checkbox"/>
39	23/02/19 12:22	General View	 Load JPG	<input checked="" type="checkbox"/>
40	23/02/19 12:22	General View	 Load JPG	<input checked="" type="checkbox"/>
41	23/02/19 12:22	General View	 Load JPG	<input checked="" type="checkbox"/>
42	23/02/19 12:22	General View	 Load JPG	<input checked="" type="checkbox"/>
43	23/02/19 12:22	General View	 Load JPG	<input checked="" type="checkbox"/>
44	23/02/19 12:22	General View	 Load JPG	<input checked="" type="checkbox"/>
45	23/02/19 12:22	General View	 Load JPG	<input checked="" type="checkbox"/>
46	23/02/19 12:22	General View	 Load JPG	<input checked="" type="checkbox"/>
47	23/02/19 12:22	General View	 Load JPG	<input checked="" type="checkbox"/>
48	23/02/19 12:22	General View	 Load JPG	<input checked="" type="checkbox"/>
49	23/02/19 12:22	General View	 Load JPG	<input checked="" type="checkbox"/>
50	23/02/19 12:22	General View	 Load JPG	<input checked="" type="checkbox"/>
51	23/02/19 12:22	General View	 Load JPG	<input checked="" type="checkbox"/>
52	23/02/19 12:22	Rear View Left	 Load JPG	<input checked="" type="checkbox"/>
53	23/02/19 12:22	Rear View Right	 Load JPG	<input checked="" type="checkbox"/>
54	23/02/19 12:23	General View	 Load JPG	<input checked="" type="checkbox"/>
55	23/02/19 12:23	General View	 Load JPG	<input checked="" type="checkbox"/>
56	23/02/19 12:23	General View	 Load JPG	<input checked="" type="checkbox"/>
57	23/02/19 12:23	General View	 Load JPG	<input checked="" type="checkbox"/>
58	23/02/19 12:23	General View	 Load JPG	<input checked="" type="checkbox"/>
59	23/02/19 12:23	General View	 Load JPG	<input checked="" type="checkbox"/>
60	23/02/19 12:23	General View	 Load JPG	<input checked="" type="checkbox"/>
61	23/02/19 12:23	General View	 Load JPG	<input checked="" type="checkbox"/>
62	23/02/19 12:23	General View	 Load JPG	<input checked="" type="checkbox"/>
63	23/02/19 12:23	General View	 Load JPG	<input checked="" type="checkbox"/>
64	23/02/19 12:23	General View	 Load JPG	<input checked="" type="checkbox"/>
65	23/02/19 12:23	General View	 Load JPG	<input checked="" type="checkbox"/>
66	23/02/19 12:23	General View	 Load JPG	<input checked="" type="checkbox"/>
67	23/02/19 12:23	General View	 Load JPG	<input checked="" type="checkbox"/>
68	23/02/19 12:23	General View	 Load JPG	<input checked="" type="checkbox"/>
69	23/02/19 12:23	General View	 Load JPG	<input checked="" type="checkbox"/>
70	23/02/19 12:23	General View	 Load JPG	<input checked="" type="checkbox"/>
71	23/02/19 12:23	General View	 Load JPG	<input checked="" type="checkbox"/>
72	23/02/19 12:23	General View	 Load JPG	<input checked="" type="checkbox"/>
73	23/02/19 12:23	General View	 Load JPG	<input checked="" type="checkbox"/>
74	23/02/19 12:23	General View	 Load JPG	<input checked="" type="checkbox"/>
75	23/02/19 12:23	General View	 Load JPG	<input checked="" type="checkbox"/>
76	23/02/19 12:23	General View	 Load JPG	<input checked="" type="checkbox"/>
77	23/02/19 12:23	General View	 Load JPG	<input checked="" type="checkbox"/>
78	23/02/19 12:23	General View	 Load JPG	<input checked="" type="checkbox"/>
79	23/02/19 12:23	General View	 Load JPG	<input checked="" type="checkbox"/>
80	23/02/19 12:23	General View	 Load JPG	<input checked="" type="checkbox"/>

Assessment Reports			1 per page	<input checked="" type="checkbox"/>
No	Finalized On	MSIG Insurance (Singapore) Pte. Ltd. (HQ)	Thumbnail	Print
81	23/02/19 12:23	General View	 Load JPG	<input checked="" type="checkbox"/>
82	23/02/19 12:23	General View	 Load JPG	<input checked="" type="checkbox"/>
83	23/02/19 12:23	General View	 Load JPG	<input checked="" type="checkbox"/>
84	23/02/19 12:23	General View	 Load JPG	<input checked="" type="checkbox"/>
85	23/02/19 12:24	General View	 Load JPG	<input checked="" type="checkbox"/>
86	23/02/19 12:24	General View	 Load JPG	<input checked="" type="checkbox"/>
87	23/02/19 12:24	General View	 Load JPG	<input checked="" type="checkbox"/>
88	23/02/19 12:24	General View	 Load JPG	<input checked="" type="checkbox"/>
89	23/02/19 12:24	General View	 Load JPG	<input checked="" type="checkbox"/>
90	23/02/19 12:24	General View	 Load JPG	<input checked="" type="checkbox"/>
91	23/02/19 12:24	General View	 Load JPG	<input checked="" type="checkbox"/>
92	23/02/19 12:24	General View	 Load JPG	<input checked="" type="checkbox"/>
93	23/02/19 12:24	General View	 Load JPG	<input checked="" type="checkbox"/>
94	23/02/19 12:24	General View	 Load JPG	<input checked="" type="checkbox"/>
95	23/02/19 12:24	General View	 Load JPG	<input checked="" type="checkbox"/>
96	23/02/19 12:24	General View	 Load JPG	<input checked="" type="checkbox"/>
97	23/02/19 12:24	General View	 Load JPG	<input checked="" type="checkbox"/>
98	23/02/19 12:24	General View	 Load JPG	<input checked="" type="checkbox"/>
99	23/02/19 12:24	General View	 Load JPG	<input checked="" type="checkbox"/>
100	23/02/19 12:24	General View	 Load JPG	<input checked="" type="checkbox"/>
101	23/02/19 12:24	General View	 Load JPG	<input checked="" type="checkbox"/>
102	23/02/19 12:24	General View	 Load JPG	<input checked="" type="checkbox"/>
103	23/02/19 12:24	General View	 Load JPG	<input checked="" type="checkbox"/>
104	23/02/19 12:24	General View	 Load JPG	<input checked="" type="checkbox"/>
105	23/02/19 12:24	General View	 Load JPG	<input checked="" type="checkbox"/>
106	23/02/19 12:24	General View	 Load JPG	<input checked="" type="checkbox"/>
107	23/02/19 12:24	General View	 Load JPG	<input checked="" type="checkbox"/>
108	23/02/19 12:24	General View	 Load JPG	<input checked="" type="checkbox"/>
109	23/02/19 12:24	General View	 Load JPG	<input checked="" type="checkbox"/>
110	23/02/19 12:24	General View	 Load JPG	<input checked="" type="checkbox"/>
111	23/02/19 12:24	General View	 Load JPG	<input checked="" type="checkbox"/>
112	23/02/19 12:24	General View	 Load JPG	<input checked="" type="checkbox"/>
113	23/02/19 12:24	General View	 Load JPG	<input checked="" type="checkbox"/>
114	23/02/19 12:24	General View	 Load JPG	<input checked="" type="checkbox"/>
115	23/02/19 12:24	General View	 Load JPG	<input checked="" type="checkbox"/>
116	23/02/19 12:24	General View	 Load JPG	<input checked="" type="checkbox"/>
117	23/02/19 12:24	General View	 Load JPG	<input checked="" type="checkbox"/>
118	23/02/19 12:24	General View	 Load JPG	<input checked="" type="checkbox"/>
119	23/02/19 12:24	General View	 Load JPG	<input checked="" type="checkbox"/>
120	23/02/19 12:24	General View	 Load JPG	<input checked="" type="checkbox"/>
121	23/02/19 12:24	General View	 Load JPG	<input checked="" type="checkbox"/>
122	23/02/19 12:24	Odometer Reading	 Load JPG	<input checked="" type="checkbox"/>
123	23/02/19 12:24	Chassis Number	 Load JPG	<input checked="" type="checkbox"/>
124	23/02/19 12:25	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
125	23/02/19 12:25	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
126	23/02/19 12:25	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
127	23/02/19 12:25	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
128	23/02/19 12:25	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
129	23/02/19 12:25	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
130	23/02/19 12:25	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>

Assessment Reports			1 per page	<input checked="" type="checkbox"/>
No	Finalized On	MSIG Insurance (Singapore) Pte. Ltd. (HQ)	Thumbnail	Print
131	23/02/19 12:25	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
132	23/02/19 12:25	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
133	23/02/19 12:25	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
134	23/02/19 12:25	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
135	23/02/19 12:25	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
136	23/02/19 12:25	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
137	23/02/19 12:25	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
138	23/02/19 12:25	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
139	23/02/19 12:25	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
140	23/02/19 12:25	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
141	23/02/19 12:25	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
142	23/02/19 12:25	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
143	23/02/19 12:25	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
144	23/02/19 12:25	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
145	23/02/19 12:25	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
146	23/02/19 12:25	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
147	23/02/19 12:25	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
148	23/02/19 12:25	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
149	23/02/19 12:25	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
150	23/02/19 12:25	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
151	23/02/19 12:25	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
152	23/02/19 12:25	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
153	23/02/19 12:25	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
154	23/02/19 12:25	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
155	23/02/19 12:25	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
156	23/02/19 12:25	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
157	23/02/19 12:25	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
158	23/02/19 12:25	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
159	23/02/19 12:25	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
160	23/02/19 12:25	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
161	23/02/19 12:25	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
162	23/02/19 12:25	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
163	23/02/19 12:25	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
164	23/02/19 12:25	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
165	23/02/19 12:25	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
166	23/02/19 12:25	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
167	23/02/19 12:25	Finishing Photo	 Load JPG	<input checked="" type="checkbox"/>
168	23/02/19 12:25	Finishing Photo	 Load JPG	<input checked="" type="checkbox"/>
169	23/02/19 12:25	Finishing Photo	 Load JPG	<input checked="" type="checkbox"/>
170	23/02/19 12:25	Finishing Photo	 Load JPG	<input checked="" type="checkbox"/>
171	23/02/19 12:25	Finishing Photo	 Load JPG	<input checked="" type="checkbox"/>
172	23/02/19 12:25	Finishing Photo	 Load JPG	<input checked="" type="checkbox"/>
Documentation			1 per page	<input checked="" type="checkbox"/>
No	Finalized On	MSIG Insurance (Singapore) Pte. Ltd. (HQ)	Thumbnail	Print
1	29/01/19 16:21	TP CHOOSE LKX	 Load PDF	
2	29/01/19 16:31	ESTIMATE, NOA AND GIA REPORT	 Load PDF	
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
1	04/03/19 12:14	Supplementary	 Load PDF	

Linked Accident Report Documents

View View in Browser

Assessment Reports			1 per page	<input checked="" type="checkbox"/>
No	Finalized On	ComfortDelGro Engineering Pte Ltd (Loyang)	Thumbnail	Print
1	28/01/19 11:43	Accident Statement	 Load HTM	
2	19/02/19 15:08	Addendum Sheet	 Load TIF	
3	19/02/19 15:08	Accident Statement Addm. #1	 Load HTM	
Photos/Images			3 per page	<input checked="" type="checkbox"/>
No	Finalized On	ComfortDelGro Engineering Pte Ltd (Loyang)	Thumbnail	Print
1	28/01/19 10:52	Accident Photo	 Load JPG	<input checked="" type="checkbox"/>
2	28/01/19 10:52	Accident Photo	 Load JPG	<input checked="" type="checkbox"/>
3	28/01/19 10:52	Accident Photo	 Load JPG	<input checked="" type="checkbox"/>
4	28/01/19 10:52	Accident Photo	 Load JPG	<input checked="" type="checkbox"/>
5	28/01/19 10:52	Accident Photo	 Load JPG	<input checked="" type="checkbox"/>
6	28/01/19 10:52	Accident Photo	 Load JPG	<input checked="" type="checkbox"/>
7	28/01/19 10:52	Accident Photo	 Load JPG	<input checked="" type="checkbox"/>
8	28/01/19 10:52	Accident Photo	 Load JPG	<input checked="" type="checkbox"/>
9	28/01/19 10:52	Accident Photo	 Load JPG	<input checked="" type="checkbox"/>
10	28/01/19 10:52	Accident Photo	 Load JPG	<input checked="" type="checkbox"/>
11	28/01/19 10:52	Accident Photo	 Load JPG	<input checked="" type="checkbox"/>
12	28/01/19 10:52	SCENE	 Load JPG	<input checked="" type="checkbox"/>
13	28/01/19 10:52	SCENE	 Load JPG	<input checked="" type="checkbox"/>
14	28/01/19 10:52	SCENE	 Load JPG	<input checked="" type="checkbox"/>
15	28/01/19 10:52	SCENE	 Load JPG	<input checked="" type="checkbox"/>
16	28/01/19 10:52	SCENE	 Load JPG	<input checked="" type="checkbox"/>
17	28/01/19 10:52	SCENE	 Load JPG	<input checked="" type="checkbox"/>
18	28/01/19 10:52	SCENE	 Load JPG	<input checked="" type="checkbox"/>
19	28/01/19 10:52	SCENE	 Load JPG	<input checked="" type="checkbox"/>
20	28/01/19 10:52	SCENE	 Load JPG	<input checked="" type="checkbox"/>
21	28/01/19 10:52	SCENE	 Load JPG	<input checked="" type="checkbox"/>
22	28/01/19 10:52	SCENE	 Load JPG	<input checked="" type="checkbox"/>
23	28/01/19 10:52	SCENE	 Load JPG	<input checked="" type="checkbox"/>
24	28/01/19 10:53	SCENE	 Load JPG	<input checked="" type="checkbox"/>
Documentation			1 per page	<input checked="" type="checkbox"/>
No	Finalized On	ComfortDelGro Engineering Pte Ltd (Loyang)	Thumbnail	Print
1	28/01/19 13:45	Sketch Plan	 Load TIF	

Documents Checklist

DOCUMENTS CHECKLIST	Reset	Save	Print
There are no document checklists configured.			
Our Checklist Remarks - LKK Auto Consultants Pte Ltd (HQ) <div style="border: 1px solid black; height: 40px; margin-top: 5px;"></div>			
Show Remarks To: <input type="checkbox"/> Handling Insurer <small>Note: Remarks are private unless you show it to other parties.</small>			

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CS/MSG19001958/DVD3E2

Date: 04/03/2019

REFERENCE

Handling Insurer: MSIG Insurance (Singapore) Pte. Ltd.

Policy No: P28959017DMA

Claimant Vehicle No: SHC8919L

Insured Vehicle No: SFH9090S

Date of Loss: 26/01/2019

Nature of Claim: TP

Claim No: 583669

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: SHC8919L

Make & Model: HYUNDAI I40, 1.7 D (A)

Engine No: D4FDGU613578

Reg. Date: 21/04/2016 (Man. Year: 2016)

Chassis No: KMHLB41UMGU087814

Colour: Blue

Odometer: 494986 km

Engine Capacity: 1685 cc

Market Value/New Car Price: N/A

Sum Insured (S\$): Market Value/New Car Price

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable):

Yes Footbrake (Serviceable): Yes

Handbrake (Serviceable): Yes Engine Modification:

No Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 205/60 R16

Rear Tyre Size: 205/60 R16

Front Left Side: West Lake 5 mm

Rear Left Side: West Lake 5 mm

Front Right Side: West Lake 5 mm

Rear Right Side: West Lake 5 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	32,304.82	20,632.50	11,672.32	36.13
Miscellaneous Items	0.00	0.00	0.00	
Labour	7,870.00	3,490.00	4,380.00	55.65
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	40,174.82	24,122.50	16,052.32	39.96
Approved Total (Overridden) (S\$)		19,000.00		
(S\$)	40,174.82	19,000.00	21,174.82	52.71
+ GST 7.00/7.00% (S\$)	2,812.24	1,330.00	1,482.24	52.71
Nett Amount (S\$)	42,987.06	20,330.00	22,657.06	52.71

INSPECTION

Date of Assignment: 30/01/2019

Date Inspected: 29/01/2019 Inspected At:

Chunni Motor Work Pte Ltd (HQ)
BLK 10 ANG MO KIO INDUSTRIAL PARK
2A AUTOPOINT #01-06 S(568047)
Singapore 568047

Estimated Period of Repair: 13.0 days

Adjuster: BRYAN TANI**Manager:** VERON CHEN

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference	
Part Source: MRM-SG	Version: 1.0 (Last Synchronised: 04 Mar 2019)
Parts: 143	HYUNDAI I40 1.7 D (A) (Catalogue:Merimen Singapore 1.0)
Labour: Repairer's	(Price-denominated Standard List)
Print Code: (Unsubmitted, no print-code for SHC8919L)	
Validity: These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info: Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*RADIATOR GRILLE	Cracked	1,110.10 FL	*1,110.10 FL
2	1		*RADIATOR GRILLE H EMBLEM	Necessary	120.30 FL	*120.30 FL
3	1		*FRONT BUMPER COVER	Mtg Cracked / Distorted	1,052.20 FL	*1,052.20 FL
4	1		*FRONT BUMPER SPONGE	Torn	99.20 FL	*99.20 FL
5	1		*FRONT BUMPER REINFORCEMENT	Bent	402.10 FL	*402.10 FL
6	2		*FRONT BUMPER BRACKET TOP (LH/RH)	Serviceable	44.80 FL	*- FL
7	2		*FRONT BUMPER BRACKET (LH/RH)	Not Necessary	49.20 FL	*- FL
8	1		*HEADLAMP SUPPORT TOP COVER	Not Necessary	222.60 FL	*- FL
9	1		*HEADLAMP SUPPORT PANEL ASSY	Bent	907.40 FL	*907.40 FL
10	2		*HEADLAMP (LH/RH)	Mtg Broken	2,776.00 FL	*2,776.00 FL
11	1		*RADIATOR	Bent	698.30 FL	*698.30 FL
12	1		*RADIATOR FAN BLADE, COWLING, MOTOR ASSY	Not Necessary	792.95 FL	*- FL
13	2		*RADIATOR BRACKET (RH/LH)	Not Necessary	13.00 FL	*- FL
14	2		*RADIATOR GUARD	Broken	40.00 FL	*40.00 FL
15	2		*HORN UNIT (LH/RH)	Broken	147.60 FL	*147.60 FL
16	1		*AIRCON CONDENSER	Bent	927.50 FL	*927.50 FL
17	1		*INTER COOLER	Bent	1,032.50 FL	*1,032.50 FL
18	2		*INTER COOLER MOUNTING	Not Necessary	25.90 FL	*- FL
19	1		*FRONT NUMBER PLATE	Cracked	25.00 FS	*25.00 FS
20	1		*FRONT NO PLATE TRIM COVER	Serviceable	30.00 FS	*- FS
21	1		*BOOTLID	Buckled	2,174.90 FL	*2,174.90 FL
22	1		*BOOT LID RUBBER	Deformed	96.50 FL	*96.50 FL
23	2		*BOOT LID HINGE (LH/RH)	Repair	284.60 FL	*- FL
24	1		*BOOT LID LOCK UPPER	Bent	102.60 FL	*102.60 FL
25	1		*BOOT LID LOCK LOWER	Bent	31.70 FL	*31.70 FL
26	1		*BOOT LID CATCH HANDLE	Not Necessary	198.00 FL	*- FL
27	1		*BOOT LID H EMBLEM	Necessary	28.70 FL	*28.70 FL
28	1		*BOOT LID CRDI PLATE	Necessary	27.90 FL	*27.90 FL
29	2		*BOOT LID LAMP (LH/RH)	Cracked / Broken	1,131.20 FL	*1,131.20 FL
30	2		*LICENCE LAMP (LH/RH)	Serviceable	67.90 FL	*- FL
31	1		*BOOT LID TRIMBOARD	Torn	116.40 FL	*116.40 FL
32	10		*BOOT LID TRIMBOARD CLIPS	Necessary	11.00 FL	*11.00 FL
33	1		*BOOTLID MOULDING	Dislodged	85.00 FL	*85.00 FL
34	1		*BOOTLID I40 EMBLEM	Necessary	27.90 FL	*27.90 FL
35	1		*BOOTLID LOWER GARNISH	Broken	227.90 FL	*227.90 FL
36	1		*REAR BUMPER	Broken	553.00 FL	*553.00 FL
37	1		*REAR BUMPER REINFORCEMENT	Broken	428.40 FL	*428.40 FL
38	2			Dented	160.60 FL	*160.60 FL

Report was unsubmitted during this print-out.

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
			*REAR BUMPER REINFORCEMENT BRACKET (LH/RH)			
39	10		*REAR BUMPER CLIP	Necessary	22.00 FL	*22.00 FL
40	1		*REAR BUMPER SPONGE	Torn	118.40 FL	*118.40 FL
41	1		*REAR BUMPER UNDER COVER	Dislodged	228.00 FL	*228.00 FL
42	2		*REAR BUMPER REFLECTOR LAMP (LH/RH)	Cracked / Broken	61.20 FL	*61.20 FL
43	2		*TAIL LAMP (LH/RH)	Broken / Cracked	1,395.60 FL	*1,395.60 FL
44	2		*TAIL LAMP QUARTER PANEL (LH/RH)	Dented	453.00 FL	*453.00 FL
45	1		*REAR PANEL	Buckled	526.70 FL	*526.70 FL
46	1		*REAR PANEL GARNISH	Mtg Deformed	57.70 FL	*57.70 FL
47	1		*REAR PANEL LOWER PANEL	Dented	495.50 FL	*495.50 FL
48	1		*SPARE TYRE HOLDER	Not Necessary	248.00 FL	*- FL
49	2		*TAIL LAMP PANEL TOP (LH/RH)	Not Necessary	1,091.80 FL	*- FL
50	1		*SPARE TYRE PANEL	Dented	852.80 FL	*852.80 FL
51	1		*SPARE TYRE PANEL CUSHION	Serviceable	209.05 FL	*- FL
52	1		*REAR TOWING HOOK	Not Necessary	94.60 FL	*- FL
53	1		*MEMBER ASSY-REAR FLOOR CENTRE	Not Necessary	570.40 FL	*- FL
54	2		*PANEL ASSY-REAR FLOOR SIDE (LH/RH)	Repair	180.20 FL	*- FL
55	1		*REAR FLOOR CHASSIS MEMBER	Repair	3,636.20 FL	*- FL
56	2		*EXHAUST PIPE INSULATOR	Not Necessary	117.10 FL	*- FL
57	2		*EXHAUST SILENCER	Bent	1,935.40 FL	*1,935.40 FL
58	2		*EXHAUST PIPE HANGER	Not Necessary	117.10 FL	*- FL
59	1		*EXHAUST PIPE CENTRE	Not Necessary	730.10 FL	*- FL
60	2		*REAR FENDER (LH/RH)	Dented	9,473.60 FL	*4,040.00 FL
61	2		*REAR FENDER INNER LINING (LH/RH)	Not Necessary	338.60 FL	*- FL
62	1		*REAR FENDER AIR-DUCT	Not Necessary	51.60 FL	*- FL
63	2		*REAR FENDER TRIM BOARD (LH/RH)	Bent	377.50 FL	*377.50 FL
64	1		*REAR WINDSCREEN MOULDING	Necessary	28.30 FL	*28.30 FL
65	1		*FUEL LID COVER	Dislodged	70.90 FL	*70.90 FL
66	1		*BOOT LID COMFORT LOGO & TEL NO. STICKER	Necessary	30.00 FS	*30.00 FS
67	1		*REAR NO. PLATE	Cracked	25.00 FS	*25.00 FS
68	1		*REAR BUMPER REVERSE SENSOR	Damaged	135.70 FS	*135.70 FS
69	1		*REAR WINDSCREEN SEALANT	Necessary	46.00 FS	*46.00 FS
70	1		*REAR SPARE TYRE BRACKET	Bent	248.00 FL	*248.00 FL
71	1		*REAR BUMPER BRACKET	N/S Broken / O/S Serviceable	71.20 FL	*35.60 FL

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (S\$) **40,308.10** **25,725.20**
 - List Item Discount on L Items 20.00/20.00% (S\$) 8,003.28 5,092.70

Total Parts (S\$) **32,304.82** **20,632.50**

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<u>Labour Items</u>				
1	PANEL BEATING	New	3,600.00	1,700.00
2	SPRAY PAINTING CHARGE	New	2,050.00	1,200.00
3	WIRING CHARGE	New	150.00	60.00
4	TOWING CHARGE	New	50.00	0.00
5	DIAGNOSTIC & RESETTING TO ERASE FAULT CODE	New	480.00	0.00
6	TUFF KOTE	New	150.00	40.00
7	REAR CHASSIS ALIGNMENT CHARGE	New	400.00	150.00
8	REMOVE / REFIX CUSHION & UPHOLSTERY REAR	New	150.00	80.00
9	REMOVE / REFIX REAR WINDSCREEN GLASS	New	120.00	80.00
10	REMOVE / REFIX REVERSE SENSOR	New	120.00	40.00
11	REMOVE / REFIX FUEL TANK	New	150.00	0.00
12	REMOVE / REFIX EXHAUST PIPE	New	300.00	60.00
13	REMOVE / REFIX AIRCON & REFILL GAS	New	150.00	80.00
Gross Labour Cost (S\$)			7,870.00	3,490.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >