

ASS. REC. BY:

REF: CS/FCI19001966/Dsd3n2 Special Instruction:

Surveyor:

Byen

ASSIGNMENT (Office)

CWS

From (Person):

Sithara

of

FCI

Date/Time: 6:18pm @ 29/1/19

Estimated Cost:

Bill to:

OD ☒ TP / WS / TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No:

SHA 5275R

Insured:

SHC 7223S

at Workshop m/s

Chunni Motor

Tel:

65425119

of

AMK Autopoint #01-05/06

Policy No:

Claim No:

D19000710MFSH

Sum Insured:

Excess:

Make of Veh:

(Client's Record)

D.O.A.

26/01/2019

CA / REV / REP. / REV 24 HRS ^{up}

H.O.D. Endorsement:

Date/Time:

9:20am @ 30/1/19

Person Contacted:

Lynn

Vehicle ☒ IN / OUT

Date/Time	Action/Instruction (✓) Estimate
	SHA 5275R - CC4 / III 1801468 / Ahb3
	SHC 7223S - NR / INC 1000782 / p1
31/01/19	@ 12:00 p.m. remind PA to sithara via email.

DUA: 31/7/18

DUA: 11/01/2010

REF:

ASSIGNMENT

COE June 2024

From: _____ Date: _____
 Estimated Cost: _____
 OD / TP / WS / TP RES / OD RES / EVA / INV / MV
 To Inspect Vehicle No: _____
 at Workshop m/s _____
 of _____
 Insured _____
 Policy No. _____
 Claims No. _____
 Sum Insured: _____ Excess: _____
 (Client's Record)
 Make of Veh: _____

(Policy Condition)

Remark: The veh had commenced its
 repair at the time of inspection.

☒	☐
N/S	O/S
☐	☐

Bal. or Market Value: _____
 IDAC Accident Rpt: _____ Consistent?: Yes or No
 GIA / PR Seen: _____ Consistent?: Yes or No
 Est. Repairs: 6 days Res.: Yes or No
 Lum Sum: 20 % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Vehicle: IN / OUT

Date: _____ Person Contacted: _____

Veh No: SHA 5275R Yr Regn: 2016 June
 Type: M. Car / M. Cycle / Bus / Van / Lorry ☒ Taxi / Prime Mover /
 Truck / Trailer or
 Make: Hyundai I40 C.C. 1685
 Colour: Blue A/C: Insured / Std / NI / NA
 Sp Reading: 316277 T/Radio: Insured / Std / NI / NA
 Eng/No: D4FDGUG26534
 C/No: KMHLB41UMGU090160
 Gen. Cond: ☒ Good / Fair / Poor / Burnt
 Steering: ☒ In order / Jammed / Leaked / Burnt or
 Brake: ☒ In order / Jammed / Leaked / Burnt or
 Modi: ☒ Nil S/Rim / STD A/Rim or

Tyre Size: F: 205/60R14
 R: — " —

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /
 TOYO / YOKO or Campion

Front _____ Rear _____
 R/Bal. 5 mm R/Bal. 5 mm
 L/Bal. 5 mm L/Bal. 5 mm
 D.O.A. 26/01/2019 D.O.I. 29/01/2019
 Survey held at Chunni AMIC

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or
Front - N/S

The U/C / Chassis frame / Body Structure affected due to collision

Date / Time Action / Instruction

First Capital SHC 72238

28/12/19 Jinapu 4/5 13500/- with 6 days.

(\$ 7,560.24 Rd - 36%)

RECEIVED 01 MAR 2019.

Date/Time, File Pass to?

01/03/19
Typist

1)

Date/Time, File Return to?

2)

☐
☒

Preli. Report

Final Report

Days Of Repair: 6Resurvey No. of Trip: 2

Add Fee: ☐ Site Insp (\$)
☐ Interview (\$)
☐ Tech Invs (\$)
☐ Weekend (\$)

Survey Fee:

Transportation

) \$ + RS \$

) Photo

) Film

) Total

TOTAL

1/3/19

11x15 = 165

170+165

50

50+50

134

619

Report Format:

Lump Sum / I.B.I. (\$) 13,500/- 4/5



Auto
Consultants
Pte Ltd

Company Registration No. 199607198R

51 UBI AVE 1, #02-25 PAYA UBI INDUSTRIAL PARK, SINGAPORE 408933 TEL : (065) 62563561 FAX : (065) 62564315

Your Ref: D19000710MFSH

Date: 31 January 2019

Our Ref: CS/FCI19001966/Dsd3

The Motor Claims Department
First Capital Insurance Ltd

Dear Sir/Madam,


INITIAL INSPECTION REPORT OF VEHICLE NO. SHA 5275R

Please be informed that we had conducted the inspection of the abovementioned vehicle on 29/01/2019 at the premises of M/s Chunni Motor Work Pte Ltd and have the following to report:-

Workshop Estimate Amount	: S\$ 21,060.84 .
Revised Estimate Amount	: S\$ 17,032.20 .
"Check" Items Amount	: S\$.
Market Value	: S\$.
LTA Reimbursement Value	: S\$.
Nett Value	: S\$.

Description of Damage:

The vehicle sustained damages at the front n/s portion.



Comments/ Present Status:

Damages Consistent.
Repair days: 6 Days

Yours faithfully,
Bryan Ang
Automotive Assessor

MOTOR SURVEY ASSIGNMENT

Date	28-01-2019	Our Ref No. D19000710MFSH
Accident Date	26-01-2019	Claim Type. Third Party
Insured Vehicle	SHC7223S	Third Party Vehicle. SHA5275R
Survey Location	AMK AUTOPOINT, SOON HOCK MOTOR, #01-05/06	
Contact Person.	LYNN OR IRENE - 65421726	
Contact No.	65427162/ 65425119	Fax No. 65426039
Survey Type	WITHOUT PREJUDICE:	
Appointed Surveyor	LKK AUTO CONSULTANTS PTE LTD	
Contact Person	NA	Fax No. 68416315
Contact Number.	NA	

FOR DIRECT SETTLEMENT

Please submit to us the Tax Invoice together with letter of claim for Rental OR Loss of use (based on NIMA Benchmark rates) together with your survey report.

THIRD PARTY SURVEY REQUEST

Cc : Workshop	CHUNNI MOTOR WORK PTE LTD	Attention. NIL
Cc : TP Solicitor	NA	TP Solicitor Fax No. NA
Officer Incharge	SITHARA	

IMPORTANT NOTE

Kindly submit the survey report via CWS within 14 days for survey assignment and 7 days for re-inspection.
This is a computer generated letter, no signature required.

Shirley Hiew (LKK Auto)

From: Shirley Hiew (LKK Auto) <ShirleyHiew@lkkauto.com>
Sent: Thursday, 31 January 2019 6:00 PM
To: 'Sithara'; 'CWS Motor Claims'
Cc: 'assignments'; 'SUR'; 'Admin-D (LKKAuto)'
Subject: RE: SURVEY ASSESSMENT - D19000710MFSH/1
Attachments: SHA 5275R - Preli Advise .pdf

Dear Sithara,

Enclosed preliminary revised of vehicle SHA 5275R.

Thank you.

Best Regards,

Shirley Hiew | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email: Sur@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Admin-D (LKKAuto) [mailto:admin-d@lkkauto.com]
Sent: Wednesday, 30 January 2019 9:22 AM
To: 'CWS Motor Claims' <cwsmotorclaims@msfirstcapital.com.sg>; assignments <assignments@lkkauto.com>
Cc: 'Sithara' <Sithara@msfirstcapital.com.sg>; SUR <sur@lkkauto.com>
Subject: RE: SURVEY ASSESSMENT - D19000710MFSH/1

Dear Sir/Mdm,

Thank you for the assignment.

BEST REGARDS,

G.Nivitha | Admin

LKK Auto Consultants Pte Ltd

Phone: 6841-1972 | email: assignments@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: CWS Motor Claims [mailto:cwsmotorclaims@msfirstcapital.com.sg]
Sent: Tuesday, 29 January 2019 6:18 PM
To: ASSIGNMENTS@LKKAUTO.COM
Cc: CWS Motor Claims <cwsmotorclaims@msfirstcapital.com.sg>; Sithara <Sithara@msfirstcapital.com.sg>
Subject: PRI: SURVEY ASSESSMENT - D19000710MFSH/1

Dear Sir/Mdm,

We refer to the above reference.

Please find attached the necessary documents for survey.

Kindly submit your report via CWS within the next 14 days.

Note: All the accident reports are uploaded into CWS for your perusal.

Best Regards,
Admin Team
Claim Workflow System
Motor Claims Department
MS First Capital Insurance Limited
Tel : 6507 3848
Fax : 6507 3849

PS: This is a system generated mail. Please do not reply to this mail.



This email has been checked for viruses by AVG antivirus software.
www.avg.com

CHUNNI MOTOR WORK PTE LTD**REPAIR ESTIMATE***

VEHICLE NO : SHA 5275R

DATE : 28.01.2019

MAKE :

TEL : 6542 5119


MODEL : HYUNDAI i40

FAX : 6542 6039

FCI

Qty	Parts Description/ Labour	Type	Unit Price	Amount
	Bonnet vt			\$ 2,265.90 ✓
	Radiator Grille broken			\$ 1,110.10 ✓
	Radiator Grille H Emblem New			\$ 120.30 ✓
	Front Bumper Cover torn			\$ 1,052.20 ✓
	Front Bumper Sponge torn			\$ 99.20 ✓
	Front Bumper Reinforcement vt			\$ 402.10 ✓
	Front Bumper Grille (LH) damaged			\$ 93.60 ✓
	Front Bumper Grille Airduct (LH) broken New			\$ 26.20 X
	Front Bumper Bracket Top (LH) New			\$ 22.40 X
	Front Bumper Bracket (LH) broken			\$ 24.60 ✓
	Headlamp Support Top Cover New			\$ 222.60 X
	Headlamp Support Panel Assy broken			\$ 907.40 ✓
	Headlamp (LH) broken			\$ 1,388.00 ✓
	Headlamp Halogen Bulb (LH) New			\$ 14.40 X
	Front Fender (LH) damaged			\$ 566.30 ✓
	Front Fender Apron Panel (LH) damaged			\$ 637.00 ✓
	Front Fender Shield (LH) svc			\$ 174.90 X
	Air Cleaner Bottom Assy broken mounting			\$ 325.00 ✓
	Front Wheel Rim (LH) distorted			\$ 325.30 ✓
	Front Wheel Hub Cap (LH) cut			\$ 107.10 ✓
	Front Wheel Bearing Done			\$ 540.50 ✓
	Front Shock Absorber (Assy) (LH) distorted			\$ 342.20 ✓
	Front Shock Absorber Mounting (LH) New			\$ 108.80 X
	Front Drive Shaft (LH) Done			\$ 1,030.80 ✓
	Rack & Pinion Assy Done			\$ 969.60 ✓
	STG Tie End distorted			\$ 62.60 ✓
	Front Suspension Lower Arm (LH) distorted			\$ 529.30 ✓
	Knuckle Arm (LH) distorted			\$ 552.00 ✓
	Engine Crossmember distorted			\$ 2,094.40 ✓
	ABS Sensor New			\$ 234.00 X
	Wiring-Engine hanging broken			\$ 3,326.00 ✓
			18871.50	
			15097.20	
	SUB TOTAL			\$ 19,674.80
	LESS 20%			\$ 3,934.96
	DISCOUNTED TOTAL			\$ 15,739.84
	Front Door Comfort Logo (LH) New			\$ 75.00 Nett ✓
	Front Tyre (LH) svc		75.00	\$ 216.00 Nett X
				\$ 291.00

SHA 5275R

Qty	Parts Description/ Labour	Type	Unit Price	Amount
	Labour Charge			\$ 1,500.00 600/-
	Panel Beating			\$ 1,000.00 600/-
	Spray Painting Charge			\$ 50.00 30/-
	Wiring Charge			\$ 100.00 40/-
	Tuff Kote			\$ 50.00 44
	Towing Charge			\$ 200.00 150/-
	Remove/Refix Undercarriage (FRT)			\$ 120.00 60/-
	FRT Wheel Alignment			\$ 150.00 44
	Remove/Refix Aircon & Refill Gas			\$ 550.00 44
	Remove/Refix Engine			\$ 450.00 150/-
	Remove/Refix Dashboard			\$ 180.00 50/-
	Remove/Refix Fuse Box			\$ 200.00
	Re-set Frt ABS System			\$ 480.00 180/-
	Diagnostic & Resetting To Erase Fault Code			
	TOTAL LABOUR			\$ 5,030.00
	ESTIMATE TOTAL			\$ 21,060.84
	29/01/2019 C 1600m		17032.20	
	Wt Antu		13500/-	
	2/5m 6 days			
				
	LKK Auto			
				
	LKK Auto Consultants hence notify the Repairer of the following: • To resurvey before/after spray painting • To display damaged part(s) during resurvey • Parts prices are subject to confirmation • Third party survey is on a "Without Prejudice" basis • No illegal modification(s) is allowed • Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company Acknowledged by Repairer Signature: Date:			

This is an initial estimate based on a visual inspection of the above vehicle. The final repair quantum will be prepared after the vehicle is surveyed by a motor Surveyor appointed by the insurance company.

NAME
ADDRESS

Home Tel.:

VIN:

Registration: SHA 5275 R

Technician:

Mileage: 316277

Time Printed 29.1.19 4:37 PM

HYUNDAI I40

Front : Left

Actual	BEFORE	Specified Range
7°26'		-3°00' 3°00'
3°30'		-0°19' 5°41'
8°02'		-1°30' 1°30'
8°34'		
15°59'		

Camber
Caster
Toe
SAI
Included Angle
Turning Angle Diff.

Front : Right

Actual	BEFORE	Specified Range
2°31'		-3°00' 3°00'
3°54'		-0°19' 5°41'
0°03'		-1°30' 1°30'
13°27'		
15°58'		

Front

Cross Camber
Cross Caster
Cross SAI
Total Toe
Cross Turn Diff.

Actual	BEFORE	Specified Range
4°55'		-3°00' 3°00'
-0°25'		-3°00' 3°00'
-4°54'		-3°00' 3°00'
8°05'		-3°00' 3°00'

Rear : Left

Actual	BEFORE	Specified Range
-1°37'		-3°30' 2°30'
0°26'		-1°30' 1°30'

Camber
Toe

Rear : Right

Actual	BEFORE	Specified Range
-0°14'		-3°30' 2°30'
-0°19'		-1°30' 1°30'

Rear

Cross Camber
Total Toe
Thrust Angle

Actual	BEFORE	Specified Range
-1°24'		-3°00' 3°00'
0°07'		-3°00' 3°00'
0°22'		-3°00' 3°00'



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
MS FIRST CAPITAL INSURANCE LTD		Ref : CS/FCI19001966/Dsd3n2		
36 ROBINSON ROAD #16-01 CITY HOUSESINGAPORE 068877		Date : 04-03-2019		
		Code : FCI2		
1. Policy Particulars :- THIRD PARTY CLAIM				
Insured Veh.	SHC 7223S	Veh. Inspected	SHA 5275R	
Policy No.		Coverage (\$)	0.00	
Claim No.	D19000710MFSH	Excess (\$)	0.00	
Assign From	SITHARA	Assign Date	29/01/2019	
2. Vehicle Particulars & Condition				
Make & Model	HYUNDAI I40	c.c	1685	
Engine No.	HIDDEN	Year of Reg.	2016	
Chassis No.	KMHLB41UMGU090160	Colour	BLUE	
Odometer	316277	Steering	IN ORDER	
Brakes	IN ORDER	Modification	NIL	
General	GOOD			
3. Conditions of Tyres				
	Size	Make	Balance	
R/H Front Tyre	205/60 R16	CAMPEON	5 mm	
L/H Front Tyre	205/60 R16	CAMPEON	5 mm	
R/H Rear Tyre	205/60 R16	CAMPEON	5 mm	
L/H Rear Tyre	205/60 R16	CAMPEON	5 mm	
4. Description of Damages				
THE VEHICLE SUSTAINED DAMAGES AT THE FRONT N/S PORTION. DAMAGES SEE DETAILS.				
5. General Information				
Accident Date	26/01/2019	Inspection Date	29/01/2019	
Survey held at	CHUNNI MOTOR WORK PTE LTD BLK 10 ANG MO KIO IND. PARK 2A, #03-19 AMK AUTOPOINT SINGAPORE 568047.			
5a. Remarks				
A) DAMAGES CONSISTENT TO ACCIDENT REPORT. B) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS. C) IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.				
5b. Estimate Days of Repair				
ESTIMATED NORMAL PERIOD FOR REPAIR:		6 Working Days		



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 2

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SHA 5275R

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	REPLACEMENT OF PARTS			
1	BONNET	BENT	2,265.90	2,265.90
1	RADIATOR GRILLE	BROKEN	1,110.10	1,110.10
1	RADIATOR GRILLE H EMBLEM	NECESSARY	120.30	120.30
1	FRONT BUMPER COVER	TORN	1,052.20	1,052.20
1	FRONT BUMPER SPONGE	TORN	99.20	99.20
1	FRONT BUMPER REINFORCEMENT	BENT	402.10	402.10
1	FRONT BUMPER GRILLE (LH)	DEFORMED	93.60	93.60
1	FRONT BUMPER GRILLE AIRDUCT (LH)	NOT NECESSARY	26.20	-
1	FRONT BUMPER BRACKET TOP (LH)	NOT NECESSARY	22.40	-
1	FRONT BUMPER BRACKET (LH)	BROKEN	24.60	24.60
1	HEADLAMP SUPPORT TOP COVER	NOT NECESSARY	222.60	-
1	HEADLAMP SUPPORT PANEL ASSY	BROKEN	907.40	907.40
1	HEADLAMP (LH)	BROKEN	1,388.00	1,388.00
1	HEADLAMP HALOGEN BULB (LH)	NOT NECESSARY	14.40	-
1	FRONT FENDER (LH)	DENTED	566.30	566.30
1	FRONT FENDER APRON PANEL (LH)	DENTED	637.00	637.00
1	FRONT FENDER SHIELD (LH)	SERVICEABLE	174.90	-
1	AIR CLEANER BOTTOM ASSY	MOUNTING BROKEN	325.00	325.00
1	FRONT WHEEL RIM (LH)	DISTORTED	325.30	325.30
1	FRONT WHEEL HUB CAP (LH)	CUT	107.10	107.10
1	FRONT WHEEL BEARING	DAMAGED	540.50	540.50
1	FRONT SHOCK ABSORBER (ASSY)(LH)	DISTORTED	342.20	342.20
1	FRONT SHOCK ABSORBER MOUNTING (LH)	NOT NECESSARY	108.80	-
1	FRONT DRIVE SHAFT (LH)	DAMAGED	1,030.80	1,030.80
1	RACK & PINION ASSY	DAMAGED	969.60	969.60
1	STG TIE END	DISTORTED	62.60	62.60
1	FRONT SUSPENSION LOWER ARM (LH)	DISTORTED	529.30	529.30
1	KNUCKLE ARM (LH)	DISTORTED	552.00	552.00
1	ENGINE CROSSMEMBER	DISTORTED	2,094.40	2,094.40
1	ABS SENSOR	NOT NECESSARY	234.00	-

Report Ref No. CS/FCI19001966/Dsd3n2



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:2 of 2

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
1	WIRING-ENGINE LESS 20% DISCOUNT	HOUSING BROKEN	3,326.00 -3,934.96 15,739.84	3,326.00 -3,774.30 15,097.20
	SPECIAL NETT ITEMS			
1	FRONT DOOR COMFORT LOGO (LH)(SN)	NECESSARY	75.00	75.00
1	FRONT TYRE (LH)(SN)	SERVICEABLE	216.00	-
			291.00	75.00
	LABOUR			
	PANEL BEATING.		1,500.00	600.00
	SPRAY PAINTING CHARGE.		1,000.00	600.00
	WIRING CHARGE.		50.00	30.00
	TUFF KOTE.		100.00	40.00
	TOWING CHARGE.	NOT NECESSARY	50.00	-
	REMOVE/REFIX UNDERCARRIAGE (FRT).		200.00	150.00
	FRT WHEEL ALIGNMENT.		120.00	60.00
	REMOVE/REFIX AIRCON & REFILL GAS.	NOT NECESSARY	150.00	-
	REMOVE/REFIX ENGINE.	NOT NECESSARY	550.00	-
	REMOVE/REFIX DASHBOARD.		450.00	150.00
	REMOVE/REFIX FUSE BOX.		180.00	50.00
	DIAGNOSTIC & RESETTING TO ERASE FAULT CODE. }		480.00	180.00
	RE-SET FRT ABS SYSTEM. }		200.00	-
			5,030.00	1,860.00
	GRAND TOTAL		21,060.84	17,032.20
	RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION)			13,500.00

Report Ref No. CS/FCI19001966/Dsd3n2

ANG BRYAN TANI

Automotive Assessor / Investigator

ADRIAN LING WAI PING

B.Eng,AMSOE,AMIRTE,AMSAE-A,M.MATAI

Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.
No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.