

**LKK Auto Consultants Pte Ltd** (Co.Reg.No:199607198R)51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park  
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

**VEHICLE DAMAGE INSPECTION REPORT****Our File No:**

CC3/AXA16009524/KEA3Q2-1

**Date:**

08/10/2021

REFERENCE

Handling Insurer:	AXA Insurance Pte Ltd	Policy No:	GA089526
<b>Claimant Vehicle No :</b>	SHD9996B	<b>Insured Vehicle No :</b>	SKR7686A
Date of Loss:	20/05/2016	Nature of Claim:	TP
		Claim No:	C0384994

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	<b>SHD9996B</b>		
Make & Model:	RENAULT LATITUDE, 2.0 CVT ABS (A)	Engine No:	M9R8839C001430
Reg. Date:	13/06/2014 (Man. Year: 2014)	Chassis No:	VF1ABL15AUC278150
Colour:	Metallic White/Red	Odometer:	188454 km
Engine Capacity:	1995 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	<b>Market Value/New Car Price</b>		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:		Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:	

CONDITION OF TYRES

Front Tyre Size:	215/60 R16	Rear Tyre Size:	215/60 R16
Front Left Side:	Falken 9 mm	Rear Left Side:	Falken 7 mm
Front Right Side:	Falken 9 mm	Rear Right Side:	Falken 7 mm

*The above values represent the remaining tyre treads depth*

<b>COST OF CLAIMS</b>	<b>Repairer's</b>	<b>Adjuster's</b>	<b>Difference</b>	<b>Diff %</b>
Parts	12,323.46	2,953.92	9,369.54	76.03
Miscellaneous Items	0.00	0.00	0.00	
Labour	8,770.00	1,590.00	7,180.00	81.87
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
<b>Gross Total (S\$)</b>	<b>21,093.46</b>	<b>4,543.92</b>	<b>16,549.54</b>	<b>78.46</b>
<b>+ GST 7.00/7.00% (S\$)</b>	<b>1,476.54</b>	<b>318.07</b>	<b>1,158.47</b>	<b>78.46</b>

<b>Nett Amount (S\$)</b>	<b>22,570.00</b>	<b>4,861.99</b>	<b>17,708.01</b>	<b>78.46</b>
<hr/>				
+ Loss of Use (5.0 x S\$50.00/day) (S\$)		250.00		
+ Car Rental (5.0 x S\$132.68/day) (S\$)		663.40		
+ Doc/Search Fee (S\$)		6.00		
<hr/>				
<b>Nett Liability (S\$)</b>		<b>5,781.39</b>		
<hr/>				

INSPECTION

Date of Assignment:	25/05/2016		
Date Inspected:	23/05/2016	Inspected At:	Trans-cab Auto Services Pte Ltd (Ang Mo Kio) 2, Ang Mo Kio Street 63 Singapore 569111
Estimated Period of Repair:	3.0 days		

**Adjuster:** KENNETH KONG**Manager:** Asher Sng Rong Yi

*NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.*

## REPAIR DETAILS

### Reference

<b>Part Source:</b>	MRM-SG	Version: 1.0 (Last Synchronised: 10 Jan 2018)
<b>Parts:</b>	143	RENAULT LATITUDE 2.0 CVT ABS (A) (Catalogue:Merimen Singapore 1.0)
<b>Labour:</b>	Repairer's	(Price-denominated Standard List)
<b>Print Code:</b>	(Unsubmitted, no print-code for SHD9996B)	
<b>Validity:</b>	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
<b>Further Info:</b>	Items/values not in reference catalogue are prefixed with an asterisk *.	

### Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*BUMPER COVER REAR (CONSISTENT)	Buckled	852.66 FL	*852.66 FL
2	1		*BUMPER LOWER REAR (CONSISTENT)	Serviceable	591.41 FL	*- FL
3	1		*BUMPER BRACKET CTR REAR (CONSISTENT)	Serviceable	87.29 FL	*- FL
4	1		*BUMPER BRACKET SIDE LH REAR (CONSISTENT)	Serviceable	104.59 FL	*- FL
5	1		*BUMPER RETAINER LH REAR (CONSISTENT)	Distorted	34.61 FL	*34.61 FL
6	1		*BUMPER REFLECTOR LH (CONSISTENT)	Serviceable	33.55 FL	*- FL
7	1		*FENDER PANEL REAR LH (CONSISTENT)	Repair	2,537.80 FL	*- FL
8	1		*FENDER WHEELARCH REAR LH (CONSISTENT)	Serviceable	418.06 FL	*- FL
9	1		*TAILLAMP LH (CONSISTENT)	Serviceable	425.04 FL	*- FL
10	1		*ROCKER PANEL OUTER LH (CONSISTENT)	Repair	759.61 FL	*- FL
11	1		*DOOR REAR LH (CONSISTENT)	Bent / Warped	2,188.20 FL	*2,188.20 FL
12	1		*DOOR WEATHERSTRIP REAR LH L70Y (CONSISTENT)	Serviceable	304.23 FL	*- FL
13	1		*DOOR PANEL FRT RH L70Y (CONSISTENT)	Repair	1,823.50 FL	*- FL
14	1		*DOOR WEATHERSTRIP FRT LH L70Y (CONSISTENT)	Serviceable	304.23 FL	*- FL
15	1		*DOOR MIRROR RH L70Y (CONSISTENT)	Serviceable	950.90 FL	*- FL
16	1		*DOOR MIRROR GLASS RH L70Y (CONSISTENT)	Serviceable	155.34 FL	*- FL
17	1		*DOOR MIRROR BACK COVER RH L70Y (CONSISTENT)	Serviceable	140.04 FL	*- FL
18	1		*DOOR MIRROR COVER INNER FRT RH L70Y (CONSISTENT)	Serviceable	60.97 FL	*- FL
19	1		*DOOR MIRROR LAMP RH L70Y (CONSISTENT)	Serviceable	124.48 FL	*- FL
20	1		*SET PARKING AID (CONSISTENT)	Serviceable	600.00 FS	*- FS
21	1		*SET REAR BUMPER CLIP (CONSISTENT)	Necessary	66.00 FS	*66.00 FS
22	1		*RIM (ROUE 7J 16H 2547) RH RR (CONSISTENT)	Serviceable	385.00 FS	*- FS
23	1		*TYRE RH RR (CONSISTENT)	Serviceable	330.00 FS	*- FS
24	1		*CAP HUB RH REAR (CONSISTENT)	Serviceable	35.60 FS	*- FS
25	1		*DOOR STICKER 6555-3333 (CONSISTENT)	Necessary	80.00 FS	*60.00 FS
26	1		*DOOR STICKER TRANS-CAB (CONSISTENT)	Necessary	120.00 FS	*60.00 FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

Report was unsubmitted during this print-out.

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount	
					Sub Total (\$)	13,513.11	3,261.47
					- List Item Discount on L Items 10.00/10.00% (\$)	1,189.65	307.55
					Total Parts (\$)	12,323.46	2,953.92

Report was unsubmitted during this print-out.

## Recommended Miscellaneous Items

There are no new miscellaneous items selected.

## Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<b><u>Labour Items</u></b>				
1	PANEL BEATING ,KNOCKING AND STRAIGHTENING THE NECESSARY PORTION,REMOVE AND RENEWAL OF PARTS ,ADJUST AND REALIGN THE SAME	New	3,600.00	500.00
2	PUTTY AND SPRAY PAINTING OF THE AFFECTED PORTION	New	3,600.00	880.00
3	TO RUST-PROOFING OF THE AFFECTED AREAS	New	170.00	30.00
4	TO REINSTALL REAR BUMPE PARKING SENSOR	New	170.00	60.00
5	TO REMOVE AND REPLACE CORPORATE STICKER	New	330.00	0.00
6	TO CHECK STEERING GEOMETRY AND COMPUTER WHEEL ALIGNMENT	New	220.00	0.00
7	TO TRANSFER OF TIRE ,RIM AND ON WHEEL BALANCING	New	170.00	0.00
8	TO TRANSFER OF DOOR FITTINGS ,ATTACHMENTS AND PERFORM WATER SEEPAGE TEST	New	340.00	60.00
9	TO TRANSFER OF FENDER FITTINGS ,ATTACHMENTS AND PERFORM WATER SEEPAGE TEST	New	170.00	60.00
<b>Gross Labour Cost (\$\$)</b>			<b>8,770.00</b>	<b>1,590.00</b>

Report was unsubmitted during this print-out.

< END OF ESTIMATES >