

BH AUTO SERVICES PTE LTD

Blk 1, Sector C, Sin Ming Industrial Estate #01-111 / 113 / 115 / 117 Singapore 575636

Tel: 6559 8944 / Fax: 6269 2404

China Taiping Insurance (Singapore) Pte Ltd

105 Cecil Street

#19-00 The Octagon

Singapore 069534

Tel: 63896111 Fax: 6224 7175/7478

E-mail: claimsdept@sg.cntaiping.com

DEAR SIR / MADAM :

ACCIDENT REPAIR ON: SCP39U

MODEL : TOYOTA LEXUS GS350 F SPORT

POLICY NO : GA111340

CHASSIS NO : JTHBE1BL005010410

YEAR OF MANUFACTURE : 2012

DATE / TIME OF ACCIDENT: 08/01/2019 Time: 1850Hrs at JALAN BOON LAY X-JUNCTION.

THIRD PARTY VEHICLE NO: SKU4402G

Date: 21/01/2019

Page : 1 of 2

Appended below are the estimated cost of repair and parts to be replaced for the above vehicle: -

<u>Replacement Of Parts</u>		Quantity	Unit Price S\$	Condition	Amount S\$
S/N					
1	Rear bumper / <i>RE.</i>	1	936.60	Dented	936.60 ✓
2	Rear bumper clip / <i>RE.</i>	12	4.10	Necessary	49.20 ✓
3	Rear bumper side retainer LH <i>X } NN</i>	1	98.10	Necessary	98.10
4	Rear bumper side retainer RH <i>X }</i>	1	98.10	Necessary	98.10
5	Rear bumper reinforcement <i>SIN BT</i>	1	543.40	Bented	543.40 ✓
6	Rear bumper tow cover <i>X NN</i>	1	45.00	Scratches	45.00
7	Rear bumper spoiler <i>X</i>	1	778.30	Scratches	778.30
8	Rear bumper reflector LH <i>X }</i>	1	89.00	Scratches	89.00
9	Rear bumper reflector RH <i>X }</i>	1	89.00	Scratches	89.00
10	Rear bumper sensor <i>X</i>	4	447.70	Malfunction	1,790.80
11	Rear bumper sponge <i>X CRA</i>	1	156.90	Broken	156.90 ✓
12	Rear end panel <i>X Repair</i>	1	786.80	Dented	786.80
13	Rear end panel trim <i>X }</i>	1	229.60	Kinked	229.60
14	Rear end panel trim clip <i>X }</i>	8	4.10	Necessary	32.80
					<i>1607.7</i>
					<i>1446.93</i>
Sub-Total:					5,723.60
Less: 10% discount -					572.36
Total Parts after 10% discount:					5,151.24

Special Nett Items

1	Anti-rust coating	1	80.00	<i>NN X</i>	80.00
2	Rear number plate with casing <i>X NN</i>	1	100.00	<i>X</i>	100.00
					180.00

Total Parts: 5,331.24

Labour Charges For Rear Portion

1	Provide skill labour to remove all damaged parts, panel beat, cut & weld if necessary and align all panel and reinstall all damaged parts.	<i>290</i>	1,250.00
2	Provide skill labour & material to putty all damaged parts & panel & to respray with 2K paint with oven spray booth facilities	<i>200</i>	1,000.00
3	Provide skill labour to disconnect and check electrical wiring	<i>NNX</i>	60.00

4	Remove and reinstall cushions, seats, backrest, inner trim, garnish, roof lining and or upholstery to facilitate repairs	150.00
5	Provide skill labour to remove and replace bumper sensors	80.00
Total Labour:		2,540.00
Total Parts & Labour:		7,871.24
GST 7%		550.99
Grand Total:		8,422.23

Estimate Repair Duration 09 days

ACCIDENT VEHICLE OF : SCP39U

Page : 2 of 2

Remark: Supplementary estimate will be raised in the event additional damaged parts are found in the course of repair.

2086.93

Yours sincerely,

ESTIMATOR: WEN ZHENG

Survey attended by:

Name : Guo Qiao
Company : LKK
Date : 24/1/19
Time : _____
Contact No : 8288 0282
Email : _____

[Signature]
31/1/19

<p>LKK Auto Consultants hence notify the Repairer of the following:</p> <ul style="list-style-type: none"> • To resurvey before/after spray painting • To display damaged part(s) during resurvey • Parts prices are subject to confirmation • Third party survey is on a "Without Prejudice" basis • No illegal modification(s) is allowed • Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company <p>Acknowledged by Repairer Signature: _____ Date: _____</p>
--

2 Days.
part by part.
before pt paint photos.