

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933 TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

TAX INVOICE

LONPAC INSURANCE BHD 300 BEACH ROAD #17-04/07 THE CONCOURSE SINGAPORE 199555 INV No. AC2005373 INV Date 03/08/2020

Reference CC4/LPC19002007/R1ba3s2

Code LPC2

PROFESSIONAL SERVICE FEE

Vehicle No. SKZ 5781D

Insured Veh. GBC 36H

Claim No. 19/19/VC05/021377

Policy No. Z19VC05001510

Accident Date 28/01/2019

Inspection Date 28/02/2019

Description	Total
Third Party Express Settlement	400.00
Subtotal	400.00
GST (7%)	28.00
Grand Total	428.00

We shall be glad if you could forward the payment at your early convenience.

Cheque should be crossed and made payable to 'LKK Auto Consultants Pte Ltd'

LKK Auto Consultants Pte Ltd

NSA



51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

	Affiliated to Federation Internationale Des Experts En Automobile							
LONI	LONPAC INSURANCE BHD		Ref : CC4/LPC19002007	7/R1ba3s2				
300 BEACH ROAD #17-04/07 THE CONCOURS		DURSESINGAPORE 199555	Date: 03-08-2020 Code: LPC2					
1.	1. Policy Particulars :- THIRD PARTY CLAIM							
	Insured Veh.	GBC 36H	Veh. Inspected	SKZ 5781D				
	Policy No.	Z19VC05001510	Coverage (\$)	0.00				
	Claim No.	19/19/19/VC05/021377	Excess (\$)	0.00				
	Assign From	GERALD POH	Assign Date	30/01/2019				
2.		Vehicle Partic	culars & Condition					
	Make & Model	NISSAN SYLPHY	c.c	1798				
	Engine No.	HIDDEN	Year of Reg.	2015				
	Chassis No.	MNTBBAB17Z0026666	Colour	RED				
	Odometer	95359	Steering	IN ORDER				
	Brakes	IN ORDER	Modification	SPORTS RIM				
	General	FAIR						
3.		Conditi	ons of Tyres					
		Size	Make	Balance				
	R/H Front Tyre	195/60 R16	YOKOHAMA	6 mm				
	L/H Front Tyre	195/60 R16	YOKOHAMA	6 mm				
	R/H Rear Tyre	195/60 R16	YOKOHAMA	6 mm				
	L/H Rear Tyre	195/60 R16	YOKOHAMA	6 mm				
4.		•	on of Damages					
	THE VEHICLE SU	STAINED DAMAGES AT THE REA	AR PORTION.					
	DAMAGES SEE D	ETAILS.						
5.		Genera	Information					
	Accident Date	28/01/2019	Inspection Date	28/02/2019				
	Survey held at	KUM CHEW MOTOR WORKSH	OP					
		160 SIN MING DRIVE #05-08 SIN MING AUTOCITY SINGAPORE 575722						
5a.		Re	emarks					
	A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.							
5b.	b. Estimate Days of Repair							
	ESTIMATED NOR	MAL PERIOD FOR REPAIR:	5 Working Days					



51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 2

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SKZ 5781D

Qty	Description of Parts	Condition	Estimate By Workshop (\$))	Our Adjusted (\$)
	REPLACEMENT OF PARTS			
1	REAR BUMPER (N)	DEFORMED	607.00	607.00
2	REAR BUMPER BRACKET @ \$41.40 (N)	NECESSARY	82.80	82.80
8	REAR BUMPER CLIPS @ \$5.10 (N)	NECESSARY	40.80	40.80
2	REAR BUMPER RETAINER - SIDE @ \$44.00 (N)	SERVICEABLE	88.00	-
2	REAR BUMPER REFLECTOR @ \$55.00 (N)	SERVICEABLE	110.00	-
1	REAR BUMPER INNER SPONGE - CENTRE (N)	CRACKED	43.90	43.90
1	REAR BUMPER INNER SPONGE - R/H (SIDE) (N)	CRACKED	85.90	85.90
1	REAR BUMPER INNER SPONGE - L/H (SIDE) (N)	CRACKED	127.80	127.80
2	REAR LAMP @ \$371.90 (N)	SERVICEABLE	743.80	-
4	REAR LAMP CLIP @ \$5.70 (N)	SERVICEABLE	22.80	-
2	REAR LAMP PANEL @ \$277.50 (N)	SERVICEABLE	555.00	-
1	REAR END PANEL (N)	TO REPAIR SEE LABOUR	428.40	-
1	REAR END PANEL INNER GARNISH (N)	DEFORMED	109.10	109.10
4	REAR END PANEL INNER GARNISH CLIPS @ \$5.10 (N)	NECESSARY	20.40	20.40
1	REAR SPARE TYRE PANEL SPONGE - TOP (N)	SERVICEABLE	159.40	-
2	REAR FENDER INNER GARNISH @ \$417.80 (N)	SERVICEABLE	835.60	-
8	REAR FENDER INNER GARNISH CLIP @ \$5.10 (N)	NOT NECESSARY	40.80	-
1	REAR LID (N)	BENT	1,163.80	1,163.80
1	REAR LID LOCK (N)	SERVICEABLE	115.00	-
1	REAR LID RUBBER (N)	NECESSARY	101.50	101.50
2	REAR LID HINGE @ \$87.50 (N)	SERVICEABLE	175.00	-
2	REAR LID REFLECTOR @ \$141.60 (N)	SERVICEABLE	283.20	-
2	REAR NUMBER PLATE LAMP @ \$78.30 (N)	SERVICEABLE	156.60	-
1	REAR LID CHROME MOULDING - TOP (N)	CRACKED	185.70	185.70
1	REAR LID CHROME MOULDING - LOWER (N)	SERVICEABLE	118.00	-
1	REAR LID HANDLE SWITCH (N)	CRACKED	78.50	78.50
	LESS 10% DISCOUNT		-647.88	-264.72
			5,830.92	2,382.48
	SPECIAL NETT ITEMS			
1	REAR NUMBER PLATE (SN)	SERVICEABLE	60.00	-

Report Ref No. CC4/LPC19002007/R1ba3s2



51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:2 of 2

3,200.00

Qty	Description of Parts	Condition	Estimate By Workshop (\$))	Our Adjusted (\$)
1	REAR REVERSE SENSOR (SN)	NOT WORKING	280.00	200.00
			340.00	200.00
	LABOUR			
	TO PULL, KNOCK ON ACCIDENT PORTION & REPLACE THE ABOVE PARTS. INCLUSIVE OF THE REPAIR OF REAR END PANEL.		850.00	600.00
	TO SPRAY & PAINT ON REAR ACCIDENT PORTION.		950.00	700.00
	TO ANTI-RUST REAR AFFECTED AREAS.		150.00	60.00
	TO CHECK WIRING FUNCTION.	NOT NECESSARY	150.00	-
	TO DISMANTLE & REPLACE REVERSE SENSOR.		150.00	60.00
			2,250.00	1,420.00
	GRAND TOTAL		8,420.92	4,002.48

Report Ref No. CC4/LPC19002007/R1ba3s2

RECOMMENDED COST OF LUMP SUM REPAIRS

(TO ITS PRE-ACCIDENT CONDITION)

MOHAMMED RASUL BIN MOHD YUNUS

Automotive Assessor

HO LEONG CHUAN

Automotive Assessor




51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933 TEL: 6256 3581 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

PHOTOGRAPHS FOR VEHICLE NO. SKZ 5781D

INSPECTION















51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933 TEL: 6256 3581 FAX: 6256 4315















51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933 TEL: 6256 3581 FAX: 6256 4315















51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933 TEL: 6256 3581 FAX: 6256 4315















51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933 TEL: 6256 3581 FAX: 6256 4315















51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933 TEL: 6256 3581 FAX: 6256 4315















51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933 TEL: 6256 3581 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

PHOTOGRAPHS FOR VEHICLE NO. SKZ 5781D

RE-INSPECTION

















51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933 TEL: 6256 3581 FAX: 6256 4315
















51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933 TEL: 6256 3581 FAX: 6256 4315















51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933 TEL: 6256 3581 FAX: 6256 4315















51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933 TEL: 6256 3581 FAX: 6256 4315
















51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933 TEL: 6256 3581 FAX: 6256 4315
















51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933 TEL: 6256 3581 FAX: 6256 4315
















51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933 TEL: 6256 3581 FAX: 6256 4315

















51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933 TEL: 6256 3581 FAX: 6256 4315















51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933 TEL: 6256 3581 FAX: 6256 4315
















51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933 TEL: 6256 3581 FAX: 6256 4315















51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933 TEL: 6256 3581 FAX: 6256 4315















51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933 TEL: 6256 3581 FAX: 6256 4315















51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933 TEL: 6256 3581 FAX: 6256 4315







