

**LIU'S BROTHER AUTO ENGINEERING WORKSHOP**

No. 1 Kaki Bukit Avenue 6 #01-01 Auto Bay @ Kaki Bukit Singapore 417883

ROB No: 53291793J . Tel: 6741-1730 / 731 . Fax: 6744-5746. Email: liusbros@gmail.com

Invoice/Ref No: GBC9842M181123

Estimate**Customer**

Name: AXA Insurance Singapore Pte Ltd

Date: 29-01-19

Address: Motor Claims Department

Vehicle No: GBC9842M

8 Shenton Way #27-01

Model/Make: Fiat Doblo Cargo

AXA Tower

Singapore 068811

SX JTD 1.6MJ Panel

Item No.	Descriptions Of Parts	Original Quotation / Estimation	Revised Quotation / Cost Of Repair
1	Rear Bumper <i>D/A</i>	\$ 745.00	
2	Bumper Reinforcement <i>su</i>	\$ 475.30	<i>X</i>
3	Bumper Reflector <i>scr</i>	\$ 98.60	
4	Bumper Reverse Sensor <i>su</i>	\$ 220.00	<i>SN X</i>
	To check all wiring & electrical component for proper function	\$ 40.00	<i>20</i>
	Remove and refix rear bumper reverse sensor	\$ 120.00	<i>50</i>
	Labor for Panel Beating, Cut, Weld, Straighten & Replacing Parts Etc	\$ 400.00	<i>220</i>
	To putty & spray painting & including touch up paint on accident affected area	\$ 400.00	<i>200</i>

Total Parts & Labour of estimate for damaged vehicle

\$ 2,498.90

Total amount in Lump Sum Basis for repaired vehicle

SDLS:



M/s Liu's Brother Auto Engrg Wks

Not Authorized
mercus hah
3.1.19
2 dy.

2/s \$ 900

Take photo of the repair

P-843.60
50%

P-421.80

14km 490.00

911.80

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: