



Auto
Consultants
Pte Ltd

Company Registration No. 199607198R

51 UBI AVE 1, #02-25 PAYA UBI INDUSTRIAL PARK, SINGAPORE 408933 TEL : (065) 62563561 FAX : (065) 62564315

Your ref: VC012234
Our ref: CC4/QBE19002023/R1fa3

Date: 18/02/2019

The Motor Claims Department
M/s QBE INSURANCE (SINGAPORE) PTE LTD

Dear Sir/Madam,

PRELIMINARY ADVICE OF VEHICLE NO.

PA 6290U

We refer to the above matter.

Please be informed that we had conducted the inspection of the above mentioned vehicle on 13/2/2019 at the premises of M/s UCB Engineering Pte Ltd and have the following to report:-

Workshop Estimate Amount	: S\$	5,443.00	(est.)
Revised Estimate Amount	: S\$	1,413.00	(est.)
"Check" Items Amount	: S\$	-	(est.)
Total (Including Check Items)	: S\$	1,413.00	(est.)

Market Value	: S\$	-	(est.)
LTA Reimbursement Value	: S\$	-	(est.)
Nett Value	: S\$	-	(est.)

Description of Damage:

The vehicle sustained damages at the
N/S Front Portion



Comments/Present Status:

Damages Consistent

Estimated normal period for repairs: 4 days

Yours faithfully,

MOHD. RASUL
Licensed Appraiser



UCB Engineering Pte Ltd

GST Registration Number: 19-9501338-G

Business Reg. No. 199501338G

Our ref: 190103.VGS(PA6290U)

23 January 2019

Vaya Garden Scene Cruiser Pte Ltd
Blk 637 Hpugang Ave 8
#10-121
Singapore 530637

QUOTATION
without Prejudice

Dear Sir,

COST OF REPAIR FOR PA 6290 U

QTY DESCRIPTIONS

1 pc 1st LHS panel *repair*
1 pc Signal lamp *can*
1 pc Side lamp *can*

PRICE
SS

2,680.00 X
358.00 } 463
105.00 }

463
25%
347.25

Labour charges for remove & replace the above damaged part

800.00 *450*

Labour charges for dismantle & assemble window glass x 2

300.00 X

950

To putty & spray painting onto affected areas

600.00 *500*

Total

5,443.00

(SGD: Five Thousand four hundred and forty-three only)

Price quoted above is subjected to 7% GST

Yours faithfully,
Tan Tiong Chia

Resue
Up 90010068

4 days

4/5

13/02/19 @ 1000h

Resue after repair

347.25
950.00
1297.25

20%
1037.80

4/5-1000

4 days

Customer's Representative should notify the repairer of the following:

- The work to be done before spray painting
- The work to be done during the repair
- The work to be done after the repair
- The work to be done after the repair
- The work to be done after the repair
- The work to be done after the repair
- The work to be done after the repair

Accepted by Repairer

Signature:

Date:

2C Jalan Pasawat, Jurong, Singapore 619359
Tel: 6268 1281 Fax: 6268 1282
E-mail: unitedcb@singnet.com.sg



UCB Engineering Pte Ltd

GST Registration Number: 19-9501338-G

Business Reg. No. 199501338G

Our ref: 190103.VGS(PA6290U)

23 January 2019

Vaya Garden Scene Cruiser Pte Ltd
Blk 637 Hpugang Ave 8
#10-121
Singapore 530637

QUOTATION
without Prejudice

Dear Sir,

COST OF REPAIR FOR PA 6290 U

QTY	DESCRIPTIONS	PRICE S\$
1 pc	1st LHS panel <i>repair</i>	2,680.00
1 pc	Signal lamp <i>CA</i>	358.00
1 pc	Side lamp <i>CA</i>	105.00
		<i>3463.00</i>
	Labour charges for remove & replace the above damaged part	800.00 <i>450</i>
	Labour charges for dismantle & assemble window glass x 2	300.00 <i>X</i>
	To putty & spray painting onto affected areas	600.00 <i>500</i>
Total		<u>5,443.00</u>

(SGD: Five Thousand four hundred and forty-three only)

Price quoted above is subjected to 7% GST

Yours faithfully,
Tan Tiong Chia

Rasul
Hp 90010068
4 days
43
13/02/19 @ 1000hrs
Repair after repair

UK Auto Consultants hereby notify the Repairer of the following:

- To remove before any spray painting
- To display damaged car(s) during warranty
- Parts prices are subject to confirmation
- The liability warranty is not a "Without Prejudice" price
- The Repairer must be approved by the insurance company
- The Repairer must be approved by the insurance company

Accepted by Repairer

Signature:

Date:

2C Jalan Pesawat, Jurong, Singapore 619359

Tel: 6268 1281 Fax: 6268 1282

E-mail: unitedcb@singnet.com.sg

**LKK Auto Consultants Pte Ltd**

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile

QBE INSURANCE (SINGAPORE) PTE LTD

Ref : CC4/QBE19002023/R1ha3q2

1 RAFFLES QUAY #29-10 SOUTH
TOWERSINGAPORE 048583

Date : 03-02-2020



Code : QBE

1. Policy Particulars :- THIRD PARTY CLAIM

Insured Veh.	SLS 3895Y	Veh. Inspected	PA 6290U
Policy No.	8-V0016038-MVA-R001	Coverage (\$)	0.00
Claim No.	VC012234	Excess (\$)	0.00
Assign From	JENNY	Assign Date	29/01/2019

2. Vehicle Particulars & Condition

Make & Model	MITSUBISHI BE639JRMHDEA	c.c	3908
Engine No.	HIDDEN	Year of Reg.	2006
Chassis No.	BE639JD00331	Colour	WHITE
Odometer	595141	Steering	IN ORDER
Brakes	IN ORDER	Modification	NIL
General	FAIR		

3. Conditions of Tyres

	Size	Make	Balance
R/H Front Tyre	7.00 R16	GT RADIAL	7 mm
L/H Front Tyre	7.00 R16	GT RADIAL	7 mm
R/H Rear Tyre	7.00 R16 (D)	GT RADIAL	7/7 mm
L/H Rear Tyre	7.00 R16 (D)	GT RADIAL	7/7 mm

4. Description of Damages

THE VEHICLE SUSTAINED DAMAGES AT THE N/S FRONT PORTION. DAMAGES SEE DETAILS.

5. General Information

Accident Date	12/01/2019	Inspection Date	13/02/2019
Survey held at	UCB ENGINEERING PTE LTD 2C, JALAN PESAWAT, JURONG, SINGAPORE 619359		

5a. Remarks

A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.
--

5b. Estimate Days of Repair

ESTIMATED NORMAL PERIOD FOR REPAIR:	4 Working Days
-------------------------------------	-----------------------



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607196R GST Reg. No. 19-9607196-R

Page No.:1 of 1

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. PA 6290U

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	REPLACEMENT OF PARTS			
1	1ST LHS PANEL	TO REPAIR SEE LABOUR	2,680.00	-
1	SIGNAL LAMP	CRACKED	358.00	358.00
1	SIDE LAMP	CRACKED	105.00	105.00
	LESS 25% DISCOUNT		-	-115.75
			3,143.00	347.25
	LABOUR			
	LABOUR CHARGES FO REMOVE & REPLACE THE ABOVE DAMAGED PART.INCLUSIVE OF THE REPAIR OF 1ST LHS PANEL.		800.00	450.00
	LABOUR CHARGES FOR DISMANTLE & ASSEMBLE WINDOW GLASS X2 .	NOT NECESSARY	300.00	-
	TO PUTTY & SPRAY PAINTING ONTO AFFECTED AREAS.		600.00	500.00
			1,700.00	950.00
	GRAND TOTAL		4,843.00	1,297.25
	RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION)			1,000.00

Report Ref No. CC4/QBE19002023/R1ha3q2

MOHAMMED RASUL BIN MOHD YUNUS

Automotive Assessor

HO LEONG CHUAN

Automotive Assessor

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.