

SS. REC. BY:

REF:

cs/msg19002053/ktd3

n2

Special Instruction:

Sub Veyor

Menimen

Kenneth

ASSIGNMENT (Office)

From (Person)

Monica chung

of

MSG

Date/Time

31/1/19 @ 1:44pm

Estimated Cost:

Bill to:

OD (TP) WS / TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No:

SFZ 8601E

Insured:

SFJ 5908A

at Workshop m/s

Lim Yew Boo Spray

Tel:

9685 2332

of

Blk 10, Sin Ming Ind Est #01-10

Policy No:

27141898 SMP

Claim No:

583929

Sum Insured:

Excess:

Make of Veh:

(Client's Record)

D.O.A.

27/01/2019

CA / REV / REP. / REV 24 HRS

H.O.D. Endorsement:

Date/Time:

2:25pm @ 31/1/19

Person Contacted:

Suzene

Vehicle IN/OUT

Date/Time

Action/Instruction (✓) Estimate

SFZ 8601E - NA/INC10009562/r

D.O.A: 15/05/2010

SFJ 5908A - X

7/1/2019

Revised via menimen preli advise.

7/5 11pm 89001 Confirm (Red: 2020.10', 69%)

REF: MSIG

ASSIGNMENT

From: Date: 01/02/2019

Estimated Cost:

OD: ☒ TP / ☐ WS / ☐ TP RES / ☐ OD RES / ☐ EVA / ☐ INV / ☐ MV

To inspect Vehicle No: SFZ 8601E

at Workshop no/s: Lim Yew Boo

of: Blk 10, Sin Ming Ind. Est #01-10

Insured:

Policy No:

Claims No:

Sum Insured:

Excess:


(Client's Record)

Make of Veh:

10am

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.



Bal. or Market Value:

IDAC Accident Rpt: Consistent? : Yes or No

GIA / PR Seen: Consistent? : Yes or No

Est. Repairs: 2-4 days Res: Yes or No

Lum Sum: 1-B-1 % 3 Val: Yes or No

CA / REV / REP. / 24 HRS (up)

Date: Person Contacted:

Vehicle: IN / OUT

Veh No:

SFZ 8601E Regn: 09 15

Type: ☒ M.Car / ☐ M.Cycle / ☐ Bus / ☐ Van / ☐ Lorry / ☐ Taxi / ☐ Prime Mover /

Truck / Trailer or

Make:

Toy Camry

C.C.

1998

Colour:

M. Silver

Insured / Std / NI / NA

Sp. Reading:

94413

T/Radio: Insured / Std / NI / NA

Eng/No:

C/No:

MR0530K 5100103222

Gen. Cond: ☒ Good / ☐ Fair / ☐ Poor / ☐ BurntSteering: ☒ In order / ☐ Jammed / ☐ Leaked / ☐ Burnt orBrake: ☒ In order / ☐ Jammed / ☐ Leaked / ☐ Burnt or

Modi: Nil / S/Rim / STD A/Rim or

Tyre Size:

F:

215/60R6

R:

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

Front

R/Bal:

9

mm

Rear

R/Bal:

9

mm

L/Bal:

9

mm

L/Bal:

9

mm

D.O.A.

27/1/19

D.O.I.

1/2/19

Survey held at

Des. of Damages: Frt / ☒ Rear / ☐ O/S / ☐ N/S / ☐ U/C / ☐ Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time Action / Instruction

RECEIVED 08 MAY 2019

Date/Time, File Pass to?

1) Hb Typist



Preli. Report



Final Report

Date/Time, File Return to?

2)

Report Format:

Lump Sum / I.B.I. (\$)

TP

900+

Days Of Repair: 2

Resurvey No. of Trip: —

Add Fee:



Site Insp (\$)



Interview (\$)



Tech. Invs (\$)



Weekend (\$)

Survey Fee:

Transportation

1) G + RS \$

2) Photos

3) Others

4) TOTAL

TOTAL

150
10
160

Signature: [Signature]
Date: 15/2/2019

Note: This document has not been finalised.

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

To: MSIG Insurance (Singapore) Pte. Ltd.
4 Shenton Way
#21-01 SGX Centre 2
Singapore 068807

From: LKK Auto Consultants Pte Ltd
51 Ubi Ave 1 #01-25
Paya Ubi Industrial Park
Singapore 408933

Attn: Monica Chung Pei Zhen

Date: 07 Feb 2019

Preliminary Advice

Insured Vehicle No	: SFJ5908A	Accident Date	: 27/01/2019
TP Vehicle No	: SFZ8601E	Assignment Date	: 31/01/2019
Make	: TOYOTA CAMRY	Est. Duration of Repair	: 2.00
Date of Inspection	: 07/02/2019		
Inspection At	: LIM YEW BOO SPRAY PAINT CO (HQ) BLK 10 SIN MING INDUSTRIAL ESTATE, #01-10 SINGAPORE 575645		

Point of Impact / General Description of Damages

The vehicle sustained impact / damages rear portion and parts claimed are consistent to the accident.

Repairer's Estimate (Gross)	:S\$	2,920.10
Revised Amount	:S\$	966.35
Check Items (Estimated)	:S\$	793.70
Total	:S\$	1,760.05

Lump Sum Repair	:S\$	
-----------------	------	--

Total Loss Consideration

New for Old Value	:S\$	
Pre-Accident Value	:S\$	
COE / PARF Rebate	:S\$	
Salvage Value	:S\$	
Margin for Repair	:S\$	

Remarks

- () The vehicle is economical/not economical for repair.
- (x) The above survey was conducted on a 'without prejudice' basis.

...CLAIM SUBFOLDER...(New Assignment)

CLAIM SUBFOLDER TRACKING

Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'd	Status
Main	29 Jan 2019		31 Jan 2019 13:44 Assign				New Assignment Cancel Case

Main	Reference	Claim Details	Documents	Show All
------	-----------	---------------	-----------	--------------------------

CLAIM SUBFOLDER DETAILS [Created by insurer]

Insured:	Keyur Jitendra Dave, ID: S6978413E		
Main Claimant:	ONG SIEW MING, ID: S6918972E		
Vehicle Reg. No.:	SFZ8601E	Date of Loss:	27/01/2019 10:00 - :59 [39 Months and 30 Days From LTA Reg Date (Man Yr)]
Claim Type:	TP / 583929	Policy/Cover Note No.:	27141898SMP (Comprehensive) Coverage: 16/06/2011 - 15/06/2019
Vehicle Reg. No. (Insured):	SFJ5908A	Policy No. (Claimant):	
		Excess:	
Repairer:	Lim Yew Boo Spray Paint Co (HQ) Blk 10 Sin Ming Industrial Estate, #01-10, 575645 Sin Ming - Tel: 96852332		
Handling Insurer:	MSIG Insurance (Singapore) Pte. Ltd. (HQ) - Tel: +65 6827 7888 ... [Handled by Monica Chung Pei Zhen - 6594 2552]		
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Imm.Advice due 01/02/2019]		
Adj Asg. Remarks:	Liability (Non-reporting) SJE AGREE LKK, Contact Person: Serene Lim Hp : +65 96852332		

ASSOCIATED MAIL RECEIVED

[View All](#)
[Compose Case Mail](#)

There are no mail for this case.

ALL ASSOCIATED TASKS ☐

[View All](#)
[Search Tasks](#)
[Create New Task](#)
[Complete](#)

Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

LIM YEW BOO SPRAY PAINT CO.

BLK 10, SIN MING INDUSTRIAL ESTATE, SECTOR C, #01-10 S'575645
 NO. 176, SIN MING DRIVE, #03-05, SIN MING AUTOCARE, S'PORE 575721
 Tel No. : 64534177 Fax No. : 64593724
 E-Mail : limyewboo@singnet.com.sg
 Website : www.limyewboo.com.sg
 Buss. Reg. No. : 200514/00L

MSIG INSURANCE (SINGAPORE) PTE LTD
 16 RAFFLES QUAY #24-01
 HONG LEONG BUILDING SINGAPORE 048581

Attention : Motor Claim Department
 Contact : 62209644 Fax No. : 62257402

Estimate : TP19/005

Date : 30/01/2019
 Vehicle Num. : SFZ 8601E
 Make/Model : TOYOTA CAMRY 2.0-2015
 Chassis/Eng# : MR053DK510010322/6ARP047974
 Accident Date : 27/01/2019
 Claim No. :
 Reference : LYB/SFZ8601E/MSIG/tp/sl
 Policy No. :

Not Notarized
Repair B4 paint
2 days

S/N	Quantity	Particular	Unit Price	Amount S\$
-----	----------	------------	------------	------------

- | | | | | |
|----|---|----------------------|--|--|
| 1. | 1 | LIST ITEMS : | | |
| 2. | 1 | REAR BUMPER | | |
| 3. | 2 | REAR BUMPER BEAM | | |
| | | REAR BUMPER RETAINER | | |

List TotalS\$:
 25.00% Discount S\$:

Not Notarized
 901.80
 391.60
 86.70 173.40
 1,466.80
 366.70
 1,100.10

- | | | | | |
|----|---|----------------------|--|--|
| 1. | 4 | SPECIAL NETT ITEMS : | | |
| | | REAR REVERSE SENSOR | | |

Special Nett Total S\$:

120.00 480.00 X
 480.00

- LABOUR :
- TO APPLY RUST-PROOFING ON REPAIRED/ REPLACED PANELS
 - TO CHECK WATER SEEPAGE
 - TO REPLACE REVERSE SENSOR SET & CHECK WIRING FUNCTIONS
 - TO REPAIR, PANEL BEAT ON REAR AFFECTED PANEL, RE-ALIGN ON REAR BOOT LID & LABOUR TO REPLACE THE ABOVE PARTS

120.00 X
 60.00 X
 60.00 501
 500.00 780

CONTINUE / ...

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modifications allowed
- Supplementary repair must be resurveyed and is subject to final approval from Insurance Company

Authorized by: [Signature]

LIM YEW BOO SPRAY PAINT CO.

BLK 10, SIN MING INDUSTRIAL ESTATE, SECTOR C, #01-10 S'575645
 NO. 176, SIN MING DRIVE, #03-05, SIN MING AUTOCARE, S'PORE 575721
 Tel No. : 64534177 Fax No. : 64593724
 E-Mail : limyewboo@singnet.com.sg
 Website : www.limyewboo.com.sg
 Buss. Reg. No. : 200514/00L

MSIG INSURANCE (SINGAPORE) PTE LTD
 16 RAFFLES QUAY #24-01
 HONG LEONG BUILDING SINGAPORE 048581

Attention : Motor Claim Department
 Contact : 62209644 Fax No. : 62257402

Estimate : TP19/005

Date : 30/01/2019
 Vehicle Num. : SFZ 8601E
 Make/Model : TOYOTA CAMRY 2.0-2015
 Chassis/Eng# : MR053DK510010322/6ARP047974
 Accident Date : 27/01/2019
 Claim No. :
 Reference : LYB/SFZ8601E/MSIG/tp/sl
 Policy No. :

S/N	Quantity	Particular	Unit Price	Amount S\$
		TO PUTTY, PRIMER & SPRAY PAINT ON REAR AFFECTED PANEL, BEAM, BUMPER, SENSOR USING 2K PAINT		600.00
		Labour Total S\$:		1,340.00

2k


 for LIM YEW BOO SPRAY PAINT CO.



E. & O.E.

Total S\$: 2,920.10

=====

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CS/MSG19002053/KTD3N2

Date: 09/05/2019

REFERENCE

Handling Insurer:	MSIG Insurance (Singapore) Pte. Ltd.	Policy No:	27141898SMP
Claimant Vehicle No :	SFZ8601E	Insured Vehicle No :	SFJ5908A
Date of Loss:	27/01/2019	Nature of Claim:	TP
		Claim No:	583929

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SFZ8601E	Engine No:	6ARP047974
Make & Model:	TOYOTA CAMRY, 2.0 (A)	Chassis No:	MR053DK5100103222
Reg. Date:	28/09/2015 (Man. Year: 2015)	Odometer:	94413 km
Colour:	Metallic Silver		
Engine Capacity:	1998 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	215/60R16	Rear Tyre Size:	215/60R16
Front Left Side:	Michelin 9 mm	Rear Left Side:	Michelin 9 mm
Front Right Side:	Michelin 9 mm	Rear Right Side:	Michelin 9 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS

	Repairer's	Adjuster's	Difference	Diff %
Parts	1,580.10	676.35	903.75	57.20
Miscellaneous Items	0.00	0.00	0.00	
Labour	1,340.00	470.00	870.00	64.93
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	2,920.10	1,146.35	1,773.75	60.74
Approved Total (Overridden) (S\$)		900.00		
Nett Amount (S\$)	2,920.10	900.00	2,020.10	69.18

INSPECTION

Date of Assignment: 31/01/2019

Date Inspected: 01/02/2019 Inspected At:

Lim Yew Boo Spray Paint Co (HQ)
Blk 10 Sin Ming Industrial Estate, #01-10
Singapore 575645

Estimated Period of Repair: 2.0 days

Adjuster: KENNETH KONG

Manager: DENISE TAY KWEE CHENG

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference

Part Source: MRM-SG	Version: 1.0 (Last Synchronised: 09 May 2019)
Parts: 143	TOYOTA CAMRY 2.0 (A) (Catalogue:Merimen Singapore 1.0)
Labour: Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for SFZ8601E)
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*REAR BUMPER	Dented/Buckled	901.80 FL	*901.80 FL
2	1		*REAR BUMPER BEAM	Repair	391.60 FL	*- FL
3	2		*REAR BUMPER RETAINER	Serviceable	173.40 FL	*- FL
4	4		*REAR REVERSE SENSOR	Serviceable	480.00 FS	*- FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (\$\$)	1,946.80	901.80
- List Item Discount on L Items 25.00/25.00% (\$\$)	366.70	225.45
Total Parts (\$\$)	1,580.10	676.35

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	TO APPLY RUST-PROOFING ON REPAIRED/REPLACED PANELS	New	120.00	0.00
2	TO CHECK WATER SEEPAGE	New	60.00	0.00
3	TO REPLACE REVERSE SENSOR SET & CHECK WIRING FUNCTIONS	New	60.00	50.00
4	TO REPAIR,PANEL BEAT ON REAR AFFECTED PANEL,RE-ALIGN ON REAR BOOT LID & LABOUR TO REPLACE THE ABOVE PARTS	New	500.00	180.00
5	TO PUTTY,PRIMER & SPRAY PAINT ON REAR AFFECTED PANEL,BEAM,BUMPER,SENSOR USING 2K PAINT	New	600.00	240.00
Gross Labour Cost (\$\$)			1,340.00	470.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >