

Accident Photo



Accident Photo



Accident Photo



Accident Photo



Accident Photo



Revol Carz Garage Pte Ltd

Blk 10 Ang Mo Kio Industrial Park 2a, Ang Mo Kio Autopoint #02-18

Singapore 568047

Tel: 65551171 Fax: 62679317

Name : Kuan Shee Kai (Guan Shukai)

Date : 20-Dec-18

Address : c/o Blk 10 Ang Mo Kio Industrial Park 2A
#02-18 Ang Mo Kio Autopoint
Singapore 568047

Final repair bill for BMW 120i SJV 6617 Y

To supply and replace parts, labour charges for
repairing, knocking, welding and to respray painting
(Lump Sum Repair)

\$ 4,100.00

Dollars : Four Thousand One Hundred Only

PAL'S

APPRAISER PTE LTD

No. 1 Kaki Bukit Ave 6 #01-53 AutoBay @ Kaki Bukit Singapore 417883
Tel: 81818802 Fax: 67471017 Registration No: 201000268D

Billing Name & Address

Kuan Shee Kai (Guan Shukai)
c/o Blk 10 Ang Mo Kio Industrial Park 2A
#02-18 Ang Mo Kio Autopoint
Singapore 568047

Invoice No 11-18039/AY

Date 20 Dec 2018

Vehicle No : SJV 6617 Y

Model : BMW 120i

Item	Descriptions	Amount S\$
1	Date of inspection : <u>26 Nov 2018</u> A copy of the inspection / survey report Correspondence, postages and etc.	
2	Photography Services - Purchase of films, develop negatives - Storage of negatives - Submission of photographs <u>60</u> copies	
3	Transportation Charges	
4	2nd Inspection & Final Inspection	
	Total	<u>\$ 600.00</u>
	SDLS : SIX HUNDRED ONLY	

Notes :

1. All cheque payment should be "Crossed" and made payable to "Pal's Appraiser Pte. Ltd."
2. All cheque should have our "Invoice No." written on the reverse side of the cheque
3. For further enquiries on this invoice, please feel free to contact us



Official Stamp

E & O. E

PAL'S

APPRAISER PTE LTD

No. 1 Kaki Bukit Ave 6 #01-53 AutoBay @ Kaki Bukit Singapore 417883
Tel: 81818802 Fax: 67471017 Registration No: 201000268D

Report Reference : TP / 11-18039/AY / 2018
Date of Report : 20 Dec 2018

Kuan Shee Kai (Guan Shukai)
c/o Blk 10 Ang Mo Kio Industrial Park 2A
#02-18 Ang Mo Kio Autopoint
Singapore 568047

THIRD PARTY SURVEY

ACCIDENT HAPPENED ON 15 Nov 2018

As per your instruction dated 26 Nov 2018 with regard to the above matter. We have carried out a physical inspection on the said vehicle SJV 6617 Y. We enclosed herewith our report and findings as follows:

1. VEHICLE PARTICULARS

Registration No : SJV 6617 Y
Model : BMW 120i
Year / Capacity : 2010/1995
Chassis No : WBAUM52090VF97796
Engine No : B095I267N43B20AA
Mileage : 119231
Colour : Silver

2. TYRES CONDITION

			<u>Size</u>	<u>Made</u>	<u>Balance</u>		<u>Rim</u>
FRONT	O/S	:	225/40 R18	Michelin	5.00	mm	Sport
REAR	O/S	:	225/40 R18	Michelin	5.00	mm	Sport
FRONT	N/S	:	225/40 R18	Michelin	5.00	mm	Sport
REAR	N/S	:	225/40 R18	Michelin	5.00	mm	Sport

PAL'S

APPRAISER PTE LTD

No. 1 Kaki Bukit Ave 6 #01-53 AutoBay @ Kaki Bukit Singapore 417883
Tel: 81818802 Fax: 67471017 Registration No: 201000268D

3. DESCRIPTION OF DAMAGES

At the time of inspection, we noted that the vehicle has sustained an impact damages on the front n/s portion(s). For more detail of the damages, please see photograph attached.

4. Workshop Address : Revol Carz Garage Pte Ltd
Blk 10 Ang Mo Kio Industrial Park 2A
#02-18 Ang Mo Kio Autopoint
Singapore 568047

5. Estimated normal period of repair : 6 working days to complete.

6. Enclosed number of photograph : 60 copies.

7. In accordance to your instruction, we have Not Authorised repair to the vehicle and the survey was done on a "Without Prejudice" basis. We hope that this report will be of assistance to you in dealing with the matter.

8. Should you discover any discrepancy in the report, please kindly notify us within 2 weeks, or the report will be treated as correct.

Disclaimer

The rates and assessment of damages as stated in this report is to be used solely for legal proceedings in relation to the surveyed vehicle and the accident in which the surveyed vehicle was involved in. The rates and assessment of damages must not be used in any circumstances for comparison with other vehicles and/or other accidents in other legal proceedings.

Vehicle No: SJV 6617 Y
 Report No: TP/ 11-18039/AY / 2018

SPARE PARTS

Qty	Parts Description	Condition	Workshop's Estimation	Our Revised Estimation
<u>List Items</u>				
1	Front n/s headlamp	Damage	\$ 1675.00	\$ 1675.00 <i>cut ✓</i>
1	Front bumper	Damage	\$ 854.00	\$ 854.00 <i>cut ✓</i>
1	Front bumper reinforcement	Repair	\$ 489.00	\$
1	Front bumper side retainer	Damage	\$ 11.90	\$ 11.90 <i>NECV</i>
1	Front n/s fender	Damage	\$ 518.50	\$ 518.50 <i>RX</i>
1	Front n/s fender inner shield	Damage	\$ 198.00	\$ 198.00 <i>NNX</i>
			<u>\$ 3746.40</u>	<u>\$ 3257.40</u>
	Discount	5.0%	\$ 187.32	\$ 162.87
			<u>\$ 3559.08</u>	<u>\$ 3094.53</u>
<u>Special Nett Items</u>				
1	Front fender inner shield clip (1 set)	Necessary	\$ 40.00	\$ 40.00 <i>25.00 NECV</i>
			<u>\$ 40.00</u>	<u>\$ 40.00</u>

4 days

[Signature]
11/2/2019

Spare Parts Total \$ 3599.08 \$ 3134.53

Vehicle No: SJV 6617 Y
Report No: TP/ 11-18039/AY / 2018

LABOUR COST

S/No	Job Descriptions	Workshop's Estimation	Our Revised Estimation
	Spare Parts Total c/f	\$ 3599.08	\$ 3134.53
1	To remove and refit damage parts, test for proper functioning and focus of headlamps.	\$ 50.00	\$ 40.00
2	To remove and refit front undercarriage.	\$ 200.00	Not Required
3	To check and re-adjust (Computerized) all wheel alignment.	\$ 200.00	\$ 120.00 <i>NN X</i>
4	To remove and replace the above damaged parts, straighten, knock out, realign and repair including cut and weld body panels. To re-adjust to the original position using power tools.	\$ 1000.00	\$ 880.00 <i>400.00</i>
5	To spray paint on the replaced and repaired parts, prepare spray such as masking tape the unaffected areas with paper, cleaning and sanding of surfaces, final polishing and waxing are also available.	\$ 1000.00	\$ 880.00 <i>400.00</i>
6	To apply undercoating on the repaired and replaced panels for rust protection.	\$ 150.00	\$ 30.00 ✓
Total		<u>\$ 6199.08</u>	<u>\$ 5084.53</u>

The repairer has agreed to undertake the repair under a Lump Sum Basis. We have further adjusted the amount to a Lump Sum Repair Contract of:

\$ 4100.00

SDLS: FOUR THOUSAND ONE HUNDRED ONLY


Qualified Appraiser

...CLAIM SUBFOLDER...(Pending for Survey Report)

CLAIM SUBFOLDER TRACKING							
Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'd	Status
Main	15 Nov 2018		21 Nov 2018 15:54 Edit Adj Rpt	S\$2,650.00 Edit Estimates	S\$2,650.00 View Rpt		Pending for Survey Report Cancel Case

Main	Reference	Claim Details	Documents	Show All
----------------------	---------------------------	-------------------------------	---------------------------	--------------------------

CLAIM SUBFOLDER DETAILS

[Created by insurer]

Insured:	ISMAIL BIN ALI , ID: S7412519J		
Main Claimant:	KUAN SHEE KAI (GUAN SHUKAI) , ID: S7306301I		
Vehicle Reg. No.:	SJV6617Y	Date of Loss:	15/11/2018 08:00 - :59 [105 Months and 11 Days From LTA Reg Date (Man Yr)]
Claim Type:	TP / MSC/V/18-001513	Policy/Cover Note No.:	MSD/VMS/18-388553 (TP, Fire & Theft) Coverage: 04/09/2018 - 06/09/2019
Vehicle Reg. No. (Insured):	FBK4618K	Policy No. (Claimant):	
		Excess:	
Repairer:	Revol Carz Garage Pte Ltd (HQ) Block 10, Ang Mo Kio Ind Park 2A, #02-18, AMK Auto Point, 568047 Ang Mo Kio - Tel:		
Handling Insurer:	MSIG Insurance (Singapore) Pte. Ltd. (HQ) - Tel: +65 6827 7888 ... [Handled by Monica Chung Pei Zhen - 6594 2552]		
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Handled by Lim Teow Guan] ... [Final Rpt due 04/02/2019]		
Driver/Custodian (Insured):	ISMAIL BIN ALI (44 / Male), NRIC: S7412519J		
Adj Asg. Remarks:	SJE DISAGREE APPOINT LKK. Liab not clear, kindly arrange survey on 26th November 2018, Monday Afternoon and contact June (9322 2338) / Gavin (9740 6855)		

ASSOCIATED MAIL RECEIVED

[View All](#)[Compose Case Mail](#)

- MSIG_SG (31/01/2019): Report Send Back Alerts - SJV6617Y (TP)

ALL ASSOCIATED TASKS

[View All](#)[Search Tasks](#)[Create New Task](#)[Complete](#)

Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

Claim Documents

*SJV6617Y (MSC/V/18-001513)
[FBK4618K]

TP

KUAN SHEE KAI (GUAN SHUKAI)




































Nov 15 2018 8:00AM








































[ISMAIL BIN ALI]

Revol Carz Garage Pte Ltd

[Upload Documents](#)
[Upload Photos](#)
[Compose New Letter](#)

[View](#)
[View in Browser](#)

Photos/Images			3 per page	
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
1	06/12/18 19:51	General View	 Load JPG	<input checked="" type="checkbox"/>
2	06/12/18 19:51	General View	 Load JPG	<input checked="" type="checkbox"/>
3	06/12/18 19:51	General View	 Load JPG	<input checked="" type="checkbox"/>
4	06/12/18 19:51	General View	 Load JPG	<input checked="" type="checkbox"/>
5	06/12/18 19:51	General View	 Load JPG	<input checked="" type="checkbox"/>
6	06/12/18 19:51	General View	 Load JPG	<input checked="" type="checkbox"/>
7	06/12/18 19:51	General View	 Load JPG	<input checked="" type="checkbox"/>
8	06/12/18 19:51	General View	 Load JPG	<input checked="" type="checkbox"/>
9	06/12/18 19:51	General View	 Load JPG	<input checked="" type="checkbox"/>
10	06/12/18 19:51	General View	 Load JPG	<input checked="" type="checkbox"/>
11	06/12/18 19:51	General View	 Load JPG	<input checked="" type="checkbox"/>
12	06/12/18 19:51	General View	 Load JPG	<input checked="" type="checkbox"/>
13	06/12/18 19:51	General View	 Load JPG	<input checked="" type="checkbox"/>
14	06/12/18 19:51	General View	 Load JPG	<input checked="" type="checkbox"/>
15	06/12/18 19:51	General View	 Load JPG	<input checked="" type="checkbox"/>
16	06/12/18 19:51	General View	 Load JPG	<input checked="" type="checkbox"/>
17	06/12/18 19:51	General View	 Load JPG	<input checked="" type="checkbox"/>
18	06/12/18 19:52	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
19	06/12/18 19:52	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
20	06/12/18 19:52	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
21	06/12/18 19:52	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
22	06/12/18 19:52	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
23	06/12/18 19:52	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
24	06/12/18 19:52	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
25	06/12/18 19:52	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
26	06/12/18 19:52	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
27	06/12/18 19:52	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
28	06/12/18 19:52	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
29	06/12/18 19:52	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
30	06/12/18 19:52	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
31	06/12/18 19:52	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
32	06/12/18 19:52	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
33	06/12/18 19:52	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
34	06/12/18 19:52	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
35	06/12/18 19:52	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>

Photos/Images			3 per page ▼	✓
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
36	06/12/18 19:52	Photographs of Damaged Parts	 Load JPG	✓
37	06/12/18 19:52	Photographs of Damaged Parts	 Load JPG	✓
38	06/12/18 19:52	Photographs of Damaged Parts	 Load JPG	✓
39	06/12/18 19:52	Photographs of Damaged Parts	 Load JPG	✓
40	06/12/18 19:52	Photographs of Damaged Parts	 Load JPG	✓
41	06/12/18 19:52	Photographs of Damaged Parts	 Load JPG	✓
42	06/12/18 19:52	Photographs of Damaged Parts	 Load JPG	✓
43	06/12/18 19:52	Photographs of Damaged Parts	 Load JPG	✓
44	06/12/18 19:52	Photographs of Damaged Parts	 Load JPG	✓
45	06/12/18 19:52	Photographs of Damaged Parts	 Load JPG	✓
46	06/12/18 19:52	Photographs of Damaged Parts	 Load JPG	✓
47	06/12/18 19:52	Photographs of Damaged Parts	 Load JPG	✓
48	06/12/18 19:52	Photographs of Damaged Parts	 Load JPG	✓
49	06/12/18 19:52	Photographs of Damaged Parts	 Load JPG	✓
50	06/12/18 19:52	Photographs of Damaged Parts	 Load JPG	✓
51	06/12/18 19:52	Photographs of Damaged Parts	 Load JPG	✓
52	06/12/18 19:52	Photographs of Damaged Parts	 Load JPG	✓
53	06/12/18 19:52	Photographs of Damaged Parts	 Load JPG	✓
54	06/12/18 19:52	Photographs of Damaged Parts	 Load JPG	✓
55	06/12/18 19:52	Photographs of Damaged Parts	 Load JPG	✓
56	06/12/18 19:52	Photographs of Damaged Parts	 Load JPG	✓
57	06/12/18 19:52	Photographs of Damaged Parts	 Load JPG	✓
58	06/12/18 19:52	Photographs of Damaged Parts	 Load JPG	✓
59	06/12/18 19:53	Photo After Spray	 Load JPG	✓
60	06/12/18 19:53	Photo After Spray	 Load JPG	✓
61	06/12/18 19:53	Photo After Spray	 Load JPG	✓
62	06/12/18 19:53	Photo After Spray	 Load JPG	✓
63	06/12/18 19:53	Photo After Spray	 Load JPG	✓
64	06/12/18 19:53	Photo After Spray	 Load JPG	✓
65	06/12/18 19:53	Photo After Spray	 Load JPG	✓
66	06/12/18 19:53	Photo After Spray	 Load JPG	✓
Documentation			1 per page ▼	✓
No	Finalized On	MSIG Insurance (Singapore) Pte. Ltd. (HQ)	Thumbnail	Print
1	21/11/18 10:42	PRI	 Load PDF	
2	21/11/18 10:42	Third Party Accident Report	 Load PDF	
3	21/11/18 10:42	OI ACCIDENT REPORT	 Load PDF	
4	21/11/18 10:42	SJE DISAGREE APPOINT LKK	 Load PDF	
5	21/11/18 11:03	workshop details - survey vehicle on 26/11 afternoon	 Load PDF	
6	30/01/19 11:27	COLOURED IMAGES	 Load PDF	
7	30/01/19 11:31	LOD, LTA SEARCH, FINAL REPAIR BILL,SURVEY REPORT, LTA SEARCH	 Load PDF	
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
1	12/02/19 14:47	PRS INVOICE	 Load PDF	

Documents Checklist

DOCUMENTS CHECKLIST

[Reset](#) [Save](#) [Print](#)

There are no document checklists configured.

Our Checklist Remarks - LKK Auto Consultants Pte Ltd (HQ)**Show Remarks To:** ☐ Handling Insurer

Note: Remarks are private unless you show it to other parties.

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CS3/MSG18021092/BTD3S2-1
Date: 12/02/2019

REFERENCE

Handling Insurer: MSIG Insurance (Singapore) Pte. Ltd. Policy No: MSD/VMS/18-388553
Claimant Vehicle No : SJV6617Y **Insured Vehicle No :** FBK4618K
Date of Loss: 15/11/2018 **Nature of Claim:** TP **Claim No:** MSC/V/18-001513

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: **SJV6617Y**
 Make & Model: BMW 120I, 2.0 (A) Engine No: B095I267N43B20AA
 Reg. Date: 04/02/2010 (Man. Year: 2008) Chassis No: WBAUM52090VF97796
 Colour: Silver Odometer: 119231 km
 Engine Capacity: 1995 cc
 Market Value/New Car Price: N/A
 Sum Insured (S\$): **Market Value/New Car Price**

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Good Steering (Serviceable): Yes Footbrake (Serviceable): Yes
 Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 225/40R18 Rear Tyre Size: 225/40R18
 Front Left Side: Michelin 6 mm Rear Left Side: Michelin 6 mm
 Front Right Side: Michelin 6 mm Rear Right Side: Michelin 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	3,599.08	2,438.85	1,160.23	32.24
Miscellaneous Items	0.00	0.00	0.00	
Labour	2,600.00	870.00	1,730.00	66.54
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	6,199.08	3,308.85	2,890.23	46.62
Approved Total (Overridden) (S\$)		2,650.00		
Nett Amount (S\$)	6,199.08	2,650.00	3,549.08	57.25

INSPECTION

Date of Assignment: 21/11/2018
 Date Inspected: 25/11/2018 Inspected At: Revol Carz Garage Pte Ltd (HQ)
 Block 10, Ang Mo Kio Ind Park 2A, #02-18, AMK Auto Point
 Singapore 568047
 Estimated Period of Repair: 4.0 days

Adjuster: Lim Teow Guan

Manager: DENISE TAY KWEE CHENG

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference

Part Source:	(Last Synchronised: 12 Feb 2019)	
Parts:	N/A	BMW 120I 2.0 (A) (Model not available in database)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for SJV6617Y)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*FRONT N/S HEADLAMP	Cut	1,675.00 FL	*1,675.00 FL
2	1		*FRONT BUMPER	Cut	854.00 FL	*854.00 FL
3	1		*FRONT BUMPER REINFORCEMENT	Repair	489.00 FL	*- FL
4	1		*FRONT BUMPER SIDE RETAINER	Necessary	11.90 FL	*11.90 FL
5	1		*FRONT N/S FENDER	Repair	518.50 FL	*- FL
6	1		*FRONT N/S FENDER INNER SHIELD	Not Necessary	198.00 FL	*- FL
7	1		*SET FRONT FENDER INNER SHIELD CLIP	Necessary	40.00 FS	*25.00 FS
					Sub Total (S\$)	3,786.40
					- List Item Discount on L Items 5.00/5.00% (S\$)	187.32
					Total Parts (S\$)	3,599.08
						2,438.85

F=Franchise part, S=SpcNett, L=ListItemDisc.

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<u>Labour Items</u>				
1	TO REMOVE AND REFIT DAMAGE PARTS, TEST FOR PROPER FUNCTIONING AND FOCUS OF HEADLAMPS.	New	50.00	40.00
2	TO REMOVE AND REFIT FRONT UNDERCARRIAGE.	New	200.00	0.00
3	TO CHECK AND RE-ADJUST (COMPUTERIZED) ALL WHEEL ALIGNMENT.	New	200.00	0.00
4	TO REMOVE AND REPLACE THE ABOVE DAMAGED PARTS, STRAIGHTEN, KNOCK OUT, REALIGN AND REPAIR INCLUDING CUT AND WELD BODY PANELS. TO RE-ADJUST TO THE ORIGINAL POSITION USING POWER TOOLS.	New	1,000.00	400.00
5	TO SPRAY PAINT ON THE REPLACED AND REPAIRED PARTS, PREPARE SPRAY SUCH AS MASKING TAPE THE UNAFFECTED AREAS WITH PAPER, CLEANING AND SANDING OF SURFACES, FINAL POLISHING AND WAXING ARE ALSO AVAILABLE.	New	1,000.00	400.00
6	TO APPLY UNDERCOATING ON THE REPAIRED AND REPLACED PANELS FOR RUST PROTECTION.	New	150.00	30.00
Gross Labour Cost (\$\$)			2,600.00	870.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >