

ASS. REC. BY:

REF:

CS/SMO19002114/ Uvd3 12

Special Instruction:

SURVEYOR:

Mehmen

ASSIGNMENT (Office)

From (Person):

Thelma Choo

of

SMO

Date/Time:

31/1/19 @ 2:39pm

Estimated Cost:

Bill to:

OD / TP WS / TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No:

YP 9759E

Insured:

GY 75312

at Workshop m/s

Mah Tian Motor

Tel:

91070026 / 62823336

of

No. 38 Defu Lane 9

Policy No:

DI9MTHCVF000169

Claim No:

CMTD1900654

Sum Insured:

Excess:

Make of Veh:

D.O.A.

29/1/19

(Client's Record)

CA / REV / REP. / REV 24 HRS

1up

H.O.D. Endorsement:

Date/Time:

3:11pm @ 31/1/19

Person Contacted:

Wan Rae

Vehicle IN /

OUT

Date/Time	Action/Instruction (✓) Estimate
	12/02/19 - wrap open back - VNI yet
	YP 9759E - X
	GY 75312 - NA / INC 11008166 / Y / DOA: 3/5/2011
	call back on 7/2/19.
7/2/19 -	called no answer. wrap might be closed for NY. call back again on 8/2/19
8/2/19 -	called no answer at all. called more than 3 times.
11/2/19 @ 11:58am -	called no answer (more than 3 times).

(08/11/13) wef

REF:

ASS. REC. BY: Marcus

ASSIGNMENT

From: Date:

Estimated Cost:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No:

at Workshop m/s

of

Insured:

Policy No.

Claims No.

Sum Insured:

Excess:

(Client's Record)

Make of Veh:

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.

Bal. or Market Value:

IDAC Accident Rpt: Consistent? : Yes or No

GIA / PR Seen: Consistent? : Yes or No

Est. Repairs: 4 days Res.: Yes or No

Lum Sum: 20 % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Date: Person Contacted:

Vehicle: IN / OUT

Date / Time Action / Instruction

LTA 28620

Veh No: 1P9759E Yr Regn: 1018

Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make: 15424 NMR85 c.c. 2999

Colour: white A/C: Insured / Std / NI / NA

Sp. Reading: 11810 T/Radio: Insured / Std / NI / NA

Eng/No:

C/No:

Gen. Cond: Good / Fair / Poor / Burnt

Steering: Inorder / Jammed / Leaked / Burnt or

Brake: Inorder / Jammed / Leaked / Burnt or

Modi: Nil / S/Rim / STD A/Rim or

Tyre Size: F:

R:

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

Front

Rear

R/Bal. 8 mm R/Bal. 8/8 mm

L/Bal. 8 mm L/Bal. 8/8 mm

D.O.A. 29/1/19 D.O.I. 14/2/19

Survey held at

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision.

15/1/19 Informed Thelma pending est from repairer by email

27/2/19 L/s 4100 confirmed with s.hu; (Red 1750.50, 3019)

28/2/19 Send preli revised via merimen

RECEIVED 28 FEB 2019

Date/Time, File Pass to?

☐ : Preli. Report

Days Of Repair: 4

1)

☐ : Final Report

Resurvey No. of Trip: 1

Date/Time, File Return to?

Survey Fee:

2) 28/2 - typist

Add Fee: ☐ : Site Insp (\$

Transportation:

250

10

☐ : Interview (\$

Photos

☐ : Tech. Invs (\$

Others

☐ : Weekend (\$

Report Format: merimen

Lump Sum / I.B.I. (\$

4100/2

TOTAL

260

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

To: Sompo Insurance Singapore Pte. Ltd.
50 Raffles Place
#05-01/06, Singapore Land Tower
Singapore 048623

From: LKK Auto Consultants Pte Ltd
51 Ubi Ave 1 #01-25
Paya Ubi Industrial Park
Singapore 408933

Attn: Thelma Choo

Date: 28 Feb 2019

Preliminary Advice

Insured Vehicle No : GY7531Z

TP Vehicle No : YP9759E

Accident Date : 29/01/2019

Make : ISUZU NMR85UH5A

Assignment Date : 31/01/2019

Date of Inspection : 14/02/2019

Est. Duration of Repair : 4.00

Inspection At : MAH LIAN MOTOR VEHICLE REPAIRER (HQ)
NO. 38 DEFU LANE 9
SINGAPORE 539278

Point of Impact / General Description of Damages

The vehicle sustained impact / damages rear portion and parts claimed are consistent to the accident.

Repairer's Estimate (Gross)	:S\$	5,850.50
Revised Amount	:S\$	4,100.00 (LUMP SUM)
Check Items (Estimated)	:S\$	0.00
Total	:S\$	4,100.00

Lump Sum Repair	:S\$	
-----------------	------	--

Total Loss Consideration

New for Old Value	:S\$	
Pre-Accident Value	:S\$	
COE / PARF Rebate	:S\$	
Salvage Value	:S\$	
Margin for Repair	:S\$	

Remarks

() The vehicle is repairable at our adjusted amount. We have also confirmed excess and policy coverage. Kindly let us have your authorisation.

() The vehicle is uneconomical to be repaired, you are advised to invite tender for the wreck.

(X) Other comments :The above survey was conducted on a 'Without Prejudice' basis.

...CLAIM SUBFOLDER...(New Assignment)

CLAIM SUBFOLDER TRACKING							
Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'd	Status
Main	30 Jan 2019		31 Jan 2019 14:39 Assign				New Assignment Cancel Case

Main	Reference	Claim Details	Documents	Show All
------	-----------	---------------	-----------	--------------------------

CLAIM SUBFOLDER DETAILS	[Created by insurer]
Insured: ETHOZ GROUP LTD , Co. Reg. No.: 198104531H	
Main Claimant: ALLMASTER ENTERPRISE , Co. Reg. No.: 20735700E	
Vehicle Reg. No.: YP9759E	Date of Loss: 29/01/2019 09:00 - :59
Claim Type: TP / CMTD1900654	Policy/Cover Note No.: D19MTHCVE000169 (Third Party Only)
Vehicle Reg. No. (Insured): GY7531Z	Policy No. (Claimant):
	Excess:
Repairer: Mah Lian Motor Vehicle Repairer (HQ) NO. 38 DEFU LANE 9, 539278 Defu Lane - Tel:	
Handling Insurer: Sompo Insurance Singapore Pte. Ltd. (HQ) - Tel: 6461 6555 ... [Handled by Thelma Choo - 6322 4681]	
Adjuster: LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Final Rpt due 13/02/2019]	

ASSOCIATED MAIL RECEIVED	View All Compose Case Mail
There are no mail for this case.	

ALL ASSOCIATED TASKS ☐	View All Search Tasks Create New Task Complete
Due Date Priority Type Task Group Subject Handler Assigned By Completed On Created On Done?	
No results.	

View Sent Message

This mail is associated with :

***YP9759E (CMTD1900654)**
[GY7531Z]

TP

ALLMASTER ENTERPRISE
Jan 29 2019 9:00AM
[ETHOZ GROUP LTD]
Mah Lian Motor Vehicle Repairer

[Resend](#)[View Recipients](#)[Print Message](#)[Delete Message](#)[Forward](#)

From LKK Auto Consultants Pte Ltd (LKK_HQ), sent on 15/02/2019 10:36 AM.
To ThelmaChoo
Subject TP SURVEY YP 9759E

Dear Thelma,

Please be informed that we have inspected the vehicle YP 9759E on 14/2/2019.

We are pending estimate from repairer.

Best Regards,
Veron Chen

DOCUMENTS SUMMARY

There are no documents.

> Back to OneMotoring

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars	
Owner ID Type:	Business
Owner ID:	5700E
Vehicle Details	
Vehicle No.:	YP9759E
Vehicle to be Exported:	No
Intended Deregistration Date:	15 Feb 2019
Vehicle Make:	ISUZU
Vehicle Model:	NMR85UH5A MT
Primary Colour:	White
Manufacturing Year:	2018
Engine No.:	4JJ13R7350
Chassis No.:	JAANMR85HJ7102194
Maximum Power Output:	-
Open Market Value:	\$32,257.00
Original Registration Date:	29 Oct 2018
First Registration Date:	29 Oct 2018
Transfer Count:	0
Actual ARF Paid:	\$1,613.00
Intended PARF Rebate Details	
PARF Eligibility:	No
PARF Eligibility Expiry Date:	-
PARF Rebate Amount:	\$0.00
Intended COE Rebate Details	
COE Expiry Date:	28 Oct 2028
COE Category:	C - Goods Vehicle & Bus
COE Period(Years):	10
QP Paid:	\$29,501.00
COE Rebate Amount:	\$28,620.00
Total Rebate Amount:	\$28,620.00

The information contained herein is correct as at 15 Feb 2019

OK

MAH LIAN MOTOR VEHICLE REPAIRER

No.38 Defu Lane 9 Singapore 539278
 TEL: 62823336 FAX: 62893336 Email: mahlian@singnet.com.sg
 GST:M90362564P RCB NO:201327339E

not allowed
 1/5 @ 4100/
 14/2/19
 4 dy.

M/S : SOMPO Insurance Singapore Pte Ltd
 50 Raffles Place #05-01/06 Singapore
 Land Tower Singapore 048623

ATTN: Motor Claim Department
 Your Ref No: ALLMASTER ENTERPRISE
 Claim Type: Third Party
 Accident Date: 29/01/2019

Estimate No: ES1700442
 Date: 29 Jan 2019
 Policy No: 5104938164
 Veh Reg No: YP9759E
 Make/Model: ISUZU NMR85UH5A MT
 Chassis No: JAANMR85HJ7102194
 Engine No: 4JJ13R7350
 Reg. Date: 29/10/2018

Estimate Repair Cost to Vehicle No :YP9759E

Description	U/Price	Quantity	List Price	Amount
			<u>SS</u>	<u>SS</u>
List Price				
1 License Lamp	45.00	1 PC	45.00	X
			45.00	
		Less 10%	4.50	40.50
Net Price <i>S. Nett itan</i>				
2 Rear Bumper	980.00	1 PC	980.00	—
3 Rear Bumper Bracket LH/RH	180.00	2 PC	360.00	—
4 Rear Tipper Door	1,890.00	1 PC	1,890.00	—
5 Rear Tipper Door Aluminium	550.00	1 PC	550.00	400
6 Rear Wooden Crossmember	180.00	1 PC	180.00	—
7 Rear Tipper U Bolt	50.00	1 PC	50.00	—
8 Rear Number Plate	40.00	1 PC	40.00	14
9 Sticker "allmaster.com.sg"	220.00	1 PC	220.00	—
10 Sticker "60km/h"	20.00	1 PC	20.00	10
11 Sticker "13 pax"	20.00	1 PC	20.00	10
			4,310.00	4,310.00
Labour				
12 Labour to repair rear wooden frame .	40.00	1 JOB	40.00	—
13 Labour to dismantle & renew rear tipper door .	200.00	1 JOB	200.00	—
14 Labour to cut & weld & renew rear bumper .	150.00	1 JOB	150.00	790
15 Labour to dismantle rear tipper door aluminium & rivet back .	350.00	1 JOB	350.00	600
16 Labour to renew rear tipper wooden crossmember .	50.00	1 JOB	50.00	—
17 Labour to check wiring & renew & connect license lamp .	30.00	1 JOB	30.00	20
18 Labour to spray painting whole rear tipper door & bumper & rear crossmember .	680.00	1 JOB	680.00	500
			1,500.00	1,500.00

Total SS 5,850.50

Add GST @ 7% 409.54

Total Amount Payable SS 6,260.04

TOTAL: SINGAPORE DOLLAR SIX THOUSAND TWO HUNDRED SIXTY AND CENTS FOUR ONLY

LKK Auto: Consent to finance notify
 the Reparer of the following:

- To repair (e.g. cut & spray painting)
- Part to be replaced to confirmation
- Third party survey is on a "Without Prejudice" basis
- Handling of documents is allowed
- Supplementary to (a) must be re-surveyed and is subject to final approval from Insurance Company

Acknowledged by Reparer

Signature:

Date:

**For MAH LIAN MOTOR VEHICLE
 REPAIRER**

AUTHORISED SIGNATURE

5234

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CS/SMO19002114/UVD3N2

Date: 01/03/2019

REFERENCE

Handling Insurer:	Sompo Insurance Singapore Pte. Ltd.	Policy No:	D19MTHCVE000169
Claimant Vehicle No :	YP9759E	Insured Vehicle No :	GY7531Z
Date of Loss:	29/01/2019	Nature of Claim:	TP
		Claim No:	CMTD1900654

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	YP9759E	Engine No:	4JJ13R7350
Make & Model:	ISUZU NMR85UH5A, 3.0 D (M)	Chassis No:	JAANMR85HJ7102194
Reg. Date:	29/10/2018 (Man. Year: 2018)	Odometer:	11810 km
Colour:	White		
Engine Capacity:	2999 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	195/85 R16	Rear Tyre Size:	195/85 R16 (D)
Front Left Side:	Yokohama 8 mm	Rear Left Side:	Yokohama 8/8 mm
Front Right Side:	Yokohama 8 mm	Rear Right Side:	Yokohama 8/8 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS

	Repairer's	Adjuster's	Difference	Diff %
Parts	4,350.50	4,114.00	236.50	5.44
Miscellaneous Items	0.00	0.00	0.00	
Labour	1,500.00	1,120.00	380.00	25.33
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	5,850.50	5,234.00	616.50	10.54
Approved Total (Overridden) (S\$)		4,100.00		
(S\$)	5,850.50	4,100.00	1,750.50	29.92
+ GST 7.00/7.00% (S\$)	409.54	287.00	122.54	29.92
Nett Amount (S\$)	6,260.04	4,387.00	1,873.04	29.92

INSPECTION

Date of Assignment:	31/01/2019	
Date Inspected:	14/02/2019	Inspected At: Mah Lian Motor Vehicle Repairer (HQ) NO. 38 DEFU LANE 9 Singapore 539278
Estimated Period of Repair:	4.0 days	

Adjuster: MARCUS CHUA

Manager: VERON CHEN

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our

knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference

Part Source:	(Last Synchronised: 01 Mar 2019)	
Parts:	N/A	ISUZU NMR85UH5A 3.0 D (M) (Model not available in database)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for YP9759E)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*LICENSE LAMP	Not Necessary	45.00 FL	*- FL
2	1		*REAR BUMPER	Bent	980.00 FS	*980.00 FS
3	2		*REAR BUMPER BRACKET LH/RH	Necessary/Bent	360.00 FS	*360.00 FS
4	1		*REAR TIPER DOOR	Dented/Bent	1,890.00 FS	*1,890.00 FS
5	1		*REAR TIPER DOOR ALUMINIUM	Bent	550.00 FS	*400.00 FS
6	1		*REAR WOODEN CROSSMEMBER	Cracked	180.00 FS	*180.00 FS
7	1		*REAR TIPER U BOLT	Bent	50.00 FS	*50.00 FS
8	1		*REAR NUMBER PLATE	Bent	40.00 FS	*14.00 FS
9	1		*STICKER ALLMASTER.COM.SG	Necessary	220.00 FS	*220.00 FS
10	1		*STICKER 60KM/H	Necessary	20.00 FS	*10.00 FS
11	1		*STICKER 13PAX	Necessary	20.00 FS	*10.00 FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (S\$)	4,355.00	4,114.00
- List Item Discount on L Items 10.00/10.00% (S\$)	4.50	0.00
Total Parts (S\$)	4,350.50	4,114.00

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	LABOUR TO DISMANTLE REAR TIPPER DOOR ALUMINIUM & RIVET BACK }	New	350.00	600.00
2	LABOUR TO REPAIR REAR WOODEN FRAME }	New	40.00	0.00
3	LABOUR TO DISMANTLE & RENEW REAR TIPPER DOOR }	New	200.00	0.00
4	LABOUR TO CUT & WELD & RENEW REAR BUMPER }	New	150.00	0.00
5	LABOUR TO RENEW REAR TIPPER WOODEN CROSSMEMBER }	New	50.00	0.00
6	LABOUR TO CHECK WIRING & RENEW & CONNECT LICENSE LAMP	New	30.00	20.00
7	LABOUR TO SPRAY PAINTING WHOLE REAR TIPPER DOOR & BUMPER & REAR CROSSMEMBER	New	680.00	500.00
Gross Labour Cost (S\$)			1,500.00	1,120.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >