

ASS. REC. BY:

REF

CS/CT119002153/Dqd3n2

A Instruction:

Surveyor's

Mentor

Byer

ASSIGNMENT (Office)

From (Person)

Chany Boon Jun

of

CTP

Date/Time:

1/2/19 @ 3:44pm

Estimated Cost:

Bill to:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No:

SHA 7816 S

Insured:

SLR 804K

at Workshop m/s

Chunni Motor

Tel:

85425119

of

Blk 10, AMK Ind. Park 2A # 03-19

Policy No:

DMPCS N3051121801

Claim No:

Sum Insured:

Excess:

Make of Veh:

D.O.A.

30/01/2019

(Client's Record)

07/02/2019

H.O.D. Endorsement

CA / REV / REP. / REV 24 HRS up

Date/Time:

4:06pm @ 1/2/19

Person Contacted:

Lynn

Vehicle IN/OUT

Date/Time

Action/Instruction (✓) Estimate

1/2/19 -

Repairer agreed survey on 7/2/2019

SHA 7816S - CS/CT118006675/Kqd3n2


Joa: 5/4/2018

SLR 804K - X

CVE June 2023

INSURANCE

Date: \_\_\_\_\_  
 Estimated Cost: \_\_\_\_\_  
 OD / TP / WS / IP / RES / OD RES / EVA / HW / MY: \_\_\_\_\_  
 Complete Vehicle No: \_\_\_\_\_  
 at Work / Shop / Home: \_\_\_\_\_  
 at: \_\_\_\_\_  
 In use: \_\_\_\_\_  
 Policy No: \_\_\_\_\_  
 Claim No: \_\_\_\_\_  
 Claim Insured: \_\_\_\_\_  
 (Clean) Record: \_\_\_\_\_  
 Make of Vehicle: \_\_\_\_\_  
 (Policy Condition) \_\_\_\_\_  
 Remark: The veh had commenced its repair at the time of inspection.  
 Bal. or Market Value: \_\_\_\_\_  
 IDAC Accident Report: \_\_\_\_\_ Consistent? Yes or No  
 GLA / PR Seen: \_\_\_\_\_ Consistent? Yes or No  
 Est. repairs: 14 days Res: Yes or No  
 Lump Sum: 20 % 3 Val: Yes or No  
 CA / REV / REP. / 24 HRS  
 Date: \_\_\_\_\_ Person Contacted: \_\_\_\_\_ Vehicle: IN / OUT



Vehicle: SHA 7816 8 Date: 2015 June  
 Type: M/Car / H/Cycle / Bus / Van / Lorry / Taxi / Prime Mover /  
 Truck / Trailer or \_\_\_\_\_  
 Make: Hyundai I40 CC 1685  
 Color: Blue AC Insured / Std / NI / NA  
 Sp Reading: H.A I/Radio: Insured / Std / NI / NA  
 Eng/No: D4FDEu 495798  
 ChNo: KMHLB4UM6u075088  
 Gen. Cond: Good / Fair / Poor / Burnt  
 Steering: In order / Jammed / Leaked / Burnt or  
 Brake: In order / Jammed / Leaked / Burnt or  
 Mod: Oil / SRim / STD A/Rim or  
 Tyre Size: F: 205/60 R16  
 R: 11  
 BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /  
 TOYO / YOKO or Campeon  
 Front Rear  
 R/Bal: S mm R/Bal: S mm  
 L/Bal: S mm L/Bal: S mm  
 D.O.A: 30/01/2019 D.O.I: 11/02/2019  
 Survey held at Churni MK  
 Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or  
 Front  
 The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time Action / Instruction  
 Churni Triping SLR 804K

20/03/2019 Juma 2/5 24 000/- with 14 days of reg  
 (Red. 675100.88, 51%)

RECEIVED 20 MAR 2019

Date/Time: File Pass by: ☐ Preli. Report  
 20/3/2019 ☐ Final Report  
 Date/Time: File Return by:

Days Of Repair: 14  
 Resurvey No. of Trip: 2 Survey Fee:

Add Fee: ☐ Safe Insp (\$)  
☐ Interjey (\$)  
☐ Tech. Insp (\$)  
☐ Weekend (\$)  
☐ Other (\$)  
☐ Other (\$)

Report Format: MER-TP  
 Lump Sum / H.A: 24000

220

## ...CLAIM SUBFOLDER...(New Assignment)

### CLAIM SUBFOLDER TRACKING

Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'd	Status
Main	30 Jan 2019		01 Feb 2019 15:44 <a href="#">Assign</a>				<b>New Assignment</b> <a href="#">Cancel Case</a>

Main	Reference	Claim Details	Documents	<a href="#">Show All</a>
------	-----------	---------------	-----------	--------------------------

#### CLAIM SUBFOLDER DETAILS [Created by insurer]

Insured:	CHIN CHOON YEW, ID: S7904455E		
Main Claimant:	COMFORT TRANSPORTATION PTE LTD, Co. Reg. No.: 199303821R		
Vehicle Reg. No.:	SHA7816S	Date of Loss:	30/01/2019 00:00 - :59
Claim Type:	TP / SLR804K	Policy/Cover Note No.:	DMPCSN3051121801 (Comprehensive) Coverage: 22/07/2018 - 21/07/2019
Vehicle Reg. No. (Insured):	SLR804K	Policy No. (Claimant):	
		Excess:	S\$500.00
Repairer:	Chunni Motor Pte Ltd (HQ) 10 Ang Mo Kio Industrial Park 2A, #03-19 AMK Autopoint, 568047 Ang Mo Kio - Tel:		
Handling Insurer:	China Taiping Insurance (Singapore) Pte. Ltd. (HQ) - Tel: 6389 6111 ... [Handled by Chong Boon Sen]		
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... <b>[Final Rpt due 14/02/2019]</b>		
Adj Asg. Remarks:	Please survey SHA7816S while waiting for Insured to file accident report		

**ASSOCIATED MAIL RECEIVED**
[View All](#) [Compose Case Mail](#)

There are no mail for this case.

**ALL ASSOCIATED TASKS**
[View All](#) [Search Tasks](#) [Create New Task](#) [Complete](#)

Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

MCD819014437 / ComfortDelGro Engineering Pte Ltd - Loyang  
 ENTRY DATE & TIME: 30/01/2019 15:56  
 SUBMITTED BY: Huang XiaoYen

## SINGAPORE ACCIDENT STATEMENT

## IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

## ACCIDENT STATEMENT

Date Of Report	30/01/2019 15:56
Date Of Accident	30/01/2019 00:05
Exact Location Of Accident	UPPER SERANGOON RD TWDS POTONG PASIR
Country/State of Loss	SINGAPORE

## DETAILS OF OWN VEHICLE

Vehicle Registration Number	SHA7816S
Insured/Policyholder	
Name Of Registered Owner	COMFORT TRANSPORTATION PTE LTD
Co Reg No	199303821R
Email Address	FLEETSAFETY@CDGTAXI.COM.SG
Mobile Phone No	
Alternative Phone No	OFFICE-65508768
Vehicle Particulars	
Manufacturer	HYUNDAI
Model	I40
Exact Purpose for which vehicle was being used at time of accident	
Are you claiming under your own insurance policy for repair to your vehicle?	NO
If No, Please state action to be taken	THIRD PARTY
Vehicle Category	TAXI
Insurance Company	
Name of Insurance Company	MS FIRST CAPITAL INSURANCE LTD
Type Of Coverage	THIRD PARTY FIRE AND/OR THEFT
Fleet Policy	YES
Policy Number	D-18088936MFSH
Cover Note Number	
Driver	
Name of Driver	OH KUAN HUI
NRIC No	S7514110F
Date Of Birth	15/05/1975
Occupation	OUTDOOR
Date Of Driving Pass	22/03/1997
Driving Experience	21 YEARS AND 10 MONTHS
Gender	MALE
Mobile Number	(LOCAL) +65-97828942
Fax Number	
Contact Number	
Email Address	KUANHUIOH@YAHOO.COM

Address BLK 310B ANG MO KIO AVENUE 1 #19-373  
 Postcode 562310  
 Was driver an employee of the Insured's Company NO  
 If No, Relationship of the Driver with the Insured OTHER - TAXI DRIVER  
 Vehicle Registration Number of Driver's Own Vehicle -  
 -  
 -  
 Insurance Company of Driver's Own Vehicle -  
 -  
 -

**General Information of the Accident**

Type Of Accident COLLISION - CROSS JUNCTION  
 Weather Conditions CLEAR  
 Road Surface DRY  
 Other Information

Was any foreign vehicle involved in this accident? NO  
 Number of vehicles (including own vehicle) involved in the accident 2  
 Was any body injured in the Accident? YES  
 Was any injured conveyed to hospital by ambulance? NO  
 Was any other material or property damaged? YES  
 I have been approached by unknown person(s) soliciting/offering accident claims assistance. NO  
 Number of Passengers (Including Driver) 1

**Details of Police Action**

Was the accident reported to the police? YES  
 If Yes, Please state which Police Station  
 POLICE STATION NAME [OTHER] BISHAN N.P.C  
 Was notice of intended Prosecution given? NO  
 If Yes, against whom?

**Circumstances of Accident**

PLS REFER TO POLICE REPORT : T/20190130/2059 / Type Of Accident: HEAD TO SIDE

**Attachment(s)**

Are accident photos available for attachment? YES  
 Was there any video captured by Car Camera? YES  
 Remarks/ Reasons: -  
 Was there any audio recorded? NO

**DETAILS OF OTHER VEHICLE PROPERTY 1**

Vehicle Registration Number SLR804K  
 Vehicle Make/Model/Colour  
 Details Of Properties  
 Vehicle Category PRIVATE CAR  
 Name of Driver LEE SUM HOU VERNIA  
 NRIC/Passport Number S8334710D  
 Contact Number 92398466  
 Address  
 Postcode  
 Insurance Company Name CHINA TAIPING INSURANCE (SINGAPORE) PTE. LTD.  
 Nature Of Damage RIGHT REAR  
 No. Of Passenger (Including Driver)

**DETAILS OF INJURED PERSON 1**

Name	OH KUAN HUI
Approximate Age	43
Injuries Sustain	PAIN ON SHOLDER AND BACK, ON 5 DAYS MC.
Injured person in which vehicle?	SHA7816S
Were seat belts worn?	YES
Was this injured conveyed to hospital by ambulance?	NO
Address	
Postcode	

**SKETCH PLAN****IMPORTANT NOTICE**

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. The report will be forwarded by the Insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgment of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.
8. **Consent under the Personal Data Protection Act (PDPA)**

I understand, acknowledge, agree and consent that:

- (a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this [form] and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the Insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of :
  - (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
  - (ii) investigating the accident and/or my claims;
  - (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
  - (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
  - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims.(collectively the "Purposes")
- (b) all insurer(s) who have insured vehicle(s) involved in this accident and the Insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
- (c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third party service providers or agents(including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.
- (d) my Personal Information will also be collected and used to compile claims history for the purpose of fraud detection, investigation and management in present and all future claims.
- (e) the information so collected under (d) above may be shared / disclosed:
  - (i) to all insurers and/or any other third parties that assist in evaluating, investigating, controlling or managing fraud, regulators, law enforcement and government agencies as reasonably required for the purposes stated, or
  - (ii) for complying with requirements under any regulations, laws or court orders.

COMFORT TRANSPORTATION PTE LTD  
CO. REG. NO. 199303821R

Policyholder's Signature  
Date & Time:

Driver's Signature  
(If driver is not the policyholder)


Date & Time: 30.01.2019@1330HRS

Reporting Centre Personnel's Signature  
Name:

NRIC/FIN No.: June Tan



## SKETCH PLAN



## DESCRIBE CIRCUMSTANCES OF THE ACCIDENT

## DECLARATION

I/We declare the foregoing particulars are true in every respect.

COMFORT TRANSPORTATION PTE LTD  
CO. REG. NO. 199303821R

Policyholder's Signature  
Date & Time:

Driver's Signature  
(If driver is not the policyholder)  
Date & Time: 30.01.2019@1330HRS

Reporting Centre Personnel's Signature  
Name:  
NRIC/FIN No.: June Tan





**SINGAPORE  
POLICE FORCE**



T/20190130/2059

1 of 3

Police Station Of Origin:  
Bishan N.P.C  
20 Bishan Street 23 SINGAPORE 579757  
Tel No: 1800-5529999

Report No. T/20190130/2059

**REPORT OF A TRAFFIC ACCIDENT**

Date/Time Report Made: 30/01/2019 12:03		Vide Report No.:		Station Diary No.: 81
<b>Informant's Particulars</b>				
Name of Informant: OH KUAN HUI		Address: APT BLK 310B ANG MO KIO AVENUE 1 #19-373 SINGAPORE 562310		
ID Type / ID No.: NRIC NO / S7514110F		Contact No.: Home/Office: Mobile: 97828942		
Nationality: SINGAPORE CITIZEN		Email:		
Sex: Male	Age: 43	Date of Birth: 15/05/1975	Type of Informant: Driver	
Race: Chinese		Language: English		Institution / School Name:
Occupation: Taxi driver		Driving Licence Information: Class: 3 Date of Expiry:		

**General Information of the Accident**

Type of Accident:	Injury Attended by Police	Drink Drive: No	Date/Time of Accident: 30/01/2019 00:00 00:05 hr	Type of Location: T-Junction
Location: Along Road 1 UPPER SERANGOON ROAD TOWARDS POTONG PASIR				
Weather: Clear		Road Surface: Dry		Road Speed Limit:
Traffic Flow: Two Way		Traffic Control: Traffic Light - Working		Traffic Volume: Light
Type of Collision: Between Moving Vehicles - Head To Side				Anyone conveyed by ambulance: No

**Details of Vehicle Involved**

Vehicle No.	Type	Make	Model	Color	Condition	No of Passenger
SHA7816S	Car				Seriously Damaged	0
SLR804K	Car					0

**Details of Person Involved**

Any Pedestrian Involved: No	Use of Pedestrian Crossing: NA
No. of Pedestrians Injured: NIL	



**SINGAPORE  
POLICE FORCE**



T/20190130/2059

2 of 3

Police Station Of Origin:

Bishan N.P.C

20 Bishan Street 23 SINGAPORE 579757

Tel No: 1800-5529999

Report No. T/20190130/2059

## CONTINUATION OF REPORT

<b>Driver</b>			
Name	OH KUAN HUI		ID No. S7514110F
Related Vehicle	SHA7816S (Car)		Contact No. 97828942
Hospital/Clinic	MOUNT ALVERNIA HOSPITAL		Class of Driving Licence & Expiry Date Class: 3 Date of Expiry: NIL
Date Treatment	30/01/2019	Date Discharge	30/01/2019
No. of Days granted Medical Leave	05	Degree of Injury	Slight
<b>Driver</b>			
Name	LEE SUM HOU, VERNIA		ID No. S8334710D
Related Vehicle	SLR804K (Car)		Contact No. 92398466
Hospital/Clinic	NIL		Class of Driving Licence & Expiry Date Class: NIL Date of Expiry: NIL
Date Treatment	NIL	Date Discharge	NIL
No. of Days granted Medical Leave	NIL	Degree of Injury	NIL

**Brief Details.**

On 30/01/2019, at round midnight, I was driving my vehicle along the said road. When I was driving at the T-junction under Upper Serangoon Viaduct (traffic light was green in my favour), another vehicle suddenly appeared at the junction (vehicle was from Bartley Road). I applied my brakes however was unable to stop in time and my vehicle collided onto the other vehicle right rear portion. TP and ambulance came down shortly to render assistance. Both parties managed to exchanged particulars. After the accident, I went to see a doctor and was given 5 days MC. I also wish to state that my vehicle video camera captured the accident. Purpose to lodge this report is for traffic police investigation and also for claiming insurance purposes.

**SINGAPORE  
POLICE FORCE**

T/20190130/2059

3 of 3

Police Station Of Origin:  
Bishan N.P.C  
20 Bishan Street 23 SINGAPORE 579757  
Tel No: 1800-5529999

Report No. T/20190130/2059

**CONTINUATION OF REPORT****Sketch Plan**

Informant is not able to provide sketch plan

**IMPORTANT:** Please attach a copy of your vehicle's Insurance Certificate to this report. If you don't have the certificate with you now, please fax a copy to 65474885 stating the report number as reference.

Signature Of Officer Recording The Report:  
E /  
Sr Staff Sgt AZMI BIN MOHAMED HAMZAH

Signature Of Informant:

Signature Of Interpreter:  
Not applicable

Date/Time:  
30/01/2019 12:03

Officer In Charge Of Case  
TP / GIT /  
SI THABAGESH JEYATHESH  
Contact No.: 65476232

SINGAPORE  
POLICE FORCES-261  
Classification Of Case:

Authentication Stamp  
NP188

SIGNATURE

**CHUNNI MOTOR WORK PTE LTD****REPAIR ESTIMATE\***

VEHICLE NO : SHA 7816S

DATE : 30.01.2019

MAKE :

TEL : 6542 5119

MODEL : HYUNDAI i40



FAX : 6542 6039

China Taiping

Qty	Parts Description/ Labour	Type	Unit Price	Amount	
	Bonnet <i>inc</i>			\$ 2,265.90	✓
	Bonnet Hinge (LH/RH) <i>1st</i>	\$	41.00	\$ 82.00	✓
	Bonnet Lock <i>1st</i>			\$ 36.90	✓
	Bonnet Absorber <i>new</i>	\$	58.10	\$ 116.20	X
	Bonnet Insulator <i>new</i>			\$ 196.50	X
	Bonnet Insulator Clips <i>new</i>			\$ 8.40	X
	Bonnet Cable <i>new 1st</i>			\$ 28.60	X ✓
	Radiator Grille <i>broken</i>			\$ 1,110.10	✓
	Radiator Grille H Emblem <i>new 1st dislodged</i>			\$ 120.30	✓
	Front Bumper Cover <i>new</i>			\$ 1,052.20	✓
	Front Bumper Sponge <i>new</i>			\$ 99.20	✓
	Front Bumper Reinforcement <i>1st</i>			\$ 402.10	✓
	Front Bumper Grille (LH) <i>new</i>			\$ 93.60	✓
	Front Bumper Grille Airduct (LH) <i>new</i>			\$ 26.20	X
	Front Bumper Lip <i>new</i>			\$ 54.90	X
	Front Bumper Bracket Top (LH/RH) <i>new</i>	\$	22.40	\$ 44.80	X
	Front Bumper Bracket (LH/RH) <i>new broken o/s new</i>	\$	24.60	\$ 49.20	✓
	Headlamp Support Top Cover <i>broken</i>			\$ 222.60	✓
	Headlamp Support Panel Assy <i>new</i>			\$ 907.40	✓
	Headlamp (LH/RH) <i>broken 1st mounting broken</i>	\$	1,388.00	\$ 2,776.00	✓
	Radiator <i>1st</i>			\$ 698.30	✓
	Radiator Fan Blade, Cowling, Motor Assy <i>broken</i>			\$ 792.95	✓
	Radiator Bracket (RH/LH) <i>new</i>	\$	6.50	\$ 13.00	X
	Radiator Hose Upper <i>1st defined</i>			\$ 105.80	✓
	Radiator Hose Lower <i>1st defined</i>			\$ 52.70	✓
	Radiator Expansion Tank <i>new</i>			\$ 28.30	X
	Radiator Guard <i>new</i>	\$	20.00	\$ 40.00	X
	Horn Unit (LH/RH) <i>broken</i>	\$	73.80	\$ 147.60	✓
	Horn Wire <i>new</i>			\$ 156.50	X
	Front Fender (LH/RH) <i>Dented</i>	\$	566.30	\$ 1,132.60	✓
	Front Fender Apron Panel (LH/RH) <i>o/s 1st new 1st</i>	\$	637.00	\$ 1,274.00	✓
	Front Fender Shield (LH/RH) <i>o/s 1st new 1st</i>	\$	174.90	\$ 349.80	✓
	Air Cleaner Assy <i>broken</i>			\$ 118.60	✓
	Air Duct <i>broken</i>			\$ 134.60	✓
	Air Flow Sensor <i>new</i>			\$ 502.20	X
	Air Cleaner Bottom Assy <i>broken</i>			\$ 325.00	✓
	Aircon Condenser <i>fractured</i>			\$ 927.50	✓
	Aircon Suction & Liquid Hose <i>new 1st</i>			\$ 624.00	X ✓
	Aircon Discharge Hose <i>new 1st</i>			\$ 162.60	X ✓
	Aircon Compressor <i>new 1st</i>			\$ 2,578.00	X ✓
	Front Windscreen Glass <i>crack</i>			\$ 1,017.80	✓
	Front Windscreen Moulding <i>new</i>			\$ 113.30	✓
	Front Windscreen Pillar Outer (RH) <i>new</i>			\$ 1,745.50	✓
	Wiper Panel Top Garnish <i>broken</i>			\$ 222.60	✓
	Wiper Container <i>new 1st crack</i>			\$ 61.90	✓
	Wiper Container Motor <i>new</i>			\$ 75.00	✓
	Front Chassis Member <i>new 1st</i>			\$ 1,060.70	✓

22767.45



Qry	Parts Description/ Labour	Type	Unit Price	Amount
	Sensor -Ambient <i>dislodged</i>			\$ 287.50
	Bonnet Switch <i>dislodged</i>			\$ 155.00
	SUB TOTAL			\$ 442.50
	LESS 20%			\$ 88.50
	DISCOUNTED TOTAL			\$ 354.00
	<p><i>14/02/2019</i></p>  <p><i>J &amp; K Auto</i></p> 			

This is an initial estimate based on a visual inspection of the above vehicle. The final repair quantum will be prepared after the vehicle is surveyed by a motor Surveyor appointed by the insurance company.



## LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

## VEHICLE DAMAGE INSPECTION REPORT

Our File No: CS/CT119002153/DQD3N2

Date: 01/04/2019

## REFERENCE

Handling Insurer:	China Taiping Insurance (Singapore) Pte. Ltd.	Policy No:	DMPCSN3051121801	
Claimant Vehicle No :	SHA7816S	Insured Vehicle No :	SLR804K	
Date of Loss:	30/01/2019	Nature of Claim:	TP	Claim No: SLR804K

## DESCRIPTION &amp; IDENTIFICATION OF VEHICLE

Reg No:	SHA7816S	Engine No:	D4FDEU495798
Make & Model:	HYUNDAI I40, 1.7 D (A)	Chassis No:	KMHLB41UMGU075088
Reg. Date:	30/06/2015 (Man. Year: 2015)	Odometer:	0 km
Colour:	Blue		
Engine Capacity:	1685 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	Market Value/New Car Price		

## CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

## CONDITION OF TYRES

Front Tyre Size:	205/60 R16	Rear Tyre Size:	205/60 R16
Front Left Side:	Campeon 5 mm	Rear Left Side:	Campeon 5 mm
Front Right Side:	Campeon 5 mm	Rear Right Side:	Campeon 5 mm

The above values represent the remaining tyre treads depth

## COST OF CLAIMS

	Repairer's	Adjuster's	Difference	Diff %
Parts	42,060.88	27,083.08	14,977.80	35.61
Miscellaneous Items	0.00	0.00	0.00	
Labour	7,040.00	2,960.00	4,080.00	57.95
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
<b>Calculated Gross Total (S\$)</b>	<b>49,100.88</b>	<b>30,043.08</b>	<b>19,057.80</b>	<b>38.81</b>
<b>Approved Total (Overridden) (S\$)</b>		<b>24,000.00</b>		
(S\$)	49,100.88	24,000.00	25,100.88	51.12
+ GST 7.00/7.00% (S\$)	3,437.06	1,680.00	1,757.06	51.12
<b>Nett Amount (S\$)</b>	<b>52,537.94</b>	<b>25,680.00</b>	<b>26,857.94</b>	<b>51.12</b>

## INSPECTION

Date of Assignment:	01/02/2019	
Date Inspected:	11/02/2019 Inspected At:	Chunni Motor Pte Ltd (HQ) 10 Ang Mo Kio Industrial Park 2A, #03-19 AMK Autopoint Singapore 568047
Estimated Period of Repair:	14.0 days	

Adjuster: BRYAN TANI

Manager: SHIAU CHAN



*NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.*

## REPAIR DETAILS

### Reference

<b>Part Source:</b> MRM-SG	Version: 1.0 (Last Synchronised: 01 Apr 2019)
<b>Parts:</b> 143	HYUNDAI I40 1.7 D (A) (Catalogue:Merimen Singapore 1.0)
<b>Labour:</b> Repairer's	(Price-denominated Standard List)
<b>Print Code:</b> (Unsubmitted, no print-code for SHA7816S)	
<b>Validity:</b>	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page
<b>Further Info:</b>	Items/values not in reference catalogue are prefixed with an asterisk *.

### Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*BONNET	Buckled	2,265.90 FL	*2,265.90 FL
2	2		*BONNET HINGE (LH/RH)	Bent	82.00 FL	*82.00 FL
3	1		*BONNET LOCK	Bent	36.90 FL	*36.90 FL
4	2		*BONNET ABSORBER	Not Necessary	116.20 FL	*- FL
5	1		*BONNET INSULATOR	Not Necessary	196.50 FL	*- FL
6	1		*BONNET INSULATOR CLIPS	Not Necessary	8.40 FL	*- FL
7	1		*BONNET CABLE	Bent	28.60 FL	*28.60 FL
8	1		*RADIATOR GRILLE	Broken	1,110.10 FL	*1,110.10 FL
9	1		*RADIATOR GRILLE H EMBLEM	Necessary / Dislodged	120.30 FL	*120.30 FL
10	1		*FRONT BUMPER COVER	Torn	1,052.20 FL	*1,052.20 FL
11	1		*FRONT BUMPER SPONGE	Torn	99.20 FL	*99.20 FL
12	1		*FRONT BUMPER REINFORCEMENT	Bent	402.10 FL	*402.10 FL
13	1		*FRONT BUMPER GRILLE (LH)	Cut	93.60 FL	*93.60 FL
14	1		*FRONT BUMPER GRILLE AIRDUCT (LH)	Not Necessary	26.20 FL	*- FL
15	1		*FRONT BUMPER LIP	Not Necessary	54.90 FL	*- FL
16	2		*FRONT BUMPER BRACKET TOP (LH/RH)	Not Necessary	44.80 FL	*- FL
17	1		*FRONT BUMPER BRACKET (LH/RH)	N/S Broken / O/S Not Necessary	49.20 FL	*24.60 FL
18	1		*HEADLAMP SUPPORT TOP COVER	Broken	222.60 FL	*222.60 FL
19	1		*HEADLAMP SUPPORT PANEL ASSY	Buckled	907.40 FL	*907.40 FL
20	2		*HEADLAMP (LH/RH)	Mtg Broken	2,776.00 FL	*2,776.00 FL
21	1		*RADIATOR	Bent	698.30 FL	*698.30 FL
22	1		*RADIATOR FAN BLADE ,COWLING ,MOTOR ASSY	Broken	792.95 FL	*792.95 FL
23	2		*RADIATOR BRACKET (RH/LH)	Not Necessary	13.00 FL	*- FL
24	1		*RADIATOR HOSE UPPER	Deformed	105.80 FL	*105.80 FL
25	1		*RADIATOR HOSE LOWER	Deformed	52.70 FL	*52.70 FL
26	1		*RADIATOR EXPANSION TANK	Not Necessary	28.30 FL	*- FL
27	2		*RADIATOR GUARD	Not Necessary	40.00 FL	*- FL
28	2		*HORN UNIT (LH/RH)	Broken	147.60 FL	*147.60 FL
29	1		*HORN WIRE	Not Necessary	156.50 FL	*- FL
30	2		*FRONT FENDER (LH/RH)	Dented	1,132.60 FL	*1,132.60 FL
31	2		*FRONT FENDER APRON PANEL (LH/RH)	O/S Dented / N/S Bent	1,274.00 FL	*1,274.00 FL
32	1		*FRONT FENDER SHIELD (LH/RH)	O/S Torn / N/S Not Necessary	349.80 FL	*174.90 FL
33	1		*AIR CLEANER ASSY	Broken	118.60 FL	*118.60 FL
34	1		*AIR DUCT	Broken	134.60 FL	*134.60 FL
35	1		*AIR FLOW SENSOR	Not Necessary	502.20 FL	*- FL
36	1		*AIR CLEANER BOTTOM ASSY	Broken	325.00 FL	*325.00 FL
37	1		*AIRCON CONDENSER	Punctured	927.50 FL	*927.50 FL
38	1		*AIRCON SUCTION & LIQUID HOSE	Bent	624.00 FL	*624.00 FL
39	1		*AIRCON DISCHARGE HOSE	Bent	162.60 FL	*162.60 FL
40	1		*AIRCON COMPRESSOR	Distorted	2,578.00 FL	*2,578.00 FL

Report was unsubmitted during this print-out.

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
41	1		*FRONT WINDSCREEN GLASS	Cracked	1,017.80 FL	*1,017.80 FL
42	1		*FRONT WINDSCREEN MOULDING	Necessary	113.30 FL	*113.30 FL
43	1		*FRONT WINDSCREEN PILLAR OUTER (RH)	Buckled	1,745.50 FL	*1,745.50 FL
44	1		*WIPER PANEL TOP GARNISH	Broken	222.60 FL	*222.60 FL
45	1		*WIPER CONTAINER	Mtg Cracked	61.90 FL	*61.90 FL
46	1		*WIPER CONTAINER MOTOR	Damaged	75.00 FL	*75.00 FL
47	1		*FRONT CHASSIS MEMBER	Bent	1,060.70 FL	*1,060.70 FL
48	1		*ENGINE MOUNTING	Damaged	456.30 FL	*456.30 FL
49	1		*ENGINE MTG (REAR)	Not Necessary	279.60 FL	*- FL
50	1		*GEARBOX	Not Necessary	14,808.00 FL	*- FL
51	1		*GEARBOX MOUNTING	Damaged	215.40 FL	*215.40 FL
52	1		*STARTER MOTOR ASSY	Not Necessary	790.60 FL	*- FL
53	1		*INTER COOLER	Bent / Punctured	1,032.50 FL	*1,032.50 FL
54	2		*INTER COOLER MOUNTING	Not Necessary	25.90 FL	*- FL
55	1		*HOSE B TO INTER COOLER	Distorted	229.70 FL	*229.70 FL
56	1		*HOSE C TO INTER COOLER INLET	Distorted	294.50 FL	*294.50 FL
57	1		*PIPE TO INTER COOLER	Not Necessary	167.05 FL	*- FL
58	1		*PIPE TO INTER COOLER OUTLET	Distorted	244.55 FL	*244.55 FL
59	1		*WIRING-ENGINE	Torn	3,326.00 FL	*3,326.00 FL
60	1		*WIRING-FEM ,LH	Not Necessary	168.00 FL	*- FL
61	1		*ACTUATOR-SWIRL CONTROL	Mtg Cracked	814.60 FL	*814.60 FL
62	1		*THROTTLE BODY ASSY	Not Necessary	1,096.60 FL	*- FL
63	1		*INTAKE MANIFOLD ASSY	Cracked	1,141.10 FL	*1,141.10 FL
64	1		*EGR VALVE & PIPE ASSY	Damaged	2,480.50 FL	*2,480.50 FL
65	1		*FRONT NUMBER PLATE	Cracked	25.00 FS	*25.00 FS
66	1		*FRONT NO PLATE TRIM COVER	Bent	30.00 FS	*30.00 FS
67	2		*FRONT FENDER ADVERTISEMENT LOGO (LH/RH)	Necessary	200.00 FS	*200.00 FS
68	1		*FRONT WINDSCREEN SEALANT	Necessary	46.00 FS	*46.00 FS
69	1		*FRONT ERP STICKER	Necessary	26.00 FS	*26.00 FS
70	1		*SENSOR AMBIENT	Dislodged	287.50 FL	*287.50 FL
71	1		*BONNET SWITCH	Dislodged	155.00 FL	*155.00 FL

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (S\$)	52,494.35	33,772.10
- List Item Discount on L Items 20.00/20.00% (S\$)	10,433.47	6,689.02
<b>Total Parts (S\$)</b>	<b>42,060.88</b>	<b>27,083.08</b>

Report was unsubmitted during this print-out.

## Recommended Miscellaneous Items

There are no new miscellaneous items selected.

## Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<b>Labour Items</b>				
1	PANEL BEATING	New	2,400.00	1,200.00
2	SPRAY PAINTING CHARGE	New	1,500.00	1,000.00
3	WIRING CHARGE	New	100.00	30.00
4	TUFF KOTE	New	150.00	40.00
5	TOWING CHARGE	New	50.00	0.00
6	FRONT CHASSIS ALIGNMENT CHARGE	New	400.00	150.00
7	REMOVE/REFIX UNDERCARRIAGE (FRT)	New	200.00	0.00
8	FRT WHEEL ALIGNMENT	New	120.00	0.00
9	REMOVE/REFIX AIRCON & REFILL GAS	New	150.00	80.00
10	REMOVE/REFIX ENGINE /GEARBOX	New	650.00	0.00
11	REMOVE/REFIX DASHBOARD	New	450.00	150.00
12	REMOVE/REFIX FUSE BOX	New	180.00	50.00
13	REMOVE/REFIX FRONT WINDSCREEN GLASS	New	120.00	80.00
14	REMOVE/REFIX CUSHION & UPHOLSTERY FRONT	New	90.00	0.00
15	DIAGNOSTIC & RESETTING TO ERASE FAULT CODE	New	480.00	180.00
Gross Labour Cost (\$\$)			7,040.00	2,960.00

Report was unsubmitted during this print-out.

&lt; END OF ESTIMATES &gt;