LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

To: Sompo Insurance Singapore Pte. Ltd.

50 Raffles Place

51 Ubi Ave 1 #01-25 #05-01/06, Singapore Land Tower Paya Ubi Industrial Park Singapore 048623 Singapore 408933

Attn: Thelma Choo Date: 18 Mar 2019

Preliminary Advice

Vehicle No : SLV163E **Accident Date** : 02/02/2019

: D18MTPV01019848 Make : BMW X5 Policy No.

Assignment Date : 07/02/2019 **Excess** : S\$600.00 Date of Inspection : 07/02/2019 Est. Duration of Repair : 6 days

Inspection At : Performance Motors Limited (Alexandra)

303 Alexandra Road, Sime Darby Performance Centre

Singapore 159941

Point of Impact / General Description of Damages

The vehicle sustained impact / damages o/s front portion and parts claimed are consistent to the accident.

Repairer's Estimate (Gross) :S\$ 20,828.85 (INCLUSIVE SUPPLEMENTARY) **Revised Amount** 17,583.45 (INCLUSIVE SUPPLEMENTARY) :S\$

From: LKK Auto Consultants Pte Ltd

Check Items (Estimated) :S\$ 0.00 Total :S\$ 17,583.45

Lump Sum Repair :S\$

Total Loss Consideration

New for Old Value :S\$

146,000.00 Pre-Accident Value :S\$ 110,000.00 COE / PARF Rebate :S\$

Salvage Value :S\$

36,000.00 Margin for Repair :S\$

Remarks

(X)	The vehicle is repairable at our adjusted amount. We have also confirmed excess and policy coverage.	
	Kindly let us have your authorisation.	

- The vehicle is uneconomical to be repaired, you are advised to invite tender for the wreck.
- Other comments: We have received supplementary from repairer. Our surveyor had since checked and (X) verified the supplementary parts and is of the view that the supplementary parts are consistent to the nature of the accident and is economical to repair. Supplementary amount is \$ 733.55.