

ASS. REC. BY:

REF

CS/SM019002257/Dtd3n2

Special Instruction:

Surveyor

Bryan

ASSIGNMENT (Office)

From (Person)

Menmen Hwang shiang Yi

of

SMO

Date/Time

8/2/19 @ 10:37am

Estimated Cost:

Bill to:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No:

SHC 8140R

Insured:

SGR 5539C

at Workshop m/s

Chunni Motor

Tel:

65425119

of

Blk 10 # 01-05/06 Amk Autopoint

Policy No:

D19MTPR 01002075

Claim No:

CM7D190074E

Sum Insured:

Excess:

Make of Veh:

(Client's Record)

D.O.A.

05/02/2019

CA / REV / REP. / REV 24 HRS

H.O.D. Endorsement:

Date/Time:

10:43am @ 8/2/19

Person Contacted:

Lynn

Vehicle IN/OUT

Date/Time

Action/Instruction (✓) Estimate

SHC 8140R-CS/FCI/8014012/Nvd3s2

DOA: 28/07/2018

SGR 5539C - X

14/2/19-

Revised via menmen prev advise.

REF:

SIGNATURE

COR May 2024

From: _____ Date: _____
 Estimated Cost: _____

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No: _____

at Work Shop no: _____

at _____

Insured: _____

Policy No: _____

Claims No: _____

Sum Insured: _____


Excess: _____

(Client's Record)

Make of Veh: _____

(Policy Condition)

Remark: The veh had commenced its
 repair at the time of inspection.



Bal. or Market Value: _____

IDAC Accident Report: _____

Consistent? : Yes or No

GIA / PR Seen: _____

Consistent? : Yes or No

Est. Repairs: 10 ~~8~~ days Res: Yes or No

Lump Sum: 20 % 3 Val: Yes or No

CA / REV / REP. / 24 HRS

Vehicle: IN / OUT

Date: _____ Person Contacted: _____

Date / Time: _____ Action / Instruction: _____

Sompo SGR 5539C

Veh No: SHC 81402 Date: 2016 May
 Type: M/Car / M/Cycle / Bus / Van / Lorry / ☒ / Prime Mover /

Truck / Trailer or

Make: Hyundai I40 c.c. 1685
 Colour: Blue A/C: Insured / Std / NI / NA

Sp. Reading: 391340 T/Radio: Insured / Std / NI / NA

Eng/No: D4FDGU625122

C/No: KMHCB41UMGU089754

Gen. Cond: ☒ / Fair / Poor / Burnt

Steering: ☒ / Jammed / Leaked / Burnt or

Brake: ☒ / Jammed / Leaked / Burnt or

Modi: ☒ S/Rim / STD A/Rim or

Tyre Size: F: 205/60 R16
 R: — 11 —

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or Campion

Front

Rear

R/Bal: S mm

R/Bal: S mm

L/Bal: S mm

L/Bal: S mm

D.O.A: 05/02/2019

D.O.I: 11/02/2019

Survey held at Chunni AMK

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

Rmt y Rev

The U/C / Chassis frame / Body Structure affected due to collision.

RECEIVED 28 MAR 2019

Date/Time: File Pass to?

☐

Prefi. Report

to

☐

Final Report

Date/Time: File Return to?

to

Days Of Repair:

Resurvey No. of Trip:

Survey Fee:

Transportation

1. S + P. 50

2. Photo

3. Call

4. ...

TOTAL

Add Fee: ☐ Site Insp. 1\$

☐ Interview 1\$

☐ Teen Toys 1\$

☐ Weekend 1\$

Report Format:

Lump Sum / I.B.F. 1\$

450
10

460

20/03/2019 Jinnu 215 16000/- into 10 days of 2

Note: This document has not been finalised.

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

To: Somp Insurance Singapore Pte. Ltd.
50 Raffles Place
#05-01/06, Singapore Land Tower
Singapore 048623

From: LKK Auto Consultants Pte Ltd
51 Ubi Ave 1 #01-25
Paya Ubi Industrial Park
Singapore 408933

Attn: Hwang Shiang Yi

Date: 14 Feb 2019

Preliminary Advice

Insured Vehicle No	: SGR5539C	Accident Date	: 05/02/2019
TP Vehicle No	: SHC8140R	Assignment Date	: 08/02/2019
Make	: HYUNDAI I40	Est. Duration of Repair	: 8.00
Date of Inspection	: 12/02/2019		
Inspection At	: CHUNNI MOTOR WORK PTE LTD - AMK (HQ) BLK 10 #01-05/06, AMK AUTOPOINT SINGAPORE 568047		

Point of Impact / General Description of Damages

The vehicle sustained impact / damages front and rear portion and parts claimed are consistent to the accident.

Repairer's Estimate (Gross)	:S\$	29,661.42
Revised Amount	:S\$	21,017.22
Check Items (Estimated)	:S\$	0.00
Total	:S\$	21,017.22

Lump Sum Repair :S\$

Total Loss Consideration

New for Old Value	:S\$
Pre-Accident Value	:S\$
COE / PARF Rebate	:S\$
Salvage Value	:S\$
Margin for Repair	:S\$

Remarks

- () The vehicle is repairable at our adjusted amount. We have also confirmed excess and policy coverage. Kindly let us have your authorisation.
- () The vehicle is uneconomical to be repaired, you are advised to invite tender for the wreck.
- (x) Other comments : survey on WP

...CLAIM SUBFOLDER...(New Assignment)

CLAIM SUBFOLDER TRACKING

Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'd	Status
Main	06 Feb 2019		08 Feb 2019 10:37 Assign				New Assignment Cancel Case

Main	Reference	Claim Details	Documents	Show All
----------------------	---------------------------	-------------------------------	---------------------------	--------------------------

CLAIM SUBFOLDER DETAILS

[Created by insurer]

Insured:	SIM LENG HONG, ID: S7427212F, Tel: +6581205848, Email: ow.junie@gmail.com		
Main Claimant:	COMFORT TRANSPORTATION PTE LTD, Co. Reg. No.: 199303821R		
Vehicle Reg. No.:	SHC8140R	Date of Loss:	05/02/2019 11:00 - :59
Claim Type:	TP / CMTD1900748	Policy/Cover Note No.:	D19MTPV01002075 (Comprehensive)
Vehicle Reg. No. (Insured):	SGR5539C	Policy No. (Claimant):	
		Excess:	
Repairer:	Chunni Motor Work Pte Ltd - Amk (HQ) Blk 10 #01-05/06, AMK Autopoint, 568047 Ang Mo Kio - Tel: 64836016		
Handling Insurer:	Sompo Insurance Singapore Pte. Ltd. (HQ) - Tel: 6461 6555 ... [Handled by Hwang Shiang Yi - 6329 5205]		
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Final Rpt due 19/02/2019]		
Driver/Custodian (Insured):	SIM LENG HONG (44 / Male), NRIC: S7427212F, Tel: +6581205848		

ASSOCIATED MAIL RECEIVED

[View All](#)

[Compose Case Mail](#)

There are no mail for this case.

ALL ASSOCIATED TASKS

[View All](#)

[Search Tasks](#)

[Create New Task](#)

[Complete](#)

Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

MC0619016809 / ComfortDelGio Engineering Pte Ltd - Layanq
 ENTRY DATE & TIME: 07/02/2019 12:59
 SUBMITTED BY: Catherine Por Moy Juan

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any willful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. This report will be forwarded by the Insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT

Date Of Report 07/02/2019 12:59
 Date Of Accident 05/02/2019 11:30
 Exact Location Of Accident UPP CHANGI RD EAST
 Country/State of Loss SINGAPORE

DETAILS OF OWN VEHICLE

Vehicle Registration Number SHC8140R
 Insured/Policyholder
 Name Of Registered Owner COMFORT TRANSPORTATION PTE LTD
 Co Reg No 199303821R
 Email Address FLEETSAFETY@CDGTAXI.COM.SG
 Mobile Phone No
 Alternative Phone No OFFICE-65508768
Vehicle Particulars
 Manufacturer HYUNDAI
 Model I40
 Exact Purpose for which vehicle was being used at time of accident
 Are you claiming under your own insurance policy for repair to your vehicle? NO
 If No, Please state action to be taken THIRD PARTY
 Vehicle Category TAXI
Insurance Company
 Name of Insurance Company MS FIRST CAPITAL INSURANCE LTD
 Type Of Coverage THIRD PARTY FIRE AND/OR THEFT
 Fleet Policy YES
 Policy Number D-18088936MFSH
 Cover Note Number
Driver
 Name of Driver CHUA YIAN HUAT
 NRIC No S1263125A
 Date Of Birth 14/11/1957
 Occupation OUTDOOR
 Date Of Driving Pass 24/10/1975
 Driving Experience 43 YEARS AND 3 MONTHS
 Gender MALE
 Mobile Number (LOCAL) +65-96158564
 Fax Number
 Contact Number
 Email Address TOMMY57@SINGNET.COM.SG

Address 286C 09-127 COMPASSVALE CRESCENT
 Postcode 543286
 Was driver an employee of the Insured's Company NO
 If No, Relationship of the Driver with the Insured OTHER - TAXI DRIVER
 Vehicle Registration Number of Driver's Own Vehicle -
 -
 -
 Insurance Company of Driver's Own Vehicle -
 -
 -

General Information of the Accident

Type Of Accident CHAIN COLLISION
 Weather Conditions CLEAR
 Road Surface DRY

Other Information

Was any foreign vehicle involved in this accident? NO
 Number of vehicles (including own vehicle) Involved in the accident 3
 Was any body injured in the Accident? NO
 Was any injured conveyed to hospital by ambulance? NO
 Was any other material or property damaged? YES
 I have been approached by unknown person(s) soliciting/offering accident claims assistance. NO
 Number of Passengers (Including Driver) 2
 Passenger 1 NAME: : -
 GENDER: : FEMALE

Details of Police Action

Was the accident reported to the police? NO
 If Yes, Please state which Police Station
 Was notice of intended Prosecution given? NO
 If Yes, against whom?

Circumstances of Accident

SEE ATTACH.

Attachment(s)

Are accident photos available for attachment? YES
 Was there any video captured by Car Camera? YES
 Remarks/ Reasons: -
 Was there any audio recorded? NO

DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number SGR5539C
 Vehicle Make/Model/Colour
 Details Of Properties
 Vehicle Category PRIVATE CAR
 Name of Driver SIM LENG HONG
 NRIC/Passport Number S7427212F
 Contact Number 81205848
 Address
 Postcode
 Insurance Company Name
 Nature Of Damage FRT

No. Of Passenger (Including Driver)

DETAILS OF OTHER VEHICLE PROPERTY 2

Vehicle Registration Number	SKE305P
Vehicle Make/Model/Colour	
Details Of Properties	
Vehicle Category	PRIVATE CAR
Name of Driver	CHUA KHENG TONG WINSON
NRIC/Passport Number	S7112269G
Contact Number	96589785
Address	
Postcode	
Insurance Company Name	
Nature Of Damage	REAR
No. Of Passenger (Including Driver)	

SKETCH PLAN**IMPORTANT NOTICE**

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. The report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgment of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.
8. **Consent under the Personal Data Protection Act (PDPA)**

I understand, acknowledge, agree and consent that:

- (a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this [form] and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the Insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of:
 - (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
 - (ii) investigating the accident and/or my claims;
 - (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
 - (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
 - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims (collectively the "Purposes")
- (b) all insurer(s) who have insured vehicle(s) involved in this accident and the Insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
- (c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third party service providers or agents (including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.
- (d) my Personal Information will also be collected and used to compile claims history for the purpose of fraud detection, investigation and management in present and all future claims.
- (e) the information so collected under (d) above may be shared / disclosed:
 - (i) to all insurers and/or any other third parties that assist in evaluating, investigating, controlling or managing fraud, regulators, law enforcement and government agencies as reasonably required for the purposes stated, or
 - (ii) for complying with requirements under any regulations, laws or court orders.


COMFORT TRANSPORTATION PTE LTD
CO. REG. NO. 199303821R
PTE LTD
199303821R

Policyholder's Signature
Date & Time:

Driver's Signature
(If driver is not the policyholder)
Date & Time: 07.02.2019@0945HRS

Reporting Centre Personnel's Signature
Name:
NRIC/FIN No: June Tan

SKETCH PLAN



DESCRIBE CIRCUMSTANCES OF THE ACCIDENT

On 05.02.2019 @ 1130HRS I was travelling along Upper Changi East with one female passenger onboard.

As I was travelling straight and veh(C) SKE 305P stopped and I followed. Suddenly, veh(B) SGR 5539C hit onto my vehicle rear portion and caused my vehicle to surge forward and hit Veh(C) SKE 305P.

As the accident took place too fast I could not take evasive action to prevent the accident.

I have company video and photos at scene to support my claims .

No injury in this accident .

Veh(B) SGR 5539C MR Sim Leng Hong S 7427212F HP: 8120 5848

Veh(C) MR Chua Kheng Tong Winson S 7112269G HP: 9658 9785

DECLARATION

I/We declare the foregoing particulars are true in every respect.
COMFORT TRANSPORTATION PTE LTD
CO. REG. NO. 199303821R

Policyholder's Signature
Date & Time:

Driver's Signature
(If driver is not the policyholder)
Date & Time: 07.02.2019@0945HRS

Reporting Centre Personnel's Signature
Name:
NRIC/FIN No.: June Tan

10 Survey by UIC

DATE : 7.02.2019

TEL : 6542 5119

FAX : 6542 6039

QTY	Parts Description/ Labour	Type	Unit Price	Amount	
	Radiator Grille <i>broken</i>			\$ 1,110.10	✓
	Radiator Grille H Emblem <i>new</i>			\$ 120.30	✓
	Front Bumper Cover <i>mounty broken</i>			\$ 1,052.20	✓
	Front Bumper Sponge <i>new</i>			\$ 99.20	✓
	Front Bumper Reinforcement <i>new</i>			\$ 402.10	✓
	Front Bumper Bracket Top (LH/RH) <i>new</i>	\$	22.40	\$ 44.80	X
	Front Bumper Bracket (LH/RH) <i>new</i>	\$	24.60	\$ 49.20	X
	Headlamp Support Top Cover <i>new</i>			\$ 222.60	X
	Headlamp Support Panel Assy <i>broken</i>			\$ 907.40	✓
	Headlamp (LH/RH) <i>mounty broken</i>	\$	1,388.00	\$ 2,776.00	✓
	Radiator <i>new</i> <i>punctured</i>			\$ 698.30	✓
	Radiator Fan Blade, Cowling, Motor Assy <i>broken</i>			\$ 792.95	✓
	Radiator Bracket (RH/LH) <i>new</i>	\$	6.50	\$ 13.00	X
	Radiator Guard <i>new</i>	\$	20.00	\$ 40.00	X
	Horn Unit (LH/RH) <i>broken</i>	\$	73.80	\$ 147.60	✓
	Aircon Condenser <i>new</i> <i>punctured</i>			\$ 927.50	✓
	Inter Cooler <i>new</i>			\$ 1,032.50	✓
	Inter Cooler Mounting (2 PCS) <i>new</i>			\$ 25.90	X
			10066.15		
			8052.92		
	SUB TOTAL			\$ 10,461.65	
	LESS 20%			\$ 2,092.33	
	DISCOUNTED TOTAL			\$ 8,369.32	
	Front Number Plate <i>scratched</i>			\$ 25.00	Nett ✓
	Front No Plate Trim Cover <i>new</i>			\$ 30.00	Nett X
			25.00		
				\$ 55.00	
	Labour Charge				
	Panel Beating			\$ 1,000.00	500/-
	Spray Painting Charge			\$ 250.00	200/-
	Wiring Charge			\$ 50.00	30/-
	Towing Charge			\$ 50.00	new
	Remove/Refix Aircon & Refill Gas			\$ 150.00	80/-
	Diagnostic & Resetting To Erase Fault Code			\$ 480.00	new
			810.00		
	TOTAL LABOUR			\$ 1,980.00	

SHC 8140R

Qty	Parts Description/ Labour	Type	Unit Price	Amount	
	Boot Lid <i>bst</i>			\$ 2,174.90	✓
	Boot Lid Rubber <i>hlc</i>			\$ 96.50	✓
	Boot Lid Hinge (LH/RH) <i>hhl</i>		\$ 142.30	\$ 284.60	X
	Boot Lid Lock Upper <i>bst</i>			\$ 102.60	✓
	Boot Lid Lock Lower <i>hhl</i>			\$ 31.70	X
	Boot Lid Key Lock <i>hhl</i>			\$ 81.60	X
	Boot Lid 'H' Emblem <i>hlc</i>			\$ 28.70	✓
	Boot Lid CRDI Plate <i>hlc</i>			\$ 27.90	✓
	Boot Lid Lamp (LH/RH) <i>crack</i>		\$ 565.60	\$ 1,131.20	✓
	Boot Lid Trimboard <i>turn</i>			\$ 116.40	✓
	Boot Lid Trimboard Clips (10pcs) <i>hlc</i>			\$ 11.00	✓
	Bootlid Moulding <i>hhl</i>			\$ 85.00	X
	Bootlid i40 Emblem <i>svl</i>			\$ 27.90	X
	Bootlid Lower Garnish <i>hhl</i>			\$ 227.90	X
	Rear Bumper <i>distal</i>			\$ 553.00	✓
	Rear Bumper Reinforcement <i>crack</i>			\$ 428.40	✓
	Rear Bumper Reinforcement Bracket (LH/RH) <i>bst</i>	<i>o/s n/s hhl</i>	<i>80.30</i>	\$ 160.60	✓
	Rear Bumper Clip 10 pcs <i>hlc</i>			\$ 22.00	✓
	Rear Bumper Bracket <i>hhl</i>		\$ 35.60	\$ 71.20	X
	Rear Bumper Sponge <i>turn</i>			\$ 118.40	✓
	Rear Bumper Under Cover <i>distal</i>			\$ 228.00	✓
	Rear Bumper Reflector Lamp (RH) <i>crack</i>			\$ 30.60	✓
	Tail Lamp (LH/RH) <i>crack</i>		\$ 697.80	\$ 1,395.60	✓
	Tail Lamp Quarter Panel (RH) <i>hhl</i>			\$ 226.50	X
	Rear Panel <i>Dental</i>			\$ 526.70	✓
	Rear Panel Garnish <i>svl</i>			\$ 57.70	X
	Rear Panel Lower Panel <i>Dental</i>			\$ 495.50	✓
	Spare Tyre Holder <i>hhl</i>			\$ 248.00	X
	Spare Tyre Panel <i>Dental</i>			\$ 852.80	✓
	Spare Tyre Panel Cushion <i>hhl</i>			\$ 209.05	X
	Rear Towing Hook <i>hhl</i>			\$ 94.60	X
	Member Assy- Rear Floor Centre <i>hhl</i>			\$ 570.40	X
	Exhaust Pipe Insulator <i>hhl</i>		\$ 58.55	\$ 117.10	X
	Exhaust Silencer <i>bst</i> <i>o/s n/s hhl</i>		<i>967.70</i>	\$ 1,935.40	✓
	Exhaust Pipe Hanger <i>hhl</i>		\$ 58.55	\$ 117.10	X
	Exhaust Pipe Centre <i>hhl</i>			\$ 730.10	X
	Rear Fender With Housing (RH) <i>Dental</i>		<i>2020.00</i>	\$ 4,236.80	✓
	Rear Windscreen Moulding <i>hlc</i>			\$ 28.30	✓
			<i>11436.50</i>		
			<i>9149.20</i>		
	SUB TOTAL			\$ 18,381.75	
	LESS 20%			\$ 3,676.35	
	DISCOUNTED TOTAL			\$ 14,705.40	
	Boot Lid Comfort Logo & Tel No. Sticker <i>hlc</i>			\$ 30.00	Nett ✓
	Rear Bumper Reverse Sensor <i>Dental</i>			\$ 135.70	Nett ✓
	Rear Windscreen Sealant <i>hlc</i>		<i>211.70</i>	\$ 46.00	Nett ✓
				\$ 211.70	

SHC 8140R

Qty	Parts Description/ Labour	Type	Unit Price	Amount
	Labour Charge			
	Panel Beating			\$ 2,000.00 900/-
	Spray Painting Charge			\$ 1,500.00 700/-
	Wiring Charge			\$ 50.00 30/-
	Tuff Kote			\$ 100.00 40/-
	Remove/Refix Cushion & Upholstery Rear			\$ 150.00 80/-
	Remove/Refix Rear Windscreen Glass			\$ 120.00 80/-
	Remove/Refix Reverse Sensor		1930.00	\$ 120.00 40/-
	Remove/Refix Exhaust Pipe			\$ 300.00 60/-
	TOTAL LABOUR			\$ 4,340.00
	ESTIMATE TOTAL			\$ 29,661.42
	11/02/2019 @ 0930am Liaison with 10 days. Ryan 2KK Auto		20178.82 1516000/-	
This is an initial estimate based on a visual inspection of the above vehicle. The final repair quantum will be prepared after the vehicle is surveyed by a motor Surveyor appointed by the insurance company.				

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607196R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CS/SMO19002257/DTD3N2

Date: 26/03/2019

REFERENCE

Handling Insurer:	Sompo Insurance Singapore Pte. Ltd.	Policy No:	D19MTPV01002075
Claimant Vehicle No :	SHC8140R	Insured Vehicle No :	SGR5539C
Date of Loss:	05/02/2019	Nature of Claim:	TP
		Claim No:	CMTD1900748

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SHC8140R	Engine No:	D4FDGU625122
Make & Model:	HYUNDAI I40, 1.7 D (A)	Chassis No:	KMHLB41UMGU089754
Reg. Date:	19/05/2016 (Man. Year: 2016)	Odometer:	391340 km
Colour:	Blue		
Engine Capacity:	1685 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	205/60R16	Rear Tyre Size:	205/60R16
Front Left Side:	Campeon 5 mm	Rear Left Side:	Campeon 5 mm
Front Right Side:	Campeon 5 mm	Rear Right Side:	Campeon 5 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS

	Repairer's	Adjuster's	Difference	Diff %
Parts	23,341.42	17,438.82	5,902.60	25.29
Miscellaneous Items	0.00	0.00	0.00	
Labour	6,320.00	2,740.00	3,580.00	56.65
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	29,661.42	20,178.82	9,482.60	31.97
Approved Total (Overridden) (S\$)		16,000.00		
(S\$)	29,661.42	16,000.00	13,661.42	46.06
+ GST 7.00/7.00% (S\$)	2,076.30	1,120.00	956.30	46.06
Nett Amount (S\$)	31,737.72	17,120.00	14,617.72	46.06

INSPECTION

Date of Assignment:	08/02/2019	
Date Inspected:	11/02/2019	Inspected At:
		Chunni Motor Work Pte Ltd - Amk (HQ)
		Blk 10 #01-05/06, AMK Autopoint
		Singapore 568047
Estimated Period of Repair:	10.0 days	

Adjuster: BRYAN TANI

Manager: DENISE TAY KWEE CHENG

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our

knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference

Part Source: MRM-SG	Version: 1.0 (Last Synchronised: 26 Mar 2019)
Parts: 143	HYUNDAI I40 1.7 D (A) (Catalogue:Merimen Singapore 1.0)
Labour: Repairer's	(Price-denominated Standard List)
Print Code: (Unsubmitted, no print-code for SHC8140R)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*RADIATOR GRILLE	Broken	1,110.10 FL	*1,110.10 FL
2	1		*RADIATOR GRILLE H EMBLEM	Necessary	120.30 FL	*120.30 FL
3	1		*FRONT BUMPER COVER	Mounting Broken	1,052.20 FL	*1,052.20 FL
4	1		*FRONT BUMPER SPONGE	Torn	99.20 FL	*99.20 FL
5	1		*FRONT BUMPER REINFORCEMENT	Bent	402.10 FL	*402.10 FL
6	2		*FRONT BUMPER BRACKET TOP (LH/RH)	Serviceable	44.80 FL	*- FL
7	2		*FRONT BUMPER BRACKET (LH/RH)	Serviceable	49.20 FL	*- FL
8	1		*HEADLAMP SUPPORT TOP COVER	Not Necessary	222.60 FL	*- FL
9	1		*HEADLAMP SUPPORT PANEL ASSY	Broken	907.40 FL	*907.40 FL
10	2		*HEADLAMP (LH/RH)	Mounting Broken	2,776.00 FL	*2,776.00 FL
11	1		*RADIATOR	Bent/Punctured	698.30 FL	*698.30 FL
12	1		*RADIATOR FAN BLADE,COWLING,MOTOR ASSY	Broken	792.95 FL	*792.95 FL
13	2		*RADIATOR BRACKET (LH/RH)	Not Necessary	13.00 FL	*- FL
14	2		*RADIATOR GUARD	Not Necessary	40.00 FL	*- FL
15	2		*HORN UNIT (LH/RH)	Broken	147.60 FL	*147.60 FL
16	1		*AIRCON CONDENSER	Bent/Punctured	927.50 FL	*927.50 FL
17	1		*INTER COOLER	Bent	1,032.50 FL	*1,032.50 FL
18	1		*INTER COOLER MOUNTING (2PCS)	Not Necessary	25.90 FL	*- FL
19	1		*BOOT LID	Bent	2,174.90 FL	*2,174.90 FL
20	1		*BOOT LID RUBBER	Necessary	96.50 FL	*96.50 FL
21	2		*BOOT LID HINGE (LH/RH)	Not Necessary	284.60 FL	*- FL
22	1		*BOOT LID LOCK UPPER	Bent	102.60 FL	*102.60 FL
23	1		*BOOT LID LOCK LOWER	Not Necessary	31.70 FL	*- FL
24	1		*BOOT LID KEY LOCK	Not Necessary	81.60 FL	*- FL
25	1		*BOOT LID H EMBLEM	Necessary	28.70 FL	*28.70 FL
26	1		*BOOT LID CRDI PLATE	Necessary	27.90 FL	*27.90 FL
27	2		*BOOT LID LAMP (LH/RH)	Cracked	1,131.20 FL	*1,131.20 FL
28	1		*BOOT LID TRIMBOARD	Torn	116.40 FL	*116.40 FL
29	10		*BOOT LID TRIMBOARD CLIPS	Necessary	11.00 FL	*11.00 FL
30	1		*BOOTLID MOULDING	Not Necessary	85.00 FL	*- FL
31	1		*BOOTLID I40 EMBLEM	Serviceable	27.90 FL	*- FL
32	1		*BOOTLID LOWER GARNISH	Not Necessary	227.90 FL	*- FL
33	1		*REAR BUMPER	Distorted	553.00 FL	*553.00 FL
34	1		*REAR BUMPER REINFORCEMENT	Cracked	428.40 FL	*428.40 FL
35	1		*REAR BUMPER REINFORCEMENT BRACKET (LH/RH)	O/s Bent/N/s Not Necessary	160.60 FL	*80.30 FL
36	10		*REAR BUMPER CLIP	Necessary	22.00 FL	*22.00 FL
37	2		*REAR BUMPER BRACKET	Not Necessary	71.20 FL	*- FL
38	1		*REAR BUMPER SPONGE	Torn	118.40 FL	*118.40 FL
39	1		*REAR BUMPER UNDER COVER	Distorted	228.00 FL	*228.00 FL
40	1		*REAR BUMPER REFLECTOR LAMP (RH)	Cracked	30.60 FL	*30.60 FL
41	2		*TAIL LAMP (LH/RH)	Cracked	1,395.60 FL	*1,395.60 FL

Report was unsubmitted during this print-out.

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
42	1		*TAIL LAMP QUARTER PANEL (RH)	Not Necessary	226.50 FL	*- FL
43	1		*REAR PANEL	Dented	526.70 FL	*526.70 FL
44	1		*REAR PANEL GARNISH	Serviceable	57.70 FL	*- FL
45	1		*REAR PANEL LOWER PANEL	Dented	495.50 FL	*495.50 FL
46	1		*SPARE TYRE HOLDER	Not Necessary	248.00 FL	*- FL
47	1		*SPARE TYRE PANEL	Dented	852.80 FL	*852.80 FL
48	1		*SPARE TYRE PANEL CUSHION	Not Necessary	209.05 FL	*- FL
49	1		*REAR TOWING HOOK	Not Necessary	94.60 FL	*- FL
50	1		*MEMBER ASSY-REAR FLOOR CENTRE	Not Necessary	570.40 FL	*- FL
51	2		*EXHAUST PIPE INSULATOR	Not Necessary	117.10 FL	*- FL
52	1		*EXHAUST SILENCER	O/s Bent/N/s Not Necessary	1,935.40 FL	*967.70 FL
53	2		*EXHAUST PIPE HANGER	Not Necessary	117.10 FL	*- FL
54	1		*EXHAUST PIPE CENTRE	Not Necessary	730.10 FL	*- FL
55	1		*REAR FENDER RH	Dented	4,736.80 FL	*2,020.00 FL
56	1		*REAR WINDSCREEN MOULDING	Necessary	28.30 FL	*28.30 FL
57	1		*FRONT NUMBER PLATE	Scratched	25.00 FS	*25.00 FS
58	1		*FRONT NO PLATE TRIM COVER	Not Necessary	30.00 FS	*- FS
59	1		*BOOT LID COMFORT LOGO & TEL NO STICKER	Necessary	30.00 FS	*30.00 FS
60	1		*REAR BUMPER REVERSE SENSOR	Damaged	135.70 FS	*135.70 FS
61	1		*REAR WINDSCREEN SEALANT	Necessary	46.00 FS	*46.00 FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (S\$)	29,110.10	21,739.35
- List Item Discount on L Items 20.00/20.00% (S\$)	5,768.68	4,300.53
Total Parts (S\$)	23,341.42	17,438.82

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	PANEL BEATING	New	3,000.00	1,400.00
2	SPRAY PAINTING CHARGE	New	1,750.00	900.00
3	WIRING CHARGE	New	100.00	60.00
4	TOWING CHARGE	New	50.00	0.00
5	REMOVE/REFIX AIRCON & REFILL GAS	New	150.00	80.00
6	DIAGNOSTIC & RESETTING TO ERASE FAULT CODE	New	480.00	0.00
7	TUFF KOTE	New	100.00	40.00
8	REMOVE/REFIX CUSHION & UPHOLSTERY REAR	New	150.00	80.00
9	REMOVE/REFIX REAR WINDSCREEN GLASS	New	120.00	80.00
10	REMOVE/REFIX REVERSE SENSOR	New	120.00	40.00
11	REMOVE/REFIX EXHAUST PIPE	New	300.00	60.00
Gross Labour Cost (\$\$)			6,320.00	2,740.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >