

42452001

ASS. REC. BY:

REF: CS3/AIG18009965/Gpd37

Special Instruction:

Surveyor: Guo Qiang
Mention: Winnie Fan

ASSIGNMENT (Office)

08/07/19

From (Person): Winnie Fan of AIG

Date/Time: 28/5/2018 3:11 pm

Estimated Cost:

Bill to:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No: SLS 2046M Insured: SLR 4896T

at Workshop m/s: N-SI Automotive Tel: 6842 0051

of: Blk 2 Kaki Bukit Ave # 01-17 / 18

Policy No: Claim No: 523855509159

Sum Insured: Excess:

Make of Veh: (Client's Record) D.O.A. 26/5/2018

CA / REV / REP. / REV 24 HRS (up)

H.O.D. Endorsement:

Date/Time: 10:43am @ 1/6/18 Person Contacted: Melody Vehicle: IN/OUT

Date/Time	Action/Instruction (X) Estimate
	<u>SLS 2046M-X</u>
	<u>SLR 4896T-X</u>
<u>4/6/18</u>	<u>Dismantled</u>

\$6950, 8 Days. (Red to 22850, 77%)

RECEIVED 26 FEB 2019

22/2/2019

PRS

Xhd

REF: AIG

C790209C

ASSIGNMENT

From: _____ Date: 1/6/18

Estimated Cost: _____

OD TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No: SLS 2046 M

at Workshop m/s: N-51 Automotive

of _____

Insured _____

Policy No. _____

Claims No. _____

Sum Insured: _____ Excess: _____

(Client's Record) _____

Make of Veh: _____

(Policy Condition) _____

Remark: The veh had commenced its repair at the time of inspection.

<input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>
N/S	O/S
<input type="checkbox"/>	<input type="checkbox"/>

Bal. or Market Value: _____

IDAC Accident Rpt: _____ Consistent? : Yes or No

GIA / PR Seen: _____ Consistent? : Yes or No

Est. Repairs: 9 days Res.: Yes or No

Lum Sum: _____ % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS ^{1 up}

Date _____ Person Contacted: _____

Vehicle: IN / OUT

Veh No: SLS2046M Yr Regn: 13 sep 2017

Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover / Truck / Trailer or _____

Make: Toyota Prius Alpha Hybrid 1.8 (79)

Colour: Grey A/C Insured / Std / NI / NA

Sp. Reading: 75552 T/Radio: Insured / Std / NI / NA

Eng/No: _____

C/No: 3VW400025 897

Gen. Cond: Good / Fair / Poor / Burnt

Steering: In order / Jammed / Leaked / Burnt or _____

Brake: In order / Jammed / Leaked / Burnt or _____

Modi: Nil / S(Rim) / STD A/Rim or _____

Tyre Size: F: 205/60 R16 R: 4

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI / TOYO / YOKO or ~~HR16AD~~ HAIDA

Front	Rear
R/Bal. 5 mm	R/Bal. 5 mm
L/Bal. 5 mm	L/Bal. 5 mm
D.O.A. _____	D.O.I. 01-06-18

Survey held at: w/s 4:30 pm

Des. of Damages: Frt / Rear / O/S / N/S / UIC / Rooftop or N/S FT

The UIC / Chassis frame / Body Structure affected due to collision

Date / Time	Action / Instruction
2/7/18	Submit DAR Report.

RECEIVED 03 JUL 2018

Date/Time, File Pass to?	<input type="checkbox"/> Preli. Report	Days Of Repair:	Survey Fee:	180
1)	<input type="checkbox"/> Final Report	Resurvey No. of Trip:	Transportation	
Date/Time, File Return to?) S+RS ___ \$	
2)) Photos	
Report Format :		Add Fee: <input type="checkbox"/> Site Insp (\$) Other	20
Lump Sum / I.B.I: (\$		<input type="checkbox"/> Interview (\$		
		<input type="checkbox"/> Tech Invs (\$		
		<input type="checkbox"/> Weekend (\$		
			TOTAL	200

Nivitha (LKK Auto)

From: Syed-Yusoff, Saliha <Saliha.Syed-Yusoff@aig.com>
Sent: Friday, 8 February 2019 5:00 PM
To: SUR; Admin-D (LKKAuto)
Subject: ref:5238555091SG-003 ll y/r ref: CS3/AIG18009965/GZ4D3E2 (part 1 of 3)
Attachments: 5238555091SG-TP survey report part 1.pdf

Dear Team,

Kindly assist with the paper RI of 3P vehicle as the PRI was previously done by your surveyor.

Kind Regards,
Saliha

Saliha Syed Yusoff
AIG

Complex Claims Examiner
Claims | AIG Asia Pacific Insurance Pte. Ltd

AIG Building, 78 Shenton Way #08-16, Singapore 079120
Tel +(65) 6419 1917 |
www.aig.sg

IMPORTANT NOTICE:

The information in this email (and any attachments) is confidential. If you are not the intended recipient, you must not use or disseminate the information. If you have received this email in error, please immediately notify me by "Reply" command and permanently delete the original and any copies or printouts thereof. Although this email and any attachments are believed to be free of any virus or other defect that might affect any computer system into which it is received and opened, it is the responsibility of the recipient to ensure that it is virus free and no responsibility is accepted by American International Group, Inc. or its subsidiaries or affiliates either jointly or severally, for any loss or damage arising in any way from its use.

IMPORTANT NOTICE:

The information in this email (and any attachments) is confidential. If you are not the intended recipient, you must not use or disseminate the information. If you have received this email in error, please immediately notify me by "Reply" command and permanently delete the original and any copies or printouts thereof. Although this email and any attachments are believed to be free of any virus or other defect that might affect any computer system into which it is received and opened, it is the responsibility of the recipient to ensure that it is virus free and no responsibility is accepted by American International Group, Inc. or its subsidiaries or affiliates either jointly or severally, for any loss or damage arising in any way from its use.

PAR Automotive Consultancy

PHOTOCOPY

Regn No: 52986974L

Thomson Rd Post Office PO Box 029 Singapore 915701. Tel : 645 31173, Fax : 645 36131.

Report No: 0753-18-N51

24 December 2018

Darwin-51 Car Rental Pte Ltd
c/o N-51 Automotive Pte Ltd
2 Kaki Bukit Ave 2 #01-18
Kaki Bukit Auto Hub
Singapore 417921

INVOICE No. **0753-18-N51**


Vehicle No. **SLS2046M**

<u>S/NO.</u>	<u>SERVICES RENDERED</u>	<u>Amount due</u>
1	Being accident vehicle appraisal services, transport, photographs and re-inspection (work in progress and post repair inspection).	\$1,432.00
	Total amount payable	<u>\$1,432.00</u>

Kindly cross your cheque in favour of "PAR Automotive Consultancy"

We thank you in anticipation for your prompt payment.

PAR Automotive Consultancy



Report No: 0753-18-N51

24 December 2018

ACCIDENT VEHICLE SURVEY REPORT

Darwin-51 Car Rental Pte Ltd
c/o N-51 Automotive Pte Ltd
2 Kaki Bukit Ave 2 #01-18
Kaki Bukit Auto Hub
Singapore 417921

VEHICLE INFORMATION:

<i>Vehicle Reg No.:</i>	SLS2046M	<i>Odometer:</i>	75552km
<i>Make & Model:</i>	Toyota Prius Alpha 1.8S	<i>Colour:</i>	Grey
<i>Chassis number:</i>	ZVW400025897	<i>Date of accident:</i>	26/05/2018
<i>Year of Regn.:</i>	13/09/2017	<i>Date inspected:</i>	01/06/2018
<i>Repairer at:</i>	N-51 Automotive Pte Ltd 2 Kaki Bukit Ave 2 #01-18 Kaki Bukit Auto Hub Singapore 417921	<i>Date inspected (After Repair):</i>	11/06/2018

STATIC CHECKS, where applicable:

<i>Steering :</i>	serviceable
<i>Footbrake :</i>	serviceable
<i>Handbrake :</i>	serviceable
<i>Paintwork :</i>	Good
<i>General condition :</i>	Good

TIRE CONDITION:

	<u>LH / Make</u>	<u>RH / Make</u>	<u>Size</u>
<i>Front:</i>	5mm/Habilead	5mm/Habilead	205/60R16
<i>Rear:</i>	5mm/Yokohama	5mm/Yokohama	205/60R16

POINT OF IMPACT AND DAMAGE, where applicable:

Impact on the RH & front LH portion.
Please see details as described in the Annex for parts and labour.

REMARKS:

We have inspected the above-mentioned vehicle on a "Without Prejudice" basis.

Parts and Labour Assessment

PARTS

Description of part	Qty	Condition	Repairer's estimate	Our adjustment
ENGINE UNDER COVER	1	fractured	300.90	300.90 X NN
FRONT ABS SENSOR L/R	2	reuse	622.40	0.00 X NN
FRONT BUMPER	1	squashed	781.10	781.10 495.2
FRONT BUMPER 'LOGO' EMBLEM	1	necessary	172.10	172.10 80
FRONT BUMPER CENTER GARNISH	1	fractured	781.85	781.85 X NN
FRONT BUMPER FOGLAMP L/R RH X NN, LH - BT	2	fractured	1,183.20	1,183.20 296.2
FRONT BUMPER INNER SPONGE	1	deformed	174.45	174.45 /
FRONT BUMPER LED LIGHT L/R RH X NN, LH - BT	2	fractured	1,945.70	1,945.70 148.7
FRONT BUMPER LOWER AIR GUIDE	1	warped	176.60	176.60 X NN
FRONT BUMPER LOWER COVER	1	fractured	200.90	200.90 X NN
FRONT BUMPER REINFORCEMENT	1	bent	691.10	691.10 /
FRONT BUMPER REINFORCEMENT BRACKET L/R RH X NN	2	bent LH - BT	745.70	745.70 250.4
FRONT BUMPER SIDE BRACKET L/R	2	bent	342.20	342.20 X
FRONT BUMPER SIDE BRACKET RETAINER HOLDER	6	necessary	77.40	77.40 X NN
FRONT BUMPER SIDE BRACKET RETAINER HOLDER PIN	6	necessary	57.00	57.00 X
FRONT BUMPER SIDE GRILLE L/R RH X NN, LH - BT	2	fractured	211.40	211.40 52
FRONT BUMPER SIDE RETAINER L/R RH X NN, LH - BT	2	necessary	264.50	264.50 65
FRONT BUMPER TOW HOOK COVER L/R	2	reuse	242.90	0.00 X NN
FRONT BUMPER UPPER COVER	1	reuse	205.00	0.00 X NN
FRONT BUMPER UPPER RUBBER SEAL	1	deformed	174.45	174.45 X NN
FRONT BUMPER WIRE HARNESS	1	snapped	2,000.90	2,000.90 Local repair 2500
FRONT ENGINE CROSS MEMBER	1	bent	2,478.00	2,478.00 X NN
FRONT GRILLE	1	fractured	651.60	651.60 203.6
FRONT HEADLAMP L/R RH X NN, LH - BT	2	fractured	7,442.20	7,442.20 1600
FRONT HEADLAMP LOWER BRACKET L/R	2	bent	130.00	130.00 X NN
FRONT KNUCKLE ARM BEARING L/R	2	dislodged	223.40	223.40 /
FRONT KNUCKLE ARM L/R	2	distorted	1,110.40	1,110.40 /
FRONT LH AIR GUIDE GARNISH	1	deformed	172.10	172.10 X NN
FRONT LH DRIVE SHAFT	1	bent	1,175.10	1,175.10 X NN
FRONT LH FENDER	1	buckled	933.10	933.10 585
FRONT LH FENDER 'HYBRID' EMBLEM	1	necessary	121.10	121.10 44.17
FRONT LH FENDER INNER SHIELD	1	fractured	259.45	259.45 165
FRONT LINKAGE L/R	2	bent	395.20	395.20 X NN
FRONT LOWER ARM L/R LH X NN, RH - BT	2	bent	1,251.80	1,251.80 422
FRONT LOWER BALL JOINT L/R	2	dislodged	346.00	346.00 X NN
FRONT RH DRIVE SHAFT	1	bent	1,297.80	1,297.80 X NN
FRONT SHOCK ABSORBER L/R	2	bent	820.00	820.00 X NN
FRONT SHOCK ABSORBER RUBBER L/R	2	necessary	100.00	100.00 X NN
FRONT SHOCK ABSORBER SPONGE L/R	2	necessary	90.00	90.00 X NN
FRONT SHOCK ABSORBER TOP MOUNTING L/R	2	necessary	312.20	312.20 X NN
FRONT SPORT RIM L/R	2	abraded	3,110.20	3,110.20 600 (9V)
FRONT STABILIZER BAR	1	bent	412.00	412.00 X NN

PAR Automotive Consultancy

Annex A: Page 2
Report No: 0753-18-N51-SLS2046M

FRONT STABILIZER BAR RUBBER BUSH BRACKET L/R	2	necessary	70.00	70.00	} XNN
FRONT STABILIZER BAR RUBBER BUSH L/R	2	necessary	110.00	110.00	
FRONT STEERING RACK & PINION	1	bent	1,620.70	1,620.70	
FRONT STEERING TIE ROD END L/R	2	dislodged	203.40	0.00	XNN
FRONT TYRE HUB CAP L/R	2	fractured	400.00	400.00	XNN
FRONT WHEEL HUB L/R	2	dislodged	331.80	331.80	XNN
REAR AXKE CARRIAGE	1	distorted	2,315.00	2,315.00	XNN
REAR RH SHOCK ABSORBER	1	bent	365.00	365.00	212.3
REAR RH SPORT RIM	1	abraded	1,555.10	1,555.10	300(SN)
REAR RH TYRE HUB CAP	1	fractured	200.00	200.00	XNN
REAR RH WHEEL BEARING	1	dislodged	1,295.70	1,295.70	667.7
Subtotal before discount			S\$ 42,650.10	S\$ 41,376.40	7486.62
Percentage discount 25% and 25%			S\$ 10,662.53	S\$ 10,344.10	5614.96
Sub-total 1			S\$ 31,987.58	S\$ 31,032.30	
FRONT 205/60/16 TYRE L/R	2	abraded	800.00	800.00	240
FRONT BUMPER CLIPS - SET	1	necessary	100.00	100.00	30
FRONT BUMPER UNDER COVER CLIPS - SET	1	necessary	20.00	20.00	10
FRONT LH AIR GUIDE GARNISH CLIPS - SET	1	necessary	20.00	20.00	10
FRONT LH FENDER INNER SHIELD CLIPS - SET	1	necessary	50.00	50.00	20
REAR RH 205/60/16 TYRE	1	abraded	400.00	400.00	120
Subtotal before discount			S\$ 1,390.00	S\$ 1,390.00	430
Sub-total 2			S\$ 1,390.00	S\$ 1,390.00	
Parts-total			S\$ 33,377.58	S\$ 32,422.30	

LABOUR

To remove, reinstall electrical wiring harness, check lighting. (to FR)	60.00	50.00	30
To remove, change front suspension parts, absorber, lower arm, knuckle arm, wheel bearing, bearing hub, drive shaft, anti-roll bar, top-arm and steering rack and pinion.	1,000.00	450.00	200
To remove, change rear suspension parts, axle carriage, absorber, lower arm, top arm, trailing arm, knuckle arm, wheel bearing, bearing hub and etc.	400.00	350.00	150
To road test driving, check and resetting wheel alignments system.	180.00	180.00	60
To re-spray painting on the change bodyparts, repair portion, and where consistent to the accident.	1,000.00	800.00	500
To provide labour, workmanship to change the above damaged bodyparts, repair, reconstruct and re-align body structure, body alignments and damaged consistent to the accident.	800.00	750.00	500
To apply anti-rust chemical on repaired and replaced panel.	100.00	60.00	1
Labour Total	S\$ 3,540.00	S\$ 2,640.00	
Parts & Labour Total	S\$ 36,917.58	S\$ 35,062.30	1500

Results of inspection of the accident vehicle are as shown above.

We have taken into consideration the age and condition of the vehicle in our recommendation.

Hence, the recommended cost of repairs based on Lump Sum repairs is : S\$ 29,800.00 and the recommended number of working days for the repairs is within 12 day(s).

B J Loi (1 Eng., MIML AIRTE)

Automotive Appraiser

SHD 2970
2X 6520H
GLU 6300S

8694.96

2% = 6950

5 days



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile			
AIG ASIA PACIFIC INSURANCE PTE LTD		Ref : CS3/AIG18009965/Gqd3e2-1	
78 SHENTON WAY #08-16 CHARTIS BUILDING SINGAPORE 079120		Date : 27-02-2019	
ATTN : SYED YUSOFF SALIHA		Code : AIG	
1. Policy Particulars :- THIRD PARTY CLAIM			
Insured Veh.	SLR 4896T	Veh. Inspected	SLS 2046M
Policy No.		Coverage (\$)	0.00
Claim No.	5238555091SG	Excess (\$)	0.00
Assign From	SYED YUSOFF SALIHA	Assign Date	08/02/2019
2. Vehicle Particulars & Condition			
Make & Model	TOYOTA PRIUS	c.c	1797
Engine No.	HIDDEN	Year of Reg.	2017
Chassis No.	ZVW400025897	Colour	GREY
Odometer	75552	Steering	IN ORDER
Brakes	IN ORDER	Modification	SPORTS RIM
General	GOOD		
3. Conditions of Tyres			
	Size	Make	Balance
R/H Front Tyre	205/60 R16	HAIDA	5 mm
L/H Front Tyre	205/60 R16	HAIDA	5 mm
R/H Rear Tyre	205/60 R16	HAIDA	5 mm
L/H Rear Tyre	205/60 R16	HAIDA	5 mm
4. Description of Damages			
THE VEHICLE SUSTAINED DAMAGES AT THE N/S FRONT AND UNDERCARRIAGE PORTION. DAMAGES SEE DETAILS.			
5. General Information			
Accident Date	26/05/2018	Inspection Date	01/06/2018
Survey held at	N-51 AUTOMOTIVE PL 2 KAKI BUKIT AVE 2 #01-17 KAKI BUKIT AUTOHUB SINGAPORE 417921		
5a. Remarks			
A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.			
5b. Estimate Days of Repair			
ESTIMATED NORMAL PERIOD FOR REPAIR:		8 Working Days	



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile			
ERGO INSURANCE PTE LTD		Ref : CS/EG119002544/Kqd3n2	
5 TEMASEK BOULEVARD #04-01 SUNTEC TOWER FIVE SINGAPORE 038985		Date : 27-02-2019	
		Code : EGI	
1. Policy Particulars :- THIRD PARTY CLAIM			
Insured Veh.	SJQ 2028A	Veh. Inspected	SGZ 7272R
Policy No.		Coverage (\$)	0.00
Claim No.	SJQ2028A/SL/WM	Excess (\$)	0.00
Assign From	CLAIMS (ERGO)	Assign Date	12/02/2019
2. Vehicle Particulars & Condition			
Make & Model	AUDI Q3 (A)	c.c	1984
Engine No.	HIDDEN	Year of Reg.	2013
Chassis No.	WAUZZZ8U3DR077419	Colour	METALLIC BLUE
Odometer	90743	Steering	IN ORDER
Brakes	IN ORDER	Modification	STANDARD ALLOY RIM
General	GOOD		
3. Conditions of Tyres			
	Size	Make	Balance
R/H Front Tyre	235/50 R18	PIRELLI	8 mm
L/H Front Tyre	235/50 R18	PIRELLI	8 mm
R/H Rear Tyre	235/50 R18	PIRELLI	8 mm
L/H Rear Tyre	235/50 R18	PIRELLI	8 mm
4. Description of Damages			
THE VEHICLE SUSTAINED DAMAGES AT THE REAR N/S PORTION. DAMAGES SEE DETAILS.			
5. General Information			
Accident Date	04/02/2019	Inspection Date	18/02/2019
Survey held at	LIM TAN MOTOR PTE LTD BLK 176 SIN MING DRIVE #03-09 SIN MING AUTOCARE SINGAPORE 575721		
5a. Remarks			
A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.			
5b. Estimate Days of Repair			
ESTIMATED NORMAL PERIOD FOR REPAIR:		3 Working Days	



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 4

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SLS 2046M

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
REPLACEMENT OF PARTS				
1	ENGINE UNDER COVER	NOT NECESSARY	300.90	-
2	FRONT ABS SENSOR L/R	NOT NECESSARY	622.40	-
1	FRONT BUMPER	SQUASHED	781.10	495.20
1	FRONT BUMPER 'LOGO' EMBLEM	NECESSARY	172.10	80.00
1	FRONT BUMPER CENTER GARNISH	NOT NECESSARY	781.85	-
2	FRONT BUMPER FOGLAMP L/R	O/S NOT NECESSARY / N/S CUT	1,183.20	296.20
1	FRONT BUMPER INNER SPONGE	DEFORMED	174.45	174.45
2	FRONT BUMPER LED LIGHT L/R	O/S NOT NECESSARY / N/S CUT	1,945.70	148.70
1	FRONT BUMPER LOWER AIR GUIDE	NOT NECESSARY	176.60	-
1	FRONT BUMPER LOWER COVER	NOT NECESSARY	200.90	-
1	FRONT BUMPER REINFORCEMENT	BENT	691.10	691.10
2	FRONT BUMPER REINFORCEMENT BRACKET L/R	O/S NOT NECESSARY / N/S BENT	745.70	250.40
2	FRONT BUMPER SIDE BRACKET L/R	NOT NECESSARY	342.20	-
6	FRONT BUMPER SIDE BRACKET RETAINER HOLDER	NOT NECESSARY	77.40	-
6	FRONT BUMPER SIDE BRACKET RETAINER HOLDER PIN	NOT NECESSARY	57.00	-
2	FRONT BUMPER SIDE GRILLE L/R	O/S NOT NECESSARY / N/S CUT	211.40	52.00
2	FRONT BUMPER SIDE RETAINER L/R	O/S NOT NECESSARY / N/S BENT	264.50	65.00
2	FRONT BUMPER TOW HOOK COVER L/R	NOT NECESSARY	242.90	-
1	FRONT BUMPER UPPER COVER	NOT NECESSARY	205.00	-
1	FRONT BUMPER UPPER RUBBER SEAL	NOT NECESSARY	174.45	-
1	FRONT ENGINE CROSS MEMBER	NOT NECESSARY	2,478.00	-
1	FRONT GRILLE	FRACTURED	651.60	203.60
2	FRONT HEADLAMP L/R	O/S NOT NECESSARY / N/S CUT	7,442.20	1,600.00

Report Ref No. CS3/AIG18009965/Gqd3e2-1



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:2 of 4

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
2	FRONT HEADLAMP LOWER BRACKET L/R	NOT NECESSARY	130.00	-
2	FRONT KNUCKLE ARM BEARING L/R	DISLODGE	223.40	223.40
2	FRONT KNUCKLE ARM L/R	DISTORTED	1,110.40	1,110.40
1	FRONT LH AIR GUIDE GARNISH	NOT NECESSARY	172.10	-
1	FRONT LH DRIVE SHAFT	NOT NECESSARY	1,175.10	-
1	FRONT LH FENDER	BUCKLED	933.10	585.00
1	FRONT LH FENDER 'HYBRID' EMBLEM	NECESSARY	121.10	44.17
1	FRONT LH FENDER INNER SHIELD	FRACTURED	259.45	165.00
2	FRONT LINKAGE L/R	NOT NECESSARY	395.20	-
2	FRONT LOWER ARM L/R	N/S NOT NECESSARY / O/S BENT	1,251.80	422.00
2	FRONT LOWER BALL JOINT L/R	NOT NECESSARY	346.00	-
1	FRONT RH DRIVE SHAFT	NOT NECESSARY	1,297.80	-
2	FRONT SHOCK ABSORBER L/R	NOT NECESSARY	820.00	-
2	FRONT SHOCK ABSORBER RUBBER L/R	NOT NECESSARY	100.00	-
2	FRONT SHOCK ABSORBER SPONGE L/R	NOT NECESSARY	90.00	-
2	FRONT SHOCK ABSORBER TOP MOUNTING L/R	NOT NECESSARY	312.20	-
1	FRONT STABILIZER BAR	NOT NECESSARY	412.00	-
2	FRONT STABILIZER BAR RUBBER BUSH BRACKET L/R	NOT NECESSARY	70.00	-
2	FRONT STABILIZER BAR RUBBER BUSH L/R	NOT NECESSARY	110.00	-
1	FRONT STEERING RACK & PINION	NOT NECESSARY	1,620.70	-
2	FRONT STEERING TIE ROD END L/R	NOT NECESSARY	203.40	-
2	FRONT TYRE HUB CAP L/R	NOT NECESSARY	400.00	-
2	FRONT WHEEL HUB L/R	NOT NECESSARY	331.80	-
1	REAR AXKE CARRIAGE	NOT NECESSARY	2,315.00	-
1	REAR RH SHOCK ABSORBER	BENT	365.00	212.30
1	REAR RH TYRE HUB CAP	NOT NECESSARY	200.00	-
1	REAR RH WHEEL BEARING	DISLODGE	1,295.70	667.70
	LESS 25% DISCOUNT		-8,995.98	-1,871.66
			26,987.92	5,614.96
1	FRONT BUMPER WIRE HARNESS (SN) (LOCAL REPAIR)	SNAPPED	2,000.90	250.00

Report Ref No. CS3/AIG18009965/Gqd3e2-1



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:3 of 4

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
2	FRONT SPORT RIM L/R (SN)	ABRADED	3,110.20	600.00
1	REAR RH SPORT RIM (SN)	ABRADED	1,555.10	300.00
	LESS 25% DISCOUNT		-1,666.55	-
			4,999.65	1,150.00
	<u>SPECIAL NETT ITEMS</u>			
2	FRONT 205/60/16 TYRE L/R (SN) (\$400.00) (60%)	ABRADED	800.00	240.00
1	SET FRONT BUMPER CLIPS (SN)	NECESSARY	100.00	30.00
1	SET FRONT BUMPER UNDER COVER CLIPS (SN)	NECESSARY	20.00	10.00
1	SET FRONT LH AIR GUIDE GARNISH CLIPS (SN)	NECESSARY	20.00	10.00
1	SET FRONT LH FENDER INNER SHIELD CLIPS (SN)	NECESSARY	50.00	20.00
1	REAR RH 205/60/16 TYRE (SN) (\$200.00) (60%)	ABRADED	400.00	120.00
			1,390.00	430.00
	<u>LABOUR</u>			
	TO REMOVE, REINSTALL ELECTRICAL WIRING HARNESS, CHECK LIGHTING. (TO FR)		60.00	30.00
	TO REMOVE, CHANGE FRONT SUSPENSION PARTS, ABSORBER, LOWER ARM, KNUCKLE ARM, WHEEL BEARING, BEARING HUB, DRIVE SHAFT, ANTI-ROLL BAR, TOP-ARM AND STEERING RACK AND PINION.		1,000.00	200.00
	TO REMOVE, CHANGE REAR SUSPENSION PARTS, AXLE CARRIAGE, ABSORBER, LOWER ARM, TOP ARM, TRAILING ARM, KNUCKLE ARM, WHEEL BEARING, BEARING HUB AND ETC.		400.00	150.00
	TO ROAD TEST DRIVING, CHECK AND RESETTING WHEEL ALIGNMENTS SYSTEM.		180.00	60.00
	TO RE-SPRAY PAINTING ON THE CHANGE BODYPARTS, REPAIR PORTION, AND WHERE CONSISTENT TO THE ACCIDENT.		1,000.00	500.00
	TO PROVIDE LABOUR, WORKMANSHIP TO CHANGE THE ABOVE DAMAGED BODYPARTS, REPAIR, RE-CONSTRUCT AND RE-ALIGN BODY STRUCTURE, BODY ALIGNMENTS AND DAMAGED CONSISTENT TO THE ACCIDENT.		800.00	500.00
	TO APPLY ANTI-RUST CHEMICAL ON REPAIRED AND REPLACED PANEL.		100.00	60.00
			3,540.00	1,500.00
GRAND TOTAL			36,917.57	8,694.96

Report Ref No. CS3/AIG18009965/Gqd3e2-1



RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION)			6,950.00
---	--	--	----------

Report Ref No. CS3/AIG18009965/Gqd3e2-1

XING GUO QIANG

M.MATAI, AMSAE-A

Automotive Assessor

ADRIAN LING WAI PING

B.Eng,AMSOE,AMIRTE,AMSAE-A,M.MATAI

Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or replying on this Report, in whole or in part, does so at his or her own risk.