	ON A
ASS. REC. BY:	cc3/7MI19002334/K+d3n2
Kenneth	SSICAL CONTROL OF THE STATE OF
From:	SSIGNMENT
Estimated Cost:	Veh No: SHC 5670 Y Yr Regn: 11, 14  Type: M.Car/M.Cycle / Bus / Van / Lam / Type: M.Car/M.Cycle / Bus / Type:
QD /TP (WS / TP RES / QD RES / EVA / INV / MY	Tall / Corry / Paxi / Prime Mover /
To Inspect Vehicle No:	Truck / Trailer or
at Workshop m/s Trans Cab	Colour h. Wit 12 Cotile c.c 1985
of Trans Cab	Colour M. White IRE AC: Insured / Std / NI / NA
Insured:	Sp.Reading 536808 T/Radio: Insured / Std / NI / NA
Policy No.	Eng/No:
Claims No.	CNO: VI-IABL 15 AUC . 280283
Sum leaves to	Gen. Cond: Good / Fair / Poor / Burnt
(Client's Record)	Steering: Inorder / Jammed / Leaked / Burnt or
Make of Veh:	Brake: Inorder / Jammed / Leaked / Burnt or
	Modi: MII S/Rim / STD A/Rim or
(Policy Condition)	Tyre Size: F: 215/60R16
Remark: The veh had commenced to	R:
repair at the time of inspection.	BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /
Bal. or Market Value:	TOYOTYOKO or Gizi
IDAC Accident Rport: Consistent? : Yes or No	Eron! Rear
GIA / PR Seen: Consistent? : Yes or No	R/Bal. mm R/Bal. mm
Est. Repairs: 04 days Res.: Yes or No	UBal, mm L/Bal.
Lum Sum: 20 % 3 Val.: Yes or No	D.O.A. 6 /2/19 D.O.I. 8/2/19
CA / REV / REP. / 24 HRS	Survey held at
Vohlale, III ( acces	Des. of Damages : Frt / Rear / O/S / N/S / U/C / Rooftop or
r disori Contactod:	1013 177
113000000	The U/C / Chassis frame / Body Structure affected due to collision.
1/1 072 1001 1001	10
8HC S690 Y-103/FCT 16011014/K	19.201, (20%)
77 1131- ×	tbg 2 DOM: 10/6/16
11/2/19 @ 240pm Ennail GIA & Estimata A	5 Trul,
RECE	IVED-0-2-APR-2019
The state of the s	TV E.D. U. Z. APR. 2019
Oate/Tyre, File Pass 107 : Prell. Report Day	ys Of Repair: 4
WHY WIND I VEINGLE	Supray No. 4 P.
Z)	
Add Fee:	: Site Insp (\$ ) _ S - RS _ SI
Report Format: TP	Interview (S
Lump Sum / I.B.I: (5 7300)-	Tech Inve (\$
2011 6001.1 1°01. (2	Weekend (\$
	10TAL 260
	700

## Shiau Chan (LKKAuto)

From:

Shiau Chan (LKKAuto)

Sent:

Monday, 11 February 2019 2:40 PM motorclaims@tokiomarine.com.sg

To: Cc:

SUR

Subject:

DIRECT SURVEY INSPECTION ON WORKSHOP - TRANS-CAB AUTO SERVICES PTE

LTD, DOA: 06/02/2019, SHC 5670Y (TP VEHICLE), SLR 1113P (OI VEHICLE)

Attachments:

SHC5670 GIA.pdf; SHC5670 EST.pdf

Dear Sir/Madam,

Please be informed that we had inspected the vehicle SHC 5670Y M/s: TRANS-CAB AUTO SERVICES PTE LTD, NO.2 ANG MO KIO ST 63, SINGAPORE 569111.

Enclosed herewith a copy of TP's GIA report and estimated cost of repair.

Meanwhile, kindly create claim in merimen for our necessary action.

Best Regards,

Shiau Chan (Ms) | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email: <u>siewsc@lkkauto.com</u> | fax: 6256-4315 Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

## > Back to OneMotoring

# Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars	
Owner ID Type:	Company
Owner ID: Vehicle Details	3878K
Vehicle No.:	SHC5670Y
Vehicle to be Exported:	Yes
Intended Deregistration Date:	07 Feb 2019
Vehicle Make:	RENAULT
Vehicle Model:	LATITUDE 2.0L DCI AUTO D/AB 4DR
Primary Colour:	Red
Manufacturing Year:	2014
Engine No.:	M9R8839C002206
Chassis No.:	VF1ABL15AUC280283
Maximum Power Output:	127.0 kW (170 bhp)
Open Market Value:	\$19,998.00
Original Registration Date:	19 Nov 2014
First Registration Date:	19 Nov 2014
Transfer Count:	0
Actual ARF Paid:	\$12,498.00
Intended PARF Rebate Details	
PARF Eligibility:	Yes
PARF Eligibility Expiry Date:	18 Nov 2022
PARF Rebate Amount: Intended COE Rebate Details	\$9,373.00
COE Expiry Date:	18 Nov 2022
COE Category:	A - Car up to 1600cc & 97kW (130bhp)
COE Period(Years):	8
PQP Paid:	\$51,337.00
COE Rebate Amount:	\$24,260.00
Total Rebate Amount: Message	\$33,633.00
Please note that the 8-year COE for this vehicle cannot vehicle reaches its statutory lifespan (if applicable), which	be further renewed. The vehicle must be de-registered upon COE expiry or when the chever is earlier.
- 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1	

The information contained herein is correct as at 07 Feb 2019

ОК

MTCS19016663 / Trans-Cab Services Pte Ltd - HQ ENTRY DATE & TIME: 07/02/2019 10:20 SUBMITTED BY: Kek ZheWei

#### SINGAPORE ACCIDENT STATEMENT

### IMPORTANT NOTICE

- Please report correctly the details of the accident to speed up the claims process.
- 2. This Form must be completed by the Policyholder and/or the Authorised Driver.
- 3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or witholding of material facts may allow insurance companies to repudiate policy liability.
- 4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
- 5. Any false reporting may be referred to the Police for investigation.
- This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
- 7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available

aforesaid.	3.9
	ACCIDENT STATEMENT
Date Of Report	07/02/2019 10:20
Date Of Accident	06/02/2019 11:05
Exact Location Of Accident	SIGLAP ROAD X UPPER EAST COAST ROAD
Country/State of Loss	SINGAPORE
D	ETAILS OF OWN VEHICLE
Vehicle Registration Number	SHC5670Y
Insured/Policyholder	
Name Of Registered Owner	TRANS-CAB SERVICES PTE LTD
Co Reg No	200303878K
Email Address	CLAIMS@TRANSCAB.COM.SG
Mobile Phone No	
Alternative Phone No	OFFICE-62876666
Vehicle Particulars	
Manufacturer	RENAULT
Model	LATITUDE-2.0 D DCI (A)
Exact Purpose for which vehicle was being used at time of accident	HIRE AND REWARD
Are you claiming under your own insurance policy for repair to your vehicle?	NO
If No, Please state action to be taken	THIRD PARTY
Vehicle Category	TAXI
Insurance Company	
Name of Insurance Company	AXA INSURANCE PTE LTD
Type Of Coverage	THIRD PARTY
Fleet Policy	YES
Policy Number	VPX/P1680520
Cover Note Number	
Driver	
Name of Driver	NG LALHENG

Name of Driver NG LAI HENG S0058505Z NRIC No 06/04/1953 Date Of Birth Occupation OUTDOOR 01/02/1978 Date Of Driving Pass

41 YEARS AND 0 MONTHS Driving Experience

MALE Gender

(LOCAL) +65-87779476 Mobile Number

Fax Number

Contact Number

NOEMAIL EMail Address

BLK 103 HOUGANG AVENUE 1

#09-1135 530103

Postcode 53

Was driver an employee of the Insured's Company NO

If No, Relationship of the Driver with the Insured

OTHER - HIRER

Vehicle Registration Number of Driver's Own

Vehicle

Address

73

50/950/7/10 97 MODER

-

Insurance Company of Driver's Own Vehicle

-

#### General Information of the Accident

Type Of Accident

SIDE SWIPE

Weather Conditions

CLEAR

Road Surface

DRY

#### Other Information

Was any foreign vehicle involved in this accident?

NO

Number of vehicles (including own vehicle)

involved in the accident

2

Was any body injured in the Accident?

YES

Was any injured conveyed to hospital by

ambulance?

NO YES

Was any other material or property damaged?

I have been approached by unknown person(s) soliciting/offering accident claims assistance.

NO

Number of Passengers (Including Driver)

Passenger 1

2 NAME:

: TONG HENG THAI

GENDER:

: MALE

#### **Details of Police Action**

Was the accident reported to the police?

NO

If Yes, Please state which Police Station

Was notice of intended Prosecution given?

NO

If Yes, against whom?

#### Circumstances of Accident

ON 06/02/2019 AT ABOUT 1105HRS, AFTER I TURNED RIGHT INTO SIGLAP ROAD FROM UPPER EAST COAST ROAD, I WAS MOVING STRAIGHT ON THE FIRST LANE OF SIGLAP ROAD. SUDDENLY VEHICLE B(SLR1113P) SWERVED INTO MY LANE AND COLLIDED ONTO THE FRONT LEFT PORTION OF MY TAXI.

#### Attachment(s)

Are accident photos available for attachment?

YES

Was there any video captured by Car Camera?

YES

Remarks/ Reasons:

FILE SIZE TOO LARGE

Was there any audio recorded?

NO

#### **DETAILS OF OTHER VEHICLE PROPERTY 1**

Vehicle Registration Number

**SLR1113P** 

Vehicle Make/Model/Colour

Details Of Properties

PRIVATE CAR

Vehicle Category Name of Driver

NRIC/Passport Number

Contact Number

Address

Postcode

Insurance Company Name

Nature Of Damage

No. Of Passenger (Including Driver)

## DETAILS OF INJURED PERSON 1

Name

NG LAI HENG

Approximate Age

Injuries Sustain

SHC5670Y Injured person in which vehicle?

Were seat belts worn?

Was this injured conveyed to hospital by

YES

ambulance?

NO

Address

Postcode

#### Sketch Plan Pg. 1

#### SKETCH PLAN

#### IMPORTANT NOTICE

- Please report correctly the details of the accident to speed up the claims process.
- This Form must be completed by the Policyholder and/or the Authorised Driver.
- Information provided must be as <u>truthful and accurate as possible</u>. Any wilful misrepresentation or withholding of material facts may allow insurance companies to <u>repudiate policy liability</u>.
- 4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
- Any false reporting may be referred to the Police for investigation.
- The report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance
  Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by
  interested parties.
- By the lodgment of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.
- 8. Consent under the Personal Data Protection Act (PDPA)

I understand, acknowledge, agree and consent that:

- (a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this [form] and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the Insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of:
  - processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
  - (ii) investigating the accident and/or my claims;
  - (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
  - (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
  - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims.(collectively the "Purposes")
- (b) all insurer(s) who have insured vehicle(s) involved in this accident and the Insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
- (c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third party service providers or agents(including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.
- (d) my Personal Information will also be collected and used to compile claims history for the purpose of fraud detection, investigation and management in present and all future claims.
- (e) the information so collected under (d) above may be shared / disclosed:
  - to all insurers and/or any other third parties that assist in evaluating, investigating, controlling or managing fraud, regulators, law enforcement and government agencies as reasonably required for the purposes stated, or
  - (ii) for complying with requirements under any regulations, laws or court orders.

4

Driver's Signature (If driver is not the policyholder)


Date & Time:

Zhanoi

Reporting Centre Personnel's Signature Name:

NRIC/FIN No.:

Policyholder's Signature Date & Time: Sketch Plan #2 Pg. 1



			+++					
ESCRIBE CIR	CUMSTANCES O	F THE ACCIDEN	т					
							100	
		и						Shirt San
				-	-			
909045-0-E								
		Rober t	a GIA	Rough.				
		Harter 1	2 041					
					111500			
				V-5		_		
							-	
	A							
	·							
100	H-CA-CO-		892					

DECLARATION

I/We declare the foregoing particulars are true in every respect.

Policyholder's Signature Date & Time: Driver's Signature (if driver is not the policyholder) Date & Time: Zherei

Reporting Centre Personnel's Signature Name: NRIC/FIN No.:

GIARMC SketchPlanForm\_V3

# Trans-cab Auto Services Pte Ltd

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No.: 6287 6666 Fax No.: 6257 1330

Vehicle No.:

Chassis No.:

Vehicle Make:

Vehicle Model:

Date of Accident:

Third Party Insurer:

CO./GST Reg. No. 201019626G

**SHC 5670Y** 

AAD1902-027

Not Authorial USing & 7300L

#### SHC 5670Y

VF1ABL15AUC280283

RENAULT LATITUDE 6.2.2019

#### TOKIO MARINE

		19/11/2014
	Date of Registration :	LIST
	PART	LIST
1	BUMPER COVER FRT	\$ B 1,259.42 —
1	BUMPER SPOILER FRT	\$ 181.75 X
1	BUMPER ABSORBER FRT	\$ Sn 394.68 X
1	BUMPER RETAINER FRT LH	\$ CM 151.41 -
1	BUMPER SUPPORT FRT	\$ 123.88 X
1	BUMPER RETAINER FRT RH	\$ 5
1	BUMPER SUPPORT FRT	\$
1	BUMPER UNDERTRAY FRT	\$
1	BUMPER GRILLE LOWER FRT	\$ 54 266.80 X
1	BUMPER FOG LAMP GRILLE LH	s cm 207.21
1	BUMPER BEAM FRT	\$ By 914.08 2
1	HEADLAMP LH	\$ CM 1,184.43 -
1	HEADLAMP PANEL FRT LH	\$ 152.15 X
1	FENDER PANEL FRT LH	\$ 783.83 <u> </u>
1	WHEELARCH FRT LH	\$ CM 278.84 —
1	FENDER BRACKET LOWER LH	\$ 5℃ 15.79 X
1	FENDER INSULATOR LH	\$ 130.84 X
1	DOOR PANEL FRT LH	\$ 72,844.66 X
1	RADIATOR GRILLE	\$ ngem 1,707.78
1	RADIATOR GRILLE BADGE 'RENAULT'	\$ 125.36
1	RADIATOR GRILLE FRAME	s CM 1,353.75 —
1	RADIATOR FAN COWLING	\$ 5~ 820.54 ×
1	RADIATOR FAN MOTOR LH	\$ 5~ 967.36 X
1	RADIATOR FAN MOTOR RH	\$ 1,479.46 X
1	RADIATOR GRILLE FRAME	\$ Mineral 624 1,353.75
1	FRAME FULL SUPPORT PANEL	\$ fr 615.90 X
1	FRAME FULL SUPPORT BRACKET	\$ R 89.79 X
1	AIR CLEANER BOX	\$ CM & 464.20
1	AIR CLEANER HOSE	\$ 175.85 X

# Trans-cab Auto Services Pte Ltd

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

SHC 5670Y

SHC 56/0	Υ.		
	TOTAL	\$	18,891.00
	10%	\$	1,889.10
		\$	17,001.90
	Specical Nett		
	Specical Nett		
1SET	BUMPER CLIP FRT	\$	Ma 66.00
1	BUMPER BRACKET CLIP FRT LH	\$	12.00 X
1	BUMPER SUPPORT CLIP FRT LH	\$	~~ 10.50 ×
1SET	BUMPER GRILLE LOWER CLIP	\$	1 69.00 ×
1SET	FRAME FULL SUPPORT PANEL CLIP	\$ \$ \$	~~ 70.00 ×
2	FRAME FULL SUPPORT PANEL NUT	\$	~~ 20.00 X
2	FRAME FULL SUPPORT PANEL STUD	\$	~~ 30.00 X
1SET	WHEELARCH CLIP FRT RH	\$	Ma 30.50
		\$	308.00
	TOTAL PARTS	\$	17,309.90
	LABOUR		
	Panel beating, knocking and straightening the		
	necessary portion, remove and renewal of parts,		
	adjust and realign the same	\$	3,500.00 6001 3,000.00 6601
	Putty and spray painting of the affected portion.	\$	3,000.00 6606
	To rust-proofing of the affected areas.	\$	170.00 30/
	To remove and refit interior fittings, trimings,		TOWN THE ST. MINE
	garnish, fittings and other, to enable repair.	\$	~~ 380.00 X
	To check steering geometry and computer wheel		220.00
	alignment	\$	220.00 beg
	To transfer of tire, rim and on wheel balancing.	\$	~~ 170.00 X
	To Check Electrical Lighting Concerned.	\$	170.00 202

# Trans-cab Auto Services Pte Ltd

AAD1902-027

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330 CO./GST Reg. No. 201019626G

**SHC 5670Y** 

LUMP SUM (REPAIR DAY)	10 DAYS 4 days		
Over All Total	\$ 26	,399.90	_
TOTAL	\$ 9	,090.00	
To transfer of front door fittings, attachment and perform water seepage test.	\$ n	380.00	×
To vacuum, replace, refix and recharge Air Intercooler	\$ NA	170.00	X
To replace, refix and top up coolant for radiator	\$ M	170.00	X
To vacuum, replace, refix and recharge air condenser	\$ Nn	380.00	X
To transfer of front fender fittings, attachment and perform water seepage test.	\$ nn	380.00	X

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- . To display damaged part(s) during resurvey
- . Parts prices are subject to confirmation
- . Third party survey is on a "Without Prejudice" basis.
- . No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from insurance Company

Acknowledged by Repairer

Signature:

Date:

## LKK Auto Consultants Pte Ltd (Co. Reg. No: 199607198R)

51 Ubi Ave 1 #01-25. Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

## VEHICLE DAMAGE INSPECTION REPORT

Our File No:

CC3/TMI19002334/KTD3N2

Date:

03/04/2019

REFERENCE

Handling Insurer:

Tokio Marine Insurance Singapore Ltd

Policy No:

MU008186

Claimant Vehicle No:

SHC5670Y

Insured Vehicle No:

**SLR1113P** 

Date of Loss:

06/02/2019

Nature of Claim:

TP

Claim No: M1900826

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:

SHC5670Y

Make & Model:

RENAULT LATITUDE, 2.0 D dCi (A) 19/11/2014 (Man. Year: 2014)

Engine No: Chassis No: M9R8839C002206

Reg. Date: Colour:

Metallic White/Red

Odometer:

VF1ABL15AUC280283 536804 km

Engine Capacity:

Market Value/New Car

1995 cc

N/A

Price: Sum Insured (S\$):

Market Value/New Car Price

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:

Steering (Serviceable):

Yes Engine Modification:

Yes Footbrake (Serviceable):

Pre-accident Condition:

Yes

Handbrake (Serviceable): CONDITION OF TYRES

Front Tyre Size: Front Left Side:

215/60R16 Giti 8 mm

Rear Tyre Size: Rear Left Side: Rear Right Side: 215/60R16 Giti 8 mm Giti 8 mm

Giti 8 mm Front Right Side: The above values represent the remaining tyre treads depth

The above values represent the femality of the services				
COST OF CLAIMS Parts Miscellaneous Items	Repairer's 17,309.89 0.00	Adjuster's 7,773.78 0.00	9,536.11 0.00	Diff % 55.09
Labour Paintwork Labour	9,090.00	1,370.00 0.00	7,720.00 0.00	84.93
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$) Approved Total (Overridden) (S\$)	26,399.89	9,143.78 7,300.00	17,256.11	65.36
(S\$)	26,399.89	7,300.00	19,099.89	72.35
+ GST 7.00/7.00% (S\$)	1,847.99	511.00	1,336.99	72.35
Nett Amount (S\$)	28.247.88	7,811.00	20,436.88	72.35

INSPECTION

Date of Assignment:

12/02/2019

Date Inspected:

08/02/2019 Inspected At:

Nett Amount (S\$)

Trans-cab Auto Services Pte Ltd (Ang

Mo Kio)

2, Ang Mo Kio Street 63 Singapore 569111

Estimated Period of Repair:

4.0 days

Adjuster: KENNETH KONG

Manager: DENISE TAY KWEE CHENG

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our

https://singapore.merimen.com/claims/index.cfm?fusebox=MTRadjuster&fuseaction=ge... 3/4/2019

knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

# REPAIR DETAILS

Reference

Part Source: MRM-SG

Version: 1.0 (Last Synchronised: 03 Apr 2019)

Parts:

143

RENAULT LATITUDE 2.0 D dCi (A) (Catalogue:Merimen Singapore 1.0)

Labour:

Repairer's

(Price-denominated Standard List)

Print Code: (Unsubmitted, no print-code for SHC5670Y)

Validity:

These estimates are valid only if they contain the print code (above) on all estimate pages, running page

numbers with the END OF ESTIMATES marker on the last estimate page

Further Info: Items/values not in reference catalogue are prefixed with an asterisk \*.

	*BUMPER COVER FRT  *BUMPER SPOILER FRT  *BUMPER ABSORBER FRT *BUMPER RETAINER FRT LH  *BUMPER SUPPORT FRT *BUMPER SUPPORT FRT *BUMPER SUPPORT FRT *BUMPER UNDERTRAY FRT *BUMPER GRILLE LOWER FRT *BUMPER FOG LAMP GRILLE LH *BUMPER BEAM FRT *HEADLAMP LH *HEADLAMP PANEL FRT LH *FENDER PANEL FRT LH *WHEELARCH FRT LH	Bent Serviceable Serviceable Cracked Serviceable Serviceable Serviceable Serviceable Serviceable Cracked Bent Cracked Repair Bent	181.75 FL 394.68 FL 151.41 FL 123.88 FL 150.77 FL 123.88 FL 472.83 FL 266.80 FL 207.21 FL 914.08 FL 1,184.43 FL	*1,259.42 FL *-FL *151.41 FL *-FL *-FL *-FL *-FL *207.21 FL *914.08 FL *1,184.43 FL *-FL
	*BUMPER SPOILER FRT  *BUMPER ABSORBER FRT  *BUMPER RETAINER FRT LH  *BUMPER SUPPORT FRT  *BUMPER SUPPORT FRT  *BUMPER SUPPORT FRT  *BUMPER UNDERTRAY FRT  *BUMPER GRILLE LOWER FRT  *BUMPER FOG LAMP GRILLE LH  *BUMPER BEAM FRT  *HEADLAMP LH  *HEADLAMP PANEL FRT LH  *FENDER PANEL FRT LH  *WHEELARCH FRT LH	Serviceable Cracked Serviceable Serviceable Serviceable Serviceable Cracked Bent Cracked Repair	394.68 FL 151.41 FL 123.88 FL 150.77 FL 123.88 FL 472.83 FL 266.80 FL 207.21 FL 914.08 FL 1,184.43 FL 152.15 FL	*-FL *151.41 FL *-FL *-FL *-FL *-FL *207.21 FL *914.08 FL *1,184.43 FL
	*BUMPER ABSORBER FRT *BUMPER RETAINER FRT LH *BUMPER SUPPORT FRT *BUMPER RETAINER FRT RH *BUMPER SUPPORT FRT *BUMPER UNDERTRAY FRT *BUMPER GRILLE LOWER FRT *BUMPER FOG LAMP GRILLE LH *BUMPER BEAM FRT *HEADLAMP LH *HEADLAMP PANEL FRT LH *FENDER PANEL FRT LH *WHEELARCH FRT LH	Cracked Serviceable Serviceable Serviceable Serviceable Serviceable Cracked Bent Cracked Repair	151.41 FL 123.88 FL 150.77 FL 123.88 FL 472.83 FL 266.80 FL 207.21 FL 914.08 FL 1,184.43 FL 152.15 FL	*151.41 FL *-FL *-FL *-FL *-FL *207.21 FL *914.08 FL *1,184.43 FL
	*BUMPER SUPPORT FRT *BUMPER RETAINER FRT RH *BUMPER SUPPORT FRT *BUMPER UNDERTRAY FRT *BUMPER GRILLE LOWER FRT *BUMPER FOG LAMP GRILLE LH *BUMPER BEAM FRT *HEADLAMP LH *HEADLAMP PANEL FRT LH *FENDER PANEL FRT LH *WHEELARCH FRT LH	Serviceable Serviceable Serviceable Serviceable Serviceable Cracked Bent Cracked Repair	123.88 FL 150.77 FL 123.88 FL 472.83 FL 266.80 FL 207.21 FL 914.08 FL 1,184.43 FL 152.15 FL	*-FL *-FL *-FL *-FL *207.21 FL *914.08 FL *1,184.43 FL
	*BUMPER RETAINER FRT RH  *BUMPER SUPPORT FRT  *BUMPER UNDERTRAY FRT  *BUMPER GRILLE LOWER FRT  *BUMPER FOG LAMP GRILLE LH  *BUMPER BEAM FRT  *HEADLAMP LH  *HEADLAMP PANEL FRT LH  *FENDER PANEL FRT LH  *WHEELARCH FRT LH	Serviceable Serviceable Serviceable Serviceable Cracked Bent Cracked Repair	150.77 FL 123.88 FL 472.83 FL 266.80 FL 207.21 FL 914.08 FL 1,184.43 FL 152.15 FL	*-FL *-FL *-FL *207.21 FL *914.08 FL *1,184.43 FL
	*BUMPER SUPPORT FRT  *BUMPER UNDERTRAY FRT  *BUMPER GRILLE LOWER FRT  *BUMPER FOG LAMP GRILLE LH  *BUMPER BEAM FRT  *HEADLAMP LH  *HEADLAMP PANEL FRT LH  *FENDER PANEL FRT LH  *WHEELARCH FRT LH	Serviceable Serviceable Serviceable Cracked Bent Cracked Repair	123.88 FL 472.83 FL 266.80 FL 207.21 FL 914.08 FL 1,184.43 FL 152.15 FL	*-FL *-FL *-FL *207.21 FL *914.08 FL *1,184.43 FL
	*BUMPER UNDERTRAY FRT  *BUMPER GRILLE LOWER FRT  *BUMPER FOG LAMP GRILLE LH  *BUMPER BEAM FRT  *HEADLAMP LH  *HEADLAMP PANEL FRT LH  *FENDER PANEL FRT LH  *WHEELARCH FRT LH	Serviceable Serviceable Cracked Bent Cracked Repair	472.83 FL 266.80 FL 207.21 FL 914.08 FL 1,184.43 FL 152.15 FL	*-FL *-FL *207.21 FL *914.08 FL *1,184.43 FL
	*BUMPER GRILLE LOWER FRT *BUMPER FOG LAMP GRILLE LH *BUMPER BEAM FRT *HEADLAMP LH *HEADLAMP PANEL FRT LH *FENDER PANEL FRT LH *WHEELARCH FRT LH	Serviceable Cracked Bent Cracked Repair	266.80 FL 207.21 FL 914.08 FL 1,184.43 FL 152.15 FL	*-FL *207.21 FL *914.08 FL *1,184.43 FL
	*BUMPER FOG LAMP GRILLE LH *BUMPER BEAM FRT *HEADLAMP LH *HEADLAMP PANEL FRT LH *FENDER PANEL FRT LH *WHEELARCH FRT LH	Cracked Bent Cracked Repair	207.21 FL 914.08 FL 1,184.43 FL 152.15 FL	*207.21 FL *914.08 FL *1,184.43 FL
	*BUMPER BEAM FRT  *HEADLAMP LH  *HEADLAMP PANEL FRT LH  *FENDER PANEL FRT LH  *WHEELARCH FRT LH	Bent Cracked Repair	914.08 FL 1,184.43 FL 152.15 FL	*914.08 FL *1,184.43 FL
	*HEADLAMP LH *HEADLAMP PANEL FRT LH *FENDER PANEL FRT LH *WHEELARCH FRT LH	Cracked Repair	1,184.43 FL 152.15 FL	*1,184.43 FL
	*HEADLAMP PANEL FRT LH *FENDER PANEL FRT LH *WHEELARCH FRT LH	Repair	152.15 FL	
	*FENDER PANEL FRT LH *WHEELARCH FRT LH			
	*WHEELARCH FRT LH	Dent	783.83 FL	*783.83 FL
		Cracked	278.84 FL	*278.84 FL
		Serviceable	15.79 FL	*-FL
	*FENDER BRACKET LOWER LH	Serviceable	130.84 FL	*-FL
	*FENDER INSULATOR LH	Repair	2,844.66 FL	*-FL
	*DOOR PANEL FRT LH	Mtg Cracked		*1,707.78 FL
	*RADIATOR GRILLE	Necessary	225.36 FL	*225.36 FL
	*RADIATOR GRILLE BADGE RENAULT	Particular and the Control of the Co	1,353.75 FL	
	HT 1987 (1987) 11 20 14 15 20 14 15 20 15 20 15 20 15 20 15 20 15 20 15 20 15 20 15 20 15 20 15 20 15 20 15 20			*-FL
				*-FL
			아이지 이 맛있다면 하게 되었다.	*-FL
				*-FL
				*-FL
		\$200000 to 000000000000000000000000000000		
	4/TUTE 5. THE TO THE COURSE COURSE SAFE SAFE SAFE SAFE			
		Comment of the Commen		
			10.50 FS	*- FS
		Not Necessary	69.00 FS	
	*SET FRAME FULL SUPPORT PANEL CLIP	Not Necessary	70.00 FS	*- FS
		Not Necessary	20.00 FS	
		Not Necessary	30.00 FS	
		Necessary	30.50 FS	*30.50 FS
se part. S=Spo		0.0000000000000000000000000000000000000		
	9994 (1 mm) (1 m	Sub Total (S\$)	19,198.99	8,626.81
	- List Item Discount on L Item			853.03
		Total Parts (S\$)	17,309.89	7,773.78
	se part. S=Spc		*RADIATOR FAN MOTOR LH *RADIATOR FAN MOTOR RH *RADIATOR FAN MOTOR RH *RADIATOR GRILLE FRAME *FRAME FULL SUPPORT PANEL *FRAME FULL SUPPORT BRACKET *AIR CLEANER BOX *AIR CLEANER HOSE *SET BUMPER CLIP FRT *BUMPER SUPPORT CLIP FRT LH *SET BUMPER GRILLE LOWER CLIP *SET FRAME FULL SUPPORT PANEL CLIP *SET FRAME FULL SUPPORT PANEL CLIP *SET BUMPER GRILLE LOWER CLIP *SET FRAME FULL SUPPORT PANEL STUD *FRAME FULL SUPPORT PANEL STUD *SET WHEELARCH CLIP FRT RH *SET SEPONENT. L=ListItemDisc.  Sub Total (S\$) - List Item Discount on L Items 10.00/10.00% (S\$)	*RADIATOR FAN COWLING Serviceable 820.54 FL *RADIATOR FAN MOTOR LH Serviceable 967.36 FL *RADIATOR FAN MOTOR RH Serviceable 1,479.46 FL *RADIATOR GRILLE FRAME Repeated 1,353.75 FL *FRAME FULL SUPPORT PANEL Serviceable 615.90 FL *FRAME FULL SUPPORT BRACKET Repair 89.79 FL *AIR CLEANER BOX Cracked 464.20 FL *AIR CLEANER HOSE Serviceable 175.85 FL *SET BUMPER CLIP FRT Necessary 66.00 FS *BUMPER BRACKET CLIP FRT LH Not Necessary 12.00 FS *BUMPER SUPPORT CLIP FRT LH Not Necessary 10.50 FS *SET BUMPER GRILLE LOWER CLIP Not Necessary 70.00 FS *SET FRAME FULL SUPPORT PANEL CLIP Not Necessary 70.00 FS *FRAME FULL SUPPORT PANEL SUPD Not Necessary 30.00 FS *FRAME FULL SUPPORT PANEL SUD Not Necessary 30.00 FS *SET WHEELARCH CLIP FRT RH Necessary 30.50 FS  *SET WHEELARCH CLIP FRT RH Necessary 30.50 FS  *SET WHEELARCH CLIP FRT RH Necessary 30.50 FS  *SET WHEELARCH CLIP FRT RH Necessary 30.50 FS  *SET WHEELARCH CLIP FRT RH Necessary 30.50 FS  *SET WHEELARCH CLIP FRT RH Necessary 30.50 FS  *SET WHEELARCH CLIP FRT RH Necessary 30.50 FS  *SET WHEELARCH CLIP FRT RH Necessary 30.50 FS  *SET WHEELARCH CLIP FRT RH Necessary 30.50 FS  *SET WHEELARCH CLIP FRT RH Necessary 30.50 FS  *SET WHEELARCH CLIP FRT RH Necessary 30.50 FS  *SET WHEELARCH CLIP FRT RH Necessary 30.50 FS  *SET WHEELARCH CLIP FRT RH Necessary 30.50 FS

# Recommended Miscellaneous Items There are no new miscellaneous items selected.

Re	commended Labour		723 CONTRACTOR	*******
No	Particulars	Lab.Type	Repairer's	Amount
Labo	our Items			
1	PANEL BEATING, KNOCKING AND STRAIGHTENING THE NECESSARY PORTION, REMOVE AND RENEWAL OF PARTS, ADJUST AND REALIGN THE SAME	New	3,500.00	600.00
2	PUTTY AND SPRAY PAINTING OF THE AFFECTED PORTION	New	3,000.00	660.00
3	TO RUST-PROOFING OF THE AFFECTED AREAS	New	170.00	30.00
4	TO REMOVE AND REFIT INTERIOR FITTINGS,TRIMINGS,GARNISH,FITTINGS AND OTHER,TO ENABLE REPAIR	New	380.00	0.00
5	TO CHECK STEERING GEOMETRY AND COMPUTER WHEEL ALIGNMENT	New	220.00	60.00
6	TO TRANSFER OF TIRE, RIM AND ON WHEEL BALANCING	New	170.00	0.00
7	TO CHECK ELECTRICAL LIGHTING CONCERNED	New	170.00	20.00
8	TO TRANSFER OF FRONT FENDER FITTINGS,ATTACHMENT AND PERFORM WATER SEEPAGE TEST	New	380.00	0.00
9	TO VACUUM, REPLACE, REFIX AND RECHARGE AIR CONDENSER	New	380.00	0.00
10	TO REPLACE, REFIX AND TOP UP COOLANT FOR RADIATOR	New	170.00	0.00
11	TO VACUUM, REPLACE, REFIX AND RECHARGE AIR INTERCOOLER	New	170.00	0.00
12	TO TRANSFER OF FRONT DOOR FITTINGS,ATTACHMENT AND PERFORM WATER SEEPAGE TEST	New	380.00	0.00
	Gross Labor	ır Cost (S\$)	9,090.00	1,370.00
	Report was unsubmitted duri	ng this print-out		

< END OF ESTIMATES >