



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 2

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SKZ 3370U

| Qty | Description of Parts | Condition | Estimate By Workshop (\$) | Our Adjusted (\$) |
|------------------------------------|--|----------------------|---------------------------|-------------------|
| <u>REPLACEMENT OF PARTS</u> | | | | |
| 1 | RH / LH FENDER (REAR) (CONSISTENT) | TO REPAIR SEE LABOUR | 1,200.00 | - |
| 1 | REAR BUMPER (CONSISTENT) | DENTED | 1,027.00 | 557.00 |
| 2 | REAR SENSOR @ \$150.00 (CONSISTENT) | BROKEN | 300.00 | 300.00 |
| 1 | END PANEL (CONSISTENT) | DENTED | 525.00 | 525.00 |
| 1 | REAR BOOT (CONSISTENT) | TO REPAIR SEE LABOUR | 986.00 | - |
| 1 | BOOT LOCK C/W CASING (CONSISTENT) | BENT | 379.00 | 379.00 |
| 1 | REAR BUMPER (CONSISTENT) | BROKEN | 1,171.00 | 500.50 |
| 1 | FRONT CHROME GRILLE (CONSISTENT) | BROKEN | 515.00 | 439.19 |
| 1 | LH REAR RETAINER (CONSISTENT) | BROKEN | 62.00 | 62.00 |
| 1 | RH REAR RETAINER (CONSISTENT) | BROKEN | 62.00 | 62.00 |
| 1 | FRONT BONNET (CONSISTENT) (ADDITIONAL) | DENTED | 1,001.00 | 1,001.00 |
| 1 | END PANEL TRIM (CONSISTENT) (ADDITIONAL) | CRUSHED | 187.30 | 187.30 |
| 1 | REINFORCEMENT BAR (REAR) (CONSISTENT) (ADDITIONAL) | DENTED | 496.70 | 496.70 |
| 1 | LH HEADLAMP (CONSISTENT) (ADDITIONAL) | BROKEN | 969.00 | 969.00 |
| 1 | RH HEADLAMP (CONSISTENT) (ADDITIONAL) | BROKEN | 969.00 | 969.00 |
| 1 | CONDENSER (CONSISTENT) (ADDITIONAL) | BENT | 450.00 | 450.00 |
| | LESS 25% DISCOUNT | | -2,575.00 | -1,724.43 |
| | | | 7,725.00 | 5,173.26 |
| <u>SPECIAL NETT ITEMS</u> | | | | |
| 1 | CLIPS / RETAINER STRUTS FOR FRONT / REAR BUMPER (SN) (CONSISTENT) | NECESSARY | 72.00 | 60.00 |
| 1 | LICENSE PLATE C/W CASING FRONT (SN) (CONSISTENT) (ADDITIONAL) | BENT | 65.00 | 35.00 |
| | | | 137.00 | 95.00 |
| <u>LABOUR</u> | | | | |
| | DISMANTLE / ASSEMBLY OF ALL AFFECTED PARTS. | NOT NECESSARY | 800.00 | - |
| | PANEL BEATING / WELDING / REPAIR / REPLACE END PANEL & 02 FENDERS. INCLUSIVE OF THE REPAIR OF RH / LH FENDER (REAR) AND REAR BOOT. | | 1,200.00 | 900.00 |



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:2 of 2

| Qty | Description of Parts | Condition | Estimate By Workshop (\$) | Our Adjusted (\$) |
|---|---|-----------|---------------------------|-------------------|
| | RESPRAY INCLUDING PUTTY, SAND PAPER, POLISH & WASH OF ALL AFFECTED PARTS. | | 1,800.00 | 1,000.00 |
| | | | 3,800.00 | 1,900.00 |
| GRAND TOTAL | | | 11,662.00 | 7,168.26 |
| RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION) | | | | 5,700.00 |

Report Ref No. CC4/ASM19002340/Ega3s2

CHEN TSUE YEE

Automotive Assessor

HO LEONG CHUAN

Automotive Assessor

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or replying on this Report, in whole or in part, does so at his or her own risk.