

**LKK Auto Consultants** hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer  
Signature: \_\_\_\_\_  
Date: \_\_\_\_\_

Steve (LKK)  
12/2/19  
LTS P/P A3228813  
Mr Lim  
LKK - old man (Van)  
13/2/19 (dismantle)

**Ailsweil Motor Traders**  
Singapore 559266  
email: ben@ailsweilmotor.com.sg

(3rd party claim against AXA insured SLQ612C  
P- 218.51 Supp- 3054.75  
NI- 95 7168.91  
L- Submitted by Ben  
COE expiry 18-01-2026  
Engine No. \_\_\_\_\_

**Estimate repair**

Vehicle No. : SKZ3370U  
Make & Model : Toyota Auro 1.6 CVT  
Chassis No. : \_\_\_\_\_  
Date of survey : \_\_\_\_\_

| S/No               | Part Description   | Qty | Unit Price | Price  | Disposition by |
|--------------------|--|-----|------------|--------|----------------|
| 01A                | RH / LH fender (near) X R  | 01  | \$1,200.00 | X      | * Repair       |
| 01                 | Rear bumper / DD   | 01  | \$1,027.00 | 557    |                |
| 02                 | Rear sensor #150x2 pc. / GR  | 01  | \$300.00   | /      |                |
| 03                 | End panel / DD   | 01  | \$525.00   | /      |                |
| 04                 | Rear boot X R  | 01  | \$986.00   | X      |                |
| 05                 | Boot lock c/w casing / BT  | 01  | \$379.00   | /      | 2874.69        |
| 06                 | Rear bumper / GR   | 01  | \$1,171.00 | 500.50 | -75%           |
| 07                 | Front climate grille / GR  | 01  | \$515.00   | 439.19 | 2118.51        |
| 08                 | LH rear returner / GR  | 01  | \$62.00    | /      |                |
| 09                 | RH rear returner / GR  | 01  | \$62.00    | /      |                |
| Special nett       |  |     |            |        |                |
| 01                 | Clips / retainer studs for front rear bumper @ \$72 / pkt              | 01  | \$72.00    | 60     | (N/A)          |
| Labour Description |  |     |            |        |                |
| 01                 | Dismantle / assembly of all affected parts                             | 01  | \$800.00   | X      |                |
| 02                 | Panel beating / welding / repair / replace end panel & 02 fenders      | 01  | \$1,200.00 | 900    |                |
| 03                 | Respray including paths, sandpaper polish & work of all affected parts | 01  | \$1,800.00 | 1000   | 1900           |
| Supplementary      |  |     |            |        |                |
| 01                 | License plate c/w casing front / BT                                    | 01  | \$65.00    | 35     | (N/A)          |
| 02                 | front bonnet / DD  | 01  | \$1,001.00 | /      |                |
| 03                 | End panel trim / CRU   | 01  | \$187.30   | /      |                |
| 04                 | Reinforcement bar (rear) / DD  | 01  | \$496.70   | /      |                |

Note: If any of the quoted parts are recommended to be repaired, then an additional labour cost will be charged accordingly under supplementary.

05 LH headlamp / GR 01 \$969.00 / 4973  
06 RH headlamp / GR 01 \$969.00 / -75%  
07 Condenser / BT 01 \$450.00 / 3054.75