

**KAH MOTOR CO. SDN. BHD.**

(A Member of the Oriental Holdings Berhad)

Service and Body Repair

Tel: +65 6841 3838

Website: www.honda.com.sg

For 24-hours Roadside Assistance, Call 98203838

QUOTATION

GST Reg No.: M200050223

Company Ref. No.: S60FC1380G

Customer : AXA INSURANCE S'PORE PTE LTD
8 SHENTON WAY
#27-01 AXA TOWER
SINGAPORE 068811

Registration No : SLC8986U
Chassis No : JHMRC1890GC203093
Model : ODYSSEY2.4 EXV-S 16YM NAVI-RES
Owner's Name : GOH CHER CHAY
Ins Policy No. :
Date of Accident : 7/2/2019

Document No. : SQT19000678
Date : 12. Feb 2019
Customer No. : WZA006
Svc Advisor : JACK NG
Engine No : K24W72011402
Date | Time : 12. Feb 2019 1:32:14 PM
Surveyor Name :
Survey Date :
Authorisation Date :

Page 1

Item	Description	Qty	Unit Price	Disc %	Amount	0% GST Amount	Amount incld GST
	TP DIRECT SETTLEMENT (J/NO:) OWNER:GOH CHER CHAY OWNER INSURER:AVIVA LTD ACC DATE:07/02/2019 SURVEYED BY: DATE: REF NO: TP INSURER:AXA INSURANCE TP VEH:SLA 8607 A						
04715-T6A-900ZZ	FACERR.BUMPER <i>Di-</i>	1	568.30	25	426.22	29.84	456.06
33505-SLJ-013	REFLECTOR ASSYR.RR. <i>X</i>	1	45.40	25	34.05	2.38	36.43
33555-SLJ-013	REFLECTOR ASSYL.RR. <i>X</i>	1	45.40	25	34.05	2.38	36.43
71502-T6A-003ZE	FACER.RR.BUMPER GARNISH <i>X</i>	1	76.80	25	57.60	4.03	61.63
71507-T6A-003ZA	FACEL.RR.BUMPER GARNISH <i>X</i>	1	76.80	25	57.60	4.03	61.63
71593-T6A-003	SPACERR.RR.BUMPER SIDE <i>m</i>	1	19.10	25	14.32	1.00	15.32
71598-T6A-003	SPACERL.RR.BUMPER SIDE <i>m</i>	1	19.10	25	14.32	1.00	15.32
91505-TM8-003	CLIP,BUMPER <i>m</i>	8	2.30	25	13.80	0.97	14.77
68100-T6A-Q10ZZ	TAILGATE COMP <i>Bf</i>	1	1070.80	25	803.10	56.22	859.32
74440-T6A-003	WEATHERSTRIPTAILGATE <i>m</i>	1	117.40	25	88.05	6.16	94.21
74800-TF0-J02	LOCKTAILGATE <i>?</i>	1	185.40	25	139.05	9.73	148.78
74810-T4N-H01	SWITCH ASSYTAILGATE OPENER <i>?</i>	1	105.30	25	78.97	5.53	84.50
75701-T6A-000	EMBLEMH <i>m</i>	1	26.30	25	19.72	1.38	21.10
66100-T6A-Q00ZZ	PANEL COMP,REAR <i>repair</i>	1	460.80	25	345.60	24.19	369.79
73214-T6A-003	MOLDINGRR.WINDSHIELD SIDE <i>m</i>	2	18.00	25	27.00	1.89	28.89
73215-T6A-003	MOLDINGR.RR.WINDSHIELD CORNER <i>m</i>	1	16.90	25	12.67	0.89	13.56
73216-T6A-003	MOLDINGL.RR.WINDSHIELD CORNER <i>m</i>	1	16.90	25	12.67	0.89	13.56
73221-SR4-000	SPACERRR.W/SHIELD <i>m</i>	4	3.90	25	11.70	0.82	12.52
73225-TM8-000	RUBBER AWINDSHIELD DAM <i>m</i>	1	3.70	25	2.77	0.19	2.96
73226-SZW-000	DAMPERSTD 5X5 <i>m</i>	2	8.50	25	12.75	0.89	13.64
76711-T6A-003	CAPPVOT <i>m</i>	1	4.80	25	3.60	0.25	3.85

**KAH MOTOR CO. SDN. BHD.**

(A Member of the Oriental Holdings Berhad)

Service and Body Repair

Tel: +65 6841 3838

Website: www.honda.com.sg

For 24-hours Roadside Assistance, Call 98203838

QUOTATION

GST Reg No.: M200050223

Company Ref. No.: S60FC1380G

Customer : AXA INSURANCE S'PORE PTE LTD
8 SHENTON WAY
#27-01 AXA TOWER
SINGAPORE 068811

Registration No : SLC8986U

Chassis No : JHMRC1890GC203093

Model : ODYSSEY2.4 EXV-S 16YM NAVI-RES

Owner's Name : GOH CHER CHAY

Ins Policy No. :

Date of Accident : 7/2/2019

Document No. : SQT19000678

Date : 12. Feb 2019

Customer No. : WZA006

Svc Advisor : JACK NG

Engine No : K24W72011402

Date | Time : 12. Feb 2019 1:32:14 PM

Surveyor Name :

Survey Date :

Authorisation Date :

Page 2

Item	Description	Qty	Unit Price	Disc %	Amount	0% GST Amount	Amount incld GST
BO-WS-SEALANT	WINDSCREEN SEALANT (N) <i>ne /</i>	2	60.00		120.00	8.40	128.40
Sum Item					<u>2329.61</u>	<u>163.06</u>	<u>2,492.67</u>
BOSUN	SUNDRIES	1	100.00 <i>30</i>		100.00	7.00	107.00
BOJSE	BODY JOINT SEALANT FOR TAILGATE	1	150.00 <i>120</i>		150.00	10.50	160.50
BOJSE	BODY JOINT SEALANT FOR END PANEL	1	150.00 <i>X</i>		150.00	10.50	160.50
BML02I	INSPECT RR LIGHTING MECHANISMS. PERFORM WATER	1	380.00 <i>280</i>		380.00	26.60	406.60
BA02R	REMOVE & RENEW REVERSE SENSORS-4 PCS (N)	1	380.00 <i>/</i>		380.00	26.60	406.60
BOMISC1	REMOVE & RE-INSTALL REAR VIEW CAMERA. (N)	1	450.00 <i>/</i>		450.00	31.50	481.50
BOMISC1	RESET & CALLIBRATE SMART ENTRY SYSTEM (N)	1	450.00 <i>/</i>		450.00	31.50	481.50
BODAMKIT	WINDSCREEN DAM KIT.	1	200.00 <i>150</i>		200.00	14.00	214.00
BG02R	REPLACE RR. WINDSCREEN.(N)	1	560.00 <i>/</i>		560.00	39.20	599.20
BKTG02R	REMOVE & TRANSFER ITEMS TO NEW TAILGATE. (N)	1	560.00 <i>/</i>		560.00	39.20	599.20
BMI03D	REMOVE & INSTALL REAR COMPARTMENT LININGS	1	800.00 <i>280</i>		800.00	56.00	856.00
BKRP02M	CUT OFF & RENEW RR PANEL. RENEW ALL DAMAGE PARTS	1	6000.00 <i>1680</i>		6000.00	420.00	6420.00
BP06R	SPRAY PAINTING ON REPAIRED OR REPLACED AREAS. (6P)	1	4000.00 <i>1350</i>		4000.00	280.00	4280.00
Sum Labor					<u>14180.00</u>	<u>992.60</u>	<u>15,172.60</u>

Survey By

Date & Time

Excess

Status

Signature

*RASUL - Hp 90010068**13/02/19 @ 1720**5 days**[Signature]**Reg by paint*

Total Amount 16,509.61 1,155.66 17,665.27

Total (Inclusive of GST) 17,665.27

Printed on 12/2/2019 1:49:28 PM

This is a computer generated invoice. No signature is required.

Part prices are subjected to change without notice.

The above estimated cost of repair do not include any unforeseen damages.

GST Amount is calculated from individual line(s)