



Case Details

Case Reference Number : TAX/01/19/2145
 Type of Repair : Accident Repair
 Vehicle Registration Number : SHF3R

Company Type : SMRT Taxis Pte Ltd
 Estimation ID : EST-5586-ID
 Assigned By : Taxi Claims Manager Team

Insurance Company Name : Lonpac Insurance Bhd
 Accident Date and Time : 31/01/2019 07:05 AM
 Vehicle Age(In Months) : 14

Documents / Photographs

[View Documents / Photographs](#)

Total Documents: 1

Estimation Details

Spare Part's Cost Detail

SMRT Recommendation											Surveyor Approval			
BOM Type	Costing Type	Portion	Material Number	Part Name	Qty	List Price Per Unit(\$)	List Price(\$)	Dis(%)	Final Price(\$)	Repair/ Replace	Surveyor Quantity	Surveyor Final Price(\$)	Repair/Replace	Remarks
One Time Key In	Main			PANEL SUB-ASSY, REAR DOOR , RH	1	1,243.90	1,243.90	25.00	932.93	Replace	1	0	Repair ▼	
One Time Key In	Main			PIXEL STICKER	1	60.00	60.00	0.00	60.00	Replace	1	60.00	Replace ▼	
One Time Key In	Main			MOULDING ASSY, BODY ROCKER PANEL , RH	1	576.00	576.00	25.00	432.00	Replace	1	0	Repair ▼	
One Time Key In	Main			PANEL SUB-ASSY, FENDER REAR RH	1	824.80	824.80	25.00	618.60	Replace	1	0	Repair ▼	
One Time Key In	Main			LINER, REAR FENDER , RH	1	135.80	135.80	25.00	101.85	Replace	0	0	Check ▼	
One Time Key In	Main			WHEEL, DISC	1	1,555.10	1,555.10	25.00	1,166.32	Replace	1	0	Repair ▼	
Total Spare Part Cost									3,311.70		Surveyor Total		60.00	
Lump Sum Discount (%)									0.00		Lump Sum Dis (%)		0	
Final Spare Part Cost									3,311.70		Final Sur Total		60.00	

Labour's Cost Detail

S.No.	Costing Type	Job Scope	SMRT Recommendation(\$)	Surveyor Adjustment(\$)	Remarks
1	Main	TO REPAIR RH PORTION	845.00	600	
Total:			845.00	600.00	

Spray Cost Detail

S.No.	Costing Type	Job Scope	SMRT Recommendation(\$)	Surveyor Adjustment(\$)	Remarks
1	Main	TO RESPRAY RH REAR DOOR	378.00	200	
2	Main	TO RESPRAY ROCKER PANEL MOULDING	180.00	100	
3	Main	TO RESPRAY REAR FENDER RH	378.00	200	
4	Main	TO RESPRAY RIM	180.00	50	
Total:			1,116.00	550.00	

Other Cost Detail

S.No.	Costing Type	Job Scope	SMRT Recommendation(\$)	Surveyor Adjustment(\$)	Remarks
1	Main	TO CHECK WIRING AND SYSTEM FUNCTION	80.00	0	
2	Main	TO APPLY RUST-PROOFING ON AFFECTED AREA	100.00	30	
3	Main	TO DO WHEEL ALIGNMENT / TYRE BALANCING	120.00	60	
4	Main	TO REMOVE AND REFIT TYRE RIM (SPRAYING PURPOSE)	120.00	30	
5	Main	TO REMOVE / REFIT SEAT	120.00	0	
6	Main	TO REPLACE SUNDRY PARTS	100.00	0	
7	Main	TO WASH AND VACUUM	60.00	0	
Total:			700.00	120.00	

Summary

	Estimator Assesment(\$)	Surveyor Assesment(\$)
Total Spare Part Detail	3,311.70	60.00
Total Labour Cost	845.00	600.00
Total Spray Painting	1,116.00	550.00
Other	700.00	120.00
Overall Total	5,972.70	1,330.00
Lump Sum Repair Option	0.00	0.00
Lump Sum Total	0.00	1,330.00
Surveyor Approved Amount		1,330.00

	Estimator Assesment(\$)	Surveyor Assesment(\$)
No of Repair Days*	6	3
Remarks	-	P/P REPAIR, PHOTO AFTER PAINT.
Surveyor Name		Hwee jie
Signature		
		Save Clear
Survey Date	01/02/2019	

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: