LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

To: China Taiping Insurance (Singapore) Pte. Ltd. From: LKK Auto Consultants Pte Ltd

3 Anson Road

51 Ubi Ave 1 #01-25 #16-00 Springleaf Tower Paya Ubi Industrial Park Singapore 079909 Singapore 408933

Attn: Chong Boon Sen Date: 12 Mar 2019

Preliminary Advice

Vehicle No : XE3554M **Accident Date** : 29/01/2019

Make : ISUZU CYZ52K Policy No. : DMCVSN1763211801

Assignment Date : 11/02/2019 **Excess** : S\$1,500.00 Date of Inspection : 12/02/2019 Est. Duration of Repair : 14.00

Inspection At : KOK TONG TRANSPORT & ENGINEERING WORKS PTE LTD (HQ)

11 SUNGEI KADUT STREET 2,

SINGAPORE 729232

Point of Impact / General Description of Damages

The vehicle sustained impact / damages front portion and parts claimed are consistent to the accident.

Repairer's Estimate (Gross)	:S\$	27,486.50 (inclusive supplementary)
Revised Amount	:S\$	14,251.20 (inclusive supplementary)

Check Items (Estimated) :S\$ 11,302.80 Total :S\$ 25,554.00

Lump Sum Repair :S\$

Total Loss Consideration

New for Old Value :S\$

Pre-Accident Value :S\$ 140,000.00 COE / PARF Rebate :S\$ 37,240.00

Salvage Value :S\$

102,760.00 Margin for Repair :S\$

Remarks

(X)	The vehicle is repairable at our adjusted amount. We have	e also confirmed excess and policy coverag	e.
	Kindly let us have your authorisation.		

- The vehicle is uneconomical to be repaired, you are advised to invite tender for the wreck.
- Other comments: Kindly approve of supplementary amount \$4,193.50. Some parts items pending parts (X) prices of the supplementary.