

2/10/2011

ASS. REC. BY:

REF:

CS/CTI19002389/RSD301

Special Instruction:

Surveyor

Merimen

Resu

ASSIGNMENT (Office)

From (Person):

Chong Boon Sen

of

CTI

Date/Time:

11/2/19 @ 2.39pm

Estimated Cost:

Bill to:

OD/TP/WS/TP/RES/OD RES/EVA/INV/MV/CS

To Inspect Vehicle No:

XE3554M

Insured:

at Workshop m/s:

KOK Tong Transport

Tel:

68045046

of

11 Sungai Kerdut Street 2

Policy No:

DMCVSN1783211801

Claim No:

SNM19D200551C01

Sum Insured:

Excess:

\$1,500.00

Make of Veh:

D.O.A.

29/01/2019.

(Client's Record)

zongyu.chua@KTCgroup.com.sg

CA (REV)

/ REP.

/ REV 24 HRS

12/2/19

H.O.D. Endorsement:

Date/Time:

3.16pm @ 11/2/19

Person Contacted:

zhongyu

Vehicle

IN/OUT

Date/Time

Action/Instruction (✓) Estimate

XE3554M-NA/CTI19001953/h4

D.O.A. 29/01/2019

12/2/19

Revert via merimen

15/2/19 @ 16.06

authorise repair by Irene Tay. Lump Sum

15/2/19 @ 4.47pm

email to zongyu authorise repair excess \$1500+


Paul

REF:

ASSIGNMENT

417E
52000
COO XP 24: 2027/04

From: _____ Date: _____
 Estimated Cost: _____
 () TP / WS / TP RES / OD RES / EVA / INV / MV
 To Inspect Vehicle No: **XE 3554M**
 at Workshop n/s: **KOK TONG TRANSPORT**
 of: **11, SUNKET KANG ST 2**
 Insured: **CTI**
 Policy No: _____
 Claims No: _____
 Sum Insured: _____ Excess: **1,500**
 (Client's Record)
 Make of Veh: _____
MR 2 HAWK
 (Policy Condition) **64 5046**
 Remark: The veh had commenced its repair at the time of inspection.
 Bail. or Market Value: **140K**
 IDAC Accident Rpt: _____ Consistent? : Yes or No
 GIA / PR Seen: _____ Consistent? : Yes or No
 Est. Repairs: _____ days Res: Yes or No
 Lum Sum: _____ % 3 Val: Yes or No
 CA / ☒ REV / REP. / 24 HRS
 Date: _____ Person Contacted: _____
 Vehicle: IN / OUT



Veh No: **XE 3554M** Yr Pogn: **2017 OCT**
 Type: M/Car / M/Cycle / Bus / Van / Lorry / Taxi / Prime Mover /
 () Truck / Trailer or _____
 Make: **ISUZU C4Z52K** S/C: **15681**
 Colour: **WHITE** A/C: _____ Insured / Std / NI / NA
 Sp Reading: _____ T/Radio: Insured / Std / NI / NA
 Eng/No: _____
 C/Ho: **JAL C4Z52KH 7 000065**
 Gen. Cond: Good / Fair / Poor / Burnt
 Steering: ☒ In order / Jammed / Leaked / Burnt or _____
 Brake: ☒ In order / Jammed / Leaked / Burnt or _____
 Modi: ☒ Nil / S/Rim / STD A/Rim or _____
 Tyre Size: F: **295/80R22.5**
 R: **0/0**
 BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /
 TOYO / YOKO or **DOUBLE HAPPINESS**
 Front: _____ Rear: _____
 R/Bal: **8** mm R/Bal: **8/8** mm
 L/Bal: **8** mm L/Bal: **8/8** mm
 D.O.A: **29/01/19** D.O.I: **12/02/19**
 Survey held at: **KOK TONG**
 Des. of Damages: ☒ Frt / ☒ Rear / O/S / N/S / U/C / Rooftop or _____
 The U/C / Chassis frame / Body Structure affected due to collision

Date / Time: _____ Action / Instruction: _____
11/06/19 Confirmed L/S \$ 14,400/- @ 14 days with Result
(B 13,086.50 Red - 48%)

RECEIVED 13 JUN 2019

12/6/2019

Date/Time: File Pass to? **13/06/19**
 () Prel. Report
 () Typ. M ☒ Final Report
 Date/Time: File Return to? _____

Days Of Repair: **14**
 Resurvey No. of Trip: **1**

Survey Fee
 Transportation

220

Report Format:
 () Lump Sum / L.B. / L.S. **14,400/- HS**

Add Fee: ☐ Site Insp (\$)
☐ Interview (\$)
☐ Tech. Insp (\$)
☐ Weekend (\$)

1. Phone
 1. Other

220

...CLAIM SUBFOLDER...(New Assignment)

CLAIM SUBFOLDER TRACKING

Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'd	Status
Main	11 Feb 2019		11 Feb 2019 14:39 Assign				New Assignment Cancel Case

Main	Reference	Claim Details	Documents	Show All
----------------------	---------------------------	-------------------------------	---------------------------	--------------------------

CLAIM SUBFOLDER DETAILS

[Created by insurer]

Insured:	KOK TONG TRANSPORT & ENGINEERING WORKS PTE LTD, Co. Reg. No.: -		
Vehicle Reg. No.:	XE3554M	Date of Loss:	29/01/2019 15:00 - :59
Claim Type:	OD / SNM19D200551C01	Policy/Cover Note No.:	DMCVSN1763211801 (Comprehensive)
		Excess:	S\$1,500.00
Repairer:	Kok Tong Transport & Engineering Works Pte Ltd (HQ) 11 Sungai Kadut Street 2,, 729232 Sungai Kadut - Tel:		
Handling Insurer:	China Taiping Insurance (Singapore) Pte. Ltd. (HQ) - Tel: 6389 6111 ... [Handled by Chong Boon Sen]		
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Final Rpt due 20/02/2019]		
Driver/Custodian:	TAN YEW LONG (30 / Male), NRIC: G8001917W, Tel: +6582283380		
Adj Asg. Remarks:	SURVEY REVERT		

ASSOCIATED MAIL RECEIVED

[View All](#)

[Compose Case Mail](#)

There are no mail for this case.

ALL ASSOCIATED TASKS

[View All](#)

[Search Tasks](#)

[Create New Task](#)

[Complete](#)

Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
----------	----------	------	------------	---------	---------	-------------	--------------	------------	-------

No results.

> Back to OneMotoring

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Details	
Owner ID Type:	Company
Owner ID:	4117E
Vehicle Details	
Vehicle No.:	XE3554M
Vehicle to be Exported:	No
Intended Deregistration Date:	12 Feb 2019
Vehicle Make:	ISUZU
Vehicle Model:	CYZ52K
Primary Colour:	White
Manufacturing Year:	2017
Engine No.:	6WG1432968
Chassis No.:	JALCYZ52KH7000065
Maximum Power Output:	-
Open Market Value:	\$87,084.00
Original Registration Date:	11 Oct 2017
First Registration Date:	11 Oct 2017
Transfer Count:	0
Actual ARF Paid:	\$4,355.00
Intended PARF Rebate Details	
PARF Eligibility:	No
PARF Eligibility Expiry Date:	-
PARF Rebate Amount:	\$0.00
Intended COE Rebate Details	
COE Expiry Date:	10 Oct 2027
COE Category:	C - Goods Vehicle & Bus
COE Period(Years):	10
QP Paid:	\$43,002.00
COE Rebate Amount:	\$37,240.00
Total Rebate Amount:	\$37,240.00

The information contained herein is correct as at 12 Feb 2019

OK

140,000
 37,240

 102,760
 //

Shirley Hiew (LKK Auto)

From: Shirley Hiew (LKK Auto) <ShirleyHiew@lkkauto.com>
Sent: Thursday, 13 June 2019 9:34 AM
To: 'Phyo Wai Hlaing Oo'
Cc: Rasul (LKKAuto); SUR
Subject: RE: XE3554M
Attachments: CHINA TAIPING (DV)_0001.pdf

Dear Phyo,

Attached DV, please filled in and revert us.

Thank you.

Best Regards,

Shirley Hiew | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email: Sur@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Phyo Wai Hlaing Oo [mailto:waihlaingoo.phyo@ktcgroup.com.sg]
Sent: Tuesday, 11 June 2019 3:13 PM
To: Rasul (LKKAuto) <Rasul@lkkauto.com>
Cc: Shirley Hiew (LKK Auto) <ShirleyHiew@lkkauto.com>
Subject: RE: XE3554M

Hi Rasul,

we confirmed \$14,400 before excess \$1500. Once ready for billing, please let me know.

Thanks & Regards,

Phyo

Sr. Technician



Kok Tong Transport & Engineering Works Pte Ltd
11 Sungei Kadut Street 2 Singapore 729232
DID: +65 6804 5046 | M: +65 96454677 |
waihlaingoo.phyo@ktcgroup.com.sg; www.ktcgroup.com.sg

From: Rasul (LKKAuto) [mailto:Rasul@lkkauto.com]
Sent: Tuesday, 11 June, 2019 2:57 PM
To: Phyo Wai Hlaing Oo
Cc: Shirley Hiew (LKK Auto)
Subject: RE: XE3554M

Hi Phyo,

Refer to attachment

Finalised amount is \$ 14,400 / 14 days lump sum

Kindly confirm

Best Regards,

Rasul | Assessor

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email: Rasul@lkkauto.com | fax: 6841-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)



Auto
Consultants
Pte Ltd

Save the Earth. Print only when necessary.

From: Phyto Wai Hlaing Oo [<mailto:waihlaingoo.phyo@ktcgroup.com.sg>]

Sent: Tuesday, 11 June, 2019 1:23 PM

To: Rasul (LKKAuto)

Subject: RE: XE3554M

Hi Mr Rasul,

Kindly cancel this two items for which we are unable to provide the price and invoice.

Thanks & Regards,

Phyo

Sr. Technician



Kok Tong Transport & Engineering Works Pte Ltd

11 Sungei Kadut Street 2 Singapore 729232

DID: +65 6804 5046 | M: +65 96454677 |

waihlaingoo.phyo@ktcgroup.com.sg; www.ktcgroup.com.sg

From: Rasul (LKKAuto) [<mailto:Rasul@lkkauto.com>]

Sent: Tuesday, 11 June, 2019 11:32 AM

To: Phyto Wai Hlaing Oo

Subject: RE: XE3554M

Hi Phyo,

Item 26 and 27 COVER how much is the price?

Best Regards,

Rasul | Assessor

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email: Rasul@lkkauto.com | fax: 6841-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)



Auto
Consultants
Pte Ltd

Save the Earth. Print only when necessary.

From: Phyto Wai Hlaing Oo [<mailto:waihlaingoo.phyo@ktcgroup.com.sg>]

Sent: Friday, 8 March, 2019 4:09 PM

To: Rasul (LKKAuto)

Cc: SUR; Denise Tay (LKKAuto)
Subject: XE3554M

Hi Mr Rasul,

Kindly resurvey for the supplementary items as per attached.

Thanks & Regards,

Phyo
Sr. Technician



Kok Tong Transport & Engineering Works Pte Ltd
11 Sungei Kadut Street 2 Singapore 729232
DID: +65 6804 5046 | M: +65 96454677 |
waihlaingoo.phyo@ktcgroup.com.sg; www.ktcgroup.com.sg

Denise Tay (LKKAuto)

From: Denise Tay (LKKAuto)
Sent: Friday, 15 February 2019 4:47 PM
To: 'zongyu.chua@ktcgroup.com.sg'
Cc: SUR
Subject: FW: XE 3554M / OD / CHINA TAIPING

Dear Sir,

As instructed by our client, please proceed to repair the insured vehicle **XE 3554M (Excess \$1,500/-). On lump sum repair.**

If there are any check items or supplementary items please inform our office's Assignment Team at Tel: 6741 8434 to arrange our surveyor for inspection.

All supplementary items and unconfirm items are subjected to further approval from insurance company before completion of the repair.

*Our client reserve their right not to pay if there is no valid approval obtained before repair.

Best Regards,

Denise Tay | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email: denisetay@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

View Received Message

This mail is associated with :

***XE3554M (SNM19D200551C01)**

OD

Jan 29 2019 3:00PM

[KOK TONG TRANSPORT & ENGINEERING WORKS PTE LTD]
Kok Tong Transport & Engineering Works Pte Ltd

[Reply](#) [Reply All](#) [Mark as Unread](#) [Print Message](#) [Delete Message](#) [Forward](#)

From China Taiping Insurance (Singapore) Pte. Ltd. (HQ) (CHINA_TAIPING), sent on **14/03/2019 11:22 AM.**
To LKK_HQ
Subject Alert - Adj Mandate Approved (S\$25554.00) - XE3554M - Claim Handler: Chong Boon Sen

Approved:25554,00:Proceed to authorize repairs UP TO \$25,554.00 BEFORE Excess of \$1,500.00. Re-inspection of vehicle required.

DOCUMENTS SUMMARY

There are no documents.

Claim Audit

AUDIT TRAIL				
No.	On	Audit	Remarks	By
1	11 Feb 2019 14:38	Cim Veh Model Changed	(203080) ISUZU CYZ52K 15.7 D (M).	[I] Chong Boon Sen
2	11 Feb 2019 14:38	Cim Created	Reg No: XE3554M, Policy No: DMCVSN1763211801, Acct Date: 2019/01/29, Claim Type: OD, Insurer: China Taiping Insurance (Singapore) Pte. Ltd. (HQ), Workshop: Kok Tong Transport & Engineering Works Pte Ltd (HQ), Ins.Status => Incoming Claim, Created from SAS	[I] Chong Boon Sen
3	11 Feb 2019 14:39	Adj Co Assigned	LKK Auto Consultants Pte Ltd (HQ):SURVEY REVERT	[I] Chong Boon Sen
4	11 Feb 2019 14:39	Adj Next Rpt Changed	Next Rpt:Final Rpt.Due Date:2019/02/20	[I] Chong Boon Sen
5	11 Feb 2019 14:39	Adj Mandate Set	Approved:0.00.	[I] Chong Boon Sen
6	11 Feb 2019 14:59	Assignment 1st Accessed		[A] Nivitha Govindasamy
7	11 Feb 2019 16:27	Adj Adjuster Assigned	[None] -> ONG HWEE JIE	[A] Nivitha Govindasamy
8	12 Feb 2019 13:19	Adj Adjuster Assigned	ONG HWEE JIE -> MOHD RASUL	[A] Nivitha Govindasamy
9	12 Feb 2019 14:29	Adj Rpt Initiated		[A] VERON CHEN
10	12 Feb 2019 14:29	Cim Dtl Modified	JPJ Reg. Date: -> 2017/10/11.	[A] VERON CHEN
11	12 Feb 2019 14:29	Cim Details Notified		[A] VERON CHEN
12	12 Feb 2019 15:37	Adj Im. Advice Submitted	Next Rpt:Final Rpt.Due Date:2019/02/20	[A] VERON CHEN
13	12 Feb 2019 15:43	Adj Mandate Request	Cur.Req:21360.50:Damages Consistent Repair Cost Economical	[A] VERON CHEN
14	15 Feb 2019 16:06	Adj Next Rpt Changed	Next Rpt:Final Rpt.Due Date:2019/02/20	[I] Irene Tay Hui Ping
15	15 Feb 2019 16:06	Adj Mandate Set	Approved:17100.00.	[I] Irene Tay Hui Ping

Date From



Date To



Audit Type None

Go

ACTIVITY

[11/02/2019 15:32] Nivitha Govindasamy:

Please be informed repairer agreed survey on 12/02/2019.

Merimen Billing for this case - Transaction History

Self Ref No	Bill Date	Acc Type	Acc Name	Co Name (Branch)	Ref 1	Ref 2	Amount
2054101	12/02/2019 14:29	Motor	LKK Auto Consultants Pte Ltd	LKK Auto Consultants Pte Ltd (HQ)	XE3554M		10.70

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

To: China Taiping Insurance (Singapore) Pte. Ltd.
3 Anson Road
#16-00 Springleaf Tower
Singapore 079909

From: LKK Auto Consultants Pte Ltd
51 Ubi Ave 1 #01-25
Paya Ubi Industrial Park
Singapore 408933

Attn: Chong Boon Sen

Date: 12 Mar 2019

Preliminary Advice

Vehicle No	: XE3554M	Accident Date	: 29/01/2019
Make	: ISUZU CYZ52K	Policy No.	: DMCVSN1763211801
Assignment Date	: 11/02/2019	Excess	: S\$1,500.00
Date of Inspection	: 12/02/2019	Est. Duration of Repair	: 14.00
Inspection At	: KOK TONG TRANSPORT & ENGINEERING WORKS PTE LTD (HQ) 11 SUNGEI KADUT STREET 2, SINGAPORE 729232		

Point of Impact / General Description of Damages

The vehicle sustained impact / damages front portion and parts claimed are consistent to the accident.

Repairer's Estimate (Gross)	:S\$	27,486.50 (inclusive supplementary)
Revised Amount	:S\$	14,251.20 (inclusive supplementary)
Check Items (Estimated)	:S\$	11,302.80
Total	:S\$	25,554.00

Lump Sum Repair :S\$

Total Loss Consideration

New for Old Value	:S\$	
Pre-Accident Value	:S\$	140,000.00
COE / PARF Rebate	:S\$	37,240.00
Salvage Value	:S\$	
Margin for Repair	:S\$	102,760.00

Remarks

- (X) The vehicle is repairable at our adjusted amount. We have also confirmed excess and policy coverage. Kindly let us have your authorisation.
- () The vehicle is uneconomical to be repaired, you are advised to invite tender for the wreck.
- (X) Other comments : Kindly approve of supplementary amount \$ 4,193.50 .Some parts items pending parts prices of the supplementary.

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

To: China Taiping Insurance (Singapore) Pte. Ltd.
3 Anson Road
#16-00 Springleaf Tower
Singapore 079909

From: LKK Auto Consultants Pte Ltd
51 Ubi Ave 1 #01-25
Paya Ubi Industrial Park
Singapore 408933

Attn: Chong Boon Sen

Date: 12 Feb 2019

Preliminary Advice

Vehicle No	: XE3554M	Accident Date	: 29/01/2019
Make	: ISUZU CYZ52K	Policy No.	: DMCVSN1763211801
Assignment Date	: 11/02/2019	Excess	: S\$1,500.00
Date of Inspection	: 12/02/2019	Est. Duration of Repair	: 14.00
Inspection At	: KOK TONG TRANSPORT & ENGINEERING WORKS PTE LTD (HQ) 11 SUNGEI KADUT STREET 2, SINGAPORE 729232		

Point of Impact / General Description of Damages

The vehicle sustained impact / damages front portion and parts claimed are consistent to the accident.

Repairer's Estimate (Gross)	:S\$	23,293.00
Revised Amount	:S\$	11,326.10
Check Items (Estimated)	:S\$	10,034.40
Total	:S\$	21,360.50

Lump Sum Repair (estimated)	:S\$	17,100.00
-----------------------------	------	-----------

Brake System : In Order
Steering System : In Order
Tyre Condition (Front) : 8/8 mm
Tyre Condition (Rear) : 8/8 mm(D)

Total Loss Consideration

New for Old Value	:S\$	
Pre-Accident Value	:S\$	140,000.00
COE / PARF Rebate	:S\$	37,240.00
Salvage Value	:S\$	
Margin for Repair	:S\$	102,760.00

Remarks

(X) The vehicle is repairable at our adjusted amount. We have also confirmed excess and policy coverage. Kindly let us have your authorisation.

() The vehicle is uneconomical to be repaired, you are advised to invite tender for the wreck.

() Other comments :

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. **Any false reporting may be referred to the Police for investigation.**
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT	
Date Of Report	30/01/2019 11:13
Date Of Accident	29/01/2019 15:25
Exact Location Of Accident	BKE TWDS PIE AFTER MANDAI EXIT
Country/State of Loss	SINGAPORE
DETAILS OF OWN VEHICLE	
Vehicle Registration Number	XE3554M
Insured/Policyholder	
Name Of Registered Owner	KOK TONG TRANSPORT & ENGINEERING WORKS PTE LTD
Co Reg No	-
Email Address	NOEMAIL
Mobile Phone No	
Alternative Phone No	OFFICE-96155910
Vehicle Particulars	
Manufacturer	ISUZU
Model	CYZ52K
Exact Purpose for which vehicle was being used at time of accident	WORKING
Are you claiming under your own insurance policy for repair to your vehicle?	YES
If No, Please state action to be taken	
Vehicle Category	COMMERCIAL VEHICLE
Insurance Company	
Name of Insurance Company	CHINA TAIPING INSURANCE (SINGAPORE) PTE. LTD.
Type Of Coverage	COMPREHENSIVE
Fleet Policy	NO
Policy Number	DMCVSN1763211801
Cover Note Number	-
Driver	
Name of Driver	TAN YEW LONG
NRIC No	G8001917W
Date Of Birth	25/07/1988
Occupation	OUTDOOR
Date Of Driving Pass	10/04/2015
Driving Experience	3 YEARS AND 9 MONTHS
Gender	MALE
Mobile Number	(LOCAL) +65-82283380
Fax Number	
Contact Number	
Email Address	NOEMAIL

Address 14 JALAN PINANG 51 TAMAN DAYA 81100 JOHOR BAHRU

Postcode

Was driver an employee of the Insured's Company YES

If No, Relationship of the Driver with the Insured

Vehicle Registration Number of Driver's Own Vehicle -

Insurance Company of Driver's Own Vehicle -

General Information of the Accident

Type Of Accident COLLISION - HEAD TO REAR

Weather Conditions CLEAR

Road Surface DRY

Other Information

Was any foreign vehicle involved in this accident? NO

Number of vehicles (including own vehicle) involved in the accident 2

Was any body injured in the Accident? NO

Was any injured conveyed to hospital by ambulance?

Was any other material or property damaged? YES

I have been approached by unknown person(s) soliciting/offering accident claims assistance. NO

Number of Passengers (Including Driver) 1

Details of Police Action

Was the accident reported to the police? NO

If Yes, Please state which Police Station

Was notice of intended Prosecution given? NO

If Yes, against whom?

Circumstances of Accident

I WAS TRAVELLING ALONG BKE TWDS PIE AFTER MANDAI EXIT. SUDDENLY VEH B (BEARING NO XE4123S) WHICH WAS IN FRONT OF ME JAMMED BRAKE, I MANAGE TO STOP BUT CANNOT STOP IN TIME. AS THE RESULT, MY LORRY HIT ONTO THE VEH B REAR PORTION.

Attachment(s)

Are accident photos available for attachment? YES

Was there any video captured by Car Camera? YES

Remarks/ Reasons: WITH DRIVER

Was there any audio recorded? NO

DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number XE4123S

Vehicle Make/Model/Colour

Details Of Properties

Vehicle Category COMMERCIAL VEHICLE

Name of Driver

NRIC/Passport Number

Contact Number

Address

Postcode

Insurance Company Name

Nature Of Damage

No. Of Passenger (Including Driver)

Accident Sketch Plan

ACCIDENT PLAN

IMPORTANT NOTES

1. This document is intended for the use of the accident to assist in the claims process.
2. This form must be completed by the Policyholder and/or the Authorized Driver.
3. Information provided must be as truthful and accurate as possible. Any willful misrepresentation is withholding of material facts may affect insurer's compliance for immediate policy liability.
4. This form will be submitted to my insurer for insurance company's use as admission of policy liability on the part of the insured and/or insured.
5. This form may be referred to the Police for investigation.
6. This report will be forwarded by the insurers of the GRS Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will be a free-to-use available upon application by interested parties.
7. By the submission of this report to the insurers, you hereby consent to the archiving of this report at the source and to copies of the report being made available elsewhere.
8. Covered under the Personal Data Protection Act (PDPA):
 - (a) I understand, acknowledge, agree and consent that:
 - (i) My insurer, my workmate and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this form and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the Insurers' lawyers/law firm, the Attorney-Generals of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of:
 - (i) investigating, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
 - (ii) investigating the accident and/or my claims;
 - (iii) carrying out audits relating with my insurances or responding to any enquiries by me;
 - (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me) which could involve disclosure of certain personal data about me to help about delivery of the same as well as on the national issue of cross-border packages); and/or
 - (v) complying with applicable laws or administering, processing, handling and/or dealing with my claims (collectively the "Purposes").
 - (ii) all insurer(s) who have insured vehicle(s) involved in this accident and the Insurers' lawyers/law firm, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
 - (iii) my Personal Information may/are be disclosed by any of the Insurers under GIA to their third party service providers or agents (including their lawyers/law firms), which may be used outside of Singapore, for one or more of the above Purposes;
 - (iv) my Personal Information will also be collected and used to compile claims history for the purpose of fraud detection, investigation and to be provided to present and all future claims;
 - (v) my Personal Information collected under (ii) above may be shared if authorized;
 - (vi) all Insurers and/or any other third parties that assist in investigating, investigating, controlling or managing fraud involves law enforcement and government agencies as necessary required for the purposes stated; or
 - (vii) for complying with requirements under any regulations, law or court orders.


 Policyholder's Signature
 (If shown is not for policyholder)


 Driver's Signature
 (If shown is not for policyholder)


 Reporting Centre Person's Signature
 Name:
 NRIC/Fin No:

Accident Sketch Plan

DESCRIBING THE INSTANCES OF THE ACCIDENT

Please Refer to Statement

DECLARATION

2. We derive the following propositions and treat as policy options:

1. *Pharmaceuticals* 2. *Pharmaceuticals*
 3. *Pharmaceuticals* 4. *Pharmaceuticals*

© 2004 Blackwell Publishing Ltd
Journal of Internal Medicine 255: 105–112

Reporting Card for Personnel's Signature
Name: _____
Title: _____

DRIVING DOC





DRIVING DOC

FWPDL546C - Notification Letter - Renew (Non-Reporting)



TAN YEW LONG
KOK TONG CONSTRUCTION PTE LTD
27 PANDAN CRESCENT
SINGAPORE 128476

XE355e0/S



402453842140316

For Immigration Use (To clear by PRC)



G8001917W

25 Jan 2019

Your card will be delivered to you after we have verified your documents

Dear TAN YEW LONG

We have received a request to renew your work permit on 25 Jan 2019 and will be checking the documents submitted to us. Once this is completed, we will SMS / email the delivery details to your authorised recipient(s) at least 1 working day before the delivery.

This Notification Letter allows you to work and stay in Singapore until you get your new card. It is valid from 25 Jan 2019 till 24 Feb 2019

You must return your existing card to us by 01 Feb 2019. You may mail it to the Work Pass Division, Ministry of Manpower, 18 Havelock Road, Singapore 069764

Yours sincerely,

Mdm Chow Choon Yen
for Controller of Work Passes

YOUR NAME
TAN YEW LONG
FIN
G8001917W
WORK PERMIT NO
4 02453842
DATE OF APPLICATION
14 Mar 2016
DATE OF ISSUE
25 Jan 2019
WORK PERMIT EXPIRY DATE
27 Feb 2021
DATE OF BIRTH
25 Jul 1988
SEX
MALE
NATIONALITY
MALAYSIAN
TRAVEL DOCUMENT NO
A38024916
TRAVEL DOCUMENT EXPIRY DATE
25 Nov 2021
YOUR EMPLOYER'S NAME
KOK TONG CONSTRUCTION PTE LTD
SECTION
CONSTRUCTION
OCCUPATION
LORRY/ TRUCK DRIVER
SALARY
\$850

IMPORTANT

- If the documents submitted are incomplete / incorrect, we will SMS / email the contact person provided to re-submit the documents. The card will only be delivered to the authorised recipient(s) 4 working days after the successful verification of documents.
- You must keep this Notification Letter with you until you get your card. If you need to leave / enter Singapore, you will have to show this letter at the Immigration Checkpoints.

Ministry of Manpower Work Pass Division
www.mom.gov.sg
http://www.mom.gov.sg/employment

Page 1 of 2

Accident Photo



Accident Photo



Accident Photo



Accident Photo



Accident Photo



Accident Photo



Accident Photo



Accident Photo



Accident Photo



Accident Photo



Accident Photo




Accident Photo



Accident Photo



Accident Photo



Accident Photo



Accident Photo



Accident Photo



Accident Photo

CHASSIS NO : JALCYZ52KH7000065

U/W : ~~12960~~ KG

M/L/W : 28000 KG

PASS CAP : 02

TYRE SIZE : F 295-80R22-5(S)
: R 295-80R22-5(D)x2



Repair Estimates

Date: 02/02/2019

From:

Kok Tong Transport & Engineering
Works Pte Ltd
11, Sungei Kadut, Street 2, Singapore 729232.

Tel: 68045046,

Contact person: Chua Zongyu

HP: 96728578

DOA: 29/01/2019

Policy No: DMCVSN 1763211801

To:

China Taiping Insurance (Singapore) Pte. Ltd
3 Anson Road # 16-00 Spring Leaf Tower
S 079909

Tel: 63896111

Attn:

HP:

Vehicle No: XE3554M

Chassis No: JALCYZ52KH7000065

Sr No	Part	Description	Qty	Total Price
1	8-98130-331-1	BUMPER ASM <i>PA</i>	1	\$1,100.00
2	1-86792-077-0	BUMPER LID RH <i>X</i>	1	\$100.00
3	1-86792-076-0	BUMPER LID LH <i>PA</i>	1	\$100.00
4	1-71707-177-1	LH MIRROR STAY <i>PA</i>	1	\$145.60
5	1-71798-829-1	LH MIRROR STAY BRACKET <i>PA</i>	1	\$28.70
6	1-71797-809-2	LH BRACKET OUTSIDE MIRROR <i>cut</i>	1	\$21.00
7	1-71798-732-0	COVER, STAY OUTSIDE MIRROR <i>new</i>	1	\$14.00
8	1-71798-733-0	COVER, STAY OUTSIDE MIRROR <i>new</i>	1	\$14.00
9	1-86855-031-0	POWER UNIT, MIRROR STAY <i>new</i>	1	\$304.50
10	1-71998-939-3	GRIP, ASSIST FRT PANEL LH <i>PA</i>	1	\$42.70
11	1-71998-940-3	GRIP, ASSIST FRT PANEL RH <i>PA</i>	1	\$42.70
12	1-21410-933-2	RADIATOR ASM <i>new</i>	1	\$4,175.50
13	1-14431-060-1	COOLER, CHARGE AIR <i>new</i>	1	\$4,294.50
14	1-76210-704-0	EMBLEM, RAD GRILLE <i>cut</i>	1	\$109.20
15	1-76217-189-0	DECAL MODEL <i>new</i>	1	\$18.20
16	1-83312-112-2	LINK ASM, FRT WIPER <i>PA</i>	1	\$174.30
17	1-86810-122-0	BRACKET, WIPER MOTOR <i>new</i>	1	\$250.00
18	1-86810-121-0	MOTOR ASM, WIPER <i>new</i>	1	\$459.90
19	1-76117-057-0	WINDSHIELD GLASS <i>new</i>	1	\$1,507.80
20	1-76737-158-4	WEATHER STRIP <i>new</i>	1	\$204.40
21	1-61281-410-2	FRT PILLAR LH <i>new</i>	1	\$550.00
22	1-61270-773-3	LH PANEL OUTER BACK CORNER <i>repair</i>	1	\$494.90
23	8-98125-810-4	CLOSING SIDE STEP LH <i>new</i>	1	\$222.60
24	1-64080-394-2	LH DOOR ASM <i>PA</i>	1	\$1,500.00
25	1-71101-023-1	FRT PANEL <i>new</i>	1	\$1,127.00
26	1-71117-270-1	GRILLE LH <i>new</i>	1	\$46.20
27	1-71117-269-1	GRILLE RH <i>new</i>	1	\$46.20
28	1-71117-268-2	GRILLE CENTER <i>new</i>	1	\$129.50
29	1-71107-864-0	PANEL SUPPORT ASM <i>new</i>	1	\$132.30
30	1-79347-007-3	CABLE FRT LID <i>new</i>	1	\$26.60
31	1-65473-144-0	WIPER PANEL <i>PA</i>	1	\$115.50
32	1-79317-026-1	LOCK ASM FRT LID LH <i>new</i>	1	\$44.80
33	1-79317-025-1	LOCK ASM FRT LID RH <i>new</i>	1	\$44.80
34	1-79318-008-1	STRIKER FRT LID <i>new</i>	2	\$22.40
35	1-65473-185-4	LH CORNER PANEL <i>new</i>	1	\$336.70

36	8-98154-745-1	LH CABIN FENDER	CRA ✓	1	\$486.50
37	8-98105-664-1	LH DOOR FENDER	DE ✓	1	\$240.00
38	NIL	PAINT		1	1400 \$1,500.00

Part Cost

\$20,173.00

Labour (Bodywork, Mech, Elect)

2000 ~~\$3,120.00~~

Total Cost (Excluded GST)

\$23,293.00

Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modifications to be allowed
- Supplementary item(s) must be authorised and is subject to final approval from Insurance Company

Acknowledged by Repairer:

Signature: _____

Date: _____

Case

Hp 90010068

14 days

4s

12/02/19 @ 0900hrs

EXCESS: 1500

Revet

Resurvey after repair



Repair Estimates

Date: 8/03/2019

From:

Kok Tong Transport & Engineering
Works Pte Ltd
11, Sungai Kadut, Street 2, Singapore 729232.

Tel: 68045046,
Contact person: Chua Zongyu
HP: 96728578
DOA: 29/01/2019
Policy No: DMCVSN 1763211801

To:

China Taiping Insurance (Singapore) Pte. Ltd
3 Anson Road # 16-00 Spring Leaf Tower
S 079909

Tel: 63896111
Attn:
HP:
Vehicle No: XE3554M
Chassis No: JALCYZ52KH7000065

Sr No	Part	Description	Qty	Total Price
1	8-97608-505-1	LH HEAD LAMP BRACKET <i>PK Repair</i>	1	\$210.70
2	8-98121-414-3	RH HEAD LAMP BRACKET <i>PK Repair</i>	1	\$181.30
3	8-98145-253-1	PAD TRIM FRT DOOR LH <i>3 / CRA</i>	1	\$270.20
4	1-74338-069-3	CHANNEL DOOR GLASS FRT LH <i>3 / CRA</i>	1	\$53.20
5	1-74418-179-3	REGULATOR ASM DOOR LH <i>3 / CRA</i>	1	\$119.70
6	1-74338-071-3	MOTOR POWER WINDOW REG DOOR LH <i>3 / CRA</i>	1	\$37.80
7	1-74518-115-3	LOCK DOOR FRT LH <i>3 / CRA</i>	1	\$178.50
8	1-74518-094-3	LINK DOOR LOCK INSIDE <i>BT</i>	1	\$9.10
9	1-09983-151-1	GROMMET SCREW DOOR PAD <i>BT</i>	2	\$2.80
10	1-09987-272-0	CLIP DOOR PAD <i>BT</i>	2	\$2.80
11	8-94279-043-0	GROMMET SCREW ASY TRAY DOOR <i>BT</i>	4	\$2.10
12	1-64780-088-3	LH DOOR HINGE UPPER <i>BT</i>	1	\$87.50
13	1-64780-098-2	LH DOOR HINGE LOWER <i>BT</i>	1	\$81.00
14	1-09983-160-3	GROMMET LH CORNER PANEL <i>BT</i>	1	\$3.50
15	1-65671-725-8	FRAME FACIA <i>BT</i>	1	\$307.30
16	1-72418-009-6	PANEL SW INST <i>BT</i>	1	\$151.90
17	1-65671-828-2	BEZEL ASM LENTER <i>BT</i>	1	\$42.00
18	1-86815-013-7	TANK ASSM WASHER <i>DE</i>	1	\$133.70
19	1-83567-877-1	PIPE COOLER EVAP TO TANK <i>BT</i>	1	\$154.70
20	8-98028-191-0	HOSE FLEX UNIT TO CMPR <i>BT</i>	1	\$426.30
21	1-82699-585-2	COVER BOX FRAME HARNESS <i>CRA</i>	1	\$22.40
22	1-82699-581-3	BOX CONN FRT PNL <i>3 / CRA</i>	1	\$120.40
23	1-82699-582-1	COVER CONNETOR BOX FRT PNL <i>CRA</i>	1	\$29.40
24	1835611822	BLOWER UNIT <i>CRA</i>	1	\$1,013.60
25	8-98238-476-0	HEATER UNIT <i>BT</i>	1	\$551.60
26	8-98055-383-0	COVER <i>27 DEF / XSC</i>		TBA
27		COVER <i>17 DEF / XSC</i>		TBA

Part Cost

Labour (Bodywork, Mech, Elect)

Total Cost (Excluded GST)

ASUL CURK
11/03/19



Repair Estimates

Date: 8/03/2019

From:

Kok Tong Transport & Engineering
Works Pte Ltd
11, Sungei Kadut, Street 2, Singapore 729232.

Tel: 68045046,
Contact person: Chua Zongyu
HP: 96728578
DOA: 29/01/2019
Policy No: DMCVSN 1763211801

To:

China Taiping Insurance (Singapore) Pte. Ltd
3 Anson Road # 16-00 Spring Leaf Tower
S 079909

Tel: 63896111
Attn:
HP:
Vehicle No: XE3554M
Chassis No: JALCYZ52KH7000065

Sr No	Part	Description	Qty	Total Price
1	8-97608-505-1	LH HEAD LAMP BRACKET ?	1	\$210.70
2	8-98121-414-3	RH HEAD LAMP BRACKET ?	1	\$181.30
3	8-98145-253-1	PAD TRIM FRT DOOR LH ?	1	\$270.20
4	1-74338-069-3	CHANNEL DOOR GLASS FRT LH ?	1	\$53.20
5	1-74418-179-3	REGULATOR ASM DOOR LH	1	\$119.70
6	1-74338-071-3	MOTOR POWER WINDOW REG DOOR LH	1	\$37.80
7	1-74518-115-3	LOCK DOOR FRT LH ?	1	\$178.50
8	1-74518-094-3	LINK DOOR LOCK INSIDE ?	1	\$9.10
9	1-09983-151-1	GROMMET SCREW DOOR PAD	2	\$2.80
10	1-09987-272-0	CLIP DOOR PAD	2	\$2.80
11	8-94279-043-0	GROMMET SCREW ASY TRAY DOOR	4	\$2.10
12	1-64780-088-3	LH DOOR HINGE UPPER	1	\$87.50
13	1-64780-098-2	LH DOOR HINGE LOWER	1	\$81.00
14	1-09983-160-3	GROMMET LH CORNER PANEL	1	\$3.50
15	1-65671-725-8	FRAME FACIA ?	1	\$307.30
16	1-72418-009-6	PANEL SW INST	1	\$151.90
17	1-65671-828-2	BEZEL ASM LENTER	1	\$42.00
18	1-86815-013-7	TANK ASSM WASHER	1	\$133.70
19	1-83567-877-1	PIPE COOLER EVAP TO TANK	1	\$154.70
20	8-98028-191-0	HOSE FLEX UNIT TO CMPR	1	\$426.30
21	1-82699-585-2	COVER BOX FRAME HARNESS	1	\$22.40
22	1-82699-581-3	BOX CONN FRT PNL ?	1	\$120.40
23	1-82699-582-1	COVER CONNETOR BOX FRT PNL	1	\$29.40
24	1835611822	BLOWER UNIT	1	\$1,013.60
25	8-98238-476-0	HEATER UNIT	1	\$551.60
26	8-98055-383-0	COVER	1	TBA
27		COVER	1	TBA

Part Cost

Labour (Bodywork, Mech, Elect)

Total Cost (Excluded GST)

ASUL CURK
11/03/19



Repair Estimates

Date: 02/02/2019

From:

Kok Tong Transport & Engineering
Works Pte Ltd
11, Sungei Kadut, Street 2, Singapore 729232.

Tel: 68045046,
Contact person: Chua Zongyu
HP: 96728578
DOA: 29/01/2019
Policy No: DMCVSN 1763211801

To:

China Taiping Insurance (Singapore) Pte. Ltd
3 Anson Road # 16-00 Spring Leaf Tower
S 079909

Tel: 63896111
Attn:
HP:
Vehicle No: XE3554M
Chassis No: JALCYZ52KH7000065

Sr No	Part	Description	Qty	Total Price
1	8-98130-331-1	BUMPER ASM <i>PA</i>	1	\$1,100.00
2	1-86792-077-0	BUMPER LID RH <i>X SUC</i>	1	\$100.00
3	1-86792-076-0	BUMPER LID LH <i>PA</i>	1	\$100.00
4	1-71707-177-1	LH MIRROR STAY <i>PA</i>	1	\$145.60
5	1-71798-829-1	LH MIRROR STAY BRACKET <i>PA</i>	1	\$28.70
6	1-71797-809-2	LH BRACKET OUTSIDE MIRROR <i>cut</i>	1	\$21.00
7	1-71798-732-0	COVER, STAY OUTSIDE MIRROR <i>Ang CRA</i>	1	\$14.00
8	1-71798-733-0	COVER, STAY OUTSIDE MIRROR <i>MIS</i>	1	\$14.00
9	1-86855-031-0	POWER UNIT, MIRROR STAY <i>X an</i>	1	\$304.50
10	1-71998-939-3	GRIP, ASSIST FRT PANEL LH <i>PA</i>	1	\$42.70
11	1-71998-940-3	GRIP, ASSIST FRT PANEL RH <i>PA</i>	1	\$42.70
12	1-21410-933-2	RADIATOR ASM <i>CRA</i>	1	\$4,175.50
13	1-14431-060-1	COOLER, CHARGE AIR <i>X an</i>	1	\$4,294.50
14	1-76210-704-0	EMBLEM, RAD GRILLE <i>cut</i>	1	\$109.20
15	1-76217-189-0	DECAL MODEL <i>an</i>	1	\$18.20
16	1-83312-112-2	LINK ASM, FRT WIPER <i>PA</i>	1	\$174.30
17	1-86810-122-0	BRACKET, WIPER MOTOR <i>PA ? PA</i>	1	\$250.00
18	1-86810-121-0	MOTOR ASM, WIPER <i>PA ? PA</i>	1	\$459.90
19	1-76117-057-0	WINDSHIELD GLASS <i>an cut</i>	1	\$1,507.80
20	1-76737-158-4	WEATHER STRIP <i>an</i>	1	\$204.40
21	1-61281-410-2	FRT PILLAR LH <i>PA</i>	1	\$550.00
22	1-61270-773-3	LH PANEL OUTER BACK CORNER <i>repair</i>	1	\$494.90
23	8-98125-810-4	CLOSING SIDE STEP LH <i>PA</i>	1	\$222.60
24	1-64080-394-2	LH DOOR ASM <i>PA</i>	1	\$1,500.00
25	1-71101-023-1	FRT PANEL <i>PA</i>	1	\$1,127.00
26	1-71117-270-1	GRILLE LH <i>CRA</i>	1	\$46.20
27	1-71117-269-1	GRILLE RH <i>X SUC</i>	1	\$46.20
28	1-71117-268-2	GRILLE CENTER <i>PA</i>	1	\$129.50
29	1-71107-864-0	PANEL SUPPORT ASM <i>CRA</i>	1	\$132.30
30	1-79347-007-3	CABLE FRT LID <i>X SUC</i>	1	\$26.60
31	1-65473-144-0	WIPER PANEL <i>PA</i>	1	\$115.50
32	1-79317-026-1	LOCK ASM FRT LID LH <i>PA</i>	1	\$44.80
33	1-79317-025-1	LOCK ASM FRT LID RH <i>X SUC</i>	1	\$44.80
34	1-79318-008-1	STRIKER FRT LID <i>an</i>	2	\$22.40
35	1-65473-185-4	LH CORNER PANEL <i>CRA</i>	1	\$336.70

13,361.50

36	8-98154-745-1	LH CABIN FENDER	CRA ✓	1	\$486.50
37	8-98105-664-1	LH DOOR FENDER	DE ✓	1	\$240.00
38	NIL	PAINT		1	\$1,800.00

Part Cost

\$20,173.00

Labour (Bodywork, Mech, Elect)

\$3,120.00

Total Cost (Excluded GST)

\$23,293.00

3400 } 1400 } 2000

Paul
14/2/19

Hp 90010068

14 days

4s

23486.50

12/04/19 @ 0900hrs

EXCESS: 1500

Revert

Resurvey after repair

Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modifications are allowed
- Supplementary items must be approved and is subject to final approval of the insurance Company

Acknowledged by Repairer:
Signature:
Date:



Repair Estimates

From:

Kok Tong Transport & Engineering
Works Pte Ltd
11, Sungai Kadut, Street 2, Singapore 729232.

Tel: 68045046,
Contact person: Chua Zongyu
HP: 96728578
DOA: 29/01/2019
Policy No: DMCVSN 1763211801

To:

China Taiping Insurance (Singapore) Pte. Ltd
3 Anson Road # 16-00 Spring Leaf Tower
S 079909

Tel: 63896111
Attn:
HP:
Vehicle No: XE3554M
Chassis No: JALCYZ52KH7000065

Date: 8/03/2019

Sr No	Part	Description	Qty	Total Price
1	8-97608-505-1	LH HEAD LAMP BRACKET <i>repair</i>	1	\$210.70
2	8-98121-414-3	RH HEAD LAMP BRACKET <i>repair</i>	1	\$181.30
3	8-98145-253-1	PAD TRIM FRT DOOR LH <i>car</i>	1	\$270.20
4	1-74338-069-3	CHANNEL DOOR GLASS FRT LH <i>bt</i>	1	\$53.20
5	1-74418-179-3	REGULATOR ASM DOOR LH <i>bt</i>	1	\$119.70
6	1-74338-071-3	MOTOR POWER WINDOW REG DOOR LH <i>me</i>	1	\$37.80
7	1-74518-115-3	LOCK DOOR FRT LH <i>CR</i>	1	\$178.50
8	1-74518-094-3	LINK DOOR LOCK INSIDE <i>bt</i>	1	\$9.10
9	1-09983-151-1	GROMMET SCREW DOOR PAD <i>me</i>	2	\$2.80
10	1-09987-272-0	CLIP DOOR PAD <i>me</i>	2	\$2.80
11	8-94279-043-0	GROMMET SCREW ASY TRAY DOOR <i>me</i>	4	\$2.10
12	1-64780-088-3	LH DOOR HINGE UPPER <i>bt</i>	1	\$87.50
13	1-64780-098-2	LH DOOR HINGE LOWER <i>bt</i>	1	\$81.00
14	1-09983-160-3	GROMMET LH CORNER PANEL <i>me</i>	1	\$3.50
15	1-65671-725-8	FRAME FACIA <i>bt</i>	1	\$307.30
16	1-72418-009-6	PANEL SW INST <i>bt</i>	1	\$151.90
17	1-65671-828-2	BEZEL ASM LENTER <i>me</i>	1	\$42.00
18	1-86815-013-7	TANK ASSM WASHER <i>DE</i>	1	\$133.70
19	1-83567-877-1	PIPE COOLER EVAP TO TANK <i>bt</i>	1	\$154.70
20	8-98028-191-0	HOSE FLEX UNIT TO CMPR <i>bt</i>	1	\$426.30
21	1-82699-585-2	COVER BOX FRAME HARNESS <i>CR</i>	1	\$22.40
22	1-82699-581-3	BOX CONN FRT PNL <i>car</i>	1	\$120.40
23	1-82699-582-1	COVER CONNETOR BOX FRT PNL <i>CR</i>	1	\$29.40
24	1835611822	BLOWER UNIT <i>CR</i>	1	\$1,013.60
25	8-98238-476-0	HEATER UNIT <i>bt</i>	1	\$551.60
26	8-98055-383-0	COVER <i>2 ? de X sul</i>	1	TBA
27		COVER <i>1 - de X sul</i>	1	TBA

Part Cost

Labour (Bodywork, Mech, Elect)

Total Cost (Excluded GST)

LIGK Auto Consultants hereby notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

Faruk (LKK)
11/03/19

2925.10

1763.4000

4193.50

14,588.55
3,400.00
17,988.55
20%

4/5-14,400

14 days

Lumpsum

14,390.84

3201.70

17,163

1520

14,588.55

...CLAIM SUBFOLDER...(Pending for Survey Report)

CLAIM SUBFOLDER TRACKING							
Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'd	Status
Main	11 Feb 2019		11 Feb 2019 14:39 Edit Adj Rpt	S\$14,400.00 Edit Estimates	S\$14,400.00 View Rpt		Pending for Survey Report Cancel Case

Main	Reference	Claim Details	Documents	Show All					
CLAIM SUBFOLDER DETAILS [Created by Insurer]									
Insured:	KOK TONG TRANSPORT & ENGINEERING WORKS PTE LTD. Co. Reg. No.: -								
Vehicle Reg. No.:	XE3554M	Date of Loss:	29/01/2019 15:00 - :59 [15 Months and 18 Days From LTA Reg Date (Man Yr)]						
Claim Type:	OD / SNM19D200551C01	Policy/Cover Note No.:	DMCVSN1763211801 (Comprehensive)						
		Excess:	S\$1,500.00						
Repairer:	Kok Tong Transport & Engineering Works Pte Ltd (HQ) 11 Sungei Kadut Street 2., 729232 Sungei Kadut - Tel:								
Handling Insurer:	China Taiping Insurance (Singapore) Pte. Ltd. (HQ) - Tel: 6389 6111 ... [Handled by Chong Boon Sen]								
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Handled by MOHD RASUL] ... [Final Rpt due 20/02/2019]								
Driver/Custodian:	TAN YEW LONG (30 / Male) , NRIC: G8001917W, Tel: +6582283380 Email: NOEMAIL								
Adj Asg. Remarks:	SURVEY REVERT								
ASSOCIATED MAIL RECEIVED View All Compose Case Mail									
- CHINA_TAIPING (14/03/2019): Alert - Adj Mandate Approved (S\$25554.00) - XE3554M - Claim Handler: Chong Boon ... - CHINA_TAIPING (15/02/2019): Alert - Adj Mandate Approved (S\$17100.00) - XE3554M - Claim Handler: Chong Boon ...									
ALL ASSOCIATED TASKS View All Search Tasks Create New Task Complete									
Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

Claim Documents

*XE3554M (SNM19D200551C01)

OD

Jan 29 2019 3:00PM

[KOK TONG TRANSPORT & ENGINEERING WORKS PTE LTD]

Kok Tong Transport & Engineering Works Pte Ltd

Upload Documents		Upload Photos	Compose New Letter	View View in Browser	
Assessment Reports				1 per page	☒
No	Finalized On	National Assessment Centre Services (Ubi)		Thumbnail	Print
1	30/01/19 11:27	Accident Statement		Load HTM	
No	Finalized On	LKK Auto Consultants Pte Ltd (HQ)		Thumbnail	Print
1	12/02/19 15:37	Adjuster Immediate Advice		Load HTM	
2	12/03/19 09:50	Adjuster Immediate Advice		Load HTM	
Photos/Images				3 per page	☒
No	Finalized On	National Assessment Centre Services (Ubi)		Thumbnail	Print
1	30/01/19 11:25	Accident Photo [Linked Accident Report Documents]		Load JPG	☒
2	30/01/19 11:25	Accident Photo [Linked Accident Report Documents]		Load JPG	☒
3	30/01/19 11:25	Accident Photo [Linked Accident Report Documents]		Load JPG	☒
4	30/01/19 11:25	Accident Photo [Linked Accident Report Documents]		Load JPG	☒
5	30/01/19 11:25	Accident Photo [Linked Accident Report Documents]		Load JPG	☒
6	30/01/19 11:25	Accident Photo [Linked Accident Report Documents]		Load JPG	☒
7	30/01/19 11:25	Accident Photo [Linked Accident Report Documents]		Load JPG	☒
8	30/01/19 11:25	Accident Photo [Linked Accident Report Documents]		Load JPG	☒
9	30/01/19 11:25	Accident Photo [Linked Accident Report Documents]		Load JPG	☒
10	30/01/19 11:25	Accident Photo [Linked Accident Report Documents]		Load JPG	☒
11	30/01/19 11:25	Accident Photo [Linked Accident Report Documents]		Load JPG	☒
12	30/01/19 11:25	Accident Photo [Linked Accident Report Documents]		Load JPG	☒
13	30/01/19 11:25	Accident Photo [Linked Accident Report Documents]		Load JPG	☒
14	30/01/19 11:25	Accident Photo [Linked Accident Report Documents]		Load JPG	☒
15	30/01/19 11:25	Accident Photo [Linked Accident Report Documents]		Load JPG	☒
16	30/01/19 11:25	Accident Photo [Linked Accident Report Documents]		Load JPG	☒
17	30/01/19 11:25	Accident Photo [Linked Accident Report Documents]		Load JPG	☒
18	30/01/19 11:25	Accident Photo [Linked Accident Report Documents]		Load JPG	☒
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)		Thumbnail	Print
1	12/03/19 09:52	Chassis Number		Load JPG	☒
2	12/03/19 09:52	General View		Load JPG	☒
3	12/03/19 09:52	General View		Load JPG	☒
4	12/03/19 09:52	General View		Load JPG	☒
5	12/03/19 09:52	General View		Load JPG	☒
6	12/03/19 09:52	General View		Load JPG	☒
7	12/03/19 09:52	General View		Load JPG	☒
8	12/03/19 09:52	General View		Load JPG	☒

Assessment Reports			1 per page	☒
No	Finalized On	National Assessment Centre Services (Ubi)	Thumbnail	Print
				☒
9	12/03/19 09:52	General View	 Load JPG	☒
10	12/03/19 09:52	General View	 Load JPG	☒
11	12/03/19 09:52	General View	 Load JPG	☒
12	12/03/19 09:52	General View	 Load JPG	☒
13	12/03/19 09:52	General View	 Load JPG	☒
14	12/03/19 09:52	General View	 Load JPG	☒
15	12/03/19 09:52	General View	 Load JPG	☒
16	12/03/19 09:52	General View	 Load JPG	☒
17	12/03/19 09:52	General View	 Load JPG	☒
18	12/03/19 09:52	General View	 Load JPG	☒
19	12/03/19 09:52	General View	 Load JPG	☒
20	12/03/19 09:52	General View	 Load JPG	☒
21	12/03/19 09:52	General View	 Load JPG	☒
22	12/03/19 09:52	General View	 Load JPG	☒
23	12/03/19 09:52	General View	 Load JPG	☒
24	12/03/19 09:52	General View	 Load JPG	☒
25	12/03/19 09:52	General View	 Load JPG	☒
26	12/03/19 09:52	General View	 Load JPG	☒
27	12/03/19 09:52	General View	 Load JPG	☒
28	12/03/19 09:52	General View	 Load JPG	☒
29	12/03/19 09:52	General View	 Load JPG	☒
30	12/03/19 09:52	General View	 Load JPG	☒
31	12/03/19 09:52	General View	 Load JPG	☒
32	12/03/19 09:52	General View	 Load JPG	☒
33	12/03/19 09:52	General View	 Load JPG	☒
34	12/03/19 09:52	General View	 Load JPG	☒
35	12/03/19 09:52	General View	 Load JPG	☒
36	12/03/19 09:52	General View	 Load JPG	☒
37	12/03/19 09:52	General View	 Load JPG	☒
38	12/03/19 09:52	General View	 Load JPG	☒
39	12/03/19 09:52	General View	 Load JPG	☒
40	12/03/19 09:52	General View	 Load JPG	☒
41	12/03/19 09:52	General View	 Load JPG	☒
42	12/03/19 09:52	General View	 Load JPG	☒
43	12/03/19 09:52	General View	 Load JPG	☒
44	12/03/19 09:52	General View	 Load JPG	☒
45	12/03/19 09:52	General View	 Load JPG	☒
46	12/03/19 09:52	General View	 Load JPG	☒
47	12/03/19 09:52	General View	 Load JPG	☒
48	12/03/19 09:52	General View	 Load JPG	☒
49	12/03/19 09:52	General View	 Load JPG	☒
50	12/03/19 09:52	General View	 Load JPG	☒
51	12/03/19 09:52	General View	 Load JPG	☒
52	12/03/19 09:52	General View	 Load JPG	☒
53	12/03/19 09:52	General View	 Load JPG	☒
54	12/03/19 09:52	General View	 Load JPG	☒
55	12/03/19 09:52	General View	 Load JPG	☒
56	12/03/19 09:52	General View	 Load JPG	☒
57	12/03/19 09:52	General View	 Load JPG	☒

Assessment Reports			1 per page	☒
No	Finalized On	National Assessment Centre Services (Ubi)	Thumbnail	Print
58	12/03/19 09:52	General View	 Load JPG	☒
59	12/03/19 09:52	General View	 Load JPG	☒
60	12/03/19 09:52	General View	 Load JPG	☒
61	12/03/19 09:52	General View	 Load JPG	☒
62	12/03/19 09:52	General View	 Load JPG	☒
63	12/03/19 09:52	General View	 Load JPG	☒
64	12/03/19 09:52	General View	 Load JPG	☒
65	12/03/19 09:52	General View	 Load JPG	☒
66	12/03/19 09:52	General View	 Load JPG	☒
67	12/03/19 09:52	General View	 Load JPG	☒
68	12/03/19 09:52	General View	 Load JPG	☒
69	12/03/19 09:52	General View	 Load JPG	☒
70	12/03/19 09:52	General View	 Load JPG	☒
71	12/03/19 09:52	General View	 Load JPG	☒
72	12/03/19 09:52	General View	 Load JPG	☒
73	12/03/19 09:52	General View	 Load JPG	☒
74	12/03/19 09:52	General View	 Load JPG	☒
75	12/03/19 09:52	General View	 Load JPG	☒
76	12/03/19 09:52	General View	 Load JPG	☒
77	12/03/19 09:52	General View	 Load JPG	☒
78	12/03/19 09:52	General View	 Load JPG	☒
79	12/03/19 09:52	General View	 Load JPG	☒
80	12/03/19 09:52	General View	 Load JPG	☒
81	12/03/19 09:52	General View	 Load JPG	☒
82	12/03/19 09:52	General View	 Load JPG	☒
83	12/03/19 09:52	General View	 Load JPG	☒
84	12/03/19 09:52	General View	 Load JPG	☒
85	12/03/19 09:52	General View	 Load JPG	☒
86	12/03/19 09:52	General View	 Load JPG	☒
87	12/03/19 09:52	General View	 Load JPG	☒
88	12/03/19 09:52	General View	 Load JPG	☒
89	12/03/19 09:52	General View	 Load JPG	☒
90	12/03/19 09:52	General View	 Load JPG	☒
91	12/03/19 09:52	General View	 Load JPG	☒
92	12/03/19 09:52	General View	 Load JPG	☒
93	12/03/19 09:52	General View	 Load JPG	☒
94	12/03/19 09:52	General View	 Load JPG	☒
95	12/03/19 09:52	General View	 Load JPG	☒
96	12/03/19 09:52	General View	 Load JPG	☒
97	12/03/19 09:52	General View	 Load JPG	☒
98	12/03/19 09:52	General View	 Load JPG	☒
99	12/03/19 09:52	General View	 Load JPG	☒
100	12/03/19 09:52	General View	 Load JPG	☒
101	12/03/19 09:52	General View	 Load JPG	☒
102	12/03/19 09:52	General View	 Load JPG	☒
103	12/03/19 09:52	General View	 Load JPG	☒
104	12/03/19 09:52	General View	 Load JPG	☒
105	12/03/19 09:52	General View	 Load JPG	☒
106	12/03/19 09:52	General View	 Load JPG	☒
107	12/03/19 09:52	General View	 Load JPG	☒

Assessment Reports			1 per page	☒
No	Finalized On	National Assessment Centre Services (Ubi)	Thumbnail	Print
108	12/03/19 09:52	General View	 Load JPG	☒
109	12/03/19 09:52	General View	 Load JPG	☒
110	12/03/19 09:52	General View	 Load JPG	☒
111	12/03/19 09:52	General View	 Load JPG	☒
112	12/03/19 09:52	General View	 Load JPG	☒
113	12/03/19 09:52	General View	 Load JPG	☒
114	12/03/19 09:52	General View	 Load JPG	☒
115	12/03/19 09:53	Reinspection Photo	 Load JPG	☒
116	12/03/19 09:53	Reinspection Photo	 Load JPG	☒
117	12/03/19 09:53	Reinspection Photo	 Load JPG	☒
118	12/03/19 09:53	Reinspection Photo	 Load JPG	☒
119	12/03/19 09:53	Reinspection Photo	 Load JPG	☒
120	12/03/19 09:53	Reinspection Photo	 Load JPG	☒
121	12/03/19 09:53	Reinspection Photo	 Load JPG	☒
122	12/03/19 09:53	Reinspection Photo	 Load JPG	☒
123	12/03/19 09:53	Reinspection Photo	 Load JPG	☒
124	12/03/19 09:53	Reinspection Photo	 Load JPG	☒
125	12/03/19 09:53	Reinspection Photo	 Load JPG	☒
126	12/03/19 09:53	Reinspection Photo	 Load JPG	☒
127	12/03/19 09:53	Reinspection Photo	 Load JPG	☒
128	12/03/19 09:53	Reinspection Photo	 Load JPG	☒
129	12/03/19 09:53	Reinspection Photo	 Load JPG	☒
130	12/03/19 09:53	Reinspection Photo	 Load JPG	☒
131	12/03/19 09:53	Reinspection Photo	 Load JPG	☒
132	12/03/19 09:53	Reinspection Photo	 Load JPG	☒
133	12/03/19 09:53	Reinspection Photo	 Load JPG	☒
134	12/03/19 09:53	Reinspection Photo	 Load JPG	☒
135	12/03/19 09:53	Reinspection Photo	 Load JPG	☒
136	12/03/19 09:53	Reinspection Photo	 Load JPG	☒
137	12/03/19 09:53	Reinspection Photo	 Load JPG	☒
138	12/03/19 09:53	Reinspection Photo	 Load JPG	☒
139	12/03/19 09:53	Reinspection Photo	 Load JPG	☒
140	12/03/19 09:53	Reinspection Photo	 Load JPG	☒
141	12/03/19 09:53	Reinspection Photo	 Load JPG	☒
142	12/03/19 09:53	Reinspection Photo	 Load JPG	☒
143	12/03/19 09:53	Reinspection Photo	 Load JPG	☒
144	12/03/19 09:53	Reinspection Photo	 Load JPG	☒
145	12/03/19 09:53	Reinspection Photo	 Load JPG	☒
146	12/03/19 09:53	Reinspection Photo	 Load JPG	☒
147	12/03/19 09:53	Reinspection Photo	 Load JPG	☒
148	12/03/19 09:53	Reinspection Photo	 Load JPG	☒
149	12/03/19 09:53	Reinspection Photo	 Load JPG	☒
150	12/03/19 09:53	Reinspection Photo	 Load JPG	☒
151	12/03/19 09:53	Reinspection Photo	 Load JPG	☒
152	12/03/19 09:53	Reinspection Photo	 Load JPG	☒
153	12/03/19 09:53	Reinspection Photo	 Load JPG	☒
154	12/03/19 09:53	Reinspection Photo	 Load JPG	☒
155	12/03/19 09:53	Reinspection Photo	 Load JPG	☒
156	12/03/19 09:53	Reinspection Photo	 Load JPG	☒
157	12/03/19 09:53	Reinspection Photo	 Load JPG	☒

Assessment Reports			1 per page	☒
No	Finalized On	National Assessment Centre Services (Ubi)	Thumbnail	Print
158	12/03/19 09:53	Reinspection Photo	 Load JPG	☒
159	12/06/19 10:49	Reinspection Photo	 Load JPG	☒
160	12/06/19 10:49	Reinspection Photo	 Load JPG	☒
161	12/06/19 10:49	Reinspection Photo	 Load JPG	☒
162	12/06/19 10:49	Reinspection Photo	 Load JPG	☒
163	12/06/19 10:49	Reinspection Photo	 Load JPG	☒
164	12/06/19 10:49	Reinspection Photo	 Load JPG	☒
165	12/06/19 10:49	Reinspection Photo	 Load JPG	☒
166	12/06/19 10:49	Reinspection Photo	 Load JPG	☒
167	12/06/19 10:49	Reinspection Photo	 Load JPG	☒
168	12/06/19 10:49	Reinspection Photo	 Load JPG	☒
169	12/06/19 10:49	Reinspection Photo	 Load JPG	☒
170	12/06/19 10:49	Reinspection Photo	 Load JPG	☒
171	12/06/19 10:49	Reinspection Photo	 Load JPG	☒
172	12/06/19 10:49	Reinspection Photo	 Load JPG	☒
173	12/06/19 10:49	Reinspection Photo	 Load JPG	☒
174	12/06/19 10:49	Reinspection Photo	 Load JPG	☒
175	12/06/19 10:49	Reinspection Photo	 Load JPG	☒
176	12/06/19 10:49	Reinspection Photo	 Load JPG	☒
177	12/06/19 10:49	Reinspection Photo	 Load JPG	☒
178	12/06/19 10:49	Reinspection Photo	 Load JPG	☒
179	12/06/19 10:49	Reinspection Photo	 Load JPG	☒
180	12/06/19 10:49	Reinspection Photo	 Load JPG	☒
181	12/06/19 10:49	Reinspection Photo	 Load JPG	☒
182	12/06/19 10:49	Reinspection Photo	 Load JPG	☒
183	12/06/19 10:49	Reinspection Photo	 Load JPG	☒
184	12/06/19 10:49	Reinspection Photo	 Load JPG	☒
185	12/06/19 10:49	Reinspection Photo	 Load JPG	☒
186	12/06/19 10:49	Reinspection Photo	 Load JPG	☒
187	12/06/19 10:49	Reinspection Photo	 Load JPG	☒
188	12/06/19 10:49	Reinspection Photo	 Load JPG	☒
189	12/06/19 10:49	Reinspection Photo	 Load JPG	☒
190	12/06/19 10:49	Reinspection Photo	 Load JPG	☒
191	12/06/19 10:49	Reinspection Photo	 Load JPG	☒
192	12/06/19 10:49	Reinspection Photo	 Load JPG	☒
193	12/06/19 10:49	Reinspection Photo	 Load JPG	☒
194	12/06/19 10:49	Reinspection Photo	 Load JPG	☒
195	12/06/19 10:49	Reinspection Photo	 Load JPG	☒
196	12/06/19 10:49	Reinspection Photo	 Load JPG	☒
197	12/06/19 10:49	Reinspection Photo	 Load JPG	☒
198	12/06/19 10:49	Reinspection Photo	 Load JPG	☒
199	12/06/19 10:49	Reinspection Photo	 Load JPG	☒
200	12/06/19 10:49	Reinspection Photo	 Load JPG	☒
Documentation			1 per page	☒
No	Finalized On	China Taiping Insurance (Singapore) Pte. Ltd. (HQ)	Thumbnail	Print
1	11/02/19 14:40	OD ESTIMATE AND CONTACT DETAIL	 Load PDF	
No	Finalized On	National Assessment Centre Services (Ubi)	Thumbnail	Print
1	30/01/19 11:20	Accident Sketch Plan [Linked Accident Report Documents]	 Load JPG	☒
2	30/01/19 11:20	Accident Sketch Plan [Linked Accident Report Documents]	 Load JPG	☒

Assessment Reports			1 per page	☒
No	Finalized On	National Assessment Centre Services (Ubi)	Thumbnail	Print
3	30/01/19 11:20	DRIVING DOC [Linked Accident Report Documents]	 Load JPG	☒
4	30/01/19 11:21	DRIVING DOC [Linked Accident Report Documents]	 Load JPG	☒
5	30/01/19 11:21	DRIVING DOC [Linked Accident Report Documents]	 Load JPG	☒
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
1	12/02/19 14:42	MARK ESTIMATE	 Load PDF	
2	12/03/19 09:53	SUPPLEMENTARY.pdf	 Load PDF	
3	12/06/19 10:50	ESTIMATE & SUPP MARKED.pdf	 Load PDF	
4	13/06/19 13:05	DV.pdf	 Load PDF	

Linked Accident Report Documents

Assessment Reports			1 per page	☒
No	Finalized On	National Assessment Centre Services (Ubi)	Thumbnail	Print
1	30/01/19 11:27	Accident Statement	 Load HTM	
Photos/Images			3 per page	☒
No	Finalized On	National Assessment Centre Services (Ubi)	Thumbnail	Print
1	30/01/19 11:25	Accident Photo	 Load JPG	☒
2	30/01/19 11:25	Accident Photo	 Load JPG	☒
3	30/01/19 11:25	Accident Photo	 Load JPG	☒
4	30/01/19 11:25	Accident Photo	 Load JPG	☒
5	30/01/19 11:25	Accident Photo	 Load JPG	☒
6	30/01/19 11:25	Accident Photo	 Load JPG	☒
7	30/01/19 11:25	Accident Photo	 Load JPG	☒
8	30/01/19 11:25	Accident Photo	 Load JPG	☒
9	30/01/19 11:25	Accident Photo	 Load JPG	☒
10	30/01/19 11:25	Accident Photo	 Load JPG	☒
11	30/01/19 11:25	Accident Photo	 Load JPG	☒
12	30/01/19 11:25	Accident Photo	 Load JPG	☒
13	30/01/19 11:25	Accident Photo	 Load JPG	☒
14	30/01/19 11:25	Accident Photo	 Load JPG	☒
15	30/01/19 11:25	Accident Photo	 Load JPG	☒
16	30/01/19 11:25	Accident Photo	 Load JPG	☒
17	30/01/19 11:25	Accident Photo	 Load JPG	☒
18	30/01/19 11:25	Accident Photo	 Load JPG	☒
Documentation			1 per page	☒
No	Finalized On	National Assessment Centre Services (Ubi)	Thumbnail	Print
1	30/01/19 11:20	Accident Sketch Plan	 Load JPG	☒
2	30/01/19 11:20	Accident Sketch Plan	 Load JPG	☒
3	30/01/19 11:20	DRIVING DOC	 Load JPG	☒
4	30/01/19 11:21	DRIVING DOC	 Load JPG	☒
5	30/01/19 11:21	DRIVING DOC	 Load JPG	☒

Documents Checklist

DOCUMENTS CHECKLIST	Reset	Save	Print
There are no document checklists configured.			

Our Checklist Remarks - LKK Auto Consultants Pte Ltd (HQ)**Show Remarks To:** ☐ Handling InsurerNote: Remarks are private unless you show it to other parties.

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

China Taiping Insurance (Singapore) Pte. Ltd.
3 Anson Road, #16-00 Springleaf Tower
Singapore 079909

Our File No: CS/CT119002389/R1SD3E2

Date: 01/07/2019

REFERENCE

Insured/Claimant: KOK TONG TRANSPORT &
ENGINEERING WORKS PTE LTD

Policy No: DMCVSN1763211801

Date of Loss: 29/01/2019

Nature of
Claim: OD

Claim
No: SNM19D200551C01

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	XE3554M	Engine No:	6WG1432968
Make & Model:	ISUZU CYZ52K, 15.7 D (M)	Chassis No:	JALCYZ52KH7000065
Reg. Date:	11/10/2017 (Man. Year: 2017)	Odometer:	0 km
Colour:	White		
Engine Capacity:	15681 cc		
Market Value/New Car Price:	S\$140,000.00		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	295/80 R22.5	Rear Tyre Size:	295/80 R22.5 (D)
Front Left Side:	Double Happiness 8 mm	Rear Left Side:	Double Happiness 8/8 mm
Front Right Side:	Double Happiness 8 mm	Rear Right Side:	Double Happiness 8/8 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	22,866.50	14,588.55	8,277.95	36.20
Miscellaneous Items	0.00	0.00	0.00	
Labour	4,620.00	3,400.00	1,220.00	26.41
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	27,486.50	17,988.55	9,497.95	34.55
Approved Total (Overridden) (S\$)		14,400.00		
- Excess (S\$)	1,500.00	1,500.00	0.00	0.00
(S\$)	25,986.50	12,900.00	13,086.50	50.36
+ GST 7.00/7.00% (S\$)	1,819.06	903.00	916.06	50.36
Nett Amount (S\$)	27,805.56	13,803.00	14,002.56	50.36

INSPECTION

Date of Assignment: 11/02/2019
Date Inspected: 12/02/2019 Inspected At:

Kok Tong Transport & Engineering Works
Pte Ltd (HQ)
11 Sungei Kadut Street 2,
Singapore 729232

Estimated Period of Repair: 14.0 days

Adjuster: MOHD RASUL**Manager:** Hiew May Fung

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference

Part Source:	(Last Synchronised: 01 Jul 2019)	
Parts:	N/A	ISUZU CYZ52K 15.7 D (M) (Model not available in database)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for XE3554M)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*BUMPER ASM	Bent	1,100.00 F	*1,100.00 FL
2	1		*BUMPER LID RH	Serviceable	100.00 F	*- FL
3	1		*BUMPER LID LH	Bent	100.00 F	*100.00 FL
4	1		*LH MIRROR STAY	Bent	145.60 F	*145.60 FL
5	1		*LH MIRROR STAY BRACKET	Bent	28.70 F	*28.70 FL
6	1		*LH BRACKET OUTSIDE MIRROR	Cut	21.00 F	*21.00 FL
7	1		*COVER, STAY OUTSIDE MIRROR	Cracked	14.00 F	*14.00 FL
8	1		*COVER, STAY OUTSIDE MIRROR	Missing	14.00 F	*14.00 FL
9	1		*POWER UNIT, MIRROR STAY	Not Necessary	304.50 F	*- FL
10	1		*GRIP, ASSIST FRT PANEL LH	Bent	42.70 F	*42.70 FL
11	1		*GRIP, ASSIST FRT PANEL RH	Bent	42.70 F	*42.70 FL
12	1		*RADIATOR ASM	Cracked	4,175.50 F	*4,175.50 FL
13	1		*COOLER, CHARGE AIR	Not Necessary	4,294.50 F	*- FL
14	1		*EMBLEM, RAD GRILLE	Cut	109.20 F	*109.20 FL
15	1		*DECAL MODEL	Necessary	18.20 F	*18.20 FL
16	1		*LINK ASM, FRT WIPER	Bent	174.30 F	*174.30 FL
17	1		*BRACKET, WIPER MOTOR	Bent	250.00 F	*250.00 FL
18	1		*MOTOR ASM, WIPER	Buckled	459.90 F	*459.90 FL
19	1		*WINDSHIELD GLASS	Cracked	1,507.80 F	*1,507.80 FL
20	1		*WEATHER STRIP	Necessary	204.40 F	*204.40 FL
21	1		*FRT PILLAR LH	Buckled	550.00 F	*550.00 FL
22	1		*LH PANEL OUTER BACK CORNER	Repair	494.90 F	*- FL
23	1		*CLOSING SIDE STEP LH	Deformed	222.60 F	*222.60 FL
24	1		*LH DOOR ASM	Bent	1,500.00 F	*1,500.00 FL
25	1		*FRT PANEL	Deformed	1,127.00 F	*1,127.00 FL
26	1		*GRILLE LH	Cracked	46.20 F	*46.20 FL
27	1		*GRILLE RH	Serviceable	46.20 F	*- FL
28	1		*GRILLE CENTER	Deformed	129.50 F	*129.50 FL
29	1		*PANEL SUPPORT ASM	Cracked	132.30 F	*132.30 FL
30	1		*CABLE FRT LID	Serviceable	26.60 F	*- FL
31	1		*WIPER PANEL	Bent	115.50 F	*115.50 FL
32	1		*LOCK ASM FRT LID LH	Jammed	44.80 F	*44.80 FL
33	1		*LOCK ASM FRT LID RH	Serviceable	44.80 F	*- FL
34	2		*STRIKER FRT LID	Necessary	22.40 F	*22.40 FL
35	1		*LH CORNER PANEL	Cracked	336.70 F	*336.70 FL
36	1		*LH CABIN FENDER	Cracked	486.50 F	*486.50 FL
37	1		*LH DOOR FENDER	Deformed	240.00 F	*240.00 FL
38	1		*LH HEAD LAMP BRACKET	Repair	210.70 F	*- FL
39	1		*RH HEAD LAMP BRACKET	Repair	181.30 F	*- FL

Report was unsubmitted during this print-out.

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
40	1		*PAD TRIM FRT DOOR LH	Cracked	270.20 F	*270.20 FL
41	1		*CHANNEL DOOR GLASS FRT LH	Bent	53.20 F	*53.20 FL
42	1		*REGULATOR ASM DOOR LH	Bent	119.70 F	*119.70 FL
43	1		*MOTOR POWER WINDOW REG DOOR LH	Not Working	37.80 F	*37.80 FL
44	1		*LOCK DOOR FRT LH	Cracked	178.50 F	*178.50 FL
45	1		*LINK DOOR LOCK INSIDE	Bent	9.10 F	*9.10 FL
46	2		*GROMMET SCREW DOOR PAD	Necessary	2.80 F	*2.80 FL
47	2		*CLIP DOOR PAD	Necessary	2.80 F	*2.80 FL
48	1		*GROMMET SCREW ASY TRAY DOOR (4PCS)	Necessary	2.10 F	*2.10 FL
49	1		*LH DOOR HINGE UPPER	Bent	87.50 F	*87.50 FL
50	1		*LH DOOR HINGE LOWER	Bent	81.00 F	*81.00 FL
51	1		*GROMMET LH CORNER PANEL	Necessary	3.50 F	*3.50 FL
52	1		*FRAME FACIA	Bent	307.30 F	*307.30 FL
53	1		*PANEL SW INST	Bent	151.90 F	*151.90 FL
54	1		*BEZEL ASM LENTER	Necessary	42.00 F	*42.00 FL
55	1		*TANK ASSM WASHER	Deformed	133.70 F	*133.70 FL
56	1		*PIPE COOLER EVAP TO TANK	Bent	154.70 F	*154.70 FL
57	1		*HOSE FLEX UNIT TO CMPR	Bent	426.30 F	*426.30 FL
58	1		*COVER BOX FRAME HARNESS	Cracked	22.40 F	*22.40 FL
59	1		*BOX CONN FRT PNL	Cracked	120.40 F	*120.40 FL
60	1		*COVER CONNETOR BOX FRT PNL	Cracked	29.40 F	*29.40 FL
61	1		*BLOWER UNIT	Cracked	1,013.60 F	*1,013.60 FL
62	1		*HEATER UNIT	Bent	551.60 F	*551.60 FL
63	1		*COVER (NPA)	Serviceable	0.00 F	*- FL
64	1		*COVER (NPA)	Serviceable	0.00 F	*- FL

F=Franchise part. L=ListItemDisc.

Sub Total (\$\$)	22,866.50	17,163.00
- List Item Discount on L Items 0.00/15.00% (\$\$)	0.00	2,574.45

Total Parts (\$\$)	22,866.50	14,588.55
---------------------------	------------------	------------------

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<u>Labour Items</u>				
1	PAINT	New	1,500.00	1,400.00
2	LABOUR (BODYWORK, MECH, ELECT)	New	3,120.00	2,000.00
Gross Labour Cost (S\$)			4,620.00	3,400.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >