



MY CAR CONSULTANT PTE LTD

Reg no.: 201605878Z

Address: 53 Ubi Ave 1 #01-33 Paya Ubi Industrial Park Singapore 408934

HP: 98888885

Estimation

Date: 12 February 2019
Vehicle: SKZ6321A
Make / Model: VOLVO
Chassis: YV1LFA2ACG1055086

No.	Description	Unit	Unit Price	Amount
Parts Replacement:				
1	RH SIDE SILL GARNISH STEP <i>X repair</i>	1		\$ 2,109.34
2	RH SILLGARNISH STEP CHROME <i>- Scr</i>	1		\$ 921.30
				\$ 3,030.64
			Less 10%	\$ 303.06
				\$ 2,727.59
S/NETT ITEMS				
3	RH SILL GARNISH CLIP <i>X UN</i>	1 SET		\$ 40.00
				\$ 40.00
			Parts Total:	\$ 2,767.58
Labour to:				
4	PANEL BEATING ON AFFECTED AREAS			\$ 400.00
5	SPRAY PAINTING ON AFFECTED AREAS			\$ 400.00
6	APPLY ANTI RUST ON AFFECTED AREAS			\$ 60.00
				\$ 860.00
			Grand total:	\$ 3,627.58

2 Days.

part by part.

After repair (New & old)

Caro Corp - 82580282

19/2/19.

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: