

LKK Auto Consultants Pte Ltd

(Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CC4/AIG19002481/GDS3Q2

Date: 29/07/2020

REFERENCE

Handling Insurer: AIG Asia Pacific Insurance Pte. Ltd. Policy No: 0999994639

Claimant
Vehicle No : SKT5827M **Insured Vehicle No :** SKP4466Z

Date of Loss: 29/01/2019 Nature of Claim: TP Claim No: 8229477086SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SKT5827M	Engine No:	P520288037
Make & Model:	MAZDA 3, 1.5 (A)	Chassis No:	JM6BM42A8G0311801
Reg. Date:	16/06/2015 (Man. Year: 2015)	Odometer:	60791 km
Colour:	Red		
Engine Capacity:	1496 cc		
Market Value/New Car Price:	N/A		
Sum Insured (\$\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Engine Modification:	No	Pre-accident Condition:	

CONDITION OF TYRES

Front Tyre Size:	205/60 R16	Rear Tyre Size:	205/60 R16
Front Left Side:	Bridgestone 6 mm	Rear Left Side:	Bridgestone 6 mm
Front Right Side:	Bridgestone 6 mm	Rear Right Side:	Bridgestone 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	7,118.36	2,858.68	4,259.68	59.84
Miscellaneous Items	0.00	0.00	0.00	
Labour	3,060.00	1,350.00	1,710.00	55.88
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (\$\$)	10,178.36	4,208.68	5,969.68	58.65
Approved Total (Overridden) (\$\$)		3,350.00		
Nett Amount (\$\$)	10,178.36	3,350.00	6,828.36	67.09
Global Sum Settlement (\$\$)		0.00		

INSPECTION

Date of Assignment: 12/02/2019

Date Inspected: 13/02/2019 Inspected At: My Car Consultant Pte Ltd (Ubi)
53 Ubi Ave 1, #01-33, Paya Ubi Industrial Park
Singapore 408934

Estimated Period of Repair: 5.0 days

Adjuster: XING GUO QIANG

Manager: CHAN JIA LE

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*BOOTLID	Repair	1,026.70 FL	*- FL
2	1		*BOOTLID EMBLEM LOGO	Necessary	65.80 FL	*65.80 FL
3	1		*BOOTLID EMBLEM MAZDA	Necessary	44.40 FL	*44.40 FL
4	1		*BOOTLID EMBLEM 3	Necessary	32.50 FL	*32.50 FL
5	2		*BOOTLID LAMP	Not Necessary	597.10 FL	*- FL
6	1		*BOOTLID LOCK	Not Necessary	256.40 FL	*- FL
7	1		*BOOTLID LOCK CATCH	Not Necessary	112.90 FL	*- FL
8	2		*BOOTLID HINGE	Not Necessary	113.80 FL	*- FL
9	2		*BOOTLID DAMPER	Not Necessary	171.40 FL	*- FL
10	1		*BOOTLID RUBBER	Not Necessary	130.60 FL	*- FL
11	1		*END PANEL	Buckled	548.10 FL	*447.60 FL
12	1		*END PANEL TOP GARNISH	Deformed	179.45 FL	*179.45 FL
13	1		*REAR BUMPER	Deformed	1,074.80 FL	*1,074.80 FL
14	2		*REAR BUMPER REFLECTOR	Not Necessary	154.90 FL	*- FL
15	2		*REAR BUMPER SIDE RETAINER	Not Necessary	134.30 FL	*- FL
16	2		*REAR BUMPER BRACKET INNER	Not Necessary	121.10 FL	*- FL
17	1		*REAR BUMPER REINFORCEMENT	Bent	591.70 FL	*541.70 FL
18	1		*REAR TAILLAMP	N/S Broken / O/S Not Necessary	2,338.40 FL	*849.60 FL
19	1		*SPARE TYRE TOP BOARD	Not Necessary	453.60 FL	*- FL
20	1		*SET REAR BUMPER CLIP	Necessary	50.00 FS	*30.00 FS
21	1		*SET REAR REVERSE SENSOR	Necessary	400.00 FS	*200.00 FS
22	1		*JOINT SEALANT	Necessary	150.00 FS	*40.00 FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (\$\$)	8,747.95	3,505.85
- List Item Discount on L Items 20.00/20.00% (\$\$)	1,629.59	647.17
Total Parts (\$\$)	7,118.36	2,858.68

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<u>Labour Items</u>				
1	CHECK REAR WIRING AND LIGHTING SYSTEM	New	60.00	30.00
2	REMOVE AND REFIT REAR LINING ,TRIM AND LINING	New	150.00	60.00
3	REMOVE AND RENEW REAR REVERSE SENSOR	New	150.00	40.00
4	REMOVE AND STRAIGHTEN REAR EXHAUST	New	150.00	0.00
5	TRANSFER PARTS ,ATTACHMENT FROM OLD BOOTLID TO NEW	New	200.00	60.00
6	PANEL BEATING ON AFFECTED AREAS	New	1,200.00	500.00
7	SPRAY PAINTING ON AFFECTED AREAS	New	1,000.00	600.00
8	APPLY ANTI RUST ON AFFECTED AREAS	New	150.00	60.00
Gross Labour Cost (\$\$)			3,060.00	1,350.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >