

LKK Auto Consultants Pte Ltd

(Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CC4/FWD19002487/JPA3Q2

Date: 23/06/2020

REFERENCE

Handling Insurer: FWD Singapore Pte. Ltd. Policy No: PNPV2018-00016385

Claimant
Vehicle No : SHC4754X **Insured Vehicle No :** SGP8845J

Date of Loss: 08/02/2019 Nature of Claim: TP Claim No: 1201900004275

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SHC4754X		
Make & Model:	TOYOTA PRIUS TAXI, 1.8 (A)	Engine No:	2ZR1673589
Reg. Date:	01/04/2016 (Man. Year: 2015)	Chassis No:	JTDKN36U805767751
Colour:	Maroon	Odometer:	347048 km
Engine Capacity:	1798 cc		
Market Value/New Car Price:	N/A		
Sum Insured (\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	195/65 R15	Rear Tyre Size:	195/65 R15
Front Left Side:	Falken 6 mm	Rear Left Side:	Falken 6 mm
Front Right Side:	Falken 6 mm	Rear Right Side:	Falken 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	2,953.80	149.40	2,804.40	94.94
Miscellaneous Items	0.00	0.00	0.00	
Labour	1,903.00	870.00	1,033.00	54.28
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Nett Amount (\$\$)	4,856.80	1,019.40	3,837.40	79.01
+ Loss of Use (5.0 x S\$50.00/day) (\$\$)		250.00		
+ Car Rental (5.0 x S\$112.35/day) (\$\$)		561.75		
+ Doc/Search Fee (\$\$)		7.00		
Nett Liability (\$\$)		1,838.15		
Global Sum Settlement (\$\$)		1,830.00		

INSPECTION

Date of Assignment: 11/02/2019

Date Inspected: 13/02/2019 Inspected At:

Smrt Automotive Services Pte Ltd
(HQ)
No. 61 Woodlands Industrial Park E9,
#04-04 Premium Building
Singapore 757047

Estimated Period of Repair: 3.0 days

Adjuster: ONG HWEE JIE

Manager: CHEW HSIAO TONG

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference

Part Source:	MRM-SG	Version: 1.0 (Last Synchronised: 21 Nov 2019)
Parts:	144	TOYOTA PRIUS TAXI 1.8 (A) (Catalogue:Merimen Singapore 1.0)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for SHC4754X)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	2		*PIXEL STICKER (SN)	Necessary	120.00 F	*120.00 F
2	1		*STICKER DECAL 6555 8888 (SN)	Necessary	21.60 F	*21.60 F
3	1		*STICKER DECAL SMRT (SN)	Necessary	7.80 F	*7.80 F
4	1		*BUMPER REAR	Repair	458.60 F	*- F
5	1		*FENDER RR/RH	Repair	766.80 F	*- F
6	1		*WHEEL DISC	Repair	1,484.20 F	*- F
7	1		*BUMPER SIDE RETAINER RR/RH	Not Necessary	94.80 F	*- F
					Total Parts (\$\$)	2,953.80 149.40

F=Franchise part.

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<u>Labour Items</u>				
1	PANEL BEATING & BODY WORK	New	507.00	400.00
2	SPRAY PAINT	New	936.00	450.00
3	TO CHECK WIRING AND SYSTEM FUNCTION	New	80.00	0.00
4	TO APPLY RUST-PROOFING ON AFFECTED AREA	New	100.00	20.00
5	TO DO WHEEL ALIGNMENT /TYRE BALANCING	New	120.00	0.00
6	TO REPLACE SUNDRY PARTS	New	100.00	0.00
7	TO WASH AND VACUUM	New	60.00	0.00
Gross Labour Cost (\$\$)			1,903.00	870.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >