

22/03/2002

ASS. REC. BY:

REF:

es/MSG19002506/Dvd36

Special Instruction:

Survivor
merimen

ASSIGNMENT (Office)

From (Person):

Katherine Wong

of

MS16

Date/Time:

12/2/19 @ 2:09pm

Estimated Cost:

Bill to:

OD TP WS/TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No:

SHD 38194

Insured:

SLR 34834

at Workshop in/s

chunni Motor

Tel:

6542 5119

of

Blk 10 # 01-05/06 AMK

Policy No:

290894760MY

Claim No:

584626

Sum Insured:

Excess:

Make of Veh:

(Client's Record)

D.O.A.

10/02/2019

CA / REV / REP. / REV 24 HRS

up

13/2/19

H.O.D. Endorsement:

Date/Time:

4:05pm @ 12/2/19

Person Contacted:

Lynn

Vehicle:

IN/OUT

Date/Time

Action/Instruction

(✓)

Estimate

SHD 38194-X

SLR 34834-X

20/2/19

Send preli revised via merimen

REF

POLICY NUMBER

COR 2024 Dec

Dec 2016

Form
Estimated Cost
OD / TP / WS / TP RES / OD RES / LVA / HV / MV

Techn. and Vehicle No.

At what time?

or

Insured

Policy No.

Claim No.


Sum Insured

(Client's Record)

Make of Veh.

(Policy Condition)

Remark: The veh had commenced its
repair at the time of inspection.



Bal. or Market Value.

IDAC Accident Report.

Consistent? : Yes or No

GIA / PR Seen

Consistent? : Yes or No

Est. Repair: 9 days Res: Yes or No

Lump Sum: 20 % 3 Val: Yes or No

GA / REV / REP. / 24 HRS

Date: Person Contacted

Vehicle: IN / OUT

Veh No: SHD 38194 To Regn Dec 2016
Type: M Car / M Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make: Hyundai I40 CC: 1685

Colour: Blue A/C: Insured / Std / Nil / NA

Sp Reading: 266607 T/Radio: Insured / Std / Nil / NA

Eng/Ho: D4PDGu700953

Ch/Ho: KMHLB41UMHU097734

Gen. Cond: Good / Fair / Poor / Burnt

Steering: In order / Jammed / Leaked / Burnt or

Brake: In order / Jammed / Leaked / Burnt or

Modi: Nil / S/Rim / STD A/Rim or

Tyre Size: F: 205/60 R16

R: — 11 —

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or Champion

Front

Rear

R/Bal: 5 mm R/Bal: 5 mm

L/Bal: 5 mm L/Bal: 5 mm

D.O.A. 10/02/2019 D.O.I. 13/02/2019

Survey held at Chunni AMK

Des. of Damages: Fnt / Rear / O/S / N/S / U/C / Rooftop or

Brnd y Rev

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time Action / Instruction

MSG SLR 3483H

19/03/19 Insured 2/15 15000/- with 9 days of repair.
(Red: 9734.70, 39%)

RECEIVED 21 MAR 2019

Date/Time, File Page to:

2013 Typist

Date/Time, File Return to:

☐ : Preli. Report☒ : Final Report

Days Of Repair: 9

Resurvey No. of Trip: 2

Survey Fee:

Transportation:

F. S. & S.

F. Photo:

F. Video:

F. ...

Total:

Add Fee: ☐ Site Insp. (€)☐ Interview (€)☐ Tech. Insp. (€)☐ Weekend (€)

Report Format

Lump Sum / L.B. (€)

TP

15,000/-




200
10
210

Qty	Parts Description/ Labour	Type	Unit Price	Amount
	Radiator Grille <i>broken</i>			\$ 1,110.10
	Radiator Grille H Emblem <i>broken New</i>			\$ 120.30
	Front Bumper Cover <i>distorted mainly broken</i>			\$ 1,052.20
	Front Bumper Sponge <i>turn</i>			\$ 99.20
	Front Bumper Reinforcement <i>BT</i>			\$ 402.10
	Front Bumper Bracket Top (LH/RH) <i>NH</i>		\$ 22.40	\$ 44.80
	Front Bumper Bracket (LH/RH) <i>NH</i>		\$ 24.60	\$ 49.20
	Headlamp Support Top Cover <i>NH</i>			\$ 222.60
	Headlamp Support Panel Assy <i>& BT broken</i>			\$ 907.40
	Headlamp (LH/RH) <i>mainly broken</i>		\$ 1,388.00	\$ 2,776.00
	Radiator <i>& BT punctured</i>			\$ 698.30
	Radiator Fan Blade, Cowling, Motor Assy <i>broken</i>			\$ 792.95
	Radiator Bracket (RH/LH) <i>NH</i>		\$ 6.50	\$ 13.00
	Radiator Guard <i>broken</i>		\$ 20.00	\$ 40.00
	Horn Unit (LH/RH) <i>broken</i>		\$ 73.80	\$ 147.60
	Aircon Condenser <i>BT</i>			\$ 927.50
	Inter Cooler <i>BT</i>			\$ 1,032.50
	Inter Cooler Mounting (2 PCS) <i>NH</i>			\$ 25.90
			10106.15	
			8084.92	
	SUB TOTAL			\$ 10,461.65
	LESS 20%			\$ 2,092.33
	DISCOUNTED TOTAL			\$ 8,369.32
	Front Number Plate <i>crack</i>			\$ 25.00
	Front No Plate Trim Cover <i>broken</i>			\$ 30.00
			55.00	
				\$ 55.00
	Labour Charge			
	Panel Beating			\$ 1,000.00
	Spray Painting Charge			\$ 250.00
	Wiring Charge			\$ 50.00
	Towing Charge			\$ 50.00
	Remove/Refix Aircon & Refill Gas		810.00	\$ 150.00
	Diagnostic & Resetting To Erase Fault Code			\$ 480.00
	TOTAL LABOUR			\$ 1,980.00

SHD 3819U

Qty	Parts Description/ Labour	Type	Unit Price	Amount	
	Boot Lid <i>bst</i>			\$ 2,174.90	✓
	Boot Lid Rubber <i>deformed</i>			\$ 96.50	✓
	Boot Lid Lock Upper <i>bst</i>			\$ 102.60	✓
	Boot Lid Lock Lower <i>bst</i>			\$ 31.70	✓
	Boot Lid 'H' Emblem <i>hkc</i>			\$ 28.70	✓
	Boot Lid CRDI Plate <i>hkc</i>			\$ 27.90	✓
	Boot Lid Lamp (LH/RH) <i>crack</i>	\$	565.60	\$ 1,131.20	✓
	Boot Lid Trimboard <i>tom</i>			\$ 116.40	✓
	Boot Lid Trimboard Clips (10pcs) <i>hkc</i>			\$ 11.00	✓
	Bootlid Moulding <i>h4</i>			\$ 85.00	X
	Bootlid i40 Emblem <i>hkc h4</i>			\$ 27.90	X
	Bootlid Lower Garnish <i>h4</i>			\$ 227.90	X
	Rear Bumper <i>distorted</i>			\$ 553.00	✓
	Rear Bumper Reinforcement <i>crack</i>			\$ 428.40	✓
	Rear Bumper Reinforcement Bracket (LH/RH) <i>bst</i>	\$	80.30	\$ 160.60	✓
	Rear Bumper Clip 10 pcs <i>hkc</i>			\$ 22.00	✓
	Rear Bumper Bracket <i>h4</i>	\$	35.60	\$ 71.20	X
	Rear Bumper Sponge <i>tom</i>			\$ 118.40	✓
	Rear Bumper Under Cover <i>distorted</i>			\$ 228.00	✓
	Tail Lamp (LH/RH) <i>crack</i>	\$	697.80	\$ 1,395.60	✓
	Rear Panel <i>Dented</i>			\$ 526.70	✓
	Rear Panel Garnish <i>mostly broken</i>			\$ 57.70	✓
	Rear Panel Lower Panel <i>Dented</i>			\$ 495.50	✓
	Spare Tyre Holder <i>h4</i>			\$ 248.00	X
	Spare Tyre Panel <i>Dented</i>			\$ 852.80	✓
	Spare Tyre Panel Cushion <i>h4</i>			\$ 209.05	X
	Rear Towing Hook <i>h4</i>			\$ 94.60	X
	Member Assy- Rear Floor Centre <i>h4</i>			\$ 570.40	X
	Exhaust Pipe Insulator <i>h4</i>	\$	58.55	\$ 117.10	X
	Exhaust Silencer <i>bst</i> <i>—closed up photo?</i>	\$	967.70	\$ 1,935.40	✓
	Exhaust Pipe Hanger <i>h4</i>	\$	58.55	\$ 117.10	X
	Exhaust Pipe Centre <i>h4</i>			\$ 730.10	X
			10495.00		
			8396.00		
	SUB TOTAL			\$ 12,993.35	
	LESS 20%			\$ 2,598.67	
	DISCOUNTED TOTAL			\$ 10,394.68	
	Boot Lid Comfort Logo & Tel No. Sticker <i>hkc</i>			\$ 30.00	Nett ✓
	Boot Lid Advertisement Logo <i>hkc</i>			\$ 100.00	Nett ✓
	Rear Bumper Reverse Sensor <i>Don</i>			\$ 135.70	Nett ✓
	Rear Bumper Advertisement Logo <i>hkc</i>			\$ 50.00	Nett ✓
	Rear Bumper Rubber Mat <i>hkc</i>			\$ 50.00	Nett ✓
	Rear Fender Advertisement Logo (LH/RH) <i>hkc</i>	\$	100.00	\$ 200.00	Nett ✓
			565.70	\$ 565.70	

SHD 3819U

Qty	Parts Description/ Labour	Type	Unit Price	Amount
	Labour Charge			
	Panel Beating			\$ 1,600.00 700/-
	Spray Painting Charge			\$ 1,250.00 600/-
	Wiring Charge			\$ 50.00 30/-
	Tuff Kote			\$ 50.00 40/-
	Remove/Refix Reverse Sensor			\$ 120.00 40/-
	Remove/Refix Exhaust Pipe			\$ 300.00 60/-
	 TOTAL LABOUR			\$ 3,370.00
	ESTIMATE TOTAL			\$ 24,734.70
	13/02/2019 @ 1400pm		19381-62	
	h/a Anthony		2/515000/-	
	2/5am 9 days.			
				
	LKK Auto			
				
	<p>LKK Auto Consultants hence notify the Repairer of the following:</p> <ul style="list-style-type: none"> • To resurvey before/after spray painting • To display damaged part(s) during resurvey • Parts prices are subject to confirmation • Third party survey is on a "Without Prejudice" basis • No illegal modification(s) is allowed • Complementary item(s) must be resurveyed <u>and</u> subject to final approval from Insurance Company <p>Acknowledged by Repairer Signature: Date:</p>			
This is an initial estimate based on a visual inspection of the above vehicle. The final repair quantum will be prepared after the vehicle is surveyed by a motor Surveyor appointed by the insurance company.				

...CLAIM SUBFOLDER...(New Assignment)

CLAIM SUBFOLDER TRACKING

Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'd	Status
Main	11 Feb 2019		12 Feb 2019 14:09 Assign				New Assignment Cancel Case

Main	Reference	Claim Details	Documents	Show All
------	-----------	---------------	-----------	--------------------------

CLAIM SUBFOLDER DETAILS

[\[Created by insurer\]](#)

Insured:	Lai Ming Shan Cedric, ID: S8028715A		
Main Claimant:	Comfort Transportation Pte Ltd, Co. Reg. No.: 199303821R		
Vehicle Reg. No.:	SHD3819U	Date of Loss:	10/02/2019 12:00 - :59 [25 Months and 12 Days From LTA Reg Date (Man Yr)]
Claim Type:	TP / 584626	Policy/Cover Note No.:	29089476QMY (Comprehensive) Coverage: 11/08/2018 - 10/08/2019
Vehicle Reg. No. (Insured):	SLR3483H	Policy No. (Claimant):	
		Excess:	
Repairer:	Chunni Motor Work Pte Ltd - Amk (HQ) Blk 10 #01-05/06, AMK Autopoint, 568047 Ang Mo Kio - Tel: 64836016		
Handling Insurer:	MSIG Insurance (Singapore) Pte. Ltd. (HQ) - Tel: +65 6827 7888 ... [Handled by Katherine Wong Chew Shong - 6594 2544]		
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Imm.Advice due 13/02/2019]		
Adj Asg. Remarks:	OI not reported, Irene instructed to outsource to LKK. Contact : Lynn or Irene at 6542 5119 or 6542 7162		

ASSOCIATED MAIL RECEIVED

[View All](#)
[Compose Case Mail](#)

- MSIG_SG (12/02/2019): Cancellation of Assignment: SHD3819U

ALL ASSOCIATED TASKS [icon]

[View All](#)
[Search Tasks](#)
[Create New Task](#)
[Complete](#)

Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

To: MSIG Insurance (Singapore) Pte. Ltd. 4 Shenton Way #21-01 SGX Centre 2 Singapore 068807	From: LKK Auto Consultants Pte Ltd 51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park Singapore 408933
Attn: Katherine Wong Chew Shong	Date: 20 Feb 2019
<u>Preliminary Advice</u>	

Insured Vehicle No	: SLR3483H	Accident Date	: 10/02/2019
TP Vehicle No	: SHD3819U	Assignment Date	: 12/02/2019
Make	: HYUNDAI I40	Est. Duration of Repair	: 9.00
Date of Inspection	: 13/02/2019		
Inspection At	: CHUNNI MOTOR WORK PTE LTD - AMK (HQ) BLK 10 #01-05/06, AMK AUTOPOINT SINGAPORE 568047		

Point of Impact / General Description of Damages

The vehicle sustained impact / damages front and rear portion and parts claimed are consistent to the accident.

Repairer's Estimate (Gross)	:S\$	24,734.70
Revised Amount	:S\$	19,381.62
Check Items (Estimated)	:S\$	0.00
Total	:S\$	19,381.62
Lump Sum Repair	:S\$	
Total Loss Consideration		
New for Old Value	:S\$	
Pre-Accident Value	:S\$	
COE / PARF Rebate	:S\$	
Salvage Value	:S\$	
Margin for Repair	:S\$	

Remarks

<input type="checkbox"/>	The vehicle is economical/not economical for repair.
<input checked="" type="checkbox"/>	The above survey was conducted on a 'without prejudice' basis.

MCD019018557 / ComfortDelGro Engineering Pte Ltd - Layan
 ENTRY DATE & TIME: 11/02/2019 12:49
 SUBMITTED BY: Catherine Pui Moy Juan

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. This report will be forwarded by the Insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the Insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT	
Date Of Report	11/02/2019 12:49
Date Of Accident	10/02/2019 12:50
Exact Location Of Accident	PIE TWDS TUAS BEFORE BENDEMEER EXIT
Country/State of Loss	SINGAPORE
DETAILS OF OWN VEHICLE	
Vehicle Registration Number	SHD3819U
Insured/Policyholder	
Name Of Registered Owner	COMFORT TRANSPORTATION PTE LTD
Co Reg No	199303821R
Email Address	FLEETSAFETY@CDGTAXI.COM,SG
Mobile Phone No	
Alternative Phone No	OFFICE-65508768
Vehicle Particulars	
Manufacturer	HYUNDAI
Model	I40
Exact Purpose for which vehicle was being used at time of accident	
Are you claiming under your own Insurance policy for repair to your vehicle?	NO
If No, Please state action to be taken	THIRD PARTY
Vehicle Category	TAXI
Insurance Company	
Name of Insurance Company	MS FIRST CAPITAL INSURANCE LTD
Type Of Coverage	THIRD PARTY FIRE AND/OR THEFT
Fleet Policy	YES
Policy Number	D-18088936MFSH
Cover Note Number	
Driver	
Name of Driver	QUEK BENG LEONG
NRIC No	S0180231C
Date Of Birth	22/02/1954
Occupation	OUTDOOR
Date Of Driving Pass	10/11/1976
Driving Experience	42 YEARS AND 3 MONTHS
Gender	MALE
Mobile Number	(LOCAL) +65-86880998
Fax Number	
Contact Number	
EMail Address	QUEK0998@YAHOO.COM,SG

Address 508 09-98 WOODLANDS DRIVE 14
Postcode 730508
Was driver an employee of the Insured's Company NO
If No, Relationship of the Driver with the Insured OTHER - TAXI DRIVER
Vehicle Registration Number of Driver's Own Vehicle -
Vehicle -
Insurance Company of Driver's Own Vehicle -

General Information of the Accident

Type Of Accident CHAIN COLLISION
Weather Conditions CLEAR
Road Surface DRY
Other Information
Was any foreign vehicle involved in this accident? NO
Number of vehicles (including own vehicle) involved in the accident 4
Was any body injured in the Accident? NO
Was any injured conveyed to hospital by ambulance? NO
Was any other material or property damaged? YES
I have been approached by unknown person(s) soliciting/offering accident claims assistance. NO
Number of Passengers (Including Driver) 3
Passenger 1

NAME: : -
GENDER: : MALE

Passenger 2

NAME: : -
GENDER: : FEMALE

Details of Police Action

Was the accident reported to the police? NO
If Yes, Please state which Police Station
Was notice of intended Prosecution given? NO
If Yes, against whom?

Circumstances of Accident

SEE ATTACH.

Attachment(s)

Are accident photos available for attachment? YES
Was there any video captured by Car Camera? YES
Remarks/ Reasons: -
Was there any audio recorded? NO

DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number SLR3483H
Vehicle Make/Model/Colour
Details Of Properties
Vehicle Category PRIVATE CAR
Name of Driver LAI MING SHAN
NRIC/Passport Number S8028715A
Contact Number 83220030
Address

Postcode

Insurance Company Name

Nature Of Damage FRT

No. Of Passenger (Including Driver)

DETAILS OF OTHER VEHICLE PROPERTY 2

Vehicle Registration Number SLP6614M
Vehicle Make/Model/Colour
Details Of Properties
Vehicle Category PRIVATE CAR
Name of Driver
NRIC/Passport Number
Contact Number 98593354
Address
Postcode
Insurance Company Name
Nature Of Damage FRT & REAR
No. Of Passenger (Including Driver)

DETAILS OF OTHER VEHICLE PROPERTY 3

Vehicle Registration Number SLS4993R
Vehicle Make/Model/Colour
Details Of Properties
Vehicle Category PRIVATE CAR
Name of Driver JERRY
NRIC/Passport Number
Contact Number 92708101
Address
Postcode
Insurance Company Name
Nature Of Damage REAR
No. Of Passenger (Including Driver)

SKETCH PLAN**IMPORTANT NOTICE**


1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by Insurance companies is not an admission of policy liability on the part of the Insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. The report will be forwarded by the Insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgment of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.
8. **Consent under the Personal Data Protection Act (PDPA)**


I understand, acknowledge, agree and consent that:

- (a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this [form] and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the Insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of :
 - (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
 - (ii) investigating the accident and/or my claims;
 - (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
 - (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
 - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims.(collectively the "Purposes")
- (b) all Insurer(s) who have insured vehicle(s) involved in this accident and the Insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
- (c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third party service providers or agents(Including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.
- (d) my Personal Information will also be collected and used to compile claims history for the purpose of fraud detection, investigation and management in present and all future claims.
- (e) the information so collected under (d) above may be shared / disclosed:
 - (i) to all insurers and/or any other third parties that assist in evaluating, investigating, controlling or managing fraud, regulators, law enforcement and government agencies as reasonably required for the purposes stated, or
 - (ii) for complying with requirements under any regulations, laws or court orders.


COMFORT TRANSPORTATION PTE LTD
CO. REG. NO. 199303821R

Policyholder's Signature
Date & Time:


Driver's Signature
(If driver is not the policyholder)
Date & Time: 11.02.2019 @ 1030HRS


Reporting Centre Personnel's Signature
Name:
NRIC/FIN No.: June Tan

SKETCH PLAN



DESCRIBE CIRCUMSTANCES OF THE ACCIDENT

On 10.02.2019 @ 1250HRS I was travelling along PIE twds Tuas before Bendemeer Exit.

As I was travelling straight veh(C) SLP 6614M stopped and I followed. Suddenly veh(B) SLR 3483H hit onto my vehicle rear portion and caused my vehicle to surge forward and hit veh(C).

I have company video and photos at scene to support my claims .

No injury in this accident .

Veh(B) SLR 3483H MR Lai Ming Shan S 8028715A

Veh(C) SLP 6614M Male Driver

Veh(D) SLS 4993R Jerry Hp:9270 8101

DECLARATION

I/We declare the foregoing particulars are true in every respect.

CHUNNI MOTOR TRANSPORTATION PTE LTD

Policyholder's Signature: 199303821R

Date & Time:

Driver's Signature

(If driver is not the policyholder)

Date & Time: 11.02.2019@ 1030HRS

Reporting Centre Personnel's Signature

Name:

NRIC/FIN No.: June Tan

...CLAIM SUBFOLDER...(Pending for Survey Report)

CLAIM SUBFOLDER TRACKING							
Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'ed	Status
Main	11 Feb 2019		12 Feb 2019 14:09 Edit Adj Rpt	S\$15,000.00 Edit Estimates	S\$15,000.00 View Rpt		Pending for Survey Report Cancel Case

Main	Reference	Claim Details	Documents	Show All					
CLAIM SUBFOLDER DETAILS [Created by insurer]									
Insured:	Lai Ming Shan Cedric , ID: S8028715A								
Main Claimant:	Comfort Transportation Pte Ltd , Co. Reg. No.: 199303821R								
Vehicle Reg. No.:	SHD3819U	Date of Loss:	10/02/2019 12:00 - :59 [25 Months and 12 Days From LTA Reg Date (Man Yr)]						
Claim Type:	TP / 584626	Policy/Cover Note No.:	29089476QMY (Comprehensive) Coverage: 11/08/2018 - 10/08/2019						
Vehicle Reg. No. (Insured):	SLR3483H	Policy No. (Claimant):							
		Excess:							
Repairer:	Chunni Motor Work Pte Ltd - Amk (HQ) Blk 10 #01-05/06, AMK Autopoint, 568047 Ang Mo Kio - Tel: 64836016								
Handling Insurer:	MSIG Insurance (Singapore) Pte. Ltd. (HQ) - Tel: +65 6827 7888 ... [Handled by Katherine Wong Chew Shong - 6594 2544]								
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Handled by BRYAN TANI] ... [Final Rpt due 14/03/2019]								
Adj Asg. Remarks:	OI not reported. Irene instructed to outsource to LKK. Contact : Lynn or Irene at 6542 5119 or 6542 7162								
ASSOCIATED MAIL RECEIVED View All Compose Case Mail									
<ul style="list-style-type: none"> MSIG_SG (12/02/2019): Cancellation of Assignment: SHD3819U 									
ALL ASSOCIATED TASKS View All Search Tasks Create New Task Complete									
Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

Claim Documents

*SHD3819U (584626)

[SLR3483H]

TP



















































Comfort Transportation Pte Ltd



















































Feb 10 2019 12:00PM



















































[Lai Ming Shan Cedric]

































Chunni Motor Work Pte Ltd - Amk

Upload Documents		Upload Photos	Compose New Letter	View View in Browser	
Assessment Reports				1 per page	<input checked="" type="checkbox"/>
No	Finalized On	MSIG Insurance (Singapore) Pte. Ltd. (HQ)		Thumbnail	Print
1	15/02/19 08:57	Accident Statement From: SC - Reg. No: SLR3483H, Claimant: LAI MING SHAN CEDRIC		Load HTM	
No	Finalized On	LKK Auto Consultants Pte Ltd (HQ)		Thumbnail	Print
1	20/02/19 14:42	Adjuster Immediate Advice		Load HTM	
Photos/Images				3 per page	<input checked="" type="checkbox"/>
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)		Thumbnail	Print
1	16/03/19 15:49	Rear View Right		Load JPG	<input checked="" type="checkbox"/>
2	16/03/19 15:49	Rear View Left		Load JPG	<input checked="" type="checkbox"/>
3	16/03/19 15:50	General View		Load JPG	<input checked="" type="checkbox"/>
4	16/03/19 15:50	General View		Load JPG	<input checked="" type="checkbox"/>
5	16/03/19 15:50	General View		Load JPG	<input checked="" type="checkbox"/>
6	16/03/19 15:50	General View		Load JPG	<input checked="" type="checkbox"/>
7	16/03/19 15:50	General View		Load JPG	<input checked="" type="checkbox"/>
8	16/03/19 15:50	General View		Load JPG	<input checked="" type="checkbox"/>
9	16/03/19 15:50	General View		Load JPG	<input checked="" type="checkbox"/>
10	16/03/19 15:50	General View		Load JPG	<input checked="" type="checkbox"/>
11	16/03/19 15:50	General View		Load JPG	<input checked="" type="checkbox"/>
12	16/03/19 15:50	General View		Load JPG	<input checked="" type="checkbox"/>
13	16/03/19 15:50	General View		Load JPG	<input checked="" type="checkbox"/>
14	16/03/19 15:50	General View		Load JPG	<input checked="" type="checkbox"/>
15	16/03/19 15:50	General View		Load JPG	<input checked="" type="checkbox"/>
16	16/03/19 15:50	General View		Load JPG	<input checked="" type="checkbox"/>
17	16/03/19 15:50	General View		Load JPG	<input checked="" type="checkbox"/>
18	16/03/19 15:50	General View		Load JPG	<input checked="" type="checkbox"/>
19	16/03/19 15:50	General View		Load JPG	<input checked="" type="checkbox"/>
20	16/03/19 15:50	General View		Load JPG	<input checked="" type="checkbox"/>
21	16/03/19 15:50	General View		Load JPG	<input checked="" type="checkbox"/>
22	16/03/19 15:50	General View		Load JPG	<input checked="" type="checkbox"/>
23	16/03/19 15:50	General View		Load JPG	<input checked="" type="checkbox"/>
24	16/03/19 15:50	General View		Load JPG	<input checked="" type="checkbox"/>
25	16/03/19 15:50	General View		Load JPG	<input checked="" type="checkbox"/>
26	16/03/19 15:50	General View		Load JPG	<input checked="" type="checkbox"/>
27	16/03/19 15:50	General View		Load JPG	<input checked="" type="checkbox"/>
28	16/03/19 15:50	General View		Load JPG	<input checked="" type="checkbox"/>
29	16/03/19 15:50	General View		Load JPG	<input checked="" type="checkbox"/>
30	16/03/19 15:50	General View		Load JPG	<input checked="" type="checkbox"/>
31	16/03/19 15:50	General View		Load JPG	<input checked="" type="checkbox"/>
32	16/03/19 15:50	General View		Load JPG	

Assessment Reports			1 per page	<input checked="" type="checkbox"/>
No	Finalized On	MSIG Insurance (Singapore) Pte. Ltd. (HQ)	Thumbnail	Print
				<input checked="" type="checkbox"/>
33	16/03/19 15:50	General View	 Load JPG	<input checked="" type="checkbox"/>
34	16/03/19 15:50	General View	 Load JPG	<input checked="" type="checkbox"/>
35	16/03/19 15:50	General View	 Load JPG	<input checked="" type="checkbox"/>
36	16/03/19 15:50	General View	 Load JPG	<input checked="" type="checkbox"/>
37	16/03/19 15:50	General View	 Load JPG	<input checked="" type="checkbox"/>
38	16/03/19 15:50	General View	 Load JPG	<input checked="" type="checkbox"/>
39	16/03/19 15:50	General View	 Load JPG	<input checked="" type="checkbox"/>
40	16/03/19 15:50	General View	 Load JPG	<input checked="" type="checkbox"/>
41	16/03/19 15:50	General View	 Load JPG	<input checked="" type="checkbox"/>
42	16/03/19 15:50	General View	 Load JPG	<input checked="" type="checkbox"/>
43	16/03/19 15:50	General View	 Load JPG	<input checked="" type="checkbox"/>
44	16/03/19 15:50	General View	 Load JPG	<input checked="" type="checkbox"/>
45	16/03/19 15:50	General View	 Load JPG	<input checked="" type="checkbox"/>
46	16/03/19 15:50	General View	 Load JPG	<input checked="" type="checkbox"/>
47	16/03/19 15:50	General View	 Load JPG	<input checked="" type="checkbox"/>
48	16/03/19 15:50	General View	 Load JPG	<input checked="" type="checkbox"/>
49	16/03/19 15:50	General View	 Load JPG	<input checked="" type="checkbox"/>
50	16/03/19 15:50	General View	 Load JPG	<input checked="" type="checkbox"/>
51	16/03/19 15:50	General View	 Load JPG	<input checked="" type="checkbox"/>
52	16/03/19 15:50	General View	 Load JPG	<input checked="" type="checkbox"/>
53	16/03/19 15:50	General View	 Load JPG	<input checked="" type="checkbox"/>
54	16/03/19 15:50	General View	 Load JPG	<input checked="" type="checkbox"/>
55	16/03/19 15:50	General View	 Load JPG	<input checked="" type="checkbox"/>
56	16/03/19 15:50	General View	 Load JPG	<input checked="" type="checkbox"/>
57	16/03/19 15:50	General View	 Load JPG	<input checked="" type="checkbox"/>
58	16/03/19 15:50	General View	 Load JPG	<input checked="" type="checkbox"/>
59	16/03/19 15:50	General View	 Load JPG	<input checked="" type="checkbox"/>
60	16/03/19 15:50	General View	 Load JPG	<input checked="" type="checkbox"/>
61	16/03/19 15:50	General View	 Load JPG	<input checked="" type="checkbox"/>
62	16/03/19 15:50	General View	 Load JPG	<input checked="" type="checkbox"/>
63	16/03/19 15:50	General View	 Load JPG	<input checked="" type="checkbox"/>
64	16/03/19 15:50	General View	 Load JPG	<input checked="" type="checkbox"/>
65	16/03/19 15:50	General View	 Load JPG	<input checked="" type="checkbox"/>
66	16/03/19 15:50	General View	 Load JPG	<input checked="" type="checkbox"/>
67	16/03/19 15:50	General View	 Load JPG	<input checked="" type="checkbox"/>
68	16/03/19 15:50	General View	 Load JPG	<input checked="" type="checkbox"/>
69	16/03/19 15:50	General View	 Load JPG	<input checked="" type="checkbox"/>
70	16/03/19 15:50	General View	 Load JPG	<input checked="" type="checkbox"/>
71	16/03/19 15:50	General View	 Load JPG	<input checked="" type="checkbox"/>
72	16/03/19 15:51	Front View Left	 Load JPG	<input checked="" type="checkbox"/>
73	16/03/19 15:51	Front View Right	 Load JPG	<input checked="" type="checkbox"/>
74	16/03/19 15:52	General View	 Load JPG	<input checked="" type="checkbox"/>
75	16/03/19 15:52	General View	 Load JPG	<input checked="" type="checkbox"/>
76	16/03/19 15:52	General View	 Load JPG	<input checked="" type="checkbox"/>
77	16/03/19 15:52	General View	 Load JPG	<input checked="" type="checkbox"/>
78	16/03/19 15:52	General View	 Load JPG	<input checked="" type="checkbox"/>
79	16/03/19 15:52	General View	 Load JPG	<input checked="" type="checkbox"/>
80	16/03/19 15:52	General View	 Load JPG	<input checked="" type="checkbox"/>
81	16/03/19 15:52	General View	 Load JPG	<input checked="" type="checkbox"/>

Assessment Reports			1 per page	<input checked="" type="checkbox"/>
No	Finalized On	MSIG Insurance (Singapore) Pte. Ltd. (HQ)	Thumbnail	Print
82	16/03/19 15:52	General View	 Load JPG	<input checked="" type="checkbox"/>
83	16/03/19 15:52	General View	 Load JPG	<input checked="" type="checkbox"/>
84	16/03/19 15:52	General View	 Load JPG	<input checked="" type="checkbox"/>
85	16/03/19 15:52	General View	 Load JPG	<input checked="" type="checkbox"/>
86	16/03/19 15:52	General View	 Load JPG	<input checked="" type="checkbox"/>
87	16/03/19 15:52	General View	 Load JPG	<input checked="" type="checkbox"/>
88	16/03/19 15:52	General View	 Load JPG	<input checked="" type="checkbox"/>
89	16/03/19 15:52	General View	 Load JPG	<input checked="" type="checkbox"/>
90	16/03/19 15:52	General View	 Load JPG	<input checked="" type="checkbox"/>
91	16/03/19 15:52	General View	 Load JPG	<input checked="" type="checkbox"/>
92	16/03/19 15:52	General View	 Load JPG	<input checked="" type="checkbox"/>
93	16/03/19 15:52	General View	 Load JPG	<input checked="" type="checkbox"/>
94	16/03/19 15:52	General View	 Load JPG	<input checked="" type="checkbox"/>
95	16/03/19 15:52	General View	 Load JPG	<input checked="" type="checkbox"/>
96	16/03/19 15:52	General View	 Load JPG	<input checked="" type="checkbox"/>
97	16/03/19 15:52	General View	 Load JPG	<input checked="" type="checkbox"/>
98	16/03/19 15:52	General View	 Load JPG	<input checked="" type="checkbox"/>
99	16/03/19 15:52	General View	 Load JPG	<input checked="" type="checkbox"/>
100	16/03/19 15:52	General View	 Load JPG	<input checked="" type="checkbox"/>
101	16/03/19 15:52	General View	 Load JPG	<input checked="" type="checkbox"/>
102	16/03/19 15:52	General View	 Load JPG	<input checked="" type="checkbox"/>
103	16/03/19 15:52	General View	 Load JPG	<input checked="" type="checkbox"/>
104	16/03/19 15:52	General View	 Load JPG	<input checked="" type="checkbox"/>
105	16/03/19 15:52	General View	 Load JPG	<input checked="" type="checkbox"/>
106	16/03/19 15:52	General View	 Load JPG	<input checked="" type="checkbox"/>
107	16/03/19 15:52	General View	 Load JPG	<input checked="" type="checkbox"/>
108	16/03/19 15:52	General View	 Load JPG	<input checked="" type="checkbox"/>
109	16/03/19 15:52	General View	 Load JPG	<input checked="" type="checkbox"/>
110	16/03/19 15:52	General View	 Load JPG	<input checked="" type="checkbox"/>
111	16/03/19 15:52	General View	 Load JPG	<input checked="" type="checkbox"/>
112	16/03/19 15:52	General View	 Load JPG	<input checked="" type="checkbox"/>
113	16/03/19 15:52	General View	 Load JPG	<input checked="" type="checkbox"/>
114	16/03/19 15:52	General View	 Load JPG	<input checked="" type="checkbox"/>
115	16/03/19 15:52	General View	 Load JPG	<input checked="" type="checkbox"/>
116	16/03/19 15:52	General View	 Load JPG	<input checked="" type="checkbox"/>
117	16/03/19 15:52	General View	 Load JPG	<input checked="" type="checkbox"/>
118	16/03/19 15:52	General View	 Load JPG	<input checked="" type="checkbox"/>
119	16/03/19 15:52	General View	 Load JPG	<input checked="" type="checkbox"/>
120	16/03/19 15:52	General View	 Load JPG	<input checked="" type="checkbox"/>
121	16/03/19 15:52	General View	 Load JPG	<input checked="" type="checkbox"/>
122	16/03/19 15:52	General View	 Load JPG	<input checked="" type="checkbox"/>
123	16/03/19 15:52	General View	 Load JPG	<input checked="" type="checkbox"/>
124	16/03/19 15:52	General View	 Load JPG	<input checked="" type="checkbox"/>
125	16/03/19 15:52	Odometer Reading	 Load JPG	<input checked="" type="checkbox"/>
126	16/03/19 15:52	Chassis Number	 Load JPG	<input checked="" type="checkbox"/>
127	16/03/19 15:53	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
128	16/03/19 15:53	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
129	16/03/19 15:53	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
130	16/03/19 15:53	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
131	16/03/19 15:53	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>

Assessment Reports			1 per page	<input checked="" type="checkbox"/>
No	Finalized On	MSIG Insurance (Singapore) Pte. Ltd. (HQ)	Thumbnail	Print
132	16/03/19 15:53	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
133	16/03/19 15:53	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
134	16/03/19 15:53	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
135	16/03/19 15:53	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
136	16/03/19 15:53	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
137	16/03/19 15:53	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
138	16/03/19 15:53	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
139	16/03/19 15:53	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
140	16/03/19 15:53	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
141	16/03/19 15:53	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
142	16/03/19 15:53	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
143	16/03/19 15:53	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
144	16/03/19 15:53	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
145	16/03/19 15:53	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
146	16/03/19 15:53	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
147	16/03/19 15:53	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
148	16/03/19 15:53	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
149	16/03/19 15:53	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
150	16/03/19 15:53	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
151	16/03/19 15:53	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
152	16/03/19 15:53	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
153	16/03/19 15:53	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
154	16/03/19 15:53	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
155	16/03/19 15:53	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
156	16/03/19 15:53	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
157	16/03/19 15:53	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
158	16/03/19 15:53	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
159	16/03/19 15:53	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
160	16/03/19 15:53	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
161	16/03/19 15:53	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
162	16/03/19 15:53	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
163	16/03/19 15:53	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
164	16/03/19 15:53	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
165	16/03/19 15:53	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
166	16/03/19 15:53	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
167	16/03/19 15:53	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
168	16/03/19 15:53	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
169	16/03/19 15:53	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
170	16/03/19 15:53	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
171	16/03/19 15:53	Finishing Photo	 Load JPG	<input checked="" type="checkbox"/>
172	16/03/19 15:53	Finishing Photo	 Load JPG	<input checked="" type="checkbox"/>
173	16/03/19 15:53	Finishing Photo	 Load JPG	<input checked="" type="checkbox"/>
174	16/03/19 15:53	Finishing Photo	 Load JPG	<input checked="" type="checkbox"/>
175	16/03/19 15:53	Finishing Photo	 Load JPG	<input checked="" type="checkbox"/>
176	16/03/19 15:53	Finishing Photo	 Load JPG	<input checked="" type="checkbox"/>
177	16/03/19 15:53	Finishing Photo	 Load JPG	<input checked="" type="checkbox"/>
178	16/03/19 15:53	Finishing Photo	 Load JPG	<input checked="" type="checkbox"/>
179	16/03/19 15:53	Finishing Photo	 Load JPG	<input checked="" type="checkbox"/>
180	16/03/19 15:53	Finishing Photo	 Load JPG	<input checked="" type="checkbox"/>
181	16/03/19 15:53	Finishing Photo	 Load JPG	<input checked="" type="checkbox"/>

Assessment Reports			1 per page	<input checked="" type="checkbox"/>
No	Finalized On	MSIG Insurance (Singapore) Pte. Ltd. (HQ)	Thumbnail	Print
182	16/03/19 15:53	Finishing Photo	 Load JPG	<input checked="" type="checkbox"/>
183	16/03/19 15:53	Finishing Photo	 Load JPG	<input checked="" type="checkbox"/>
184	16/03/19 15:53	Finishing Photo	 Load JPG	<input checked="" type="checkbox"/>
185	16/03/19 15:53	Finishing Photo	 Load JPG	<input checked="" type="checkbox"/>
186	16/03/19 15:53	Finishing Photo	 Load JPG	<input checked="" type="checkbox"/>
187	16/03/19 15:53	Finishing Photo	 Load JPG	<input checked="" type="checkbox"/>
188	16/03/19 15:53	Finishing Photo	 Load JPG	<input checked="" type="checkbox"/>
189	16/03/19 15:53	Finishing Photo	 Load JPG	<input checked="" type="checkbox"/>
190	16/03/19 15:53	Finishing Photo	 Load JPG	<input checked="" type="checkbox"/>
191	16/03/19 15:53	Finishing Photo	 Load JPG	<input checked="" type="checkbox"/>
192	16/03/19 15:53	Finishing Photo	 Load JPG	<input checked="" type="checkbox"/>
193	16/03/19 15:53	Finishing Photo	 Load JPG	<input checked="" type="checkbox"/>
194	16/03/19 15:53	Finishing Photo	 Load JPG	<input checked="" type="checkbox"/>
195	16/03/19 15:53	Finishing Photo	 Load JPG	<input checked="" type="checkbox"/>
196	16/03/19 15:53	Finishing Photo	 Load JPG	<input checked="" type="checkbox"/>
197	16/03/19 15:53	Finishing Photo	 Load JPG	<input checked="" type="checkbox"/>
198	16/03/19 15:53	Finishing Photo	 Load JPG	<input checked="" type="checkbox"/>
199	16/03/19 15:53	Finishing Photo	 Load JPG	<input checked="" type="checkbox"/>
200	16/03/19 15:53	Finishing Photo	 Load JPG	<input checked="" type="checkbox"/>
201	16/03/19 15:53	Finishing Photo	 Load JPG	<input checked="" type="checkbox"/>
202	16/03/19 15:53	Finishing Photo	 Load JPG	<input checked="" type="checkbox"/>
203	16/03/19 15:53	Finishing Photo	 Load JPG	<input checked="" type="checkbox"/>
204	16/03/19 15:53	Finishing Photo	 Load JPG	<input checked="" type="checkbox"/>
205	16/03/19 15:53	Finishing Photo	 Load JPG	<input checked="" type="checkbox"/>
206	16/03/19 15:53	Finishing Photo	 Load JPG	<input checked="" type="checkbox"/>
207	16/03/19 15:53	Finishing Photo	 Load JPG	<input checked="" type="checkbox"/>
208	16/03/19 15:53	Finishing Photo	 Load JPG	<input checked="" type="checkbox"/>
209	16/03/19 15:53	Finishing Photo	 Load JPG	<input checked="" type="checkbox"/>
210	16/03/19 15:53	Finishing Photo	 Load JPG	<input checked="" type="checkbox"/>
Documentation			1 per page	<input checked="" type="checkbox"/>
No	Finalized On	MSIG Insurance (Singapore) Pte. Ltd. (HQ)	Thumbnail	Print
1	11/02/19 17:24	Estimate	 Load PDF	
2	11/02/19 17:24	SHD3819U E-file Report 3/4	 Load PDF	
3	12/02/19 10:53	Survey Agree on SJE - IHS	 Load PDF	

Documents Checklist

DOCUMENTS CHECKLIST	Reset	Save	Print
There are no document checklists configured.			
Our Checklist Remarks - LKK Auto Consultants Pte Ltd (HQ) <div style="border: 1px solid black; height: 100px; width: 100%;"></div>			
Show Remarks To: <input type="checkbox"/> Handling Insurer <small>Note: Remarks are private unless you show it to other parties.</small>			

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CS/MSG19002506/DVD3E2

Date: 25/03/2019

REFERENCE

Handling Insurer: MSIG Insurance (Singapore) Pte. Ltd.

Policy No: 29089476QMY

Claimant Vehicle No : SHD3819U

Insured Vehicle No : SLR3483H

Date of Loss: 10/02/2019

Nature of Claim: TP

Claim No: 584626

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: SHD3819U

Make & Model: HYUNDAI I40, 1.7 D CRDI F/L ABS AIRBAG 4DR (A)

Engine No: D4FDGU700953

Reg. Date: 29/12/2016 (Man. Year: 2016)

Chassis No: KMHLB41UMHU097734

Colour: Blue

Odometer: 266607 km

Engine Capacity: 1685 cc

Market Value/New Car Price: N/A

Sum Insured (S\$): Market Value/New Car Price

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes

Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 205/60 R16

Rear Tyre Size: 205/60 R16

Front Left Side: Campeon 5 mm

Rear Left Side: Campeon 5 mm

Front Right Side: Campeon 5 mm

Rear Right Side: Campeon 5 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	19,384.70	17,101.62	2,283.08	11.78
Miscellaneous Items	0.00	0.00	0.00	
Labour	5,350.00	2,280.00	3,070.00	57.38
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	24,734.70	19,381.62	5,353.08	21.64
Approved Total (Overridden) (S\$)		15,000.00		
(S\$)	24,734.70	15,000.00	9,734.70	39.36
+ GST 7.00/7.00% (S\$)	1,731.43	1,050.00	681.43	39.36
Nett Amount (S\$)	26,466.13	16,050.00	10,416.13	39.36

INSPECTION

Date of Assignment: 12/02/2019

Date Inspected: 13/02/2019 Inspected At:

Chunni Motor Work Pte Ltd - Amk (HQ)

Blk 10 #01-05/06, AMK Autopoint

Singapore 568047

Estimated Period of Repair: 9.0 days

Adjuster: BRYAN TANI**Manager:** VERON CHEN

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference		
Part Source:	MRM-SG	Version: 1.0 (Last Synchronised: 25 Mar 2019)
Parts:	143	HYUNDAI I40 1.7 D CRDI F/L ABS AIRBAG 4DR (A) (Catalogue:Merimen Singapore 1.0)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for SHD3819U)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*RADIATOR GRILLE	Broken	1,110.10 FL	*1,110.10 FL
2	1		*RADIATOR GRILLE H EMBLEM	Necessary	120.30 FL	*120.30 FL
3	1		*FRONT BUMPER COVER	Distorted / Mtg Broken	1,052.20 FL	*1,052.20 FL
4	1		*FRONT BUMPER SPONGE	Torn	99.20 FL	*99.20 FL
5	1		*FRONT BUMPER REINFORCEMENT	Bent	402.10 FL	*402.10 FL
6	2		*FRONT BUMPER BRACKET TOP (LH/RH)	Not Necessary	44.80 FL	*- FL
7	2		*FRONT BUMPER BRACKET (LH/RH)	Not Necessary	49.20 FL	*- FL
8	1		*HEADLAMP SUPPORT TOP COVER	Not Necessary	222.60 FL	*- FL
9	1		*HEADLAMP SUPPORT PANEL ASSY	Bent / Broken	907.40 FL	*907.40 FL
10	2		*HEADLAMP (LH/RH)	Mtg Broken	2,776.00 FL	*2,776.00 FL
11	1		*RADIATOR	Bent / Punctured	698.30 FL	*698.30 FL
12	1		*RADIATOR FAN BLADE, COWLING, MOTOR ASSY	Broken	792.95 FL	*792.95 FL
13	2		*RADIATOR BRACKET (RH/LH)	Not Necessary	13.00 FL	*- FL
14	2		*RADIATOR GUARD	Broken	40.00 FL	*40.00 FL
15	2		*HORN UNIT (LH/RH)	Broken	147.60 FL	*147.60 FL
16	1		*AIRCON CONDENSER	Bent	927.50 FL	*927.50 FL
17	1		*INTER COOLER	Bent	1,032.50 FL	*1,032.50 FL
18	2		*INTER COOLER MOUNTING	Not Necessary	25.90 FL	*- FL
19	1		*FRONT NUMBER PLATE	Cracked	25.00 FS	*25.00 FS
20	1		*FRONT NO PLATE TRIM COVER	Broken	30.00 FS	*30.00 FS
21	1		*BOOT LID	Bent	2,174.90 FL	*2,174.90 FL
22	1		*BOOT LID RUBBER	Deformed	96.50 FL	*96.50 FL
23	1		*BOOT LID LOCK UPPER	Bent	102.60 FL	*102.60 FL
24	1		*BOOT LID LOCK LOWER	Bent	31.70 FL	*31.70 FL
25	1		*BOOT LID H EMBLEM	Necessary	28.70 FL	*28.70 FL
26	1		*BOOT LID CRDI PLATE	Necessary	27.90 FL	*27.90 FL
27	2		*BOOT LID LAMP (LH/RH)	Cracked	1,131.20 FL	*1,131.20 FL
28	1		*BOOT LID TRIMBOARD	Torn	116.40 FL	*116.40 FL
29	10		*BOOT LID TRIMBOARD CLIPS	Necessary	11.00 FL	*11.00 FL
30	1		*BOOTLID MOULDING	Not Necessary	85.00 FL	*- FL
31	1		*BOOTLID I40 EMBLEM	Not Necessary	27.90 FL	*- FL
32	1		*BOOTLID LOWER GARNISH	Not Necessary	227.90 FL	*- FL
33	1		*REAR BUMPER	Distorted	553.00 FL	*553.00 FL
34	1		*REAR BUMPER REINFORCEMENT	Cracked	428.40 FL	*428.40 FL
35	2		*REAR BUMPER REINFORCEMENT BRACKET (LH/RH)	Bent	160.60 FL	*160.60 FL
36	10		*REAR BUMPER CLIP	Necessary	22.00 FL	*22.00 FL
37	2		*REAR BUMPER BRACKET	Not Necessary	71.20 FL	*- FL

Report was unsubmitted during this print-out.

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
38	1		*REAR BUMPER SPONGE	Torn	118.40 FL	*118.40 FL
39	1		*REAR BUMPER UNDER COVER	Distorted	228.00 FL	*228.00 FL
40	2		*TAIL LAMP (LH/RH)	Cracked	1,395.60 FL	*1,395.60 FL
41	1		*REAR PANEL	Dented	526.70 FL	*526.70 FL
42	1		*REAR PANEL GARNISH	Mtg Cracked	57.70 FL	*57.70 FL
43	1		*REAR PANEL LOWER PANEL	Dented	495.50 FL	*495.50 FL
44	1		*SPARE TYRE HOLDER	Not Necessary	248.00 FL	*- FL
45	1		*SPARE TYRE PANEL	Dented	852.80 FL	*852.80 FL
46	1		*SPARE TYRE PANEL CUSHION	Not Necessary	209.05 FL	*- FL
47	1		*REAR TOWING HOOK	Not Necessary	94.60 FL	*- FL
48	1		*MEMBER ASSY-REAR FLOOR CENTRE	Not Necessary	570.40 FL	*- FL
49	2		*EXHAUST PIPE INSULATOR	Not Necessary	117.10 FL	*- FL
50	2		*EXHAUST SILENCER	Bent	1,935.40 FL	*1,935.40 FL
51	2		*EXHAUST PIPE HANGER	Not Necessary	117.10 FL	*- FL
52	1		*EXHAUST PIPE CENTRE	Not Necessary	730.10 FL	*- FL
53	1		*BOOT LID COMFORT LOGO & TEL NO. STICKER	Necessary	30.00 FS	*30.00 FS
54	1		*BOOT LID ADVERTISEMENT LOGO	Necessary	100.00 FS	*100.00 FS
55	1		*REAR BUMPER REVERSE SENSOR	Damaged	135.70 FS	*135.70 FS
56	1		*REAR BUMPER ADVERTISEMENT LOGO	Necessary	50.00 FS	*50.00 FS
57	1		*REAR BUMPER RUBBER MAT	Necessary	50.00 FS	*50.00 FS
58	2		*REAR FENDER ADVERTISEMENT LOGO (LH/RH)	Necessary	200.00 FS	*200.00 FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (S\$) **24,075.70** **21,221.85**
 - List Item Discount on L Items 20.00/20.00% (S\$) 4,691.00 4,120.23

Total Parts (S\$) **19,384.70** **17,101.62**

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	PANEL BEATING	New	2,600.00	1,200.00
2	SPRAY PAINTING CHARGE	New	1,500.00	800.00
3	WIRING CHARGE	New	100.00	60.00
4	TOWING CHARGE	New	50.00	0.00
5	REMOVE / REFIX AIRCON & REFILL GAS	New	150.00	80.00
6	DIAGNOSTIC & RESETTING TO ERASE FAULT CODE	New	480.00	0.00
7	TUFF KOTE	New	50.00	40.00
8	REMOVE / REFIX REVERSE SENSOR	New	120.00	40.00
9	REMOVE / REFIX EXHAUST PIPE	New	300.00	60.00
Gross Labour Cost (S\$)			5,350.00	2,280.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >