

ASS. REC. BY:

REF:

CS/SM019002526/Avd3/12

Special Instruction:

Surveyor:

Adrian

ASSIGNMENT (Office)

From (Person):

Merimen  
Huang Shiang Yi

of

SMO

Date/Time:

11/2/19 @ 5.45pm

Estimated Cost:

Bill to:

OD/TP/WS/TP RES/OD RES/EVA/INV/MV/CS

To Inspect Vehicle No:

SJJ 3629X

Insured:

SBM 9909C

at Workshop m/s

Hua Meng

Tel:

67465819

of

1 Kaki Bukit Ave 6 # 01-61

Policy No:

D18M1PV01004849

Claim No:

CMTD1900809

Sum Insured:

Excess:

Make of Veh:

(Client's Record)

D.O.A.

10/02/2019

CA / REV / REP. / REV 24 HRS

H.O.D. Endorsement:

Date/Time:

2.26pm @ 12/2/19

Person Contacted:

June

Vehicle IN/OUT

Date/Time

Action/Instruction (✓) Estimate

SJJ 3629X - CC6/A1G13004314/Ka2a3g2

DOT: 1/3/13

SBM 9909C - X.

13/2/19

Informed Shiang Yi pending workshop est by merimen

30/4/19

Adrian confirmed LS \$12000 (Red 17,796.75, 60%)

2/5/19

Send preli revised via merimen

ASS. REC. BY:

REF:

Adrian

## ASSIGNMENT

From: \_\_\_\_\_ Date: \_\_\_\_\_

Estimated Cost: \_\_\_\_\_

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No: \_\_\_\_\_

at Workshop m/s \_\_\_\_\_

of \_\_\_\_\_

Insured: \_\_\_\_\_

Policy No. \_\_\_\_\_


Claims No. \_\_\_\_\_

Sum Insured: \_\_\_\_\_ Excess: \_\_\_\_\_

(Client's Record)

Make of Veh: \_\_\_\_\_

(Policy Condition)

Remark: The veh had commenced its  
repair at the time of inspection.

Bal. or Market Value: \_\_\_\_\_

IDAC Accident Rpt: \_\_\_\_\_ Consistent?: Yes or No

GIA / PR Seen: \_\_\_\_\_ Consistent?: Yes or No

Est. Repairs: 14 days Res.: Yes or No

Lum Sum: \_\_\_\_\_ % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Date: \_\_\_\_\_ Vehicle: IN / OUT

Person Contacted: \_\_\_\_\_

Veh No: SJJ3629X Yr Regn: 2008, Sept.Type: M/Car / M/Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make: Toyota Axio c.c. 1496Colour: Gold A/C: Insured / Std / Nil / NASp. Reading 356 961 T/Radio: Insured / Std / Nil / NA

Eng/No: \_\_\_\_\_

C/No: NZE1416088864Gen. Cond: Good / Fair / Poor / BurntSteering: In order / Jammed / Leaked / Burnt orBrake: In order / Jammed / Leaked / Burnt orModi: Nil / S/Rim / STD A/Rim orTyre Size: F: 185/70R14R: 185/70R14

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or Hakubond

Front

Rear

R/Bal. 06 mm R/Bal. 06 mmL/Bal. 06 mm L/Bal. 06 mmD.O.A. \_\_\_\_\_ D.O.I. 12/02/19Survey held at Hua MengDes. of Damages: Front / Rear / O/S / N/S / UIC / Rooftop or

The UIC / Chassis frame / Body Structure affected due to collision.

Date / Time

Action / Instruction

TP AXA SompCOE Expiry: 09/09/23MV: 27KPV: 14.8KNett: 12.2K

RECEIVED 02 MAY 2019

Date/Time, File Pass to?

Date/Time, File Return to?

1) >15- typist

2)

3)

4)

5)

6)

Prel. Report

Final Report

Part Prices Check:

IN

OUT

Survey Fee:

Date:

Basic &amp; Add.

S + RS, SI

Photos

Others

TOTAL

450  
10460

**LKK Auto Consultants Pte Ltd** (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

To: Somp Insurance Singapore Pte. Ltd. 50 Raffles Place #05-01/06, Singapore Land Tower Singapore 048623	From: LKK Auto Consultants Pte Ltd 51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park Singapore 408933
Attn: Hwang Shiang Yi	Date: 02 May 2019

**Preliminary Advice**

Insured Vehicle No	: SBM9909C	Accident Date	: 10/02/2019
TP Vehicle No	: SJJ3629X	Assignment Date	: 11/02/2019
Make	: TOYOTA AXIO	Est. Duration of Repair	: 14
Date of Inspection	: 12/02/2019		
Inspection At	: HUA MENG SPRAY PAINTING WORKSHOP (HQ) NO 1 KAKI BUKIT AVENUE 6, #01-61 AUTOBAY@KAKI BUKIT SINGAPORE 417883		

**Point of Impact / General Description of Damages**

The vehicle sustained impact / damages front and rear portion and parts claimed are consistent to the accident.

Repairer's Estimate (Gross)	:S\$	29,796.75
Revised Amount	:S\$	12,000.00 (LUMP SUM )
Check Items (Estimated)	:S\$	0.00
Total	:S\$	0.00
Lump Sum Repair	:S\$	

**Total Loss Consideration**

New for Old Value	:S\$	
Pre-Accident Value	:S\$	
COE / PARF Rebate	:S\$	
Salvage Value	:S\$	
Margin for Repair	:S\$	

**Remarks**

<input type="checkbox"/>	The vehicle is repairable at our adjusted amount. We have also confirmed excess and policy coverage. Kindly let us have your authorisation.
<input type="checkbox"/>	The vehicle is uneconomical to be repaired, you are advised to invite tender for the wreck.
<input checked="" type="checkbox"/>	Other comments : The above survey was conducted on a 'Without Prejudice' basis.

## View Sent Message

This mail is associated with :

**\*SJJ3629X (CMTD1900809)**  
**[SBM9909C]**

TP  
LIM YU SHENG  
Feb 10 2019 4:00PM  
[GOH HWEE HIANG]  
Hua Meng Spray Painting Workshop

[Resend](#)[View Recipients](#)[Print Message](#)[Delete Message](#)[Forward](#)

**From** LKK Auto Consultants Pte Ltd (LKK\_HQ), sent on **13/02/2019 13:17 PM.**  
**To** shiangyi.hwang@sompo.com.sg  
**Subject** TP SURVEY SJJ 3629X

Dear Shiang Yi,

Please be informed that we have inspected the vehicle SJJ 3629X on 12/2/2019.

We are pending estimate from repairer.

Best Regards,  
Veron Chen

### DOCUMENTS SUMMARY

There are no documents.

## ...CLAIM SUBFOLDER...(New Assignment)

### CLAIM SUBFOLDER TRACKING

Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'd	Status
Main	11 Feb 2019		11 Feb 2019 17:45 <a href="#">Assign</a>				<b>New Assignment</b> <a href="#">Cancel Case</a>

Main	Reference	Claim Details	Documents	<a href="#">Show All</a>
------	-----------	---------------	-----------	--------------------------

#### CLAIM SUBFOLDER DETAILS [Created by insurer]

Insured:	GOH HWEE HIANG, ID: S1686929E			
Main Claimant:	LIM YU SHENG			
Vehicle Reg. No.:	SJJ3629X	Date of Loss:	10/02/2019 16:00 - :59	
Claim Type:	TP / CMTD1900809	Policy/Cover Note No.:	D18MTPV01004849 (Comprehensive)	
Vehicle Reg. No. (Insured):	SBM9909C	Policy No. (Claimant):		
		Excess:		
Repairer:	Hua Meng Spray Painting Workshop (HQ) No 1 Kaki Bukit Avenue 6, #01-61 Autobay@Kaki Bukit, 417883 Kaki Bukit - Tel: 67478064, 67465519			
Handling Insurer:	Sompo Insurance Singapore Pte. Ltd. (HQ) - Tel: 6461 6555 ... [Handled by Hwang Shiang Yi - 6329 5205]			
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Final Rpt due 20/02/2019]			
Adj Asg. Remarks:	-PLEASE BE INFORMED THAT OUR INSURED HAS NOT REPORTED THE ACCIDENT -NO TP SAS SUBMITTED			

#### ASSOCIATED MAIL RECEIVED

[View All](#)
[Compose Case Mail](#)

There are no mail for this case.

#### ALL ASSOCIATED TASKS

[View All](#)
[Search Tasks](#)
[Create New Task](#)
[Complete](#)

Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									



## CONNECTING CAR BUYERS &amp; SELLERS.

We'll handle your loans, insurance &amp; other paperwork for FREE.

Find out more



► **SEARCH** axio Price Range Depreciation > 10 year(s) Vehicle Type Search View All Advanced Search

## ► Used Car Comparison

--- Comparing 4 Vehicles ---

Toyota Corolla Axio 1.5A X (COE till 09/2023)



Clear All

Add all to Shortlist

Back to search result

Add to Shortlist

Toyota Corolla Axio 1.5A X (New 5-yr COE)



Add to Shortlist

Toyota Corolla Axio 1.5A X (COE till 11/2023)



Add to Shortlist

Toyota Corolla Axio 1.5A X (COE till 11/2023)



Add to Shortlist

## CAR DETAILS

Price	\$27,800	\$29,800	\$30,800	\$27,800
Instalment	N.A.	N.A.	N.A.	N.A.
Registration Date	05-Sep-2008	28-Oct-2008	05-Nov-2008	07-Nov-2008
Manufactured	2008	2008	2008	2008
Mileage	-	120,000 km	90,000 km	108,000 km
Transmission	Auto	Auto	Auto	Auto
Engine Cap	1,496 cc	1,496 cc	1,496 cc	1,496 cc
Road Tax	\$750 /yr	\$750 /yr	\$750 /yr	\$750 /yr
Power	81.0 kW (108 bhp)	81.0 kW (108 bhp)	81.0 kW (108 bhp)	81.0 kW (108 bhp)
Curb Weight	1,130 kg	1,130 kg	1,130 kg	1,130 kg
Features	1.5L 16 Valves 4 Cylinders VVTi DOHC Engine. Smooth CVT Auto Transmission, ABS, SRS Airbags, Immobilizer.	Reliable & Fuel Efficient 1.5L 16 Valves 4 Cylinders Toyota VVTi DOHC Engine. Smooth CVT Auto Transmission, ABS, SRS Airbags, Immobilizer, Etc	1.5L DOHC VVTi Engine DOHC Engine, Auto Transmission Gearbox, Climate Aircon Control, ABS, Dual Airbags.	Work Late? Call Us Hour Appointment. Serve. No Obligatic STA Inspection We
Accessories	Premium Leather Seats, Sports Rim, DVD Player, Reverse Sensors, Retractable Side Mirrors. Fully Auto 4 Power Window Control.	Sports Rims, Leather Seats, Audio Player, Reverse Sensor, Retractable Side Mirror, Etc.	Leather Seats, Sports Rims, DVD Player, Reverse Sensors, Retractable Mirrors.	Fully Original, Spor Seats, CD Player/A Retractable Side M Solar Film.
Description	Lowest Fuel Consumption In The Market. In House Loan And Bank Loan Available! Well Maintained, View To Believe. Suitable And Affordable Unit. Genuine Mileage Clocked 17K P.A. Buy With A Peace Of Mind, Welcome STA/VICOM Evaluation, Loan And Trade In Available. Call Us Now To View And Test Drive The Car.	Just Arrived! Well Maintained By Previous Owner! High Loan With High Trade In Available. Price Negotiable. Call Now Or Visit Our Showroom Today.	Brand New Condition, View To Believe, \$3K Drive Away, Call Now!	Well Maintained, Si Mileage Done. Wel No Repairs Needec Months Warranty E Workshop. Free Isl Event Of Emergen Trade In, Insuranc With Flexibility. Kin More Information, Workshop Pre-Purc Welcomed! Like Ne
COE	\$16,170	-	\$14,835	\$14,835
OMV	\$11,657	\$13,720	\$12,046	\$11,822
ARF	\$7,189	\$13,720	\$12,046	\$11,822
Depreciation	\$6,100 /yr	\$5,960 /yr	\$6,520 /yr	\$5,880 /yr
No. of Owners	3	3	1	2
Type of Vehicle	Sedan	Sedan	Sedan	Sedan
Category	COE Car	COE Car	COE Car, Low Mileage Car	COE Car, Premium
Availability	Available	Available	Available	Available
Remarks				

[> Back to OneMotoring](#)**Enquire PARF/COE Rebate for Registered Vehicle****Vehicle Owner Particulars**

Owner ID Type:	Singapore NRIC
Owner ID:	1749A

**Vehicle Details**

Vehicle No.:	SJJ3629X
Vehicle to be Exported:	Yes
Intended Deregistration Date:	12 Feb 2019
Vehicle Make:	TOYOTA
Vehicle Model:	COROLLA AXIO 1.5X A
Primary Colour:	Beige
Manufacturing Year:	2008
Engine No.:	1NZD116088
Chassis No.:	NZE1416088864
Maximum Power Output:	81.0 kW (108 bhp)
Open Market Value:	\$12,173.00
Original Registration Date:	10 Sep 2008
First Registration Date:	10 Sep 2008
Transfer Count:	1
Actual ARF Paid:	\$12,173.00

**Intended PARF Rebate Details**

PARF Eligibility:	Forfeited
PARF Eligibility Expiry Date:	-
PARF Rebate Amount:	\$0.00

**Intended COE Rebate Details**

COE Expiry Date:	09 Sep 2023
COE Category:	A - Car (1600cc & below)
COE Period(Years):	5
PQP Paid:	\$16,170.00
COE Rebate Amount:	\$14,799.00
<b>Total Rebate Amount:</b>	<b>\$14,799.00</b>

**Message**

Please note that the 5-year COE for this vehicle cannot be further renewed. The vehicle must be de-registered upon COE expiry or when the vehicle reaches its statutory lifespan (if applicable), whichever is earlier.

The information contained herein is correct as at 12 Feb 2019

OK



M3ME19019058 / SME Motor Pte Ltd - Kaki Bukit  
 ENTRY DATE & TIME: 11/02/2019 17:32  
 SUBMITTED BY: Chia Pei Ying

## SINGAPORE ACCIDENT STATEMENT

### IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

### ACCIDENT STATEMENT

Date Of Report	11/02/2019 17:32
Date Of Accident	10/02/2019 16:30
Exact Location Of Accident	PIE TWDS CHANGI (PAYA LEBAR EXIT)
Country/State of Loss	SINGAPORE

### DETAILS OF OWN VEHICLE

Vehicle Registration Number	SJJ3629X
<b>Insured/Policyholder</b>	
Name Of Registered Owner	LIM YU SHENG
NRIC No	S1711749A
Email Address	NOEMAIL
Mobile Phone No	(LOCAL) +65-90465299
Alternative Phone No	OFFICE-90465299

### Vehicle Particulars

Manufacturer	TOYOTA
Model	AXIO

Exact Purpose for which vehicle was being used at time of accident

Are you claiming under your own insurance policy for repair to your vehicle? NO

If No, Please state action to be taken THIRD PARTY

Vehicle Category PRIVATE CAR

### Insurance Company

Name of Insurance Company	NTUC INCOME INSURANCE CO-OPERATIVE LTD
Type Of Coverage	COMPREHENSIVE
Fleet Policy	NO
Policy Number	5031117491-10
Cover Note Number	

### Driver

Name of Driver	SHERMAN LIM JUN HENG
NRIC No	S9438565B
Date Of Birth	14/10/1994
Occupation	INDOOR
Date Of Driving Pass	15/05/2017
Driving Experience	1 YEAR AND 8 MONTHS
Gender	MALE
Mobile Number	(LOCAL) +65-93284235
Fax Number	
Contact Number	
Email Address	NOEMAIL



Address BLK 359 WOODLANDS AVE 5 #01-364  
 Postcode 730359  
 Was driver an employee of the Insured's Company NO  
 If No, Relationship of the Driver with the Insured OTHER - SON-IN-LAW  
 Vehicle Registration Number of Driver's Own Vehicle -  
 -  
 -  
 Insurance Company of Driver's Own Vehicle -  
 -  
 -

#### General Information of the Accident

Type Of Accident CHAIN COLLISION  
 Weather Conditions CLEAR  
 Road Surface DRY

#### Other Information

Was any foreign vehicle involved in this accident? NO  
 Number of vehicles (including own vehicle) involved in the accident 3  
 Was any body injured in the Accident? YES  
 Was any injured conveyed to hospital by ambulance? NO  
 Was any other material or property damaged? YES  
 I have been approached by unknown person(s) soliciting/offering accident claims assistance. NO  
 Number of Passengers (Including Driver) 2  
 Passenger 1  
 NAME: : LIM YI YING  
 GENDER: : FEMALE

#### Details of Police Action

Was the accident reported to the police? YES  
 If Yes, Please state which Police Station  
 Police Station Name TAMPINES CHANGKAT NPP  
 Police Station Address ROAD: 109 TAMPINES STREET 11 , POSTCODE: 521109 , COUNTRY: SINGAPORE  
 Police Station Contact TEL NO: 1800-7819999 - FAX NO:  
 Was notice of intended Prosecution given? NO  
 If Yes, against whom?

#### Circumstances of Accident

REFER TO POLICE REPORT: T/20190211/2063.

#### Attachment(s)

Are accident photos available for attachment? YES  
 Was there any video captured by Car Camera? NO  
 Was there any audio recorded? NO

#### DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number SBM9909C  
 Vehicle Make/Model/Colour  
 Details Of Properties VEHICLE B  
 Vehicle Category PRIVATE CAR  
 Name of Driver H JENSHEN SINGH  
 NRIC/Passport Number S9700408J  
 Contact Number 90620152  
 Address

Postcode  
 Insurance Company Name  
 Nature Of Damage  
 No. Of Passenger (Including Driver)

**DETAILS OF OTHER VEHICLE PROPERTY 2**

Vehicle Registration Number SLU9726C  
 Vehicle Make/Model/Colour  
 Details Of Properties VEHICLE C  
 Vehicle Category PRIVATE CAR  
 Name of Driver LYNDON TEOH BOON LEE  
 NRIC/Passport Number S6977266H  
 Contact Number

Address  
 Postcode  
 Insurance Company Name  
 Nature Of Damage  
 No. Of Passenger (Including Driver)

**DETAILS OF INJURED PERSON 1**

Name SHERMAN LIM JUN HENG  
 Approximate Age  
 Injuries Sustain  
 Injured person in which vehicle? SJJ3629X  
 Were seat belts worn?  
 Was this injured conveyed to hospital by ambulance?  
 Address  
 Postcode

**DETAILS OF INJURED PERSON 2**

Name LIM YI YING  
 Approximate Age  
 Injuries Sustain  
 Injured person in which vehicle? SJJ3629X  
 Were seat belts worn?  
 Was this injured conveyed to hospital by ambulance?  
 Address  
 Postcode

## SKETCH PLAN

## IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. The report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgment of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.
8. Consent under the Personal Data Protection Act (PDPA)

I understand, acknowledge, agree and consent that:

- (a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this (form) and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of:
  - (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
  - (ii) investigating the accident and/or my claims;
  - (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
  - (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
  - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims (collectively the "Purposes")
- (b) all insurer(s) who have insured vehicle(s) involved in this accident and the Insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
- (c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third party service providers or agents (including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.
- (d) my Personal Information will also be collected and used to compile claims history for the purpose of fraud detection, investigation and management in present and all future claims.
- (e) the information so collected under (d) above may be shared / disclosed:
  - (i) to all insurers and/or any other third parties that assist in evaluating, investigating, controlling or managing fraud, regulators, law enforcement and government agencies as reasonably required for the purposes stated, or
  - (ii) for complying with requirements under any regulations, laws or court orders.

Policyholder's Signature  
Date & Time:

Driver's Signature  
(If driver is not the policyholder)  
Date & Time:

Reporting Centre Personnel's Signature  
Name:  
NRIC/FIN No.:

flua mmer

PIE towards Changi (Payah Lebar I x17)



I was travelling in lane 1 of PIE towards  
Changi (Paya Lebar Exit) on 10.02.2019 @  
1630 hrs. I was followed vehicle C  
to stop. Suddenly, I heard a bang  
sound and felt an impact from my  
rear. Vehicle B collided onto rear  
portion of my vehicle and the  
impact push me forward to hit  
vehicle C.

I/We declare the foregoing particulars are true in every respect.

Reporting Centre Personnel's Signature  
Name:  
NRIC/FIN No.:



**SINGAPORE  
POLICE FORCE**



T/20190211/2063

1 of 4

Police Station Of Origin:  
Changkat NPP  
109 Tampines Street 11 #01-261  
SINGAPORE 521109  
Tel No: 1800-7819999

Report No. T/20190211/2063

**REPORT OF A TRAFFIC ACCIDENT**

Date/Time Report Made: 11/02/2019 12:58	Vide Report No.:	Station Diary No.: 12
--	------------------	--------------------------

**Informant's Particulars**

Name of Informant: SHERMAN LIM JUN HENG			Address: APT BLK 359 WOODLANDS AVENUE 5 #01-364 SINGAPORE 730359		
ID Type / ID No.: NRIC NO / S9438565B			Contact No.: Home/Office: Mobile: 93284235		
Nationality: SINGAPORE CITIZEN			Email:		
Sex: Male	Age: 24	Date of Birth: 14/10/1994	Type of Informant: Driver		
Race: Chinese			Language: English		Institution / School Name:
Occupation: ADMIN EXECUTIVE			Driving Licence Information: Class: Date of Expiry:		

**General Information of the Accident**

Type of Accident:	Injury Others	Drink Drive: No	Date/Time of Accident: 10/02/2019 16:30	Type of Location: Straight Road
Location: Along Road 1 PAN ISLAND EXPRESSWAY				
PIE TOWARDS CHANGI (PAYA LEBAR EXIT)				
Weather: Clear		Road Surface: Dry		Road Speed Limit:
Traffic Flow: One Way		Traffic Control: Not Controlled		Traffic Volume: Moderate
Type of Collision: Between Moving Vehicles - Head To Rear				Anyone conveyed by ambulance: No

**Details of Vehicle Involved**

Vehicle No.	Type	Make	Model	Color	Condition	No of Passenger
SBM9909C	Car	SUBARU		Blue	Slightly Damaged	2
SJJ3629X	Car	TOYOTA	Axio	Gold	Seriously Damaged	1
SLU9726C	Car	TOYOTA	CHR	Yellow	Slightly Damaged	0

**Details of Vehicle Insurance**

Vehicle No.	Insurance Company	Insurance No	Effective	Expiry Date
-------------	-------------------	--------------	-----------	-------------



**SINGAPORE  
POLICE FORCE**



T/20190211/2063

2 of 4

Police Station Of Origin:  
Changkat NPP  
109 Tampines Street 11 #01-261  
SINGAPORE 521109  
Tel No: 1800-7819999

Report No. T/20190211/2063

## CONTINUATION OF REPORT

Details of Vehicle Insurance				
Vehicle No	Insurance Company	Insurance No	Effective	Expiry Date
SJJ3629X	NTUC Income Insurance Co-Operative Limited	5031117491-10	10/09/2018	09/09/2019

Details of Person Involved				
Any Pedestrian Involved: No				
No. of Pedestrians Injured: NIL			Use of Pedestrian Crossing: NA	
<b>Driver</b>				
Name	JENSHEN SINGH		ID No.	S9700408J
Related Vehicle	SBM9909C (Car)		Contact No.	NIL
Hospital/Clinic	NIL		Class of Driving Licence & Expiry Date	Class: NIL Date of Expiry: NIL
Date Treatment	NIL		Date Discharge	NIL
No. of Days granted Medical Leave	NIL		Degree of Injury	NIL
<b>Driver</b>				
Name	SHERMAN LIM JUN HENG		ID No.	S9438565B
Related Vehicle	SJJ3629X (Car)		Contact No.	93284235
Hospital/Clinic	CHANGI GENERAL HOSPITAL		Class of Driving Licence & Expiry Date	Class: NIL Date of Expiry: NIL
Date Treatment	10/02/2019		Date Discharge	10/02/2019
No. of Days granted Medical Leave	03		Degree of Injury	Slight
<b>Driver</b>				
Name	LYNDON TEOH		ID No.	S6977266H
Related Vehicle	SLU9726C (Car)		Contact No.	NIL
Hospital/Clinic	NIL		Class of Driving Licence & Expiry Date	Class: NIL Date of Expiry: NIL
Date Treatment	NIL		Date Discharge	NIL
No. of Days granted Medical Leave	NIL		Degree of Injury	NIL



SINGAPORE  
POLICE FORCE



T/20190211/2063

Police Station Of Origin:  
Changkat NPP  
109 Tampines Street 11 #01-261  
SINGAPORE 521109  
Tel No: 1800-7819999

3 of 4

Report No. T/20190211/2063

CONTINUATION OF REPORT

**Brief Details.**

I was travelling in lane 1 of PIE towards Changi (Paya Lebar Exit) on 10/2/2019 at about 1630hrs. I came to a stop behind vehicle SLU9726C when about 2 seconds later suddenly i heard a loud sound and strong impact from the rear of my vehicle. Vehicle SBM9909C collided into the rear portion of my vehicle and the impact pushed my vehicle forward to hit the vehicle infront of me. My vehicle suffered damages to the front and rear portions. No police or ambulance attended to the scene. I went to consult a doctor after the incident at Changi General Hospital and was given with 3 days MC. My passenger, Lim Yi Ying was provided 2 days. Both of us suffered slight injuries to back, neck and shoulders. I am lodging this report for insurance claims purposes.



## Sketch Plan #6 Pg. 1

SINGAPORE  
POLICE FORCE

T/20190211/2063

4 of 4

Report No. T/20190211/2063

Police Station Of Origin:  
Changkat NPP  
109 Tampines Street 11 #01-261  
SINGAPORE 521109  
Tel No: 1800-7819999

CONTINUATION OF REPORT

Sketch Plan

Informant is not able to provide sketch plan

IMPORTANT: Please attach a copy of your vehicle's Insurance Certificate to this report. If you don't have the certificate with you now, please fax a copy to 65474885 stating the report number as reference.

Signature Of Officer Recording The Report:

G /

Sgt 2 DANESH ASYRAFF BIN LEONADI

Signature Of Informant:

Signature Of Interpreter:

Not applicable

Date/Time:

11/02/2019 12:58

Officer In Charge Of Case:

TP / AEIT /

Sgt 2 SHARIFAH NOR FARIZAN BINTE SYED  
MOHD SAID

Contact No: 65476172

Authentication Stamp

NP169

Classification Of Case:

# HUA MENG SPRAY PAINTING WORKSHOP

1, Kaki Bukit Avenue 6, Blk C #01-61 / 01-34, Singapore 417883

Autobay @ Kaki Bukit

Tel: 6747 8064, 6746 5519 / 9666 9680 Fax: 6743 4896

## ESTIMATE

NZE141

LIM YU SHENG

BLK111 TAMPINES ST11

#11-223

S 521111

TP Sampo  
Veron

Date

:02.03.2019

Vehicle no

:SJJ 3629 X

Make/Model

:TOYOTA AXIO

Accident date

:10.02.2019

No	DESCRIPTION	Qty	Amount (\$\$)
----	-------------	-----	---------------

### List Items

1	Rear windscreen rubber <i>new</i>	1	\$ 107.6 <i>x</i>
2	Rear boot lid <i>Distorted</i>	1	\$ 657.4 <i>✓</i>
3	Rear boot lid hinges @ \$57.00 <i>Best</i>	2	\$ 114 <i>✓</i>
4	Rear boot lid upper lock <i>Damaged</i>	1	\$ 93.2 <i>✓</i>
5	Rear boot lid lower lock	1	\$ 32 <i>✓</i>
6	Rear boot lid handle <i>crushed</i>	1	\$ 230.1 <i>✓</i>
7	Rear boot lid centre emblem <i>New</i>	1	\$ 52.5 <i>✓</i>
8	Rear boot lid AXIO emblem	1	\$ 52.5 <i>✓</i>
9	Rear boot lid X emblem	1	\$ 38.2 <i>✓</i>
10	Rear boot lid insulation <i>new</i>	1	\$ 184.2 <i>x</i>
11	Rear boot lid weather strip <i>new</i>	1	\$ 175.5 <i>✓</i>
12	Rear boot lid number plate lamp @ \$57.90 <i>new</i>	2	\$ 115.9 <i>x</i>
13	Rear end panel <i>Distorted</i>	1	\$ 499.7 <i>✓</i>
14	Rear end panel inner top garnish <i>Deland</i>	1	\$ 182.8 <i>✓</i>
15	Rear lamp @ \$413.10 <i>crushed</i>	2	\$ 826.2 <i>652</i>
16	Rear lamp housing @ \$105.50 <i>Dented</i>	2	\$ 211 <i>✓</i>
17	Rear bumper <i>Distorted</i>	1	\$ 477.2 <i>✓</i>
18	Rear bumper side holder @ \$99.80 <i>new</i>	2	\$ 199.6 <i>95</i>
19	Rear bumper bracket @ \$53.40 <i>Dented</i>	2	\$ 106.8 <i>✓</i>
20	Rear bumper clips (1set) <i>New</i>	1	\$ 60 <i>30</i>
21	Rear fender @ \$880.20 <i>Ryis</i>	2	\$ 1760.4 <i>x</i>
22	Rear fender inner trim @ \$346.60 <i>Deland</i>	2	\$ 693.2 <i>✓</i>
23	Rear exhaust pipe <i>new</i>	1	\$ 909.2 <i>x</i>
24	Rear exhaust pipe mounting <i>new</i>	1	\$ 43.5 <i>x</i>
25	Rear centre exhaust pipe	1	\$ 2609.4 <i>x</i>
26	Rear spare tyre well <i>Ryis</i>	1	\$ 773.2 <i>x</i>
27	Rear spare tyre well insulation @ \$567.40 <i>new</i>	3	\$ 1702.2 <i>220 (SN)</i>
28	Rear spare tyre top board <i>Deland</i>	1	\$ 298 <i>✓</i>
29	Rear RH chassis frame <i>Ryis</i>	1	\$ 508.9 <i>x</i>
30	Rear RH door <i>Ryis</i>	1	\$ 993.5 <i>x</i>
31	Rear RH door inner lock <i>new</i>	1	\$ 742.4 <i>x</i>
32	Front bonnet <i>Distorted</i>	1	\$ 950 <i>✓</i>
33	Front bonnet hinges @ \$56.60 <i>new</i>	2	\$ 113.2 <i>x</i>
34	Front bonnet lock <i>Damaged</i>	1	\$ 90.7 <i>✓</i>
35	Front bonnet lock bracket <i>Best</i>	1	\$ 103.8 <i>✓</i>
			16410

# HUA MENG SPRAY PAINTING WORKSHOP

1, Kaki Bukit Avenue 6, Blk C #01-61 / 01-34, Singapore 417883

Autobay @ Kaki Bukit

Tel: 6747 8064, 6746 5519 / 9666 9680 Fax: 6743 4896

## ESTIMATE

LIM YU SHENG

BLK111 TAMPINES ST11

#11-223

S 521111

Date

:02.03.2019

Vehicle no

:SJJ 3629 X

Make/Model

:TOYOTA AXIO

Accident date

:10.02.2019

No	DESCRIPTION	Qty	Amount (\$\$)
36	Front grille <i>cracked</i>	1	\$ 385.8 ✓
37	Front inner rubber <i>new</i>	1	\$ 85.7 ✓
38	Front grille clips (1set) <i>new</i>	1	\$ <del>40</del> 20
39	Front head lamp @ \$843.90 <i>cracked</i>	2	\$ 1687.8 ✓
40	Front support panel <i>Buckled</i>	1	\$ 876.3 ✓
41	Front bumper <i>Distorted</i>	1	\$ 482 ✓
42	Front bumper side holder @ \$55.20 <i>new</i>	2	\$ 110.4 ✓
43	Front bumper reinforcement <i>Bent</i>	1	\$ 351.2 ✓
44	Front bumper sponge <i>cracked</i>	1	\$ 69.2 ✓
45	Frontbumper bracket @ \$63.20 <i>new</i>	2	\$ 126.4 ✓
46	Front bumper fog lamp garnish @ \$53.50 <i>new</i>	2	\$ 107 ✓
47	Front bumper fog lamp @ \$308.00 <i>new</i>	2	\$ <del>616</del> 308
48	Front bumper clips (1set) <i>new</i>	1	\$ <del>50</del> 30
49	Front fender @ \$742.70 <i>new</i>	2	\$ 1485.4 ✓
50	Front fender inner shield @ \$177.70 <i>new</i>	2	\$ 355.4 ✓
51	Air con condenser <i>Bent</i>	1	\$ 1490.4 ✓
52	Radiator <i>Bent</i>	1	\$ 1776.3 ✓
53	Radiator top garnish <i>new</i>	1	\$ 98.8 ✓
54	Fan motor <i>new</i>	1	\$ <del>911</del> 381 ✓
55	Fan blade <i>new</i>	1	\$ 91 ✓
56	Fan cowling <i>cracked</i>	1	\$ 135 ✓
57	Horn @ \$203.50 <i>new</i>	2	\$ 407 ✓
58	Rear fender inner shield @ \$85.90 <i>new</i>	2	\$ 171.8 ✓
59	Rear spare tyre well RH side panel <i>new</i>	1	\$ 271 ✓
			\$ 28365
		Less 25 % Disc	\$ 7091.25
		Total	\$ 21273.75

### Special Nett Items

1	Rear boot lid camera <i>Damaged</i>	1	\$ <del>800</del> 380
2	Rear number plate <i>Bent</i>	1	\$ <del>50</del> 30
3	Rear number plate holder <i>Damaged</i>	1	\$ <del>50</del> 30
4	Rear bumper reverse sensor <i>Damaged</i>	1	\$ <del>380</del> 200
5	Front number plate <i>Bent</i>	1	\$ <del>50</del> 30
6	Front number plate holder <i>Damaged</i>	1	\$ <del>50</del> 30
		Total	\$ 1380

# HUA MENG SPRAY PAINTING WORKSHOP

1, Kaki Bukit Avenue 6, Blk C #01-61 / 01-34, Singapore 417883

Autobay @ Kaki Bukit

Tel: 6747 8064, 6746 5519 / 9666 9680 Fax: 6743 4896

## ESTIMATE

LIM YU SHENG

BLK111 TAMPINES ST11

#11-223

S 521111

Date :02.03.2019

Vehicle no :SJJ 3629 X

Make/Model :TOYOTA AXIO

Accident date :10.02.2019

No	DESCRIPTION	Qty	Amount (\$\$)
----	-------------	-----	---------------

### Labour Cost

1	Remove & reinstall air con fill in gas		\$ <del>200</del> 120
2	Remove & reinstall camera		\$ <del>100</del> 50
3	Remove & reinstall petrol tank		\$ 150 x
4	Remove & reinstall exhaust pipe		\$ 150 x
5	Remove & reinstall reverse sensor		\$ <del>150</del> 50
6	Remove & reinstall cushion & roof lining		\$ <del>250</del> 60
7	Remove & reinstall rear windscreen		\$ 150 x
8	Remove, replace & repair consistent to the accident	4400	\$ 3000 2000
9	Respray painting		\$ <del>2200</del> 2000
10	Tuff kote		\$ <del>150</del> 60
11	To supply rear windscreen sealant		\$ 50 x
12	To supply rear end panel inner sealant		\$ <del>200</del> 60
Total			\$ 6750
Grand Total			\$ 29403.75 29,796.75

total: 15268.50  
1/5 12K  
(Nett Value)  
14 days.

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

## LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

## VEHICLE DAMAGE INSPECTION REPORT

Our File No: CS/SMO19002526/AVD3N2

Date: 08/05/2019

## REFERENCE

Handling Insurer:	Sompo Insurance Singapore Pte. Ltd.	Policy No:	D18MTPV01004849
Claimant Vehicle No :	SJJ3629X	Insured Vehicle No :	SBM9909C
Date of Loss:	10/02/2019	Nature of Claim:	TP
		Claim No:	CMTD1900809

## DESCRIPTION &amp; IDENTIFICATION OF VEHICLE

Reg No:	SJJ3629X	Engine No:	1NZD116088
Make & Model:	TOYOTA COROLLA, AXIO 1.5 X (A)	Chassis No:	NZE1416088864
Reg. Date:	10/09/2008 (Man. Year: 2008)	Odometer:	356961 km
Colour:	Gold		
Engine Capacity:	1496 cc		
Market Value/New Car Price:	N/A		
Sum Insured (\$\$):	Market Value/New Car Price		

## CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

## CONDITION OF TYRES

Front Tyre Size:	185/70R14	Rear Tyre Size:	185/70R14
Front Left Side:	Habilead 6 mm	Rear Left Side:	Habilead 6 mm
Front Right Side:	Habilead 6 mm	Rear Right Side:	Habilead 6 mm

The above values represent the remaining tyre treads depth

## COST OF CLAIMS

	Repairer's	Adjuster's	Difference	Diff %
Parts	23,296.75	11,128.50	12,168.25	52.23
Miscellaneous Items	0.00	0.00	0.00	
Labour	6,500.00	4,340.00	2,160.00	33.23
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
<b>Calculated Gross Total (\$\$)</b>	<b>29,796.75</b>	<b>15,468.50</b>	<b>14,328.25</b>	<b>48.09</b>
<b>Approved Total (Overridden) (\$\$)</b>		<b>12,000.00</b>		
<b>Nett Amount (\$\$)</b>	<b>29,796.75</b>	<b>12,000.00</b>	<b>17,796.75</b>	<b>59.73</b>

## INSPECTION

Date of Assignment:	11/02/2019	
Date Inspected:	12/02/2019 Inspected At:	Hua Meng Spray Painting Workshop (HQ) No 1 Kaki Bukit Avenue 6, #01-61 Autobay@Kaki Bukit Singapore 417883

Estimated Period of Repair: 14.0 days

Adjuster: ADRIAN LING

Manager: VERON CHEN

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.



## REPAIR DETAILS

## Reference

<b>Part Source:</b> MRM-SG	Version: 1.0 (Last Synchronised: 08 May 2019)
<b>Parts:</b> 143	TOYOTA COROLLA AXIO 1.5 X (A) (Catalogue:Merimen Singapore 1.0)
<b>Labour:</b> Repairer's	(Price-denominated Standard List)
<b>Print Code:</b> (Unsubmitted, no print-code for SJJ3629X)	
<b>Validity:</b>	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page
<b>Further Info:</b>	Items/values not in reference catalogue are prefixed with an asterisk *.

## Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*REAR WINDSCREEN RUBBER	Not Necessary	107.60 FL	*- FL
2	1		*REAR BOOT LID	Distorted	657.40 FL	*657.40 FL
3	2		*REAR BOOT LID HINGES	Bent	114.00 FL	*114.00 FL
4	1		*REAR BOOT LID UPPER LOCK	Damaged	93.20 FL	*93.20 FL
5	1		*REAR BOOT LID LOWER LOCK	Damaged	32.00 FL	*32.00 FL
6	1		*REAR BOOT LID HANDLE	Cracked	230.10 FL	*230.10 FL
7	1		*REAR BOOT LID CENTRE EMBLEM	Necessary	52.50 FL	*52.50 FL
8	1		*REAR BOOT LID AXIO EMBLEM	Necessary	52.50 FL	*52.50 FL
9	1		*REAR BOOT LID X EMBLEM	Necessary	38.20 FL	*38.20 FL
10	1		*REAR BOOT LID INSULATION	Not Necessary	184.20 FL	*- FL
11	1		*REAR BOOT LID WEATHER STRIP	Cut	175.50 FL	*175.50 FL
12	2		*REAR BOOT LID NUMBER PLATE LAMP	Not Necessary	115.90 FL	*- FL
13	1		*REAR END PANEL	Distorted	499.70 FL	*499.70 FL
14	1		*REAR END PANEL INNER TOP GARNISH	Deformed	182.80 FL	*182.80 FL
15	2		*REAR LAMP	Cracked	826.20 FL	*652.00 FL
16	2		*REAR LAMP HOUSING	Dented	211.00 FL	*211.00 FL
17	1		*REAR BUMPER	Distorted	477.20 FL	*477.20 FL
18	2		*REAR BUMPER SIDE HOLDER	Necessary	199.60 FL	*95.00 FL
19	2		*REAR BUMPER BRACKET	Dented	106.80 FL	*106.80 FL
20	1		*SET REAR BUMPER CLIPS	Necessary	60.00 FL	*30.00 FL
21	2		*REAR FENDER	Repair	1,760.40 FL	*- FL
22	2		*REAR FENDER INNER TRIM	Deformed	693.20 FL	*693.20 FL
23	1		*REAR EXHAUST PIPE	Not Necessary	909.20 FL	*- FL
24	1		*REAR EXHAUST PIPE MOUNTING	Not Necessary	43.50 FL	*- FL
25	1		*REAR CENTRE EXHAUST PIPE	Not Necessary	2,609.40 FL	*- FL
26	1		*REAR SPARE TYRE WELL	Repair	773.20 FL	*- FL
27	1		*REAR SPARE TYRE TOP BOARD	Deformed	298.00 FL	*298.00 FL
28	1		*REAR RH CHASSIS FRAME	Repair	508.90 FL	*- FL
29	1		*REAR RH DOOR	Repair	993.50 FL	*- FL
30	1		*REAR RH DOOR INNER LOCK	Not Necessary	742.40 FL	*- FL
31	1		*FRONT BONNET	Distorted	950.00 FL	*950.00 FL
32	2		*FRONT BONNET HINGES	Not Necessary	113.20 FL	*- FL
33	1		*FRONT BONNET LOCK	Damaged	90.70 FL	*90.70 FL
34	1		*FRONT BONNET LOCK BRACKET	Bent	103.80 FL	*103.80 FL
35	1		*FRONT GRILLE	Cracked	385.80 FL	*385.80 FL
36	1		*FRONT INNER RUBBER	Not Necessary	85.70 FL	*- FL
37	1		*SET FRONT GRILLE CLIPS	Necessary	40.00 FL	*20.00 FL
38	2		*FRONT HEAD LAMP	Cracked	1,687.80 FL	*1,687.80 FL
39	1		*FRONT SUPPORT PANEL	Buckled	876.30 FL	*876.30 FL
40	1		*FRONT BUMPER	Distorted	482.00 FL	*482.00 FL
41	2		*FRONT BUMPER SIDE HOLDER	Necessary	110.40 FL	*110.40 FL
42	1		*FRONT BUMPER REINFORCEMENT	Bent	351.20 FL	*351.20 FL
43	1		*FRONT BUMPER SPONGE	Cracked	69.20 FL	*69.20 FL
44	2		*FRONT BUMPER BRACKET	Not Necessary	126.40 FL	*- FL

Report was unsubmitted during this print-out.



No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
45	2		*FRONT BUMPER FOG LAMP GARNISH	Not Necessary	107.00 FL	*- FL
46	1		*FRONT BUMPER FOG LAMP	N/s Cracked	616.00 FL	*308.00 FL
47	1		*SET FRONT BUMPER CLIPS	Necessary	50.00 FL	*30.00 FL
48	2		*FRONT FENDER	Repair	1,485.40 FL	*- FL
49	2		*FRONT FENDER INNER SHIELD	Not Necessary	355.40 FL	*- FL
50	1		*RADIATOR	Bent	1,776.30 FL	*1,776.30 FL
51	1		*RADIATOR TOP GARNISH	Not Necessary	98.80 FL	*- FL
52	1		*FAN MOTOR	Not Necessary	911.10 FL	*- FL
53	1		*FAN BLADE	Not Necessary	91.00 FL	*- FL
54	1		*FAN COWLING	Cracked	135.00 FL	*135.00 FL
55	2		*HORN	Not Necessary	407.00 FL	*- FL
56	2		*REAR FENDER INNER SHIELD	Not Necessary	171.80 FL	*- FL
57	1		*REAR SPARE TYRE WELL RH SIDE PANEL	Repair	271.00 FL	*- FL
58	1		*REAR SPARE TYRE WELL INSULATION	Necessary	1,276.65 FS	*200.00 FS
59	1		*REAR BOOT LID CAMERA	Damaged	800.00 FS	*380.00 FS
60	1		*REAR NUMBER PLATE	Bent	50.00 FS	*30.00 FS
61	1		*REAR NUMBER PLATE HOLDER	Deformed	50.00 FS	*30.00 FS
62	1		*REAR BUMPER REVERSE SENSOR	Damaged	380.00 FS	*200.00 FS
63	1		*FRONT NUMBER PLATE	Bent	50.00 FS	*30.00 FS
64	1		*FRONT NUMBER PLATE HOLDER	Deformed	50.00 FS	*30.00 FS
65	1		*REAR WINDSCREEN SEALANT	Not Necessary	50.00 FS	*- FS
66	1		*REAR END PANEL INNER SEALANT	Necessary	200.00 FS	*60.00 FS
67	1		*AIR CON CONDENSER	Bent	1,490.40 FL	*1,490.40 FL

F=Franchise part. S=SpcNett. L=ListItemDisc.

<b>Sub Total (\$\$)</b>	<b>30,093.45</b>	<b>14,518.00</b>
<b>- List Item Discount on L Items 25.00/25.00% (\$\$)</b>	<b>6,796.70</b>	<b>3,389.50</b>
<b>Total Parts (\$\$)</b>	<b>23,296.75</b>	<b>11,128.50</b>

Report was unsubmitted during this print-out.

## Recommended Miscellaneous Items

There are no new miscellaneous items selected.

## Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<b>Labour Items</b>				
1	REMOVE & REINSTALL AIR CON FILL IN GAS	New	200.00	120.00
2	REMOVE & REINSTALL CAMERA	New	100.00	50.00
3	REMOVE & REINSTALL PETROL TANK	New	150.00	0.00
4	REMOVE & REINSTALL EXHAUST PIPE	New	150.00	0.00
5	REMOVE & REINSTALL REVERSE SENSOR	New	150.00	50.00
6	REMOVE & REINSTALL CUSHION & ROOF LINING	New	250.00	60.00
7	REMOVE & REINSTALL REAR WINDSCREEN	New	150.00	0.00
8	REMOVE,REPLACE & REPAIR CONSISTENT TO THE ACCIDENT	New	3,000.00	2,000.00
9	RESPRAY PAINTING	New	2,200.00	2,000.00
10	TUFF KOTE	New	150.00	60.00
<b>Gross Labour Cost (\$\$)</b>			<b>6,500.00</b>	<b>4,340.00</b>

Report was unsubmitted during this print-out.

< END OF ESTIMATES >