

ASS. REC. BY:

REP:

CS/MSG19002533/Eqd3<sup>52</sup>

Special Instruction:

Surveyor:

Meinen

ASSIGNMENT (Office)

From (Person):

Monica Chung

of

M81G

Date/Time:

12/2/19 @

Estimated Cost:

Bill to:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No:

SLL 9124L

Insured:

SKN 8868 G

at Workshop m/s

SMRT

Tel:

8666 8567

of

Amk police Division, 51 Amk Ave 9

Policy No:

277 31965QMY

Claim No:

584416

Sum Insured:

Excess:

Make of Veh:

(Client's Record)

D.O.A.

10/11/2018

CA / REV / REP. / REV 24 HRS

1up

12/2/19 @ 3pm

H.O.D. Endorsement:

Date/Time:

3:52pm 12/2/19

Person Contacted:

Deniel

Vehicle IN/OUT

Date/Time

Action/Instruction (✓) Estimate

SLL 9124L-CS/CNB18021136/Arbe 2

DOI: 10/11/18

SKN 8868 G-X

12/2/19 @ 9:27am revised to Monica Chung via Meinen.

Submit for reb. 94, 15 days (Red 0%.)

\* Note = We are unable to check the capacity of vehicle due to no GTA report provided at the time of inspection.

Steve

REF: MSIG

ASSIGNMENT

Form: \_\_\_\_\_ Date: 14/2/19

Estimated Cost: \_\_\_\_\_

OD:  WS / TP RES / OD RES / EVA / INV / MV

To inspect Vehicle No: SLL 9124L

at Work location: SMRT

of: 51 AMK AVE 9, AMK Depot

Insured: \_\_\_\_\_

Policy No: \_\_\_\_\_

Claim No: \_\_\_\_\_

Sum Insured: \_\_\_\_\_ Excess: \_\_\_\_\_

(Client's Record)

Make of Veh: 3pm Daniel @ 8666 8567

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.

Bal. or Market Value: \_\_\_\_\_

IDAC Accident Report: \_\_\_\_\_ Consistent?: Yes or No

GIA / PR Seen: \_\_\_\_\_ Consistent?: Yes or No

Est. Repairs: 15 days Res: Yes or No

Lump Sum: \_\_\_\_\_ % 3 Val: Yes or No

CA / REV / REP. / 24 HRS

Date: \_\_\_\_\_ Person Contacted: \_\_\_\_\_ Vehicle: IN / OUT

Veh No: SLL 9124L

Type:  M. Car /  M. Cycle /  Bus /  Van /  Lorry /  Taxi /  Prime Mover /  Truck /  Trailer or

Make: Mazda 3

Colour: Gray

Sp. Reading: 26176

Eng No: \_\_\_\_\_

Ch No: JM 68 M4 2A86 0346265

Gen. Cond:  Good /  Fair /  Poor /  Burnt

Steering:  in order /  Jammed /  Leaked /  Burnt or

Brake:  in order /  Jammed /  Leaked /  Burnt or

Mod: Nil /  S/Rim /  STD A/Rim or

Tyre Size: F: 205/60R16 R: 11

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI / TOYO / YOKO or TOYO

Front	Rear
R/Bal: 5 mm	R/Bal: 5 mm
L/Bal: 5 mm	L/Bal: 5 mm
D.O.A: 10/11/18	D.O.A: 14/2/19

Survey held at: 51 AMK Avenue 9

Des. of Damages:  Frt /  Rear /  O/S /  N/S /  U/C /  Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time: \_\_\_\_\_ Action / Instruction: \* Workshop send in GIA report

OL 26/2/19

-RECEIVED 26 FEB 2019

Date/Time, File Pass to:  : Preli. Report

11/26/2/19/19:30:  : Final Report

Date/Time, File Return to: \_\_\_\_\_

Days Of Repair: 15

Resurvey No. of Trip: \_\_\_\_\_

Add Fee:  Site Insp (\$)

Interview (\$)

Tech. Inv (\$)

Weekend (\$)

Survey Fee: 150

Transportation: \_\_\_\_\_

Other: \_\_\_\_\_

10

Report Format: NET-TP

Lump Sum / I.B.E. / I.S: 3006.94

## ...CLAIM SUBFOLDER...(New Assignment)

### CLAIM SUBFOLDER TRACKING

Case	Notified	Est. Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'ed	Status
Main	08 Feb 2019		12 Feb 2019 13:45 <a href="#">Assign</a>				<b>New Assignment</b> <a href="#">Cancel Case</a>

Main	Reference	Claim Details	Documents	<a href="#">Show All</a>
------	-----------	---------------	-----------	--------------------------

### CLAIM SUBFOLDER DETAILS

[Created by insurer]

Insured:	Tew Siew Lian, ID: S6846531A		
Main Claimant:	Central Narcotics Bureau, Co. Reg. No.: T08GA0031A		
Vehicle Reg. No.:	SLL9124L	Date of Loss:	10/11/2018 12:00 - :59
Claim Type:	TP / 584416	Policy/Cover Note No.:	27731965QMY (Comprehensive) Coverage: 25/06/2014 - 24/06/2019
Vehicle Reg. No. (Insured):	SKN8868G	Policy No. (Claimant):	
		Excess:	
Repairer:	SMRT Automotive Services Pte Ltd (AMK) ANG MO KIO DEPOT, Ang Mo Kio - Tel: 6480 6282 / 6482 3888		
Handling Insurer:	MSIG Insurance (Singapore) Pte. Ltd. (HQ) - Tel: +65 6827 7888 ... [Handled by Monica Chung Pei Zhen - 6594 2552]		
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Imm.Advice due 13/02/2019]		
Adj Asg. Remarks:	Liability (Non-reporting) appoint LKK. survey the vehicle at Ang Mo Kio Police Division, 51 Ang Mo Kio Ave 9 S(569784) and Contact person: Mr Daniel @8666 8567		

### ASSOCIATED MAIL RECEIVED

[View All](#) [Compose Case Mail](#)

There are no mail for this case.

### ALL ASSOCIATED TASKS

[View All](#) [Search Tasks](#) [Create New Task](#) [Complete](#)

Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

**Note: This document has not been finalised.****LKK Auto Consultants Pte Ltd** (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

To: MSIG Insurance (Singapore) Pte. Ltd.  
4 Shenton Way  
#21-01 SGX Centre 2  
Singapore 068807

From: LKK Auto Consultants Pte Ltd  
51 Ubi Ave 1 #01-25  
Paya Ubi Industrial Park  
Singapore 408933

Attn: Monica Chung Pei Zhen

Date: 19 Feb 2019

**Preliminary Advice**

Insured Vehicle No	: SKN8868G	Accident Date	: 10/11/2018
TP Vehicle No	: SLL9124L	Assignment Date	: 12/02/2019
Make	: MAZDA 3	Est. Duration of Repair	: 15
Date of Inspection	: 14/02/2019		
Inspection At	: SMRT - AMK POLICE DIVISION		

**Point of Impact / General Description of Damages**

The vehicle sustained impact / damages front &amp; rear portion and parts claimed are consistent to the accident.

Repairer's Estimate (Gross)	:S\$	3,006.94
Revised Amount	:S\$	3,006.94
Check Items (Estimated)	:S\$	0.00
Total	:S\$	3,006.94
Lump Sum Repair	:S\$	

**Total Loss Consideration**

New for Old Value	:S\$
Pre-Accident Value	:S\$
COE / PARF Rebate	:S\$
Salvage Value	:S\$
Margin for Repair	:S\$

**Remarks**

- ( ) The vehicle is economical/not economical for repair.
- ( X ) The above survey was conducted on a 'without prejudice' basis. KINDLY AMEND THE MAKE & MODEL TO MAZDA 3 INSTEAD OF VOLKSWAGEN.



**SINGAPORE  
POLICE FORCE**



F/20181110/2118

1 of 3

**POLICE REPORT (NP299)**

Report No. F/20181110/2118

Police Station Of Origin  
Ang Mo Kio North N.P.C  
51 Ang Mo Kio Avenue 9 SINGAPORE  
569784  
Tel No: 1800-4849999

Date/Time Report Made 10/11/2018 17:44		Vide Report No.		Station Diary No. 61	
Name Of Informant MICHAEL SYLVESTER		Address APT BLK 301 UBI AVENUE 1 #03-305 SINGAPORE 400301			
ID Type / ID No. NRIC NO / [REDACTED]		Contact No. Home/Office		Mobile 81013670	
Nationality SINGAPORE CITIZEN		Email Address			
Occupation CNB OFFICER		Sex Male	Age 30	Date of Birth 05/03/1988	Race Indian
Institution/School Name		Language English			
Date/Time Of Incident 10/11/2018 12:55		Location Of Incident CENTRAL EXPRESSWAY SINGAPORE LAMP POST 337 AND 339F			

Brief details.

On 10/11/2018 at or about 1255hrs, while [REDACTED] from AMK Police Div to Police Cantonment Complex [REDACTED] my CNB car got involved in traffic accident along CTE towards City. No one was injured in the said accident. No one was conveyed by ambulance and no Police attended to the case. I switched lane to give way to an ambulance and after doing so, the car behind mine banged into my rear. I stop my car because the car in front of mine stopped. The impact from the rear collision sent my car forward and hit

Signature Of Officer Recording The Report: F / SI MOHAMMED BIN ZAINOL		Signature Of Informant:	
Signature Of Interpreter: Not applicable		Date/Time: 10/11/2018 17:44	
Officer In-Charge Of Case: F / Ang Mo Kio Police Divisional Investigation Branch / Insp LIM THIAN LENG Contact No.: 62181343		Classification Of Case:	

Authentication Stamp





onto the rear of the infront car. My car has front-and-rear camera and I believed the accident footage is captured. I have since handed over the SD memory card to my CNB Transport Officer.

The other two cars involved are namely SGU6999K (front car) and SKN8868G (rear car). All the drivers exchanged particulars at scene and took our own accident photos before leaving the scene.

As a result of the accident my CNB car sustained a dented front number plate, scratches on the front right bumper, right bumper was slightly dislodged. There was scratches and dents on the rear bumper.

At the time of the accident, the [REDACTED] SGT2 Alvin Lim Zhing Hsien and W/Si Ping Siok Hick.

I cannot recall seeing any visible damage on the front bumper of the rear car but I do recall seeing visible damages on the front car's rear bumper. I also do not recall seeing any visible injuries on anyone at the scene and I do not recall hearing anyone there complaining of any bodily pain or injuries. I even asked the other two drivers [REDACTED] and my two colleagues if they were injured or not and all of them told me they were not injured. The other two drivers left thereafter and informed me that they will liase with me thru their respective insurance companies. I wish to state that I informed both other drivers that my car was a government vehicle and they acknowledged me.

The reason as to why I drove to Police Cantonment Complex was because [REDACTED]

[REDACTED]

[REDACTED]

Signature Of Officer Recording The Report:  
F / SI MOHAMMED BIN ZAINOL

Signature Of Informant:

Signature Of Interpreter:  
Not applicable

Date/Time:  
10/11/2018 17:44

Officer In-Charge Of Case:  
F / Ang Mo Kio Police Divisional Investigation Branch /  
Insp LIM THIAN LENG  
Contact No.: 62181343

Classification Of Case:

Authentication Stamp

SN 085

Signature:

Singapore Police Force



**SINGAPORE  
POLICE FORCE**



F/20181110/2118

3 of 3

POLICE REPORT (NP299)

CONTINUATION OF REPORT

Report No. F/20181110/2118

Person Name	Ang Pei Yee		
ID Type	NRIC NO	ID No	S7918534E
Gender	Female	Age	39
Nationality	SINGAPORE CITIZEN	Race	Chinese
Mobile No	91788118		
Person Name	Yeung Zhi Hao		
ID Type	NRIC NO	ID No	S9703039A
Gender	Male	Age	21
Nationality	SINGAPORE CITIZEN	Race	Chinese
Mobile No	81187739		

Signature Of Officer Recording The Report: F / SI MOHAMMED BIN ZAINOL	Signature Of Informant: 
Signature Of Interpreter: Not applicable	Date/Time: 10/11/2018 17:44
Officer In-Charge Of Case: F / Ang Mo Kio Police Divisional Investigation Branch / Insp LIM THIAN LENG Contact No.: 62181343	Classification Of Case:

Authentication Stamp

SN 085

Signature:   
Singapore Police Force



**Scope Of Work  
Home Team Agency**

98576861 King

Steve (LKK) 14/2/19 4:00pm  
PIP  
Reasoning before & after spray  
"without prejudice" 15 days

*[Signature]*  
18/2/19

**SCOPE OF WORK**

**1 To provide labour, materials, transportation, tools and parts and others deemed necessary to carry out the following repairs:**

CONTRACTOR:	SMRT	VEH TYPE:	UNMARKED	UNIT:	CNB SUP F
VEH NO:	QX1286H / SLL9124L	REPAIR TYPE:	ACCIDENT		
VEH MAKE/MODEL:	MAZDA 3	ODOMETER:	26174		

Reference No.	1286/CNB/4W/18/11/01
ILMS No.	-

S/N	Front PARTS DESCRIPTION	PART COST (\$)	QTY	Mark Up Rate	Parts Cost Per Unit After Mark Up (\$)	Total Parts Cost Per Unit After Mark Up (\$)
<b>1</b>	<b>Scope Of Repairs</b>					
1.1	Front Bumper / DO		1		665.50	665.50
1.2	Front RH Bumper Retainer / BR		1		33.88	33.88
1.3	Radiator Grill / BR		1		350.90	350.90
1.4	Front RH Bumper Lower Grill Cover / MIS		1		36.30	36.30
1.5	Front LH Bumper Lower Grill Cover / MIS		1		36.30	36.30
1.6	Front Number Plate / BT		1		60.50	60.50
<b>Remarks:</b>					<b>Parts Total:</b>	\$ 1,183.38
S/N	Front LABOUR DESCRIPTION	Man-Hour Rate (\$)	Man-Hour Qty	Total Man-Hour Cost (\$)		
<b>1</b>	<b>Scope Of Repairs</b>					
1.1	<b>Front Bumper:</b>		5	340.00 ✓		
	Remove & Replace Front Bumper					
	Remove & Replace Front RH Bumper Retainer					
	Putty & Spray Paint for Front Complete Bumper					
1.2	<b>Radiator Grill, Front Bumper Lower Grill Cover :</b>		1	68.00 ✓		
	Remove & Replace Radiator Grill					
	Replace Front RH Bumper Lower Grill Cover					
	Replace Front LH Bumper Lower Grill Cover					
					<b>Labour Total:</b>	\$ 408.00
					<b>Front TOTAL :</b>	<b>\$ 1,591.38</b>

S/N	Rear PARTS DESCRIPTION	PART COST (\$)	QTY	Mark Up Rate	Parts Cost Per Unit After Mark Up (\$)	Total Parts Cost Per Unit After Mark Up (\$)
<b>1</b>	<b>Scope Of Repairs</b>					
1.1	Rear Bumper / DO		1		701.80	701.80
1.2	Rear RH Bumper Tow Eye Cover / BR		1		33.88	33.88
1.3	Rear LH Bumper Tow Eye Cover / BR		1		33.88	33.88
<b>Remarks:</b>					<b>Parts Total:</b>	\$ 769.56
S/N	Rear LABOUR DESCRIPTION	Man-Hour Rate (\$)	Man-Hour Qty	Total Man-Hour Cost (\$)		
<b>1</b>	<b>Scope Of Repairs</b>					
1.1	<b>Rear Bumper:</b>		5	340.00 ✓		
	Remove & Replace Rear Bumper					
	Remove & Re-Install back Reverse Sensor onto new Rear Bumper					
	Putty & Spray Paint for Rear Complete Bumper					
1.2	<b>Rear Bumper Tow Eye Cover:</b>		1	68.00 ✓		
	Remove & Replace Rear RH Bumper Tow Eye Cover					
	Remove & Replace Rear LH Bumper Tow Eye Cover					
	Putty & Spray Paint for Rear RH Bumper Tow Eye Cover					
	Putty & Spray Paint for Rear LH Bumper Tow Eye Cover					
					<b>Labour Total:</b>	\$ 408.00
					<b>Rear TOTAL :</b>	<b>\$ 1,177.56</b>

<b>2</b>	<b>Additional Services</b>					
2.1	Towing Service From Station to Workshop (SOR 10)	176.80	1	176.80 ✓		
2.2	Return Service From Workshop to Station (SOR 9)	61.20	1	61.20 ✓		
					<b>SUB-TOTAL</b>	<b>2 238.00</b>
					<b>Front &amp; Rear GRAND TOTAL :</b>	<b>\$ 3,006.94</b>
<b>Contractor shall complete the entire repair within <u>15</u> working days upon approval date . (Include parts awaiting time)</b>						

Verification of Scope of Work		
Contractor QC	Vetted By:	Approved By:

## ...CLAIM SUBFOLDER...(Pending for Survey Report)

CLAIM SUBFOLDER TRACKING							
Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'ed	Status
Main	08 Feb 2019		12 Feb 2019 13:45 <a href="#">Edit Adj Rpt</a>	<b>S\$3,006.94</b> <a href="#">Edit Estimates</a>	<b>S\$3,006.94</b> <a href="#">View Rpt</a>		<b>Pending for Survey Report</b> <a href="#">Cancel Case</a>

Main	Reference	Claim Details	Documents	<a href="#">Show All</a>
------	-----------	---------------	-----------	--------------------------

CLAIM SUBFOLDER DETAILS		[Created by insurer]	
Insured:	Tew Siew Lian, ID: S6846531A		
Main Claimant:	Central Narcotics Bureau, Co. Reg. No.: T08GA0031A		
Vehicle Reg. No.:	SLL9124L	Date of Loss:	10/11/2018 12:00 - :59 [346 Months and 9 Days From LTA Reg Date (Man Yr)]
Claim Type:	TP / 584416	Policy/Cover Note No.:	27731965QMY (Comprehensive) Coverage: 25/06/2014 - 24/06/2019
Vehicle Reg. No. (Insured):	SKN8868G	Policy No. (Claimant):	
		Excess:	
Repairer:	SMRT Automotive Services Pte Ltd (AMK) ANG MO KIO DEPOT, Ang Mo Kio - Tel: 6480 6282 / 6482 3888		
Handling Insurer:	MSIG Insurance (Singapore) Pte. Ltd. (HQ) - Tel: +65 6827 7888 ... [Handled by Monica Chung Pei Zhen - 6594 2552]		
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Handled by CHEN TSUE YEE] ... [Final Rpt due 14/03/2019]		
Adj Asg. Remarks:	Liability (Non-reporting) appoint LKK. survey the vehicle at Ang Mo Kio Police Division, 51 Ang Mo Kio Ave 9 S(569784) and Contact person: Mr Daniel @8666 8567		
<b>ASSOCIATED MAIL RECEIVED</b>		<a href="#">View All</a>	<a href="#">Compose Case Mail</a>
There are no mail for this case.			
<b>ALL ASSOCIATED TASKS</b>		<a href="#">View All</a>	<a href="#">Search Tasks</a>
		<a href="#">Create New Task</a>	<a href="#">Complete</a>
Due Date	Priority	Type	Task Group
			Subject
			Handler
			Assigned By
			Completed On
			Created On
			Done?
No results.			



## Claim Documents

**\*SLL9124L (584416)**  
**[SKN8868G]**  
**TP**  
**Central Narcotics Bureau**  
**Nov 10 2018 12:00PM**  
**[Tew Siew Lian]**  
**SMRT Automotive Services Pte Ltd**

<a href="#">Upload Documents</a> <a href="#">Upload Photos</a> <a href="#">Compose New Letter</a>			View	View In Browser ▼
<b>Letters/Correspondences</b>			1 per page ▼	<input checked="" type="checkbox"/>
No	Finalized On	MSIG Insurance (Singapore) Pte. Ltd. (HQ)		Thumbnail Print
1	12/02/19 10:53	<b>Non Reporting Letter to OI</b>	1	Load HTM
<b>Assessment Reports</b>			1 per page ▼	<input checked="" type="checkbox"/>
No	Finalized On	LKK Auto Consultants Pte Ltd (HQ)		Thumbnail Print
1	19/02/19 09:27	<b>Adjuster Immediate Advice</b>	1	Load HTM
<b>Photos/Images</b>			3 per page ▼	<input checked="" type="checkbox"/>
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)		Thumbnail Print
1	19/02/19 09:28	<b>Odometer Reading</b>	1	Load JPG <input checked="" type="checkbox"/>
2	19/02/19 09:28	<b>Chassis Number</b>	1	Load JPG <input checked="" type="checkbox"/>
3	19/02/19 09:28	<b>General View</b>	1	Load JPG <input checked="" type="checkbox"/>
4	19/02/19 09:28	<b>General View</b>	1	Load JPG <input checked="" type="checkbox"/>
5	19/02/19 09:28	<b>General View</b>	1	Load JPG <input checked="" type="checkbox"/>
6	19/02/19 09:28	<b>General View</b>	1	Load JPG <input checked="" type="checkbox"/>
7	19/02/19 09:28	<b>General View</b>	1	Load JPG <input checked="" type="checkbox"/>
8	19/02/19 09:28	<b>General View</b>	1	Load JPG <input checked="" type="checkbox"/>
9	19/02/19 09:28	<b>General View</b>	1	Load JPG <input checked="" type="checkbox"/>
10	19/02/19 09:28	<b>General View</b>	1	Load JPG <input checked="" type="checkbox"/>
11	19/02/19 09:28	<b>General View</b>	1	Load JPG <input checked="" type="checkbox"/>
12	19/02/19 09:28	<b>General View</b>	1	Load JPG <input checked="" type="checkbox"/>
13	19/02/19 09:28	<b>General View</b>	1	Load JPG <input checked="" type="checkbox"/>
14	19/02/19 09:28	<b>General View</b>	1	Load JPG <input checked="" type="checkbox"/>
15	19/02/19 09:28	<b>General View</b>	1	Load JPG <input checked="" type="checkbox"/>
16	19/02/19 09:28	<b>General View</b>	1	Load JPG <input checked="" type="checkbox"/>
17	19/02/19 09:28	<b>General View</b>	1	Load JPG <input checked="" type="checkbox"/>
18	19/02/19 09:28	<b>General View</b>	1	Load JPG <input checked="" type="checkbox"/>
19	19/02/19 09:28	<b>General View</b>	1	Load JPG <input checked="" type="checkbox"/>
20	19/02/19 09:28	<b>General View</b>	1	Load JPG <input checked="" type="checkbox"/>
21	19/02/19 09:28	<b>General View</b>	1	Load JPG <input checked="" type="checkbox"/>
22	19/02/19 09:28	<b>General View</b>	1	Load JPG <input checked="" type="checkbox"/>
23	19/02/19 09:28	<b>General View</b>	1	Load JPG <input checked="" type="checkbox"/>
24	19/02/19 09:28	<b>General View</b>	1	Load JPG <input checked="" type="checkbox"/>
25	19/02/19 09:28	<b>General View</b>	1	Load JPG <input checked="" type="checkbox"/>
26	19/02/19 09:28	<b>General View</b>	1	Load JPG <input checked="" type="checkbox"/>
27	19/02/19 09:28	<b>General View</b>	1	Load JPG <input checked="" type="checkbox"/>
28	19/02/19 09:28	<b>General View</b>	1	Load JPG <input checked="" type="checkbox"/>

Letters/Correspondences			1 per page	
No	Finalized On	MSIG Insurance (Singapore) Pte. Ltd. (HQ)		Thumbnail Print
29	19/02/19 09:28	General View		Load JPG
30	19/02/19 09:28	General View		Load JPG
31	19/02/19 09:28	General View		Load JPG
32	19/02/19 09:28	General View		Load JPG
33	19/02/19 09:28	General View		Load JPG
34	19/02/19 09:28	General View		Load JPG
35	19/02/19 09:28	General View		Load JPG
36	19/02/19 09:28	General View		Load JPG
37	19/02/19 09:28	General View		Load JPG
38	19/02/19 09:28	General View		Load JPG
39	19/02/19 09:28	General View		Load JPG
40	19/02/19 09:28	General View		Load JPG
41	19/02/19 09:28	General View		Load JPG
42	19/02/19 09:28	General View		Load JPG
43	19/02/19 09:28	General View		Load JPG
44	19/02/19 09:28	General View		Load JPG
45	19/02/19 09:28	General View		Load JPG
46	19/02/19 09:28	General View		Load JPG
47	19/02/19 09:28	General View		Load JPG
48	19/02/19 09:28	General View		Load JPG
Documentation			1 per page	
No	Finalized On	MSIG Insurance (Singapore) Pte. Ltd. (HQ)		Thumbnail Print
1	08/02/19 16:28	police report		Load PDF
2	08/02/19 16:28	ESTIMATE REPAIR		Load PDF
3	12/02/19 10:28	APPOINT LKK		Load PDF
4	12/02/19 10:32	workshop details		Load PDF
5	13/02/19 15:11	Arrange survey on 14/02/2019 at 3pm		Load PDF

## Documents Checklist

### DOCUMENTS CHECKLIST

Reset

Save

Print

There are no document checklists configured.

### Our Checklist Remarks - LKK Auto Consultants Pte Ltd (HQ)

Show Remarks To:  Handling Insurer

Note: Remarks are private unless you show it to other parties.

## LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

## VEHICLE DAMAGE INSPECTION REPORT

Our File No: CS/MSG19002533/EQD3S2

Date: 26/02/2019

## REFERENCE

Handling Insurer:	MSIG Insurance (Singapore) Pte. Ltd.	Policy No:	27731965QMY
Claimant Vehicle No :	SLL9124L	Insured Vehicle No :	SKN8868G
Date of Loss:	10/11/2018	Nature of Claim:	TP
		Claim No:	584416

## DESCRIPTION &amp; IDENTIFICATION OF VEHICLE

Reg No:	<b>SLL9124L</b>	Engine No:	HIDDEN
Make & Model:	MAZDA 3, 1.6 (A)	Chassis No:	JM6BM42A8G0346265
Reg. Date:	01/01/1990 (Man. Year: 1990)	Odometer:	26176 km
Colour:	Grey		
Engine Capacity:	0 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	<b>Market Value/New Car Price</b>		

## CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Good	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:	

## CONDITION OF TYRES

Front Tyre Size:	205/60R16	Rear Tyre Size:	205/60R16
Front Left Side:	Toyo 5 mm	Rear Left Side:	Toyo 5 mm
Front Right Side:	Toyo 5 mm	Rear Right Side:	Toyo 5 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	1,952.94	1,952.94	0.00	0.00
Miscellaneous Items	0.00	0.00	0.00	
Labour	1,054.00	1,054.00	0.00	0.00
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
<b>Gross Total (S\$)</b>	<b>3,006.94</b>	<b>3,006.94</b>	<b>0.00</b>	<b>0.00</b>
<b>+ GST 7.00/7.00% (S\$)</b>	<b>210.49</b>	<b>210.49</b>	<b>0.00</b>	<b>0.00</b>
<b>Nett Amount (S\$)</b>	<b>3,217.43</b>	<b>3,217.43</b>	<b>0.00</b>	<b>0.00</b>

## INSPECTION

Date of Assignment:	12/02/2019		
Date Inspected:	14/02/2019	Inspected At:	SMRT Automotive Services Pte Ltd AMK POLICE DIVISION 51 ANG MO KIO AVE 9, ANG MO KIO DEPOT
Estimated Period of Repair:	15.0 days		

Adjuster: CHEN TSUE YEE

Manager: SHIAU CHAN

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

NOTE: WE ARE UNABLE TO CHECK THE CAPACITY OF VEHICLE DUE TO NO GIA REPORT PROCEED TO US AT THE TIME OF INSPECTION.

**REPAIR DETAILS****Reference**

<b>Part Source:</b> MRM-SG	Version: 1.0 (Last Synchronised: 26 Feb 2019)
<b>Parts:</b> 144	MAZDA 3 1.6 (A) (Catalogue:Merimen Singapore 1.0)
<b>Labour:</b> Repairer's	(Price-denominated Standard List)
<b>Print Code:</b> (Unsubmitted, no print-code for SLL9124L)	
<b>Validity:</b>	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page
<b>Further Info:</b>	Items/values not in reference catalogue are prefixed with an asterisk *.

**Recommended Parts**

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*FRONT BUMPER	Dented	665.50 F	*665.50 F
2	1		*FRONT RH BUMPER RETAINER	Broken	33.88 F	*33.88 F
3	1		*RADIATOR GRILLE	Broken	350.90 F	*350.90 F
4	1		*FRONT RH BUMPER LOWER GRILL COVER	Missing	36.30 F	*36.30 F
5	1		*FRONT LH BUMPER LOWER GRILL COVER	Missing	36.30 F	*36.30 F
6	1		*FRONT NUMBER PLATE	Bent	60.50 F	*60.50 F
7	1		*REAR BUMPER	Dented	701.80 F	*701.80 F
8	1		*REAR RH BUMPER TOW EYE COVER.	Broken	33.88 F	*33.88 F
9	1		*REAR LH BUMPER TOW EYE COVER	Broken	33.88 F	*33.88 F
<b>Total Parts (S\$)</b>					<b>1,952.94</b>	<b>1,952.94</b>

F=Franchise part.

Report was unsubmitted during this print-out.

## Recommended Miscellaneous Items

There are no new miscellaneous items selected.

## Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<b>Labour Items</b>				
1	FRONT BUMPER: REMOVE & REPLACE FRONT BUMPER. }	New	340.00	340.00
2	REMOVE & REPLACE FRONT RH BUMPER RETAINER. }	New	0.00	0.00
3	PUTTY & SPRAY PAINT FOR FRONT COMPLETE BUMPER. }	New	0.00	0.00
4	RADIATOR GRILL, FRONT BUMPER LOWER GRILLE COVER: REMOVE & REPLACE RADIATOR GRILL.}	New	68.00	68.00
5	REPLACE FRONT RH BUMPER LOWER GRILL COVER. }	New	0.00	0.00
6	REPLACE FRONT LH BUMPER LOWER GRILL COVER. }	New	0.00	0.00
7	REAR BUMPER: REMOVE & REPLACE REAR BUMPER. }	New	340.00	340.00
8	REMOVE & RE-INSTALL BACK REVERSE SENSOR ONTO NEW REAR BUMPER. }	New	0.00	0.00
9	PUTTY & SPRAY PAINT FOR REAR COMPLETE BUMPER. }	New	0.00	0.00
10	REAR BUMPER TOW EYE COVER: REMOVE & REPLACE REAR RH BUMPER TOW EYE COVER. }	New	68.00	68.00
11	REMOVE & REPLACE REAR LH BUMPER TOW EYE COVER. }	New	0.00	0.00
12	PUTTY & SPRAY PAINT FOR REAR RH BUMPER TOW EYE COVER. }	New	0.00	0.00
13	PUTTY & SPRAY PAINT FOR REAR LH BUMPER TOW EYE COVER. }	New	0.00	0.00
14	TOEING SERVICE FROM STATION TO WORKSHOP (SOR 10)	New	176.80	176.80
15	RETURN SERVICE FROM WORKSHOP TO STATION (SOR 9)	New	61.20	61.20
<b>Gross Labour Cost (S\$)</b>			<b>1,054.00</b>	<b>1,054.00</b>

Report was unsubmitted during this print-out.

< END OF ESTIMATES >