

**LKK Auto Consultants Pte Ltd** (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

**VEHICLE DAMAGE INSPECTION REPORT****Our File No:** CS/MSG19002533/EQD3S2**Date:** 27/02/2019REFERENCE

|                              |                                      |                             |             |
|------------------------------|--------------------------------------|-----------------------------|-------------|
| Handling Insurer:            | MSIG Insurance (Singapore) Pte. Ltd. | Policy No:                  | 27731965QMY |
| <b>Claimant Vehicle No :</b> | SLL9124L                             | <b>Insured Vehicle No :</b> | SKN8868G    |
| Date of Loss:                | 10/11/2018                           | Nature of Claim:            | TP          |
|                              |                                      | Claim No:                   | 584416      |

DESCRIPTION & IDENTIFICATION OF VEHICLE

|                             |                                   |             |                   |
|-----------------------------|-----------------------------------|-------------|-------------------|
| Reg No:                     | <b>SLL9124L</b>                   | Engine No:  | HIDDEN            |
| Make & Model:               | MAZDA 3, 1.6 (A)                  | Chassis No: | JM6BM42A8G0346265 |
| Reg. Date:                  | 01/01/1990 (Man. Year: 1990)      | Odometer:   | 26176 km          |
| Colour:                     | Grey                              |             |                   |
| Engine Capacity:            | 0 cc                              |             |                   |
| Market Value/New Car Price: | N/A                               |             |                   |
| Sum Insured (S\$):          | <b>Market Value/New Car Price</b> |             |                   |

CONDITION OF VEHICLE AT THE TIME OF SURVEY

|                          |      |                         |     |                          |     |
|--------------------------|------|-------------------------|-----|--------------------------|-----|
| General Condition:       | Good | Steering (Serviceable): | Yes | Footbrake (Serviceable): | Yes |
| Handbrake (Serviceable): | Yes  | Engine Modification:    | No  | Pre-accident Condition:  |     |

CONDITION OF TYRES

|                   |           |                  |           |
|-------------------|-----------|------------------|-----------|
| Front Tyre Size:  | 205/60R16 | Rear Tyre Size:  | 205/60R16 |
| Front Left Side:  | Toyo 5 mm | Rear Left Side:  | Toyo 5 mm |
| Front Right Side: | Toyo 5 mm | Rear Right Side: | Toyo 5 mm |

*The above values represent the remaining tyre treads depth*

| <b>COST OF CLAIMS</b>         | <b>Repairer's</b> | <b>Adjuster's</b> | <b>Difference</b> | <b>Diff %</b> |
|-------------------------------|-------------------|-------------------|-------------------|---------------|
| Parts                         | 1,952.94          | 1,952.94          | 0.00              | 0.00          |
| Miscellaneous Items           | 0.00              | 0.00              | 0.00              |               |
| Labour                        | 1,054.00          | 1,054.00          | 0.00              | 0.00          |
| Paintwork Labour              | 0.00              | 0.00              | 0.00              |               |
| Towing                        | 0.00              | 0.00              | 0.00              |               |
| <b>Gross Total (S\$)</b>      | <b>3,006.94</b>   | <b>3,006.94</b>   | <b>0.00</b>       | <b>0.00</b>   |
| <b>+ GST 7.00/7.00% (S\$)</b> | <b>210.49</b>     | <b>210.49</b>     | <b>0.00</b>       | <b>0.00</b>   |
| <b>Nett Amount (S\$)</b>      | <b>3,217.43</b>   | <b>3,217.43</b>   | <b>0.00</b>       | <b>0.00</b>   |

INSPECTION

|                             |                          |  |
|-----------------------------|--------------------------|--|
| Date of Assignment:         | 12/02/2019               |  |
| Date Inspected:             | 14/02/2019 Inspected At: | SMRT Automotive Services Pte Ltd<br>AMK POLICE DIVISION 51 ANG MO KIO AVE 9,<br>ANG MO KIO DEPOT |
| Estimated Period of Repair: | 15.0 days                |  |

**Adjuster:** CHEN TSUE YEE**Manager:** SHIAU CHAN*NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.*

2/27/2019

Adjuster Report

NOTE: WE ARE UNABLE TO CHECK THE CAPACITY OF VEHICLE DUE TO NO GIA REPORT PROVIDED TO US AT THE TIME OF INSPECTION.

**REPAIR DETAILS****Reference**

|                            |  |
|----------------------------|--|
| <b>Part Source:</b> MRM-SG | Version: 1.0 (Last Synchronised: 26 Feb 2019)  |
| <b>Parts:</b> 144          | MAZDA 3 1.6 (A) (Catalogue:Merimen Singapore 1.0)  |
| <b>Labour:</b> Repairer's  | (Price-denominated Standard List)  |
| <b>Print Code:</b>         | (Unsubmitted, no print-code for SLL9124L)  |
| <b>Validity:</b>           | These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page |
| <b>Further Info:</b>       | Items/values not in reference catalogue are prefixed with an asterisk *.   |

**Recommended Parts**

| No. | Qty | Part No. | Particulars                        | Condition | Repairer's               | Amount          |                 |
|-----|-----|----------|------------------------------------|-----------|--------------------------|-----------------|-----------------|
| 1   | 1   |          | *FRONT BUMPER                      | Dented    | 665.50 F                 | *665.50 F       |                 |
| 2   | 1   |          | *FRONT RH BUMPER RETAINER          | Broken    | 33.88 F                  | *33.88 F        |                 |
| 3   | 1   |          | *RADIATOR GRILLE                   | Broken    | 350.90 F                 | *350.90 F       |                 |
| 4   | 1   |          | *FRONT RH BUMPER LOWER GRILL COVER | Missing   | 36.30 F                  | *36.30 F        |                 |
| 5   | 1   |          | *FRONT LH BUMPER LOWER GRILL COVER | Missing   | 36.30 F                  | *36.30 F        |                 |
| 6   | 1   |          | *FRONT NUMBER PLATE                | Bent      | 60.50 F                  | *60.50 F        |                 |
| 7   | 1   |          | *REAR BUMPER                       | Dented    | 701.80 F                 | *701.80 F       |                 |
| 8   | 1   |          | *REAR RH BUMPER TOW EYE COVER.     | Broken    | 33.88 F                  | *33.88 F        |                 |
| 9   | 1   |          | *REAR LH BUMPER TOW EYE COVER      | Broken    | 33.88 F                  | *33.88 F        |                 |
|     |     |          |                                    |           | <b>Total Parts (S\$)</b> | <b>1,952.94</b> | <b>1,952.94</b> |

F=Franchise part.

Report was unsubmitted during this print-out.

## Recommended Miscellaneous Items

There are no new miscellaneous items selected.

## Recommended Labour

| No                  | Particulars  | Lab.Type | Repairer's                    | Amount          |
|---------------------|--|----------|-------------------------------|-----------------|
| <b>Labour Items</b> |  |          |                               |                 |
| 1                   | FRONT BUMPER: REMOVE & REPLACE FRONT BUMPER. }                                     | New      | 340.00                        | 340.00          |
| 2                   | REMOVE & REPLACE FRONT RH BUMPER RETAINER. }                                       | New      | 0.00                          | 0.00            |
| 3                   | PUTTY & SPRAY PAINT FOR FRONT COMPLETE BUMPER. }                                   | New      | 0.00                          | 0.00            |
| 4                   | RADIATOR GRILL, FRONT BUMPER LOWER GRILLE COVER: REMOVE & REPLACE RADIATOR GRILL.} | New      | 68.00                         | 68.00           |
| 5                   | REPLACE FRONT RH BUMPER LOWER GRILL COVER. }                                       | New      | 0.00                          | 0.00            |
| 6                   | REPLACE FRONT LH BUMPER LOWER GRILL COVER. }                                       | New      | 0.00                          | 0.00            |
| 7                   | REAR BUMPER: REMOVE & REPLACE REAR BUMPER. }                                       | New      | 340.00                        | 340.00          |
| 8                   | REMOVE & RE-INSTALL BACK REVERSE SENSOR ONTO NEW REAR BUMPER. }                    | New      | 0.00                          | 0.00            |
| 9                   | PUTTY & SPRAY PAINT FOR REAR COMPLETE BUMPER. }                                    | New      | 0.00                          | 0.00            |
| 10                  | REAR BUMPER TOW EYE COVER: REMOVE & REPLACE REAR RH BUMPER TOW EYE COVER. }        | New      | 68.00                         | 68.00           |
| 11                  | REMOVE & REPLACE REAR LH BUMPER TOW EYE COVER. }                                   | New      | 0.00                          | 0.00            |
| 12                  | PUTTY & SPRAY PAINT FOR REAR RH BUMPER TOW EYE COVER. }                            | New      | 0.00                          | 0.00            |
| 13                  | PUTTY & SPRAY PAINT FOR REAR LH BUMPER TOW EYE COVER. }                            | New      | 0.00                          | 0.00            |
| 14                  | TOEING SERVICE FROM STATION TO WORKSHOP (SOR 10)                                   | New      | 176.80                        | 176.80          |
| 15                  | RETURN SERVICE FROM WORKSHOP TO STATION (SOR 9)                                    | New      | 61.20                         | 61.20           |
|                     |  |          | <b>Gross Labour Cost (\$)</b> | <b>1,054.00</b> |
|                     |  |          |                               | <b>1,054.00</b> |

Report was unsubmitted during this print-out.

< END OF ESTIMATES >