

**LKK Auto Consultants Pte Ltd** (Co.Reg.No:199607198R)  
 51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park  
 Singapore 408933  
 Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

## VEHICLE DAMAGE INSPECTION REPORT

**Our File No:** CC6/LCR19002546/UPA3Q2  
**Date:** 18/03/2021

### REFERENCE

|                              |                                      |                             |              |
|------------------------------|--------------------------------------|-----------------------------|--------------|
| Handling Insurer:            | AIG Asia Pacific Insurance Pte. Ltd. | Policy No:                  | 0999994778   |
| <b>Claimant Vehicle No :</b> | SLV6235S                             | <b>Insured Vehicle No :</b> | SLJ7886U     |
| Date of Loss:                | 06/02/2019                           | Nature of Claim:            | TP           |
|                              |                                      | Claim No:                   | 4370202680SG |

### DESCRIPTION & IDENTIFICATION OF VEHICLE

|                             |                                   |             |                   |
|-----------------------------|-----------------------------------|-------------|-------------------|
| Reg No:                     | <b>SLV6235S</b>                   | Engine No:  | R16A13001872      |
| Make & Model:               | HONDA CIVIC, 1.6 (A)              | Chassis No: | JHMFD46208S200528 |
| Reg. Date:                  | 10/01/2008 (Man. Year: 2007)      | Odometer:   | 195872 km         |
| Colour:                     | Blue                              |             |                   |
| Engine Capacity:            | 1595 cc                           |             |                   |
| Market Value/New Car Price: | N/A                               |             |                   |
| Sum Insured (S\$):          | <b>Market Value/New Car Price</b> |             |                   |

### CONDITION OF VEHICLE AT THE TIME OF SURVEY

|                          |                         |                      |                          |                         |
|--------------------------|-------------------------|----------------------|--------------------------|-------------------------|
| General Condition:       | Steering (Serviceable): | Yes                  | Footbrake (Serviceable): | Yes                     |
| Handbrake (Serviceable): | Yes                     | Engine Modification: | No                       | Pre-accident Condition: |

### CONDITION OF TYRES

|                   |               |                  |               |
|-------------------|---------------|------------------|---------------|
| Front Tyre Size:  | 205/55Z R16   | Rear Tyre Size:  | 205/55Z R16   |
| Front Left Side:  | Michelin 6 mm | Rear Left Side:  | Michelin 6 mm |
| Front Right Side: | Michelin 6 mm | Rear Right Side: | Michelin 6 mm |

*The above values represent the remaining tyre treads depth*

| COST OF CLAIMS                                  | Repairer's      | Adjuster's      | Difference      | Diff %       |
|-------------------------------------------------|-----------------|-----------------|-----------------|--------------|
| Parts                                           | 158.24          | 0.00            | 158.24          | 100.00       |
| Miscellaneous Items                             | 0.00            | 0.00            | 0.00            |              |
| Labour                                          | 1,930.00        | 1,080.00        | 850.00          | 44.04        |
| Paintwork Labour                                | 0.00            | 0.00            | 0.00            |              |
| Towing                                          | 0.00            | 0.00            | 0.00            |              |
| <b>Gross Total (S\$)</b>                        | <b>2,088.24</b> | <b>1,080.00</b> | <b>1,008.24</b> | <b>48.28</b> |
| <b>+ GST 7.00/7.00% (S\$)</b>                   | 146.18          | 75.60           | 70.58           | 48.28        |
| <b>Nett Amount (S\$)</b>                        | <b>2,234.42</b> | <b>1,155.60</b> | <b>1,078.82</b> | <b>48.28</b> |
| <b>+ Loss of Use (3.0 x S\$60.00/day) (S\$)</b> |                 | 180.00          |                 |              |
|                                                 | (S\$)           | 1,335.60        |                 |              |
| <b>Liabe Amount (50.00%) (S\$)</b>              |                 | <b>667.80</b>   |                 |              |
| <b>+ Doc/Search Fee (S\$)</b>                   |                 | 7.45            |                 |              |
| <b>Nett Liability (S\$)</b>                     |                 | <b>675.25</b>   |                 |              |
| <b>Global Sum Settlement (S\$)</b>              |                 | <b>670.00</b>   |                 |              |

### INSPECTION

Date of Assignment: 14/02/2019

Date Inspected: 14/02/2019 Inspected At:

Hock Wah Motor Workshop Pte Ltd (Bedok)  
 Blk 3011, Bedok Industrial Park E., #01-  
 2008/2010/2012  
 Singapore 489977

3/18/2021

Adjuster Report

Estimated Period of Repair: 3.0 days

---

**Adjuster:** MARCUS CHUA

**Manager:** CHEW HSIAO TONG

*NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.*

REPAIR DETAILS

Recommended Parts

| No. | Qty | Part No. | Particulars                          | Condition     | Repairer's | Amount |
|-----|-----|----------|--------------------------------------|---------------|------------|--------|
| 1   | 1   |          | *REAR DOOR PROTECTOR WITH CHROME RH  | Repair        | 90.40 FL   | *- FL  |
| 2   | 1   |          | *FRONT DOOR PROTECTOR WITH CHROME RH | Repair        | 107.40 FL  | *- FL  |
| 3   | 1   |          | *REAR BUMPER (NPA)                   | Repair        | 0.00 FS    | *- FS  |
| 4   | 1   |          | *REAR FENDER RH (NPA)                | Repair        | 0.00 FS    | *- FS  |
| 5   | 1   |          | *REAR DOOR RH(NPA)                   | Repair        | 0.00 FS    | *- FS  |
| 6   | 1   |          | *FRONT DOOR RH (NPA)                 | Repair        | 0.00 FS    | *- FS  |
| 7   | 1   |          | *ROCKER GARNISH RH (NPA)             | Repair        | 0.00 FS    | *- FS  |
| 8   | 1   |          | *WING MIRROR RH (NPA)                | Not Necessary | 0.00 FS    | *- FS  |

F=Franchise part. S=SpcNett. L=ListItemDisc.

|                                                     |        |      |
|-----------------------------------------------------|--------|------|
| Sub Total (\$\$)                                    | 197.80 | 0.00 |
| - List Item Discount on L Items 20.00/20.00% (\$\$) | 39.56  | 0.00 |
| Total Parts (\$\$)                                  | 158.24 | 0.00 |

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

| No                      | Particulars                              | Lab.Type | Repairer's | Amount   |
|-------------------------|------------------------------------------|----------|------------|----------|
| <b>Labour Items</b>     |                                          |          |            |          |
| 1                       | LABOUR TO REMOVE & REFIT NECESSARY PARTS | New      | 800.00     | 300.00   |
| 2                       | SPRAY PAINT ON THE AFFECTED AREAS        | New      | 800.00     | 780.00   |
| 3                       | ANTI-RUST COATING                        | New      | 180.00     | 0.00     |
| 4                       | TO REMOVE & REFIT REVERSE SENSOR         | New      | 150.00     | 0.00     |
| Gross Labour Cost (S\$) |                                          |          | 1,930.00   | 1,080.00 |

Report was unsubmitted during this print-out.

< END OF ESTIMATES >