

ASS. REC. BY:

REF:

CS/INC19002562/K1H302

Special Instruction:

Surveyor:

Rasul

ASSIGNMENT (Office)

From (Person):

Daniel Koh

of

INC

Date/Time:

12/2/19 @ 10:11am

Estimated Cost:

Bill to:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No:

SLM 2790D

Insured:

SHC 6977G

at Workshop m/s

World Auto

Tel:

63621776

of

No. 1 Krnji loop

Policy No:

Claim No:

MT-103/311-001

Sum Insured:

Excess:

Make of Veh:

(Client's Record)

D.O.A.

4/2/2019

CA / REV / REP. / REV 24 HRS ^{up}

H.O.D. Endorsement:

Date/Time:

11:51am @ 12/2/19

Person Contacted:

Ainee

Vehicle:

IN / OUT

Date/Time

Action/Instruction (✓) Estimate

SLM 2790D-X

SHC 6977G - Cstfcl18008917/K1H302

D.O.A: 12/5/2018

COR \$15801.20 (Red: 13831.52, 46%)
confirmed:

Issue

REF: INC

4597K

DECLARATION

From: Date: 12/2/19

Estimated Cost:

OD: ☒ TP WS / TP RES / OD RES / EVA / INV / MV

Insured Vehicle No: SLM 2790D
World Auto
No-1 kmrji loop

Insured:

Policy No:

Claim No:

Sum Insured:

Excess:

(Client's Record)

Make of Veh:

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.

Bal. or Market Value:

73K

IDAC Accident Report:

Consistent? : Yes or No

GIA / PR Seen:

Consistent? : Yes or No

Est. Repairs:

days Res: Yes or No

Lump Sum:

% 3 Val: Yes or No

CA / REV / REP. / 24 HRS

loop

Vehicle: IN / OUT

Date: Person Contacted:

Veh No: SLM 2790D Regn: 2017 MAR

Type: ☒ M. Car / M. Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make: Honda SHUTTLE 1.5 HYBRID 1496

Colour: BLACK A/C: Insured / Std / Nil / NA

Sp. Reading: - T/Radio: Insured / Std / Nil / NA

Eng/No:

C/No: GP 71101123

Gen. Cond: Good / Fair / Poor / Burnt

Steering: ☒ Harder / Jammed / Leaked / Burnt or

Brake: ☒ Harder / Jammed / Leaked / Burnt or

Mod: Nil / STD A/Rim / STD A/Rim or

Tyre Size: F:

185/60R15

R:

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / ☒ PIR / SUMI /

TOYO / YOKO or

Front

Rear

R/Bal: 6 mm

R/Bal: 6 mm

L/Bal: 6 mm

L/Bal: 6 mm

D.O.A: 04/02/19

D.O.I: 12/02/19

Survey held at

World Auto

0756pm

Des. of Damages: ☒ Front / ☒ Rear / O/S / N/S / U/C / Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision.

RECEIVED 29 APR 2019

Date/Time: File Pass to?

1) 29/4/19 Typist

Date/Time: File Return to?

2)

Report Format:

Lump Sum / L.B.F: TP 15801.20

Days Of Repair: 14

Resurvey No. of Trip:

Add Fee: ☐ Site Insp (\$)

☐ Interview (\$)

☐ Tech. Insp (\$)

☐ Weekend (\$)

Survey Fee:

Transportation:

1) S + P: \$

1) Hotel:

1) Other:

1) Total:

TOTAL

290

290

Nivitha (LKK Auto)

From: Daniel Koh <daniel.koh@income.com.sg>
Sent: Tuesday, 12 February 2019 10:11 AM
To: 'assignments@lkkauto.com'
Cc: Teng Ken Leong; Thio Tse Kiat
Subject: FW: TP CASES FARMED OUT TO LKK ON 12/2/2019

Dear Veron / Catherine,

Please assist to survey the vehicles as per Mr Toh's instruction :-

S/NO	THIRD PARTY	OUR INSURED	WORKSHOP / CONTACT	DOA / REF / OFFICER	TIMING
1	SLH1636A	SJK3446B	VERMOGEN ACE / Pila 63583031	11-2-2019 / MT-1031440-001 / Muhammad Airwan	
2	EV6460R	XE783M	VOLKSWAGEN CENTRE / Edmund Goh 63057299	2-2-2019 / MT-1030828-001 / Helena Tan	10:00-12:00
3	SLU8379C	SIN6151R	CAR CRAFTERS / Jie Ren 94316186	25-1-2019 / MT-1029788-002 / Charlotte Chew	
4	SFS41K	SLF646M	C & C AUTOMOTIVE / Tay Jian Ye 81680997	25-1-2019 / MT-1029518-002 / Rajeswary	11:00-16:00
5	SMC5034A	SKW5684S	C & C FRANCE / Edwin Caina 91819978	7-12-2018 / MT-1023039-002 / Serene Lim	

6	SMA7409A	SLU7485K	HUA HONG PTE LTD / Jerleen 66619688	24-11-2018 / MT-1021408- 002 / David Phua	10:00-12:00
7	YN1111L	SKJ824G	LEE KUAN HWA MOTOR / Siew Chen 62699192	1-2-2019 / MT-1030591-002 / Jeff Lin	
8	EA2318G	SHD2075E	TAN CHONG MOTOR / Lawrence Teo 64694091	23-1-2019 / MT-1029228-002 / Jared Liu	
9	SLM2790D	SHC6977G	WORLD AUTO / Ainee 63621776	4-2-2019 / MT-1031311-001 / David Phua	

Please contact workshops.

Please ack.

Thank You

Daniel Koh
Senior Admin Assistant, Motor Insurance
T +65 6430 7901
www.income.com.sg

income
made different



Denise Tay (LKKAUTO)

From: tgttan@worldauto.com.sg
Sent: Friday, 26 April 2019 3:50 PM
To: Rasul (LKKAUTO)
Subject: SLM 2790D Our ref: TP/2453/19
Attachments: 20190216_151035.jpg; 20190216_151046.jpg; 20190216_151057.jpg; 20190216_151110.jpg; 20190216_151114.jpg; 20190216_151127.jpg; 20190216_151137.jpg; 20190330_153521.jpg; 20190330_153526.jpg; 20190330_153531.jpg; 20190330_153541.jpg; 20190330_153545.jpg; 20190330_153549.jpg; 20190330_153615.jpg; 20190330_153617.jpg; 20190330_153628.jpg; 20190330_153630.jpg; 20190401_092816.jpg; 20190401_092819.jpg; 20190401_092823.jpg; 20190401_092833.jpg; 20190401_092837.jpg; 20190401_092840.jpg

Hi Rasul

Re-survey photos for your attention.

Confirmed finalised COR \$15,801.20 and 14 repair days.

Rdgs
Sophia



Reg No: 52977287 J

CASH SALE/WORK ORDER
迅速拖車服務
SPEEDWAY RECOVERY SERVICE

Singapore Post Centre Post Office P.O. Box 201 Singapore 914007

Tel: 6841 0080

No: C 23645

Date: 4/2/19

Name/Company World Ave (Exxy)

Vehicle No. SLM 27900 Model Shuttle

From 210 A Punggol Rd.

To 1 Karing Road

Remarks _____

Time: 12:30 - 13:10 - 13:55

- ☐ Jump Start
- ☐ Tyre Replacement
- ☒ Accident/Breakdown
- ☐ Multi/Basement
- ☐ With Load/Cargo Box
- ☐ King Dolly
- ☐ Transport Charge
- ☐ Low Body Kit
- ☐ Door Opening Service
- ☐ Crane Up/Winch Out
- ☐ Collect Doc/Key
- ☐ Repo Payment
- ☐ Trips

Amount \$ 80

NOTE: Vehicle is towed at owner's risk. The Company accepts no responsibility for damages or other misdemeanour to your vehicle whilst being towed.

[Signature]
 Tow Truck

24 HRS TOWING SERVICE
6841 0080

www.speedwayrecovery.com
 Email: speedwaytowing@gmail.com

[Signature]
 Received By

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. **Any false reporting may be referred to the Police for investigation.**
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT	
Date Of Report	09/02/2019 15:29
Date Of Accident	04/02/2019 11:50
Exact Location Of Accident	PUNGGOL RD
Country/State of Loss	SINGAPORE
DETAILS OF OWN VEHICLE	
Vehicle Registration Number	SLM2790D
Insured/Policyholder	
Name Of Registered Owner	LCRF PTE LTD
Co Reg No	201624597K
Email Address	NOEMAIL
Mobile Phone No	
Alternative Phone No	OFFICE-62414992
Vehicle Particulars	
Manufacturer	HONDA
Model	SHUTTLE HYBRID-1.5 (A)
Exact Purpose for which vehicle was being used at time of accident	
Are you claiming under your own insurance policy for repair to your vehicle?	NO
If No, Please state action to be taken	THIRD PARTY
Vehicle Category	PRIVATE HIRE
Insurance Company	
Name of Insurance Company	AIG ASIA PACIFIC INSURANCE PTE. LTD.
Type Of Coverage	COMPREHENSIVE
Fleet Policy	YES
Policy Number	999995110
Cover Note Number	
Driver	
Name of Driver	CHEW MARN WENG
NRIC No	S0031443I
Date Of Birth	02/10/1954
Occupation	OUTDOOR
Date Of Driving Pass	01/08/1975
Driving Experience	43 YEARS AND 6 MONTHS
Gender	MALE
Mobile Number	(LOCAL) +65-94568040
Fax Number	
Contact Number	
EEmail Address	NOEMAIL

Address NOADDRESS

Postcode

Was driver an employee of the Insured's Company NO

If No, Relationship of the Driver with the Insured PAID DRIVER

Vehicle Registration Number of Driver's Own Vehicle -

Insurance Company of Driver's Own Vehicle -

General Information of the Accident

Type Of Accident CHAIN COLLISION

Weather Conditions CLEAR

Road Surface DRY

Other Information

Was any foreign vehicle involved in this accident? NO

Number of vehicles (including own vehicle) involved in the accident 3

Was any body injured in the Accident? YES

Was any injured conveyed to hospital by ambulance? NO

Was any other material or property damaged? YES

I have been approached by unknown person(s) soliciting/offering accident claims assistance. NO

Number of Passengers (Including Driver) 1

Details of Police Action

Was the accident reported to the police? YES

If Yes, Please state which Police Station

Police Station Name ANG MO KIO SOUTH NEIGHBOURHOOD POLICE CENTRE

Police Station Address ROAD: 81 ANG MO KIO AVE 3 , POSTCODE: 569929 , COUNTRY: SINGAPORE

Police Station Contact TEL NO: 1800-4519999 - FAX NO: 65535679

Was notice of intended Prosecution given? NO

If Yes, against whom?

Circumstances of Accident

PLEASE SEE ATTACHED SKETCH

Attachment(s)

Are accident photos available for attachment? YES

Was there any video captured by Car Camera? YES

Remarks/ Reasons: VIDEO OVERWRITTEN

Was there any audio recorded? NO

DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number SHC6977G

Vehicle Make/Model/Colour

Details Of Properties

Vehicle Category TAXI

Name of Driver

NRIC/Passport Number

Contact Number

Address

Postcode

Insurance Company Name

Nature Of Damage

No. Of Passenger (Including Driver)

DETAILS OF OTHER VEHICLE PROPERTY 2

Vehicle Registration Number

SKT6711G

Vehicle Make/Model/Colour

Details Of Properties

Vehicle Category

PRIVATE CAR

Name of Driver

NRIC/Passport Number

Contact Number

Address

Postcode

Insurance Company Name

Nature Of Damage

No. Of Passenger (Including Driver)

DETAILS OF INJURED PERSON 1

Name

CHEW MARN WENG

Approximate Age

Injuries Sustain

Injured person in which vehicle?

Were seat belts worn?

Was this injured conveyed to hospital by ambulance?

Address

Postcode

Sketch Plan

SKETCH PLAN

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. The report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgment of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.
8. **Consent under the Personal Data Protection Act (PDPA)**

I understand, acknowledge, agree and consent that:

- (a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this [form] and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the Insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of:
 - (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
 - (ii) investigating the accident and/or my claims;
 - (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
 - (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
 - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims (collectively the "Purposes").
- (b) all insurer(s) who have insured vehicle(s) involved in this accident and the Insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
- (c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third party service providers or agents (including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes;
- (d) my Personal Information will also be collected and used to compile claims history for the purpose of fraud detection, investigation and management in present and all future claims;
- (e) the information so collected under (d) above may be shared / disclosed:
 - (i) to all insurer and/or any other third parties that assist in evaluating, investigating, controlling or managing fraud, regulators, law enforcement and government agencies as reasonably required for the purposes stated; or
 - (ii) for complying with requirements under any regulations, laws or court orders.




Policyholder's Signature
Date & Time:

Driver's Signature
(If driver is not the policyholder)
Date & Time:

09/02/19
1140

Reporting Centre Personnel's Signature
Name:
NRIC/PIN No:



04/02/2019
1150

The map shows the northern Adriatic coastline of Italy and Slovenia. Sampling stations are marked with numbers 1 through 10. Station 1 is near the Italian coast, while stations 2-10 are further out in the sea. The map includes latitude lines from 45°N to 46°N and longitude lines from 13°E to 14°E.

SKETCH PLAN

Refer to Attached

A hand-drawn sketch of a straight line on a grid background. The line starts from the bottom left and extends towards the top right, with a slight upward curve. The text 'Refer to Attached' is written in the top left corner.

On the 4 Feb 2019 my vehicle SLM 2790D stationed at Punggol Road to proceed to Esso station to pump my petrol

My vehicle is at the last position and another car in front of me marked car B 8KT6776.
(see sketch)

While waiting at Punggol Road a taxi vehicle coming forward my car and ram on my boot the vehicle marked B 3HC69776

Because of the impact my vehicle move forward and ram to marked car C.

The taxi went off the scene for 15 min and return back to the accident location and we exchange details + mobile No.

Because of the impact my necks have injured and with 4 days m.c (see attached)

I/We declare the foregoing particulars are true in every respect

Date & Time:

Date & Time:

Name: _____

NISC/PIN No.

09/02/19
1156

Sketch Plan #4



**SINGAPORE
POLICE FORCE**



T101302092077

1 of 4

Report No: T101302092077

Police Station Of Origin
Ang Mo Kio South N.P.C.
81 Ang Mo Kio Avenue 3 SINGAPORE
569829
Tel No: 1800-4510999

REPORT OF A TRAFFIC ACCIDENT

Date/Time Report Made: 09/02/2019 13:51 Vide Report No: Station Diary No: 95

Informant's Particulars

Name of Informant: CHEW MARN WENG	Address: 3 RIVERVALE LINK #06-28 SINGAPORE 545119		
ID Type / ID No: NRIC NO / S0031443I	Contact No: Home/Office:	Mobile: 94568040	
Nationality: SINGAPORE CITIZEN	Email:		
Sex: Male	Age: 64	Date of Birth: 02/10/1954	Type of Informant: Driver
Race: Chinese	Language:		Institution / School Name:
Occupation: PRIVATE HIRE	Driving Licence Information: Class: 3		Date of Expiry:

General Information of the Accident

Type of Accident: Non-Injury Attended by Police	Drink Drive: No	Date/Time of Accident: 04/02/2019 11:50	Type of Location: Straight Road
Location: Along Road 1 PUNGGOL ROAD			
Along Punggol Road, entrance of Esso Petrol Kiosk			
Weather: Clear	Road Surface: Dry	Road Speed Limit:	
Traffic Flow:	Traffic Control: Not Controlled	Traffic Volume: Light	
Type of Collision: Moving Vehicle Against - Parked Vehicle			Anyone conveyed by ambulance: No

Details of Vehicle Involved

Vehicle No.	Type	Make	Model	Color	Condition	No of Passenger
SHC6977G	Car	KIA	OPTIMA 1.7(A)	Silver	Slightly Damaged	1
SKT6711G	Car	HONDA	HRV 1.5 LX CVT ABS D/AIRBAG 2WD	Silver	Slightly Damaged	3
SLM2790D	Car	HONDA	SHUTTLE 1.5 HYBRID AT ABS D/AIRBAG 2WD	Black	Seriously Damaged	0

Sketch Plan #5



**SINGAPORE
POLICE FORCE**

Police Station Of Origin:
Ang Mo Kio South N.P.C.
81 Ang Mo Kio Avenue 3 SINGAPORE
569029
Tel No. 1800-4519999



1/301902052017

2 of 4

Report No. 1/301902052017

CONTINUATION OF REPORT

Details of Person Involved			
Any Pedestrian Involved: No		Use of Pedestrian Crossing: NA	
No. of Pedestrians Injured: NIL			
Driver Name	CHEW MARN WENG	ID No.	900314431
Related Vehicle	SLM2790D (Car)	Contact No.	94568040
Hospital/Clinic	PROHEALTH MEDICAL GROUP @ BUANGKOK PTE LTD	Class of Driving Licence & Expiry Date	Class: 3 Date of Expiry: NIL
Date Treatment	04/02/2019	Date Discharge	04/02/2019
No. of Days granted Medical Leave	02	Degree of Injury	Slight
Driver Name	Lee Kian Meng	ID No.	S1875995A
Related Vehicle	NIL	Contact No.	93665996
Hospital/Clinic	NIL	Class of Driving Licence & Expiry Date	Class: NIL Date of Expiry: NIL
Date Treatment	NIL	Date Discharge	NIL
No. of Days granted Medical Leave	NIL	Degree of Injury	NIL
Driver Name	Melissa Kuan Tsui Yik	ID No.	S8377331F
Related Vehicle	NIL	Contact No.	93670708
Hospital/Clinic	NIL	Class of Driving Licence & Expiry Date	Class: NIL Date of Expiry: NIL
Date Treatment	NIL	Date Discharge	NIL
No. of Days granted Medical Leave	NIL	Degree of Injury	NIL


Brief Details:

On 04/02/2019 at about 1150hrs, I was driving my vehicle, SLM2790D, queuing at the entrance of Esso Petrol Kiosk along Punggol road. Suddenly, I felt an impact from my rear and due to the impact, my car rolled forward and knocked against the rear of another vehicle, bearing plate no. SKT8711G, which was stationed in front of me too. I then came out of my vehicle, however, the taxi, bearing plate no. SHC6977G, drove off before I could speak to him. I then called the police. After about 15 minutes, the taxi came back and he explained that he had went to drop off a passenger first. All of us then exchanged particulars and nobody was injured at the point of time.

Sketch Plan #6

 **SINGAPORE
POLICE FORCE**

Police Station Of Origin
Ang Mo Kio South N.P.C.
81 Ang Mo Kio Avenue 3 SINGAPORE
569629
Tel No. 1800-4519999


T201902092077

3 of 4
Report No. T201902092077

CONTINUATION OF REPORT

POLICE REPORT



**SINGAPORE
POLICE FORCE**



1/201902092017

4 of 4

Police Station Of Origin:
Ang Mo Kio South N.P.C.
51 Ang Mo Kio Avenue 3 SINGAPORE
569929
Tel No: 1800-4519998

Report No: 1/201902092017

CONTINUATION OF REPORT

Sketch Plan

Informant is not able to provide sketch plan

IMPORTANT: Please attach a copy of your vehicle's Insurance Certificate to this report. If you don't have the certificate with you now, please fax a copy to 65474865 stating the report number as reference.

Signature Of Officer Recording The Report

F2

Sgt 1 MA DERON

Signature Of Informant

(Signature)

Signature Of Interpreter

Not applicable

Date/Time

09/02/2019 13:51

Officer In Charge Of Case

TP / GIT /

SI MOHAMMAD SHAHRIL BIN ABULLAH




Contact No: 65476963

Classification Of Case

Authentication Stamp

NP108

Individual Statement



> Back to OneMotoring

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars	
Owner ID Type:	Company
Owner ID:	4597K
Vehicle Details	
Vehicle No.:	SLM2790D
Vehicle to be Exported:	No
Intended Deregistration Date:	14 Feb 2019
Vehicle Make:	HONDA
Vehicle Model:	SHUTTLE 1.5 HYBRID AT ABS D/AIRBAG 2WD
Primary Colour:	Black
Manufacturing Year:	2016
Engine No.:	LEB6301427
Chassis No.:	GP71101123
Maximum Power Output:	101.0 kW (135 bhp)
Open Market Value:	\$21,572.00
Original Registration Date:	27 Mar 2017
First Registration Date:	27 Mar 2017
Transfer Count:	0
Actual ARF Paid:	\$5,000.00
Intended PARF Rebate Details	
PARF Eligibility:	Yes
PARF Eligibility Expiry Date:	26 Mar 2027
PARF Rebate Amount:	\$3,750.00
Intended COE Rebate Details	
COE Expiry Date:	26 Mar 2027
COE Category:	E - Open Category
COE Period(Years):	10
QP Paid:	\$52,600.00
COE Rebate Amount:	\$42,688.00
Total Rebate Amount:	\$46,438.00

The information contained herein is correct as at 14 Feb 2019

OK

73,000
 46,438

 26,562

WORLD AUTO PTE LTD

47 Jalan Pemimpin #01-02/03

Halcyon 2, S'pore 577200

Tel No. : 6451 3933 Fax No. : 6455 7576

E-Mail : worldaut@singnet.com.sg

Website : www.worldauto.com.sg

Tax Reg. No. : 200006765-H Buss. Reg. No. : 200006765H

NTUC INCOME INSURANCE CO-OPERATIVE LIMITED

73 BRAS BASAH ROAD,

\$05-01 NTUC TRADE UNION HOUSE 189556

Attention : Motor Claim Department

Estimate : ES190057

Date : 11/02/2019

Vehicle Num. : SLM 2790D (LCR)

Make/Model : HONDA SHUTTLE HYBRID

Chassis/Eng# :

Accident Date : 04/02/2019

Claim No. :

Reference :

Policy No. :

S/N	Quantity	Particular	Unit Price	Amount S\$
-----	----------	------------	------------	------------

LIST ITEMS :				
1.	1	FRONT BONNET <i>BT</i>		1,080.00 ✓
2.	2	FRONT BONNET HINGE <i>TA</i>	98.50	197.00 ✓
3.	1	FRONT BONNET INSULATOR <i>X SUC</i>		135.00 ✓
4.	1	FRONT RADIATOR GRILLE BASE <i>CRA</i>		250.00 ✓
5.	1	FRONT RADIATOR GRILLE CHROME <i>cat</i>		230.00 ✓
6.	1	FRONT RADIATOR GRILLE CHROME STRIP <i>cat</i>		180.00 ✓
7.	1	FRONT RADIATOR GRILLE EMBLEM <i>TA</i>		100.00 ✓
8.	2	FRONT HEADLAMP ASSY <i>LH-DE / RH-? X SUC</i>	950.00	1,900.00 ✓
9.	2	FRONT HEADLAMP LOWER BRACKET <i>? CRX</i>	68.00	136.00 ✓
10.	1	FRONT BUMPER <i>DE</i>		1,100.00 ✓
11.	2	FRONT BUMPER RETAINER <i>nee</i>	89.00	178.00 ✓
12.	1	FRONT BUMPER TOW COVER <i>X SUC</i>		89.00 ✓
13.	1	FRONT BUMPER LOWER GRILLE <i>? X SUC</i>		152.00 ✓
14.	1	RADIATOR <i>? X SUC</i>		1,311.90 ✓
15.	1	CONDENSER ASSY <i>? X SUC</i>		1,160.00 ✓
16.	1	FRONT BUMPER REINFORCEMENT <i>? BT</i>		550.00 <i>420</i>
17.	1	FRONT CENTER LOCK BRACKET <i>? CRA</i>		78.00 ✓
18.	1	FRONT BONNET RUBBER MOULDING <i>nee</i>		58.00 ✓
19.	1	REAR BOOT LID <i>BT</i>		1,350.00 <i>1193</i>
20.	1	REAR WINDSCREEN GLASS MOULDING <i>nee</i>		250.00 <i>95</i>
21.	2	REAR BOOT REFLECTOR LAMP <i>? X SUC</i>	580.00	1,160.00 ✓
22.	1	REAR NUMBER PLATE LAMP GARNISH <i>? CRX</i>		360.00 ✓
23.	1	REAR BOOT HYBRID EMBLEM (SHUTTLE) <i>nee</i>		89.00 ✓
24.	1	REAR BOOT SHUTTLE EMBLEM (SHUTTLE) <i>nee</i>		89.00 ✓
25.	1	REAR BOOT LOCK ASSY <i>jam</i>		565.00 <i>187</i>
26.	1	REAR BOOT INNER TRIM BOARD <i>? X SUC</i>		350.00 ✓
27.	1	REAR BOOT HAND GRIP COVER <i>? DE</i>		68.00 ✓
28.	1	REAR BOOT WEATHER STRIP <i>nee</i>		188.00 ✓
29.	1	REAR BUMPER <i>DE</i>		1,150.00 ✓

8476

CONTINUE / ...

WORLD AUTO PTE LTD

47 Jalan Pemimpin #01-02/03
 Halcyon 2, S'pore 577200
 Tel No. : 6451 3933 Fax No. : 6455 7576
 E-Mail : worldaut@singnet.com.sg
 Website : www.worldauto.com.sg
 Tax Reg. No. : 200006765-H Buss. Reg. No. : 200006765H

NTUC INCOME INSURANCE CO-OPERATIVE LIMITED
 73 BRAS BASAH ROAD,
 #05-01 NTUC TRADE UNION HOUSE 189556

Attention : Motor Claim Department

Estimate : ES190057

Date : 11/02/2019
 Vehicle Num. : SLM 2790D (LCR)
 Make/Model : HONDA SHUTTLE HYBRID
 Chassis/Eng# :
 Accident Date : 04/02/2019
 Claim No. :
 Reference :
 Policy No. :

S/N	Quantity	Particular	Unit Price	Amount S\$
				4375.50
30.	1	REAR BUMPER TOW COVER <i>DE</i>		89.00 <i>20</i>
31.	2	REAR BUMPER REFLECTOR LENS <i>RH-suc / LH-Xsuc</i>	180.00 <i>65</i>	360.00
32.	2	REAR BUMPER REFLECTOR GARNISH <i>DE LH-7/RH-DE</i>	170.00	340.00
33.	2	REAR TAIL LAMP <i>RH-CRA / LH-7.Xsuc</i>	483-580.00	1,160.00
34.	2	REAR BUMPER RETAINER <i>DE</i>	89.00	178.00
35.	1	REAR END PANEL <i>DE</i>		680.00
36.	1	REAR END PANEL TOP GARNISH <i>DE</i>		260.00 <i>165-</i>
37.	1	REAR FLOOR PANEL <i>repair suc</i>		1,140.00 <i>956-</i>
38.	1	REAR FLOOR BOARD <i>Xsuc</i>		390.00
39.	2	REAR FENDER INNER TRIM BOARD <i>?DE</i>	425.00	850.00
40.	1	REAR COMPARTMENT BOX <i>?DE</i>		330.00
41.	1	REAR COMPARTMENT BOX BACK COVER <i>?DE</i>		87.50
42.	2	REAR FLOOR SIDE PANEL <i>repair</i>	250.00	500.00
43.	1	REAR EXHAUST BOX <i>Xsuc</i>		875.00
44.	1	REAR EXHAUST MOUNTING <i>Xsuc</i>		68.00
45.	1	REAR EXHAUST PIPE <i>Xsuc</i>		750.00
46.	1	REAR EXHAUST HEAT SHIELD <i>Xsuc</i>		125.00
47.	2	REAR BOOT STOPPER <i>DE</i>	37.50	75.00
48.	1	REAR TOOLKIT COMPARTMENT FOAM <i>?Xsuc</i>		158.00
49.	2	REAR TAILLAMP LOWER PANEL <i>repair Xbt</i>	158.00	316.00
50.	1	REAR ANTENNA SENSOR <i>?X3suc</i>		188.00
51.	1	SMART BUZZER SENSOR <i>?X3suc</i>		188.00
52.	2	REAR BUMPER UNDERDUST COVER <i>?X3suc</i>	198.00	396.00
53.	2	REAR BUMPER INNER FOAM <i>?X</i>	98.00	196.00
List TotalS\$:				24,203.40
20.00% Discount S\$:				4,840.68
				19,362.72
SPECIAL NETT ITEMS :				
1.	1	FRONT BONNET INSULATOR CLIP <i>DE</i>		40.00

CONTINUE / ...

WORLD AUTO PTE LTD

47 Jalan Pemimpin #01-02/03

Halcyon 2, S'pore 577200

Tel No. : 6451 3933 Fax No. : 6455 7576

E-Mail : worldaut@singnet.com.sg

Website : www.worldauto.com.sg

Tax Reg. No. : 200006765-H Buss. Reg. No. : 200006765H

NTUC INCOME INSURANCE CO-OPERATIVE LIMITED

73 BRAS BASAH ROAD,

\$05-01 NTUC TRADE UNION HOUSE 189556

Attention : Motor Claim Department

Estimate : ES190057

Date : 11/02/2019

Vehicle Num. : SLM 2790D (LCR)

Make/Model : HONDA SHUTTLE HYBRID

Chassis/Eng# :

Accident Date : 04/02/2019

Claim No. :

Reference :

Policy No. :

S/N	Quantity	Particular	Unit Price	Amount S\$
-----	----------	------------	------------	------------

2.	1	FRONT NUMBER PLATE WITH CASING (RA ✓)		40.00 ✓
3.	1	FRONT BUMPER CLIP <i>an</i> ✓		40.00 ✓
4.	1	REAR WINDSCREEN SEALANT <i>an</i> ✓		100.00 60 ✓
5.	1	TOWING CHARGE ✓		80.00 ✓
6.	1	REAR NUMBER PLATE LAMP GARNISH CLIP <i>an</i> ✓		40.00 ✓
7.	1	REAR NUMBER PLATE W/CASING <i>SCA</i> ✓		40.00 ✓
8.	1	REAR BOOT INNER TRIM BOARD CLIP <i>an</i> ✓		40.00 ✓
9.	1	REAR BUMPER CLIP <i>an</i> ✓		40.00 ✓
10.	2	REAR TAILLAMP CLIPS <i>an</i> ✓	40.00	80.00 ✓
11.	1	REVERSE SENSOR <i>an</i> ✓	<i>200</i>	280.00 ✓
12.	1	REAR END PANEL TOP GARNISH CLIPS <i>an</i> ✓		40.00 ✓
13.	2	REAR FENDER INNER TRIM BOARD CLIPS <i>an</i> ✓	40.00	80.00 60 ✓
14.	1	REAR BUMPER UNDERDUST COVER CLIP <i>an</i> ✓		40.00 20 ✓
15.	1	AIRCON GAS X <i>3 an</i>		100.00
16.	1	COOLANT X <i>3 an</i>		100.00

Special Nett Total S\$:

1,180.00

LABOUR :

TO APPLY RUSTPROOFING/ TUFFCOATING TREATMENT TO REPLACED PARTS.

~~180.00~~ 100

TO DISMANTLE FRONT DAMAGE PARTS, CUT AND WELD FRONT SUPPORT PANEL, KNOCK, STRAIGHTEN AND RESHAPE O/S FRONT CHASSIS FRAME AND REPLACE RECOMMENDED PARTS.

~~900.00~~ ~~500~~ 600

TO PUTTY & SPRAY PAINTING ON FRONT AFFECTED AREAS

~~900.00~~ 600

REMOVE AND REPLACE RADIATOR ASSY INCLUDING PERFORMING ENGINE COOLING SYSTEM PRESSURE TEST AND REFILL COOLANT

180.00 X *an*

CONTINUE / ...

WORLD AUTO PTE LTD

47 Jalan Pemimpin #01-02/03
 Halcyon 2, S'pore 577200
 Tel No. : 6451 3933 Fax No. : 6455 7576
 E-Mail : worldaut@singnet.com.sg
 Website : www.worldauto.com.sg
 Tax Reg. No. : 200006765-H Buss. Reg. No. : 200006765H

NTUC INCOME INSURANCE CO-OPERATIVE LIMITED

73 BRAS BASAH ROAD,
 \$05-01 NTUC TRADE UNION HOUSE 189556

Attention : Motor Claim Department

Estimate : ES190057

Date : 11/02/2019
 Vehicle Num. : SLM 2790D (LCR)
 Make/Model : HONDA SHUTTLE HYBRID
 Chassis/Eng# :
 Accident Date : 04/02/2019
 Claim No. :
 Reference :
 Policy No. :

S/N	Quantity	Particular	Unit Price	Amount S\$
		REMOVE AND REPLACE AIRCON CONDENSOR ASSY INCLUDING PERFORMING AIRCON SYSTEM PRESSURE LEAK TEST INCLUDING REFILLING AIRCON GAS		180.00 X 11
		TO REMOVE, REARRANGE ELECTRICAL WIRING, CHECK LIGHTINGS & RESET HEADLAMPY FOCUSING.		180.00 30
		TO REMOVE, REFIX REAR EXHAUST BOX & PIPE.		280.00 80
		TO REMOVE REFIX FUEL TANK TO FACILITATE CHANGING OF SPARE TYRE FLOOR PARTS.		250.00 X 11
		TO DISMANTLE REAR DAMAGE PARTS, CUT AND WELD REAR SUPPORT PANEL, KNOCK, STRAIGHTEN AND RESHAPE O/S REAR CHASSIS FRAME AND REPLACE RECOMMENDED PARTS.	4700	2,800.00 1500
		TO PUTTY & SPRAY PAINTING ON REAR AFFECTED AREAS		1,800.00 1200
		TRANSFER REAR BOOTLID MECHANISM AND ACCESSORIES		180.00 60
		REMOVE & REFIT REAR WINDSCREEN GLASS		180.00 120
		DEACTIVATE HV BATTERY SYSTEM IN ORDER TO FACILITATE REPAIRS AND REACTIVATE BACK SAME (HV HYBRID SYSTEM SAFETY PROCEDURES)		450.00 280
		PERFORM WHOLE VEHICLE DIAGNOSTICS INCLUDING CLEARING FAULT CODES AND REINTIALISING HV HYBRID SYSTEM FOR POST REPAIRS. (HV HYBRID SYSTEM SAFETY PROCEDURES)		450.00 120
		TO CHECK REAR WIRES, CONNECTORS, REPLACE DAMAGED LAMPS		180.00 50

CONTINUE / ...

WORLD AUTO PTE LTD

47 Jalan Pemimpin #01-02/03
 Halcyon 2, S'pore 577200
 Tel No. : 6451 3933 Fax No. : 6455 7576
 E-Mail : worldaut@singnet.com.sg
 Website : www.worldauto.com.sg
 Tax Reg. No. : 200006765-H Buss. Reg. No. : 200006765H

NTUC INCOME INSURANCE CO-OPERATIVE LIMITED
 73 BRAS BASAH ROAD,
 \$05-01 NTUC TRADE UNION HOUSE 189556

Attention : Motor Claim Department

Estimate : ES190057

Date : 11/02/2019
 Vehicle Num. : SLM 2790D (LCR)
 Make/Model : HONDA SHUTTLE HYBRID
 Chassis/Eng# :
 Accident Date : 04/02/2019
 Claim No. :
 Reference :
 Policy No. :

S/N	Quantity	Particular	Unit Price	Amount S\$
-----	----------	------------	------------	------------

REVERSE SENSORS AND START/STOP UNIT CAPACITORS

Labour Total S\$:

9,090.00

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
 Signature:
 Date:

Resur
12/2/19
4p 90010068
14 days
P/A
12/02/19 @ 1455
Resur after repair

E. & O.E.

Total S\$: 29,632.72

=====

for WORLD AUTO PTE LTD

10,281.20
820.00
4700.00

15,801.20

14 days



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

DAMAGE ASSESSMENT REPORT

NTUC INCOME INSURANCE CO-OPERATIVE LTD Ref: CS/INC19002562/R1td3e2

73 BRAS BASAH ROAD
#05-01 NTUC TRADE UNION HOUSESINGAPORE
189556

Date: 06-05-2019



ATTN : DAVID PHUA

Code: INC

1. Policy Particulars :- THIRD PARTY CLAIM

Insured Veh.	SHC 6977G	Veh. Inspected	SLM 2790D
Policy No.		Coverage (\$)	0.00
Claim No.	MT-1031311-001	Excess (\$)	0.00
Assign From	DANIEL KOH	Assign Date	12/02/2019

2. Vehicle Particulars & Condition

Make & Model	HONDA SHUTTLE 1.5 HYBRID	c.c	1496
Engine No.	HIDDEN	Year of Reg.	2017
Chassis No.	GP71101123	Colour	BLACK
Odometer	-	Steering	IN ORDER
Brakes	IN ORDER	Modification	SPORTS RIM
General	FAIR		

3. Conditions of Tyres

	Size	Make	Balance
R/H Front Tyre	185/60 R15	PIRELLI	6 mm
L/H Front Tyre	185/60 R15	PIRELLI	6 mm
R/H Rear Tyre	185/60 R15	PIRELLI	6 mm
L/H Rear Tyre	185/60 R15	PIRELLI	6 mm

4. Description of Damages

THE VEHICLE SUSTAINED DAMAGES AT THE FRONT AND REAR PORTION. DAMAGES SEE DETAILS.
--

5. General Information

Accident Date	04/02/2019	Inspect Date / Time	12/02/2019 (02:56 PM)
Survey held at	1 KRANJI LOOP		
Repairer	WORLD AUTO PTE LTD		

5a. Remarks

A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.
--

5b. Estimate Days of Repair

ESTIMATED NORMAL PERIOD FOR REPAIR:	14 Working Days
-------------------------------------	-----------------



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 4

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SLM 2790D

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	<u>REPLACEMENT OF PARTS</u>			
1	FRONT BONNET	BENT	1,080.00	1,080.00
2	FRONT BONNET HINGE @\$98.50	BENT	197.00	197.00
1	FRONT BONNET INSULATOR	SERVICEABLE	135.00	-
1	FRONT RADIATOR GRILLE BASE	CRACKED	250.00	250.00
1	FRONT RADIATOR GRILLE CHROME	CUT	230.00	230.00
1	FRONT RADIATOR GRILLE CHROME STRIP	CUT	180.00	180.00
1	FRONT RADIATOR GRILLE EMBLEM	NECESSARY	100.00	100.00
2	FRONT HEADLAMP ASSY @\$950.00	N/S DEFORMED / O/S SERVICEABLE	1,900.00	950.00
2	FRONT HEADLAMP LOWER BRACKET @\$68.00	CRACKED	136.00	136.00
1	FRONT BUMPER	DEFORMED	1,100.00	1,100.00
2	FRONT BUMPER RETAINER @\$89.00	NECESSARY	178.00	178.00
1	FRONT BUMPER TOW COVER	SERVICEABLE	89.00	-
1	FRONT BUMPER LOWER GRILLE	SERVICEABLE	152.00	-
1	RADIATOR	SERVICEABLE	1,311.90	-
1	CONDENSER ASSY	SERVICEABLE	1,160.00	-
1	FRONT BUMPER REINFORCEMENT	BENT	550.00	420.00
1	FRONT CENTER LOCK BRACKET	CRACKED	78.00	78.00
1	FRONT BONNET RUBBER MOULDING	NECESSARY	58.00	58.00
1	REAR BOOT LID	BENT	1,350.00	1,193.00
1	REAR WINDSCREEN GLASS MOULDING	NECESSARY	250.00	195.00
2	REAR BOOT REFLECTOR LAMP @\$580.00	SERVICEABLE	1,160.00	-
1	REAR NUMBER PLATE LAMP GARNISH	CRACKED	360.00	360.00
1	REAR BOOT HYBRID EMBLEM (SHUTTLE)	NECESSARY	89.00	89.00
1	REAR BOOT SHUTTLE EMBLEM (SHUTTLE)	NECESSARY	89.00	89.00
1	REAR BOOT LOCK ASSY	JAMMED	565.00	187.00
1	REAR BOOT INNER TRIM BOARD	SERVICEABLE	350.00	-
1	REAR BOOT HAND GRIP COVER	DEFORMED	68.00	68.00
1	REAR BOOT WEATHER STRIP	NECESSARY	188.00	188.00
1	REAR BUMPER	DEFORMED	1,150.00	1,150.00
1	REAR BUMPER TOW COVER	DEFORMED	89.00	20.00

Report Ref No. CS/INC19002562/R1td3e2



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:2 of 4

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
2	REAR BUMPER REFLECTOR LENS @\$180.00	O/S SCRATCHED / N/S SERVICEABLE	360.00	65.00
2	REAR BUMPER REFLECTOR GARNISH @\$170.00	N/S NOT NECESSARY / O/S DEFORMED	340.00	170.00
2	REAR TAIL LAMP @\$580.00	O/S CRACKED / N/S SERVICEABLE	1,160.00	483.00
2	REAR BUMPER RETAINER @\$89.00	NECESSARY	178.00	178.00
1	REAR END PANEL	BENT	680.00	680.00
1	REAR END PANEL TOP GARNISH	DEFORMED	260.00	165.00
1	REAR FLOOR PANEL	BUCKLED	1,140.00	956.00
1	REAR FLOOR BOARD	SERVICEABLE	390.00	-
2	REAR FENDER INNER TRIM BOARD @\$425.00	DEFORMED	850.00	850.00
1	REAR COMPARTMENT BOX	DEFORMED	330.00	330.00
1	REAR COMPARTMENT BOX BACK COVER	DEFORMED	87.50	87.50
2	REAR FLOOR SIDE PANEL @\$250.00	TO REPAIR SEE LABOUR	500.00	-
1	REAR EXHAUST BOX	SERVICEABLE	875.00	-
1	REAR EXHAUST MOUNTING	SERVICEABLE	68.00	-
1	REAR EXHAUST PIPE	SERVICEABLE	750.00	-
1	REAR EXHAUST HEAT SHIELD	SERVICEABLE	125.00	-
2	REAR BOOT STOPPER @\$37.50	NECESSARY	75.00	75.00
1	REAR TOOLKIT COMPARTMENT FOAM	SERVICEABLE	158.00	-
2	REAR TAILLAMP LOWER PANEL @\$158.00	BENT	316.00	316.00
1	REAR ANTENNA SENSOR	SERVICEABLE	188.00	-
1	SMART BUZZER SENSOR	SERVICEABLE	188.00	-
2	REAR BUMPER UNDERDUST COVER @\$198.00	SERVICEABLE	396.00	-
2	REAR BUMPER INNER FOAM @\$98.00	SERVICEABLE	196.00	-
	LESS 20% DISCOUNT		-4,840.68	-2,570.30
			19,362.72	10,281.20
	SPECIAL NETT ITEMS			
1	FRONT BONNET INSULATOR CLIP (SN)	NECESSARY	40.00	40.00
1	FRONT NUMBER PLATE WITH CASING (SN)	CRACKED	40.00	40.00
1	FRONT BUMPER CLIP (SN)	NECESSARY	40.00	40.00

Report Ref No. CS/INC19002562/R1td3e2



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:3 of 4

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
1	REAR WINDSCREEN SEALANT (SN)	NECESSARY	100.00	60.00
1	REAR NUMBER PLATE LAMP GARNISH CLIP (SN)	NECESSARY	40.00	40.00
1	REAR NUMBER PLATE W/CASING (SN)	SCRATCHED	40.00	40.00
1	REAR BOOT INNER TRIM BOARD CLIP (SN)	NECESSARY	40.00	40.00
1	REAR BUMPER CLIP (SN)	NECESSARY	40.00	40.00
2	REAR TAILLAMP CLIPS @\$40.00 (SN)	NECESSARY	80.00	80.00
1	REVERSE SENSOR (SN)	NOT WORKING	280.00	200.00
1	REAR END PANEL TOP GARNISH CLIPS (SN)	NECESSARY	40.00	40.00
2	REAR FENDER INNER TRIM BOARD CLIPS @\$40.00 (SN)	NECESSARY	80.00	60.00
1	REAR BUMPER UNDERDUCT COVER CLIP (SN)	NECESSARY	40.00	20.00
1	AIRCON GAS (SN)	NOT NECESSARY	100.00	-
1	COOLANT (SN)	NOT NECESSARY	100.00	-
			1,100.00	740.00
	LABOUR			
	TOWING CHARGE.		80.00	80.00
	TO APPLY RUSTPROOFING / TUFFCOATING TREATMENT TO REPLACED PARTS.		180.00	100.00
	TO DISMANTLE FRONT DAMAGE PARTS, CUT AND WELD FRONT SUPPORT PANEL, KNOCK, STRAIGHTEN AND RESHAPE O/S FRONT CHASSIS FRAME AND REPLACE RECOMMENDED PARTS. INCLUSIVE OF THE REPAIR OF REAR FLOOR SIDE PANEL.		900.00	600.00
	TO PUTTY & SPRAY PAINTING ON FRONT AFFECTED AREAS.		900.00	600.00
	REMOVE AND REPLACE RADIATOR ASSY INCLUDING PERFORMING ENGINE COOLING SYSTEM PRESSURE TEST AND REFILL COOLANT.	NOT NECESSARY	180.00	-
	REMOVE AND REPLACE AIRCON CONDENSOR ASSY INCLUDING PERFORMING AIRCON SYSTEM PRESSURE LEAK TEST INCLUDING REFILLING AIRCON GAS.	NOT NECESSARY	180.00	-
	TO REMOVE, REARRANGE ELECTRICAL WIRING, CHECK LIGHTINGS & RESET HEADLAMPY FOCUSING.		180.00	30.00
	TO REMOVE, REFIX REAR EXHAUST BOX & PIPE.		280.00	80.00
	TO REMOVE, REFIX FUEL TANK TO FACILITATE CHANGING OF SPARE TYRE FLOOR PARTS.	NOT NECESSARY	250.00	-

Report Ref No. CS/INC19002562/R1td3e2



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:4 of 4

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	TO DISMANTLE REAR DAMAGE PARTS, CUT AND WELD REAR SUPPORT PANEL, KNOCK, STRAIGHTEN AND RESHAPE O/S REAR CHASSIS FRAME AND REPLACE RECOMMENDED PARTS.		2,800.00	1,500.00
	TO PUTTY & SPRAY PAINTING ON REAR AFFECTED AREAS.		1,800.00	1,200.00
	TRANSFER REAR BOOTLID MECHANISM AND ACCESSORIES.		180.00	60.00
	REMOVE & REFIT REAR WINDSCREEN GLASS.		180.00	120.00
	DEACTIVATE HV BATTERY SYSTEM IN ORDER TO FACILITATE REPAIRS AND REACTIVATE BACK SAME (HV HYBRID SYSTEM SAFETY PROCEDURES)		450.00	240.00
	PERFORM WHOLE VEHICLE DIAGNOSTICS INCLUDING CLEARING FAULT CODES AND REINITIALISING HV HYBRID SYSTEM FOR POST REPAIRS. (HV HYBRID SYSTEM SAFETY PROCEDURES)		450.00	120.00
	TO CHECK REAR WIRES, CONNECTORS, REPLACE DAMAGED LAMP REVERSE SENSORS AND START / STOP UNIT CAPACITORS.		180.00	50.00
			9,170.00	4,780.00
GRAND TOTAL			29,632.72	15,801.20
RECOMMENDED COST OF REPAIRS (CONFIRMED)				15,801.20

Report Ref No. CS/INC19002562/R1td3e2

MOHAMMED RASUL BIN MOHD YUNUS

Automotive Assessor

K.K.LAU CPT(RET)

BEng(Hons),B.Bus,MBA,PEng,PE,
MInstAEA,MASME,MIRTE

REGD Auto Consultant-SAE, Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.