

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CC4/AIG19002567/GBA3Q2

Date: 03/02/2021

REFERENCE

Handling Insurer: AIG Asia Pacific Insurance Pte. Ltd. Policy No: 0999994421
Claimant
Vehicle No : SKA4882J **Insured Vehicle No :** SMG941T
Date of Loss: 06/02/2019 Nature of Claim: TP Claim No: 6040168151SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: **SKA4882J**
Make & Model: HONDA JAZZ, 1.4 (A) Engine No: L13A54001751
Reg. Date: 04/06/2007 (Man. Year: 2007) Chassis No: JHMGD18507S221980
Colour: Black Odometer: 191853 km
Engine Capacity: 1339 cc
Market Value/New Car Price: N/A
Sum Insured (S\$): **Market Value/New Car Price**

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes
Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition: Yes

CONDITION OF TYRES

Front Tyre Size: 195/55R15 Rear Tyre Size: 195/55R15
Front Left Side: Falken 5 mm Rear Left Side: Falken 5 mm
Front Right Side: Falken 5 mm Rear Right Side: Falken 5 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	6,263.92	1,833.12	4,430.80	70.74
Miscellaneous Items	0.00	0.00	0.00	
Labour	3,460.00	1,700.00	1,760.00	50.87
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	9,723.92	3,533.12	6,190.80	63.67
Approved Total (Overridden) (S\$)		2,800.00		
(S\$)	9,723.92	2,800.00	6,923.92	71.21
+ GST 7.00/7.00% (S\$)	680.67	196.00	484.67	71.20
Nett Amount (S\$)	10,404.59	2,996.00	7,408.59	71.21
+ Loss of Use (10.0 x S\$60.00/day) (S\$)		600.00		
+ Doc/Search Fee (S\$)		7.49		
Nett Liability (S\$)		3,603.49		
Global Sum Settlement (S\$)		3,600.00		

INSPECTION

Date of Assignment: 12/02/2019
Date Inspected: 13/02/2019 Inspected At: My Car Consultant Pte Ltd (Ubi)
53 Ubi Ave 1, #01-33, Paya Ubi Industrial Park
Singapore 408934

Estimated Period of Repair: 7.0 days

Adjuster: XING GUO QIANG

Manager: CHUA ZHEN LI

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*REAR BUMPER	Deformed	540.80 FL	*495.50 FL
2	1		*TOW COVER	Not Necessary	17.40 FL	*- FL
3	2		*REAR BUMPER SIDE RETAINER	Deformed	39.80 FL	*39.80 FL
4	1		*REAR END PANEL	Serviceable	465.80 FL	*- FL
5	1		*REAR END PANEL TOP GARNISH	Not Necessary	107.90 FL	*- FL
6	1		*REAR LH TAILLAMP	Cracked	306.30 FL	*236.20 FL
7	1		*REAR LH TAILLAMP PANEL	Serviceable	228.40 FL	*- FL
8	1		*REAR LH FENDER	Buckled	837.40 FL	*692.50 FL
9	1		*REAR LH FENDER INNER TRIM	Serviceable	298.00 FL	*- FL
10	1		*REAR LH FENDER INNER SHIELD	Deformed	49.90 FL	*49.90 FL
11	1		*REAR LH FENDER AIR GRILLE	Deformed	61.00 FL	*48.00 FL
12	1		*TAILGATE	Repair	908.00 FL	*- FL
13	1		*TAILGATE EMBLEM-JAZZ	Necessary	51.00 FL	*42.00 FL
14	2		*TAILGATE GLASS MOULDING	Not Necessary	110.00 FL	*- FL
15	1		*TAILGATE LOCK	Not Necessary	196.00 FL	*- FL
16	1		*TAILGATE LOCK STRIKER	Not Necessary	59.00 FL	*- FL
17	1		*REAR AXLE BEAM	Not Necessary	1,050.00 FL	*- FL
18	1		*REAR LH SHOCK ABSORBER	Not Necessary	513.20 FL	*- FL
19	1		*REAR LH WHEEL HUB AND BEARING	Not Necessary	290.00 FL	*- FL
20	1		*SET REAR BUMPER CLIP	Necessary	40.00 FS	*30.00 FS
21	1		*SET REAR REVERSE SENSOR	Damaged	400.00 FS	*200.00 FS
22	1		*SET REAR FENDER INNER TRIM CLIP	Necessary	20.00 FS	*20.00 FS
23	1		*JOINT SEALANT	Not Necessary	150.00 FS	*- FS
24	1		*WINDSCREEN SEALANT	Not Necessary	150.00 FS	*- FS
25	1		*RIM	Cut	600.00 FS	*300.00 FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (\$)	7,489.90	2,153.90
- List Item Discount on L Items 20.00/20.00% (\$)	1,225.98	320.78
Total Parts (\$)	6,263.92	1,833.12

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	CHECK REAR WIRING AND LIGHTNING SYSTEM	New	60.00	30.00
2	REMOVE,REFIT REAR LINING,TRIM AND GARNISH	New	200.00	60.00
3	REMOVE AND RENEW REAR REVERSE SENSOR	New	150.00	40.00
4	REFIT REAR WINDSCREEN	New	150.00	0.00
5	TRANSFER PARTS,ATTACHMENT FROM OLD TAILGATE TO NEW	New	200.00	0.00
6	CHECK REAR WHEEL ALIGNMENT	New	150.00	60.00
7	REMOVE AND RENEW REAR UNDERCARRIAGE PARTS	New	200.00	50.00
8	PANEL BEATING ON AFFECTED AREAS	New	1,200.00	800.00
9	SPRAY PAINTING ON AFFECTED AREAS	New	1,000.00	600.00
10	APPLY ANTI RUST ON AFFECTED AREAS	New	150.00	60.00
Gross Labour Cost (\$)			3,460.00	1,700.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >