



## LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

### TAX INVOICE

CHINA TAIPING INSURANCE (S) PTE LTD  
3 ANSON ROAD #16-00  
SPRINGLEAF TOWER  
SINGAPORE 079909

INV No. AC2003572  
INV Date 29/04/2020  
Reference CC6/CTI19002574/Aea3n2  
Code CTI



### PROFESSIONAL SERVICE FEE

Vehicle No. SMA 3114B  
Insured Veh. SGL 8500A  
Claim No. SNM19D200576  
Policy No. DMPCSN1655381802  
Accident Date 31/01/2019  
Inspection Date 12/02/2019

Description	Total
Third Party Express Settlement	400.00
<b>Subtotal</b>	<b>400.00</b>
<b>GST (7%)</b>	<b>28.00</b>
<b>Grand Total</b>	<b>428.00</b>

We shall be glad if you could forward the payment at your early convenience.

Cheque should be crossed and made payable to **'LKK Auto Consultants Pte Ltd'**

LKK Auto Consultants Pte Ltd

*HYN*




## LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
CHINA TAIPING INSURANCE (S) PTE LTD		Ref : CC6/CTI19002574/Aea3n2		
3 ANSON ROAD #16-00 SPRINGLEAF TOWERS SINGAPORE 079909		Date : 29-04-2020		
		Code : CTI		
<b>1. Policy Particulars :- THIRD PARTY CLAIM</b>				
Insured Veh.	SGL 8500A	Veh. Inspected	SMA 3114B	
Policy No.	DMPCSN1655381802	Coverage (\$)	0.00	
Claim No.	SNM19D200576	Excess (\$)	0.00	
Assign From		Assign Date	12/02/2019	
<b>2. Vehicle Particulars &amp; Condition</b>				
Make & Model	RENAULT SCENIC	c.c	1461	
Engine No.	HIDDEN	Year of Reg.	2018	
Chassis No.	VF1RFA00X59516718	Colour	BLACK	
Odometer	73984	Steering	IN ORDER	
Brakes	IN ORDER	Modification	SPORTS RIM	
General	GOOD			
<b>3. Conditions of Tyres</b>				
	Size	Make	Balance	
R/H Front Tyre	195/55 R20	GOODYEAR	6 mm	
L/H Front Tyre	195/55 R20	GOODYEAR	6 mm	
R/H Rear Tyre	195/55 R20	GOODYEAR	6 mm	
L/H Rear Tyre	195/55 R20	GOODYEAR	6 mm	
<b>4. Description of Damages</b>				
THE VEHICLE SUSTAINED DAMAGES AT THE REAR PORTION. DAMAGES SEE DETAILS.				
<b>5. General Information</b>				
Accident Date	31/01/2019	Inspection Date	12/02/2019	
Survey held at	XIN HUA WORKSHOP PTE LTD 23 KAKI BUKIT AVENUE 4 #04-01 (SOUTH WING) SINGAPORE 415933			
<b>5a. Remarks</b>				
A) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS. B) IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.				
<b>5b. Estimate Days of Repair</b>				
ESTIMATED NORMAL PERIOD FOR REPAIR:		<b>5 Working Days</b>		



## LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 3

### ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SMA 3114B

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	<b><u>REPLACEMENT OF PARTS</u></b>			
1	RR BUMPER	DEFORMED	2,800.10	1,883.40
1	RR BUMPER LOW	DEFORMED	2,210.60	592.30
1	RR BUMPER LOW GARNISH	DEFORMED	1,380.70	559.20
1	RR BUMPER TOW COVER	MISSING	98.10	98.10
1	RR BUMPER SIDE RETAINER RH	NECESSARY	368.30	276.10
1	RR BUMPER SIDE RETAINER LH	NECESSARY	368.30	276.10
1	RR BUMPER LOW BRACKET RH	NOT NECESSARY	324.10	-
1	RR BUMPER LOW BRACKET LH	CRACKED	324.10	125.00
1	RR BUMPER REINFORCEMENT	BENT	1,121.00	911.10
1	RR KEY RECEIVER SENSOR	NOT NECESSARY	452.10	-
1	RR BUMPER REINFORCEMENT STAY LH	NOT NECESSARY	268.70	-
1	RR BUMPER REVERSE SENSOR	DAMAGED	389.60	299.80
1	RR BUMPER REVERSE SENSOR WIRE HARNESS	NOT NECESSARY	745.10	-
1	RR BUMPER REFLECTOR LH	CRACKED	920.40	354.70
1	RR TAILGATE	CRACKED	2,980.70	1,929.90
1	RR TAILGATE RENAULT LOGO	NECESSARY	128.10	128.10
1	RR TAILGATE RENAULT EMBLEM	NECESSARY	135.80	135.80
1	RR TAILGATE SCENIC EMBLEM	NECESSARY	130.60	130.60
1	RR TAILGATE LOCK	NOT NECESSARY	265.80	-
1	RR TAILGATE LOCK STRIKER	NOT NECESSARY	95.20	-
1	RR TAILGATE STOPED	NOT NECESSARY	160.80	-
1	RR TAILGATE INNER TRIM BOARD	NOT NECESSARY	1,260.80	-
1	RR TAILGATE REFLECTOR RH	NOT NECESSARY	1,890.40	-
1	RR TAILGATE REFLECTOR LH	NOT NECESSARY	1,890.40	-
1	RR TAILGATE WEATHERSTRIP	NOT NECESSARY	286.00	-
1	RR TAILGATE GLASS	NOT NECESSARY	3,200.60	-
1	RR TAILLAMP RH	NOT NECESSARY	1,840.30	-
1	RR TAILLAMP LH	NOT NECESSARY	1,840.30	-
1	RR END PANEL	TO REPAIR SEE LABOUR	1,980.50	-
1	RR END PANEL TOP GARNISH	NOT NECESSARY	365.50	-

Report Ref No. CC6/CTI19002574/Aea3n2



# LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:2 of 3

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
1	RR EXHAUST SILENCER BOX	TO REPAIR SEE LABOUR	2,800.10	-
1	RR EXHAUST HEAT BAFFLE	CRUMPLED	574.30	192.10
1	RR FENDER INNER SHIELD END LH (ADDITIONAL)	TORN	114.70	114.70
1	RR SPARE TYRE PANEL COVER (ADDITIONAL)	CRACKED	741.00	741.00
1	RR BUMPER CENTRE RETAINER (ADDITIONAL)	CRACKED	368.30	368.30
	LESS 10% DISCOUNT		-3,482.14	-911.63
			31,339.26	8,204.67
	<b><u>SPECIAL NETT ITEMS</u></b>			
10	RR BUMPER CLIP (SN)	NECESSARY	60.00	30.00
10	RR TAILGATE GARNISH CLIP (SN)	NECESSARY	60.00	30.00
10	RR TAILGATE INNER TRIM BOARD CLIP (SN)	NOT NECESSARY	60.00	-
10	RR TAILGATE TOP SPOILER CLIP (SN)	NOT NECESSARY	60.00	-
5	RR END PANEL TOP GARNISH CLIP (SN)	NECESSARY	30.00	10.00
1	RR WINDSCREEN SEALANT (SN)	NECESSARY	65.00	65.00
1	RR WINDSCREEN INNER SEAL (SN)	NECESSARY	40.00	40.00
1	RR WINDSCREEN SOLAR FILM (SN)	NOT NECESSARY	200.00	-
			575.00	175.00
	<b><u>LABOUR</u></b>			
	TO DISMANTLE /RENEW THE ACCIDENT DAMAGED PORTION ,TO PANEL BEATING ,RESHAPE ,STRAIGHTEN ,ORIENTATE AND ALIGN REPAIR /REPLACEMENT PARTS.INCLUSIVE OF THE REPAIR OF RR END PANEL AND RR EXHAUST SILENCER BOX .		1,200.00	600.00
	CARRY OUT SPRAY PAINTING ON AFFECTED AREA ,RR BUMPER ,RR TAILGATE ,RR END PANEL,RR LH FENDER ,RR RH FENDER.		1,200.00	600.00
	TO DISCONNECT FRONT WIRE HARNESS OF ELECTRICAL COMPONENT TO FACILITATE REPAIRS ,RECONNECT AND CHECK ELECTRICAL FUNCTION AFTER REPAIR.		180.00	30.00
	REMOVE AND REFIX SEAT CUSHION /UPHOLSTERY & ROOF LINING TO FACILITATE REPAIRS.		200.00	60.00
	TO REMOVE AND REFIX REVERSE SENSOR AND CONDUCT TEST.		120.00	50.00

Report Ref No. CC6/CTI19002574/Aea3n2



## LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:3 of 3

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	TO REMOVE AND REFIX REVERSE CAMERA AND CONDUCT TEST.		120.00	50.00
	TO CONDUCT TRANSFER OF PARTS FROM OLD TAILGATE TO NEW TAIGLATE.		200.00	80.00
	TO CONDUCT WATER LEAKAGE TEST AFTER REPAIRS OF VEHICLE .	NOT NECESSARY	80.00	-
	TO REMOVE AND REFIX REAR TAIL GATE WINDSCREEN.		200.00	120.00
	TO REMOVE AND REPLACE EXHAUST PIPE.	NOT NECESSARY	200.00	-
			3,700.00	1,590.00
<b>GRAND TOTAL</b>			<b>35,614.26</b>	<b>9,969.67</b>
<b>RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION)</b>				<b>7,900.00</b>

Report Ref No. CC6/CT119002574/Aea3n2

ADRIAN LING WAI PING

B.Eng,AMSOE,AMIRTE,AMSAE-A,M.MATAI

Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.