



# LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 2

## ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SGA 2832P

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
<b>REPLACEMENT OF PARTS</b>				
1	BONNET	BENT	497.00	497.00
1	HEADLAMP ASSY RH	BROKEN	310.00	310.00
1	HEADLAMP PANEL	TO REPAIR SEE LABOUR	559.00	-
1	FRONT FENDER RH	BENT	516.00	516.00
1	FRONT FENDER SHIELD	CRACKED	127.00	127.00
10	FRONT FENDER SHIELD CLIPS @\$3.80	NECESSARY	38.00	38.00
1	FRONT BUMPER	BENT	311.00	311.00
10	FRONT BUMPER CLIPS @\$3.80	NECESSARY	38.00	38.00
1	FRONT BUMPER BRACKET RH	TO REPAIR SEE LABOUR	52.20	-
1	FRONT BUMPER CORNER RETAINER RH	DISTORTED	15.60	15.60
1	FRONT BUMPER FOG LAMP RH	MTG CRACKED	215.00	215.00
1	AIR CON CONDENSER AIR GUIDE RH	CRACKED	37.00	37.00
1	GRILLE	SERVICEABLE	259.00	-
1	GRILLE EMBLEM	SERVICEABLE	62.00	-
1	FRONT WHEEL BEARING	SERVICEABLE	171.00	-
1	WIPER TANK	SERVICEABLE	97.00	-
1	WIPER TANK MOTOR	SERVICEABLE	230.00	-
	LESS 25% DISCOUNT		-883.70	-526.15
			2,651.10	1,578.45
<b>SPECIAL NETT ITEMS</b>				
1	SPORT RIM (SN)	SERVICEABLE	578.00	-
			578.00	-
<b>LABOUR</b>				
	TO CONDUCT FRONT ELECTRICAL CHECK ,LOCKING SYSTEM ,ADJUST,FOCUS HEADLAMP ETC.		30.00	20.00
	TO APPLY RUST PROOFING /RESEAL TUFF COATING TREATMENT TO RESPRAY /REPLACED /REPAIR PANEL.		60.00	60.00
	TO REMOVE/REFIT ,RADIATOR SYSTEM ,BLEED ,REFILL COOLANT.	NOT NECESSARY	60.00	-
	TO REMOVE/REFIT AIR CON CONDENSER & REFILL GAS.	NOT NECESSARY	120.00	-
	TO DISMANTLE/HI PRESSURE PRESS/WHEEL BEARING.	NOT NECESSARY	60.00	-
	TO DISMANTLE /REPLACE WHEEL BEARING (DISMANTLE UNDER CARRIAGE).	NOT NECESSARY	70.00	-

Report Ref No. CC4/QBE19002617/Kha3q2



## LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:2 of 2

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	TO CONDUCT COMPUTERIZE WHEEL ALIGNMENT TEST.	NOT NECESSARY	80.00	-
	TO CONDUCT HIGH SPEED BALANCING.	NOT NECESSARY	60.00	-
	LABOUR CHARGE-PANEL BEATING, REPLACEMENT OF FENDER, FRONT DOOR, INNER PANEL, BONNET HINGE, CNT, WELD HEADLAMP PANEL AND PARTS REPLACEMENT. INCLUSIVE OF THE REPAIR OF HEADLAMP PANEL AND FRONT BUMPER BRACKET RH.		900.00	450.00
	TO RESPRAY AFFECTED AREAS.		800.00	540.00
			2,240.00	1,070.00
	<b>GRAND TOTAL</b>		<b>5,469.10</b>	<b>2,648.45</b>
	<b>RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION)</b>			<b>2,100.00</b>

Report Ref No. CC4/QBE19002617/Kha3q2

2180

KONG SENG CHEONG

Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.  
No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.