

BOM Type	Costing Type	Portion	Material Number	Part Name	SMRT Recommendation						Surveyor Approval			Remarks
					Qty	List Price Per Unit(\$)	List Price(\$)	Dis(%)	Final Price(\$)	Repair/ Replace	Surveyor Quantity	Surveyor Final Price(\$)	Repair/Replace	
One Time Key In	Main			COOLANT	4	12.30	49.20	0.00	49.20	Replace	0	0	Check	
One Time Key In	Main			FAN RADIATOR , LH	1	181.80	181.80	25.00	136.35	Replace	0	0	Check	
One Time Key In	Main			FAN RADIATOR , RH	1	233.00	233.00	25.00	174.75	Replace	0	0	Check	
One Time Key In	Main			FAN SHROUD RADIATOR	1	219.30	219.30	25.00	164.48	Replace	0	0	Check	
One Time Key In	Main			MOTOR, COOLING FAN , RH	1	443.40	443.40	10.00	399.06	Replace	0	0	Check	
One Time Key In	Main			MOTOR, COOLING FAN , LH	1	543.50	543.50	10.00	489.15	Replace	0	0	Check	
One Time Key In	Main			HOSE, RADIATOR , NO.1	1	42.60	42.60	25.00	31.95	Replace	0	0	Check	
One Time Key In	Main			HOSE, RADIATOR , NO.2	1	40.20	40.20	25.00	30.15	Replace	0	0	Check	
One Time Key In	Main			HOSE, WATER BY-PASS , NO.2	1	37.40	37.40	25.00	28.05	Replace	0	0	Check	
One Time Key In	Main			HOSE, WATER BY-PASS , NO.3	1	20.10	20.10	25.00	15.08	Replace	0	0	Check	
One Time Key In	Main			HOSE, WATER BY-PASS , NO.4	1	13.20	13.20	25.00	9.90	Replace	0	0	Check	
One Time Key In	Main			HOSE, WATER BY-PASS , NO.1	1	37.40	37.40	25.00	28.05	Replace	0	0	Check	
One Time Key In	Main			HORN ASSY, HIGH	1	112.80	112.80	25.00	84.60	Replace	0	0	Check	
One Time Key In	Main			HORN ASSY, LOW	1	112.80	112.80	25.00	84.60	Replace	0	0	Check	
One Time Key In	Main			AIR CON CONDENSER ASSY	1	1,317.70	1,317.70	25.00	988.28	Replace	0	0	Check	

Total Spare Part Cost	29,977.43	Surveyor Total	1,848.88
Lump Sum Discount (%)	0.00	Lump Sum Dis (%)	0
Final Spare Part Cost	29,977.43	Final Sur Total	1,848.88

BOM Type	Costing Type	Portion	Material Number	Part Name	Qty	SMRT Recommendation				Repair/ Replace	Surveyor Approval			Remarks
						List Price Per Unit(\$)	List Price(\$)	Dis(%)	Final Price(\$)		Surveyor Quantity	Surveyor Final Price(\$)	Repair/Replace	
One Time Key In	Main			TUBE & ACCESSORY	1	574.40	574.40	25.00	430.80	Replace	0	0	Check	▼
One Time Key In	Main			HOSE SUB-ASSY, DISCHARGE	1	337.10	337.10	25.00	252.83	Replace	0	0	Check	▼
One Time Key In	Main			HOSE, HV WATER PUMP INLET	1	37.90	37.90	25.00	28.42	Replace	0	0	Check	▼
One Time Key In	Main			INVERTER WATER PUMP ASSY	1	432.00	432.00	10.00	388.80	Replace	0	0	Check	▼
One Time Key In	Main			HOSE, HV WATER PUMP OUTLET	1	29.60	29.60	25.00	22.20	Replace	0	0	Check	▼
One Time Key In	Main			HOSE, INVERTER RADIATOR INLET	1	40.70	40.70	25.00	30.53	Replace	0	0	Check	▼
One Time Key In	Main			INLET, AIR CLEANER, NO 3	1	35.30	35.30	25.00	26.47	Replace	0	0	Check	▼
One Time Key In	Main			INLET, AIR CLEANER, NO 2	1	93.90	93.90	25.00	70.43	Replace	0	0	Check	▼
One Time Key In	Main			INLET, AIR CLEANER, NO 1	1	130.50	130.50	25.00	97.88	Replace	0	0	Check	▼
One Time Key In	Main			AIR CLEANER ASSY	1	956.20	956.20	25.00	717.15	Replace	0	0	Check	▼
One Time Key In	Main			WIRE, ENGINE ROOM MAIN	1	6,138.00	6,138.00	10.00	5,524.20	Replace	0	0	Check	▼
One Time Key In	Main			HOOD SUB-ASSY	1	938.40	938.40	25.00	703.80	Replace	0	0	Check	▼
One Time Key In	Main			HINGE ASSY, HOOD, RH	1	57.00	57.00	25.00	42.75	Replace	0	0	Check	▼
One Time Key In	Main			HINGE ASSY, HOOD, LH	1	57.00	57.00	25.00	42.75	Replace	0	0	Check	▼
One Time Key In	Main			INSULATOR, HOOD	1	393.90	393.90	25.00	295.42	Replace	0	0	Check	▼

Total Spare Part Cost	29,977.43	Surveyor Total	1,848.88
Lump Sum Discount (%)	0.00	Lump Sum Dis (%)	0
Final Spare Part Cost	29,977.43	Final Sur Total	1,848.88

BOM Type	Costing Type	Portion	Material Number	Part Name	SMRT Recommendation						Surveyor Approval			Remarks
					Qty	List Price Per Unit(\$)	List Price(\$)	Dis(%)	Final Price(\$)	Repair/Replace	Surveyor Quantity	Surveyor Final Price(\$)	Repair/Replace	
One Time Key In	Main			INSULATOR, HOOD CLIP	6	2.30	13.80	25.00	10.35	Replace	0	0	Check	*
One Time Key In	Main			WIPER GARNISH LOUVER SUB-ASSY	1	666.90	666.90	25.00	500.17	Replace	0	0	Check	*
One Time Key In	Main			FENDER SUB-ASSY, FR , LH	1	933.10	933.10	25.00	699.83	Replace	1	0	Repair	*
One Time Key In	Main			UNIT, HEADLAMP , LH	1	2,558.90	2,558.90	10.00	2,303.01	Replace	0	0	Check	*
One Time Key In	Main			EMBLEM, SIDE PANEL (HYBRID)	1	52.90	52.90	25.00	39.67	Replace	0	0	Not Give	*
One Time Key In	Main			COMPUTER SUB-ASSY, HEADLAMP, LH NO.1	1	486.40	486.40	10.00	437.76	Replace	0	0	Check	*
One Time Key In	Main			FENDER SUB-ASSY, FR , RH	1	933.10	933.10	25.00	699.83	Replace	1	0	Repair	*
One Time Key In	Main			UNIT, HEADLAMP , RH	1	2,558.90	2,558.90	10.00	2,303.01	Replace	0	0	Check	*
One Time Key In	Main			EMBLEM, SIDE PANEL (HYBRID)	1	52.90	52.90	25.00	39.67	Replace	0	0	Not Give	*
One Time Key In	Main			COMPUTER SUB-ASSY, HEADLAMP, RH NO.1	1	486.40	486.40	10.00	437.76	Replace	0	0	Check	*
One Time Key In	Main			COVER, RR BUMPER ASSY	1	423.90	423.90	25.00	317.92	Replace	1	317.92	Replace	* DEF
One Time Key In	Main			GUARD, RR BUMPER, LOWER	1	558.30	558.30	25.00	418.72	Replace	1	418.72	Replace	* BUC
One Time Key In	Main			COVER, GUARD RR BUMPER LOWER	1	14.80	14.80	25.00	11.10	Replace	1	11.10	Replace	* SCR
One Time Key In	Main			PAD, RR BUMPER, CTR	3	2.20	6.60	25.00	4.95	Replace	3	4.95	Replace	* NEC
One Time Key In	Main			PAD, RR BUMPER, RH & LH , 1	2	3.80	7.60	25.00	5.70	Replace	2	5.70	Replace	* NEC

Total Spare Part Cost	29,977.43	Surveyor Total	1,848.88
Lump Sum Discount (%)	0.00	Lump Sum Dis (%)	0
Final Spare Part Cost	29,977.43	Final Sur Total	1,848.88

BOM .Type	%Costing Type	Portion	Material Number	Part Name	Qty	SMRT Recommendation					Surveyor Approval				Remarks
						List Price Per Unit(\$)	List Price(\$)	Dis(%)	Final Price(\$)	Repair/ Replace	Surveyor Quantity	Surveyor Final Price(\$)	Repair/Replace		
One Time Key In	Main			PAD, RR BUMPER, RH & LH , 2	2	3.80	7.60	25.00	5.70	Replace	2	5.70	Replace	NEC	
One Time Key In	Main			PAD, RR BUMPER, RH & LH , 3	2	3.80	7.60	25.00	5.70	Replace	2	5.70	Replace	NEC	
One Time Key In	Main			SEAL, RR BUMPER ARM, RH & LH	2	11.00	22.00	25.00	16.50	Replace	2	16.50	Replace	NEC	
One Time Key In	Main			SENSOR REVERSE	1	180.00	180.00	0.00	180.00	Replace	0	0	Check		
One Time Key In	Main			REAR BUMPER REINFORCEMENT	1	318.80	318.80	25.00	239.10	Replace	0	0	Check		
One Time Key In	Main			STOPPER, RR BUMPER, RH & LH	2	4.30	8.60	25.00	6.45	Replace	0	0	Not Give		
One Time Key In	Main			SEAL, RR BUMPER , RH	1	85.20	85.20	25.00	63.90	Replace	0	0	Check		
One Time Key In	Main			SEAL, RR BUMPER , LH	1	85.20	85.20	25.00	63.90	Replace	0	0	Check		
One Time Key In	Main			RETAINER, OUTSIDE , RH & LH	2	3.30	6.60	25.00	4.95	Replace	0	0	Check		
One Time Key In	Main			PIXEL STICKER	2	60.00	120.00	0.00	120.00	Replace	2	120.00	Replace	NEC	
One Time Key In	Main			FILLER, RR BUMPER , RH	1	119.90	119.90	25.00	89.93	Replace	0	0	Check		
One Time Key In	Main			FILLER, RR BUMPER , LH	1	119.90	119.90	25.00	89.93	Replace	0	0	Check		
One Time Key In	Main			LENS & BODY ASSY , RR BUMPER , RH	1	486.80	486.80	10.00	438.12	Replace	0	0	Not Give		
One Time Key In	Main			LENS & BODY ASSY , RR BUMPER , LH	1	486.80	486.80	10.00	438.12	Replace	0	0	Not Give		
One Time Key In	Main			LENS & BODY, REAR COMBINATION LAMP , RH	1	438.10	438.10	10.00	394.29	Replace	0	0	Not Give		

Total Spare Part Cost	29,977.43	Surveyor Total	1,848.88
Lump Sum Discount (%)	0.00	Lump Sum Dis (%)	0
Final Spare Part Cost	29,977.43	Final Sur Total	1,848.88

BOM Type	Costing Type	Portion	Material Number	Part Name	Qty	SMRT Recommendation				Repair/Replace	Surveyor Approval			Remarks
						List Price Per Unit(\$)	List Price(\$)	Dis(%)	Final Price(\$)		Surveyor Quantity	Surveyor Final Price(\$)	Repair/Replace	
One Time Key In	Main			LENS & BODY, REAR COMBINATION LAMP, LH	1	438.10	438.10	10.00	394.29	Replace	0	0	Not Give	
One Time Key In	Main			RETAINER, RR BUMPER, RH	1	112.70	112.70	25.00	84.53	Replace	0	0	Check	
One Time Key In	Main			RETAINER, RR BUMPER, LH	1	111.50	111.50	25.00	83.63	Replace	0	0	Check	
One Time Key In	Main			END PANEL SUB-ASSY, BODY LOWER BACK	1	629.80	629.80	25.00	472.35	Replace	0	0	Check	
One Time Key In	Main			COVER, REAR FLOOR UNDER, RH	1	169.50	169.50	25.00	127.13	Replace	0	0	Not Give	
One Time Key In	Main			COVER, REAR FLOOR UNDER, LH	1	234.30	234.30	25.00	175.73	Replace	0	0	Not Give	
One Time Key In	Main			COVER, REAR FLOOR UNDER CENTER	1	222.60	222.60	25.00	166.95	Replace	0	0	Not Give	
One Time Key In	Main			TAIL GATE PANEL SUB-ASSY, BACK DOOR	1	929.60	929.60	25.00	697.20	Replace	0	0	Not Give	
One Time Key In	Main			TAIL GATE BACK DOOR OUTSIDE GARNISH SUB-ASSY	1	891.20	891.20	25.00	668.40	Replace	1	0	Repair	
One Time Key In	Main			STICKER SMRT LOGO	1	7.80	7.80	0.00	7.80	Replace	1	7.80	Replace	NEC
One Time Key In	Main			STICKER DECAL 6555 8888	1	21.60	21.60	0.00	21.60	Replace	1	21.60	Replace	NEC
One Time Key In	Main			NAME PLATE (HYBRID), LUGGAGE COMPARTMENT DOOR	1	52.30	52.30	25.00	39.22	Replace	1	39.22	Replace	NEC
One Time Key In	Main			NAME PLATE (PRIUS), LUGGAGE COMPARTMENT DOOR	1	52.30	52.30	25.00	39.22	Replace	1	39.22	Replace	NEC
Total Spare Part Cost									29,977.43	Surveyor Total		1,848.88		
Lump Sum Discount (%)									0.00	Lump Sum Dis (%)		0		
Final Spare Part Cost									29,977.43	Final Sur Total		1,848.88		

Labour's Cost Detail

S.No.	Costing Type	Job Scope	SMRT Recommendation(\$)	Surveyor Adjustment(\$)	Remarks
Total:			2,535.00	1,000.00	

S.No.	Costing Type	Job Scope	SMRT Recommendation(\$)	Surveyor Adjustment(\$)	Remarks
1	Main	TO REPAIR FRONT PORTION	1,690.00	600	
2	Main	TO REPAIR REAR PORTION	845.00	400	
Total:			2,535.00	1,000.00	

Spray Cost Detail

S.No.	Costing Type	Job Scope	SMRT Recommendation(\$)	Surveyor Adjustment(\$)	Remarks
1	Main	TO REPSRAY FRONT BUMPER	378.00	200	
2	Main	TO RESPRAY FRONT SUPPORT PANEL	180.00	0	
3	Main	TO REPSRAY FRONT HOOD	378.00	0	
4	Main	TO RESPRAY FRONT FENDER LH	378.00	200	
5	Main	TO RESPRAY FRONT FENDER RH	378.00	200	
6	Main	TO REPSRAY REAR BUMPER	378.00	200	
7	Main	TO RESPRAY BUMPER BEAM	180.00	0	
8	Main	TO RESPRAY FILLER RR BUMPER LH	180.00	0	
9	Main	TO RESPRAY FILLER RR BUMPER RH	180.00	0	
10	Main	TO RESPRAY REAR PANEL	180.00	0	
11	Main	TO RESPRAY TAIL GATE	378.00	0	
12	Main	TO RESPRAY TAILGATE OUTSIDE GARNISH	180.00	100	
Total:			3,348.00	900.00	

Other Cost Detail

S.No.	Costing Type	Job Scope	SMRT Recommendation(\$)	Surveyor Adjustment(\$)	Remarks
1	Main	TO CHECK WIRING AND SYSTEM FUNCTION	80.00	30	
2	Main	TO APPLY RUST-PROOFING ON AFFECTED AREA	200.00	40	
3	Main	TO CHECK & RESET SYSTEM FUNCTION	350.00	0	
Total:			1,760.00	110.00	

S.No.	Costing Type	Job Scope	SMRT Recommendation(\$)	Surveyor Adjustment(\$)	Remarks
4	Main	TO REMOVE & REFIX FAN ENGINE & RADIATOR ASSY & INNER COOLER & AIR CON CONDENSER	120.00	0	
5	Main	TO REMOVE AND REFIT WIRE HARDESS	250.00	0	
6	Main	TO TEST AND REFIX REVERSE SENSOR SYSTEM	120.00	0	
7	Main	TO REMOVE AND INSTALL LUGGAGE COMPARTMENT TRIM TO FACILITATE REPAIR.	120.00	40	
8	Main	TO INSPECT RR LIGHTING, MECHANISMS & WATER TEST RR LIGHTING FOR LEAKAGE	120.00	0	
9	Main	TO TOP UP A/C GAS	120.00	0	
10	Main	TO CONDUCT RADIATOR PRESSURE CHECK	120.00	0	
11	Main	TO REPLACE SUNDRY PARTS	100.00	0	
12	Main	TO WASH AND VACUUM	60.00	0	
Total:			1,760.00	110.00	

Summary

	Estimator Assesment(\$)	Surveyor Assesment(\$)
Total Spare Part Detail	29,977.43	1,848.88
Total Labour Cost	2,535.00	1,000.00
Total Spray Painting	3,348.00	900.00
Other	1,760.00	110.00
Overall Total	37,620.43	3,858.88
Lump Sum Repair Option		
Lump Sum Total	0.00	3,858.88
Surveyor Approved Amount		3,858.88
No of Repair Days*	17	6
Remarks		p/p repair, photo before paint.
Surveyor Name		Hwee jie

Estimator Assessment(\$)

Surveyor Assessment(\$)

Signature



Save

Clear

Survey Date

08/02/2019

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed **and** is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

View Received Message

This mail is associated with :
***SHB5057Z (9957415451SG)**
[SLR7754A]
TP
SMRT TAXIS PTE LTD
Feb 2 2019 10:00PM
[Adrian (Guo Yizheng Quek Yizheng)]
SMRT Automotive Services Pte Ltd

[Reply](#) [Reply All](#) [Mark as Unread](#) [Print Message](#) [Delete Message](#) [Forward](#)

From AIG Asia Pacific Insurance Pte. Ltd. (Express) (AIG_SG_EXPRESS), sent on 13/01/2020 11:46 AM.
To LKK_HQ
Subject Alert - Adj Mandate Approved (S\$9537.41) - SHB5057Z - Claim Handler: Lee, Ming-Yao

Approved:9537.41:Please settle at best

DOCUMENTS SUMMARY
There are no documents.

View Received Message

This mail is associated with :

***SHB5057Z (9957415451SG)
[SLR7754A]**

TP

SMRT TAXIS PTE LTD

Feb 2 2019 10:00PM

[Adrian (Guo Yizheng Quek Yizheng)
SMRT Automotive Services Pte Ltd

[Reply](#) [Reply All](#) [Mark as Unread](#) [Print Message](#) [Delete Message](#) [Forward](#)

From AIG Asia Pacific Insurance Pte. Ltd. (Express) (AIG_SG_EXPRESS), sent on 14/01/2020 10:17 AM.
To LKK_HQ
Subject Alert - Adj Mandate Approved (S\$9873.89) - SHB5057Z - Claim Handler: Lee, Ming-Yao

Approved:9873.89:Offer up to 10 days in view of public holiday

DOCUMENTS SUMMARY

There are no documents.

...CLAIM SUBFOLDER...(Pending for Survey Report)

Express

CLAIM SUBFOLDER TRACKING

Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'ed	Status
Main	12 Feb 2019 Edit Reg		07 Feb 2019 00:00 Edit Adj Rpt	S\$8,184.49 Edit Estimates	S\$8,184.49 View Rpt		Pending for Survey Report Cancel Case

Main

Reference

Claim Details

Documents

[Show All](#)

CLAIM SUBFOLDER DETAILS

[Created by adjuster]

Insured:	QUEK YIZHENG, ADRIAN, ID: S8237649F		
Main Claimant:	SMRT TAXIS PTE LTD, Co. Reg. No.: 198905369K		
Vehicle Reg. No.:	SHB5057Z	Date of Loss:	02/02/2019 22:00 - :59 [15 Months and 1 Days From LTA Reg Date (Man Yr)]
Claim Type:	TP / 9957415451SG	Policy/Cover Note No.:	1700044939 (Comprehensive) Coverage: 28/08/2018 - 27/08/2019
Vehicle Reg. No. (Insured):	SLR7754A	Policy No. (Claimant):	D-18090213MFSH
		Excess:	
Repairer:	SMRT Automotive Services Pte Ltd (Woodlands) 60 Woodlands Industrial Park E4, 757705 Woodlands - Tel: 68662628		
Handling Insurer:	AIG Asia Pacific Insurance Pte. Ltd. (Express) - Tel: 65-6419-3000 ... [Handled by Lee, Ming-Yao] MingYao.Lee@aig.com		
Claimant's Insurer:	MS First Capital Insurance Ltd (HQ) - Tel: 62222311		
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Handled by ONG HWEI JIE] ... [Final Rpt due 22/02/2019]		

ASSOCIATED MAIL RECEIVED

[View All](#)[Compose Case Mail](#)

- AIG_SG_EXPRESS (14/01/2020): Alert - Adj Mandate Approved (S\$9873.89) - SHB5057Z - Claim Handler: Lee, Ming-Y...
- AIG_SG_EXPRESS (13/01/2020): Alert - Adj Mandate Approved (S\$9537.41) - SHB5057Z - Claim Handler: Lee, Ming-Y...

ALL ASSOCIATED TASKS

[View All](#)[Search Tasks](#)[Create New Task](#)[Complete](#)

Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
----------	----------	------	------------	---------	---------	-------------	--------------	------------	-------

No results.

Claim Documents

***SHB5057Z (9957415451SG)
[SLR7754A]**

TP

SMRT TAXIS PTE LTD

Feb 2 2019 10:00PM

[QUEK YIZHENG, ADRIAN]

SMRT Automotive Services Pte Ltd

[Upload Documents](#) |
 [Upload Photos](#) |
 [Compose New Letter](#) |
 [Upload Video](#) |
 [Upload Audio](#)

[View](#) [View in Browser](#) ▼

Video			1 per page	<input checked="" type="checkbox"/>
No	Finalized On	AIG Asia Pacific Insurance Pte. Ltd. (SG)	Thumbnail	Print
1	06/08/19 19:00	Video - Accident Video from FCI	Load MOV	
2	02/09/19 17:06	Video - Accident extended	Load MP4	

Letters/Correspondences			1 per page	<input checked="" type="checkbox"/>
No	Finalized On	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
1	(Draft)	Third Party Express Settlement – Payment Breakdown	Edit	

Photos/Images			3 per page	<input checked="" type="checkbox"/>
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
1	15/02/19 10:05	General View	Load JPG	<input checked="" type="checkbox"/>
2	15/02/19 10:05	General View	Load JPG	<input checked="" type="checkbox"/>
3	15/02/19 10:05	General View	Load JPG	<input checked="" type="checkbox"/>
4	15/02/19 10:05	General View	Load JPG	<input checked="" type="checkbox"/>
5	15/02/19 10:05	General View	Load JPG	<input checked="" type="checkbox"/>
6	15/02/19 10:05	General View	Load JPG	<input checked="" type="checkbox"/>
7	15/02/19 10:05	General View	Load JPG	<input checked="" type="checkbox"/>
8	15/02/19 10:05	General View	Load JPG	<input checked="" type="checkbox"/>
9	15/02/19 10:05	General View	Load JPG	<input checked="" type="checkbox"/>
10	15/02/19 10:05	General View	Load JPG	<input checked="" type="checkbox"/>
11	15/02/19 10:05	General View	Load JPG	<input checked="" type="checkbox"/>
12	15/02/19 10:05	General View	Load JPG	<input checked="" type="checkbox"/>
13	15/02/19 10:05	General View	Load JPG	<input checked="" type="checkbox"/>
14	15/02/19 10:05	General View	Load JPG	<input checked="" type="checkbox"/>
15	15/02/19 10:05	General View	Load JPG	<input checked="" type="checkbox"/>
16	15/02/19 10:05	General View	Load JPG	<input checked="" type="checkbox"/>
17	15/02/19 10:05	General View	Load JPG	<input checked="" type="checkbox"/>
18	15/02/19 10:05	General View	Load JPG	<input checked="" type="checkbox"/>
19	15/02/19 10:05	General View	Load JPG	<input checked="" type="checkbox"/>
20	15/02/19 10:05	General View	Load JPG	<input checked="" type="checkbox"/>
21	15/02/19 10:05	General View	Load JPG	<input checked="" type="checkbox"/>
22	15/02/19 10:05	General View	Load JPG	<input checked="" type="checkbox"/>
23	15/02/19 10:05	General View	Load JPG	<input checked="" type="checkbox"/>
24	15/02/19 10:05	General View	Load JPG	<input checked="" type="checkbox"/>
25	15/02/19 10:05	General View	Load JPG	<input checked="" type="checkbox"/>
26	15/02/19 10:05	General View	Load JPG	<input checked="" type="checkbox"/>
27	15/02/19 10:05	General View	Load JPG	<input checked="" type="checkbox"/>

Video			1 per page	<input checked="" type="checkbox"/>
No	Finalized On	ATIG Asia Pacific Insurance Pte, Ltd. (SG)	Thumbnail	Print
28	15/02/19 10:05	General View	 Load JPG	<input checked="" type="checkbox"/>
29	15/02/19 10:05	General View	 Load JPG	<input checked="" type="checkbox"/>
30	15/02/19 10:05	General View	 Load JPG	<input checked="" type="checkbox"/>
31	15/02/19 10:05	General View	 Load JPG	<input checked="" type="checkbox"/>
32	15/02/19 10:05	General View	 Load JPG	<input checked="" type="checkbox"/>
33	15/02/19 10:05	General View	 Load JPG	<input checked="" type="checkbox"/>
34	15/02/19 10:05	General View	 Load JPG	<input checked="" type="checkbox"/>
35	15/02/19 10:05	General View	 Load JPG	<input checked="" type="checkbox"/>
36	15/02/19 10:05	General View	 Load JPG	<input checked="" type="checkbox"/>
37	15/02/19 10:05	General View	 Load JPG	<input checked="" type="checkbox"/>
38	15/02/19 10:05	General View	 Load JPG	<input checked="" type="checkbox"/>
39	15/02/19 10:05	General View	 Load JPG	<input checked="" type="checkbox"/>
40	15/02/19 10:05	General View	 Load JPG	<input checked="" type="checkbox"/>
41	15/02/19 10:05	General View	 Load JPG	<input checked="" type="checkbox"/>
42	15/02/19 10:05	General View	 Load JPG	<input checked="" type="checkbox"/>
43	15/02/19 10:05	General View	 Load JPG	<input checked="" type="checkbox"/>
44	15/02/19 10:05	General View	 Load JPG	<input checked="" type="checkbox"/>
45	15/02/19 10:05	General View	 Load JPG	<input checked="" type="checkbox"/>
46	15/02/19 10:05	General View	 Load JPG	<input checked="" type="checkbox"/>
47	15/02/19 10:05	Dismantled Parts	 Load JPG	<input checked="" type="checkbox"/>
48	15/02/19 10:05	Dismantled Parts	 Load JPG	<input checked="" type="checkbox"/>
49	15/02/19 10:05	Dismantled Parts	 Load JPG	<input checked="" type="checkbox"/>
50	15/02/19 10:05	Dismantled Parts	 Load JPG	<input checked="" type="checkbox"/>
51	15/02/19 10:05	Dismantled Parts	 Load JPG	<input checked="" type="checkbox"/>
52	15/02/19 10:05	Dismantled Parts	 Load JPG	<input checked="" type="checkbox"/>
53	15/02/19 10:05	Dismantled Parts	 Load JPG	<input checked="" type="checkbox"/>
54	15/02/19 10:05	Dismantled Parts	 Load JPG	<input checked="" type="checkbox"/>
55	15/02/19 10:05	Dismantled Parts	 Load JPG	<input checked="" type="checkbox"/>
56	15/02/19 10:05	Dismantled Parts	 Load JPG	<input checked="" type="checkbox"/>
57	15/02/19 10:05	Dismantled Parts	 Load JPG	<input checked="" type="checkbox"/>
58	15/02/19 10:05	Dismantled Parts	 Load JPG	<input checked="" type="checkbox"/>
59	15/02/19 10:05	Dismantled Parts	 Load JPG	<input checked="" type="checkbox"/>
60	15/02/19 10:05	Dismantled Parts	 Load JPG	<input checked="" type="checkbox"/>
61	15/02/19 10:05	Dismantled Parts	 Load JPG	<input checked="" type="checkbox"/>
62	15/02/19 10:05	Dismantled Parts	 Load JPG	<input checked="" type="checkbox"/>
63	15/02/19 10:05	Dismantled Parts	 Load JPG	<input checked="" type="checkbox"/>
64	15/02/19 10:05	Dismantled Parts	 Load JPG	<input checked="" type="checkbox"/>
65	15/02/19 10:05	Dismantled Parts	 Load JPG	<input checked="" type="checkbox"/>
66	15/02/19 10:05	Dismantled Parts	 Load JPG	<input checked="" type="checkbox"/>
67	15/02/19 10:05	Dismantled Parts	 Load JPG	<input checked="" type="checkbox"/>
68	15/02/19 10:05	Dismantled Parts	 Load JPG	<input checked="" type="checkbox"/>
69	15/02/19 10:05	Dismantled Parts	 Load JPG	<input checked="" type="checkbox"/>
70	15/02/19 10:05	Dismantled Parts	 Load JPG	<input checked="" type="checkbox"/>
71	15/02/19 10:05	Dismantled Parts	 Load JPG	<input checked="" type="checkbox"/>
72	15/02/19 10:05	Dismantled Parts	 Load JPG	<input checked="" type="checkbox"/>
73	15/02/19 10:05	Dismantled Parts	 Load JPG	<input checked="" type="checkbox"/>
74	15/02/19 10:05	Dismantled Parts	 Load JPG	<input checked="" type="checkbox"/>
75	15/02/19 10:05	Dismantled Parts	 Load JPG	<input checked="" type="checkbox"/>

Video			1 per page	<input checked="" type="checkbox"/>
No	Finalized On	AIG Asia Pacific Insurance Pte. Ltd. (SG)	Thumbnail	Print
76	15/02/19 10:05	Dismantled Parts	Load JPG	<input checked="" type="checkbox"/>
77	15/02/19 10:05	Dismantled Parts	Load JPG	<input checked="" type="checkbox"/>
78	15/02/19 10:05	Dismantled Parts	Load JPG	<input checked="" type="checkbox"/>
79	15/02/19 10:05	Dismantled Parts	Load JPG	<input checked="" type="checkbox"/>
80	15/02/19 10:05	Dismantled Parts	Load JPG	<input checked="" type="checkbox"/>
81	15/02/19 10:05	Dismantled Parts	Load JPG	<input checked="" type="checkbox"/>
82	15/02/19 10:05	Dismantled Parts	Load JPG	<input checked="" type="checkbox"/>
83	18/02/19 09:29	Replacement Part Photo	Load JPG	<input checked="" type="checkbox"/>
84	18/02/19 09:29	Replacement Part Photo	Load JPG	<input checked="" type="checkbox"/>
85	18/02/19 09:29	Replacement Part Photo	Load JPG	<input checked="" type="checkbox"/>
86	18/02/19 09:29	Replacement Part Photo	Load JPG	<input checked="" type="checkbox"/>
87	18/02/19 09:29	Replacement Part Photo	Load JPG	<input checked="" type="checkbox"/>
88	18/02/19 09:29	Replacement Part Photo	Load JPG	<input checked="" type="checkbox"/>
89	18/02/19 09:29	Replacement Part Photo	Load JPG	<input checked="" type="checkbox"/>

Documentation			1 per page	<input checked="" type="checkbox"/>
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
1	13/02/19 18:48	TP ESTIMATE- MARKED	Load PDF	
2	13/02/19 18:48	TP GIA REPORT	Load PDF	
3	06/01/20 17:43	LETTER TO OI	Load PDF	
4	06/01/20 17:43	LOD	Load PDF	
5	06/01/20 17:43	LTA SEARCH	Load PDF	
6	06/01/20 17:43	RENTAL MILEAGE	Load PDF	
7	06/01/20 17:43	RENTAL RECEIPT	Load PDF	
8	04/02/20 13:26	Authorisation to Act	Load PDF	
9	04/02/20 13:26	Release Voucher	Load PDF	
10	04/02/20 13:26	WORKSHOP INVOICE	Load PDF	

No	Finalized On	AIG Asia Pacific Insurance Pte. Ltd. (SG)	Thumbnail	Print
1	14/02/19 10:29	OI GIA REPORT	Load PDF	

Documents Checklist

DOCUMENTS CHECKLIST

[Reset](#) | [Save](#) | [Print](#)

There are no document checklists configured.

Our Checklist Remarks - LKK Auto Consultants Pte Ltd (HQ)

Show Remarks To: Handling Insurer

Note: Remarks are private unless you show it to other parties.

NOTE: TO BE COMPLETED BY SURVEYOR

TEAM _____

**THIRD PARTY EXPRESS SETTLEMENT
(PAYMENT BREAKDOWN)**

Vehicle No:	SLR7754A (Insd veh)	Model:	TOYOTA PRIUS TAXI 1.8 (A)
	SHB5057Z (TP veh)		
Date of Accident:	02/02/2019		

Global Sum Settlement	:	<input checked="" type="checkbox"/> Yes	<input type="checkbox"/> No
Repair Estimate	:\$		47,261.60
Final Repair Cost	:\$		9,870.00
Loss of Use	:\$		10.00 days at \$50.00 per day
Rental (if any)	:\$		10 days
LTA / GIA Search Fee	:\$		
Others:	:\$		
	:\$		
Final Settlement Sum (GLOBAL SUM)	:\$		9,870.00
Is Third Party Workshop GIA Registered? <input type="checkbox"/> YES <input checked="" type="checkbox"/> NO (Kindly indicate below)			
A) For Non GIA Registered Workshop:		Agreed Liability _____ 100 _____ (%)	
B) For GIA Registered Workshop:		BOLA Applicable: Yes/ No BOLA Scenario No: _____	
BOLA Liability: _____ (%)		Assessed Liability (*): _____ 100 _____ (%)	
* Assessed Liability to be filled only for chain collisions and for cases where BOLA does not apply.			
Remarks _____			

Payment Instruction: Payee's Breakdown			
1)	SMRT TAXIS PTE LTD	:\$	9,870.00
2)		:\$	
3)		:\$	
4)		:\$	

NUR SHAQILAH BTE ABDOL WAHAB

LKK Auto Consultants Pte Ltd

04 Feb
2020

Date

Please attach all the supporting documents to the form.

(Final Repair Bill; Rental Invoice; Release Voucher; Authorisation to Act; Survey Report; Medical Report/ Bill (if any))

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CC3/AIG19002623/JDA3S2
Date: 04/02/2020

REFERENCE

Handling Insurer: AIG Asia Pacific Insurance Pte. Ltd. Policy No: 1700044939
Claimant Vehicle No : SHB5057Z **Insured Vehicle No :** SLR7754A
 Date of Loss: 02/02/2019 Nature of Claim: TP Claim No: 9957415451SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: **SHB5057Z**
 Make & Model: TOYOTA PRIUS TAXI, 1.8 (A) Engine No: 2ZRS099486
 Reg. Date: 01/11/2017 (Man. Year: 2017) Chassis No: JTDKB3FU103573180
 Colour: Maroon Odometer: 0 km
 Engine Capacity: 1798 cc
 Market Value/New Car Price: N/A
 Sum Insured (S\$): **Market Value/New Car Price**

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Good Steering (Serviceable): Yes Footbrake (Serviceable): Yes
 Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 195/65 R15 Rear Tyre Size: 195/65 R15
 Front Left Side: West Lake 6 mm Rear Left Side: West Lake 6 mm
 Front Right Side: West Lake 6 mm Rear Right Side: West Lake 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	39,618.60	6,174.49	33,444.11	84.42
Miscellaneous Items	0.00	0.00	0.00	
Labour	7,643.00	2,010.00	5,633.00	73.70
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Nett Amount (S\$)	47,261.60	8,184.49	39,077.11	82.68
	+ Loss of Use (10.0 x S\$50.00/day) (S\$)	500.00		
	+ Car Rental (10.0 x S\$118.24/day) (S\$)	1,182.40		
	+ Doc/Search Fee (S\$)	7.00		
	Nett Liability (S\$)	9,873.89		
	Global Sum Settlement (S\$)	9,870.00		

INSPECTION

Date of Assignment: 07/02/2019
 Date Inspected: 07/02/2019 Inspected At: SMRT Automotive Services Pte Ltd (Woodlands)
 60 Woodlands Industrial Park E4
 Singapore 757705
 Estimated Period of Repair: 6.0 days

Adjuster: ONG HWEE JIE

Manager: CHAN JIA LE

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*BRACKET, FR BUMPER (DISC 25%)	Cracked	99.80 F	*74.85 F
2	1		*EMBLEM ASSY FRONT (DISC 25%)	Necessary	87.10 F	*65.33 F
3	1		*GRILLE SUB-ASSY (DISC 25%)	Buckled	335.60 F	*251.70 F
4	1		*CLIPS PIECE, FRT & RR BUMPER (DISC 25%) 10pcs	Necessary	15.00 F	*11.25 F
5	1		*COVER, RR BUMPER ASSY (DISC 25%)	Deformed	423.90 F	*317.93 F
6	1		*GUARD, RR BUMPER, LOWER (DISC 25%)	Buckled	558.30 F	*418.73 F
7	1		*COVER, GUARD RR BUMPER LOWER (DISC 25%)	Scratched	14.80 F	*11.10 F
8	3		*PAD, RR BUMPER, CTR (DISC 25%)	Necessary	6.60 F	*4.95 F
9	2		*PAD, RR BUMPER, RH & LH, 1 (DISC 25%)	Necessary	7.60 F	*5.70 F
10	2		*PAD, RR BUMPER, RH & LH, 2 (DISC 25%)	Necessary	7.60 F	*5.70 F
11	2		*PAD, RR BUMPER, RH & LH, 3 (DISC 25%)	Necessary	7.60 F	*5.70 F
12	2		*SEAL, RR BUMPER ARM, RH & LH (DISC 25%)	Necessary	22.00 F	*16.50 F
13	1		*NAME PLATE (HYBRID), LUGGAGE (DISC 25%)	Necessary	52.30 F	*39.23 F
14	1		*NAME PLATE (PRIUS), LUGGAGE (DISC 25%)	Necessary	52.30 F	*39.23 F
15	1		*SUPPORT S/A UPPER (DISC 25%)	Dented	364.90 F	*273.68 F
16	1		*SUPPORT S/A RH (DISC 25%)	Dented	237.00 F	*177.75 F
17	1		*INLET, AIR CLEANER, NO 2 (DISC 25%)	Buckled	93.90 F	*70.43 F
18	1		*REAR BUMPER REINFORCEMENT (DISC 25%)	Dented	318.80 F	*239.10 F
19	1		*FILLER, RR BUMPER, LH (DISC 25%)	Deformed	119.90 F	*89.93 F
20	1		*TAIL GATE BACK DOOR OUTSIDE GARNISH SUB- (DISC 25%)	Cracked	891.20 F	*668.40 F
21	1		*ABSORBER, FR BUMPER (DISC 25%)	Cracked	70.30 F	*52.73 F
22	1		*UNIT, HEADLAMP, RH (DISC 25%)	Cracked	2,558.90 F	*2,303.01 F
23	1		*TAIL GATE WEATHERSTRIP, BACK (DISC 25%)	Cut	360.70 F	*270.53 F
24	1		*NAME PLATE FRAME (SN)	Missing	25.00 F	*25.00 F
25	1		*NUMBER PLATE (SN)	Cracked	35.00 F	*35.00 F
26	2		*PIXEL STICKER (SN)	Necessary	120.00 F	*120.00 F
27	1		*STICKER SMRT LOGO (SN)	Necessary	7.80 F	*7.80 F
28	1		*STICKER DECAL 6555 8888 (SN)	Necessary	21.60 F	*21.60 F
29	1		*SENSOR REVERSE (SN)	Shorted	180.00 F	*180.00 F
30	1		*SUPPORT, FR BUMPER RH	Not Necessary	76.90 F	*- F
31	1		*SUPPORT, FR BUMPER LH	Not Necessary	82.30 F	*- F
32	1		*COVER, FR BUMPER RH	Not Necessary	28.10 F	*- F
33	1		*COVER, FR BUMPER LH	Not Necessary	28.10 F	*- F
34	1		*SEAL, HOOD TO FR END	Not Necessary	24.40 F	*- F
35	1		*GRILLE, RADIATOR	Not Necessary	165.00 F	*- F
36	1		*RETAINER, FR BUMPER, LH & RH	Not Necessary	8.50 F	*- F
37	1		*REINFORCEMENT FRONT UPPER	Not Necessary	691.10 F	*- F
38	1		*ABSORBER, FR BUMPER	Not Necessary	70.30 F	*- F
39	1		*REINFORCEMENT FRONT LOWER	Not Necessary	238.50 F	*- F
40	1		*ABSORBER, FR BUMPER LOWER	Not Necessary	117.00 F	*- F
41	1		*EXTENSION SUB-ASSY, LH	Not Necessary	116.30 F	*- F
42	1		*EXTENSION SUB-ASSY, RH	Not Necessary	116.30 F	*- F
43	1		*COVER, RADIATOR	Not Necessary	227.80 F	*- F
44	1		*SUPPORT S/A LH	Not Necessary	237.00 F	*- F
45	1		*SUPPORT SUB-ASSY LOWER	Not Necessary	397.40 F	*- F
46	1		*SUPPORT, RADIATOR UPPER RH	Not Necessary	76.70 F	*- F
47	1		*SUPPORT, RADIATOR UPPER LH	Not Necessary	76.70 F	*- F
48	1		*CUSHION HOOD BUMPER	Not Necessary	8.50 F	*- F
49	1		*GUIDE RADIATOR AIR	Not Necessary	93.90 F	*- F
50	1		*BRACE, HOOD LOCK SUPPORT	Not Necessary	76.20 F	*- F
51	1		*LOCK ASSY, HOOD	Not Necessary	131.10 F	*- F

Report was unsubmitted during this print-out.

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
52	1		*CABLE ASSY, HOOD	Not Necessary	53.20 F	*-F
53	1		*SEAL, RADIATOR TO RH	Not Necessary	24.80 F	*-F
54	1		*SEAL, RADIATOR TO LH	Not Necessary	24.80 F	*-F
55	1		*GUIDE, RADIATOR AIR, RH	Not Necessary	54.60 F	*-F
56	1		*GUIDE, RADIATOR AIR, LH	Not Necessary	58.80 F	*-F
57	1		*GROMMET (FOR RADIATOR LOWER)	Not Necessary	12.70 F	*-F
58	1		*CUSHION (FOR RADIATOR UPPER)	Not Necessary	9.80 F	*-F
59	1		*GUIDE, RADIATOR AIR UPPER	Not Necessary	44.70 F	*-F
60	1		*RADIATOR ASSY	Not Necessary	1,841.10 F	*-F
61	1		*COOLANT	Not Necessary	12.30 F	*-F
62	1		*FAN RADIATOR, LH	Not Necessary	181.80 F	*-F
63	1		*FAN RADIATOR, RH	Not Necessary	233.00 F	*-F
64	1		*FAN SHROUD RADIATOR	Not Necessary	219.30 F	*-F
65	1		*MOTOR, COOLING FAN, RH	Not Necessary	443.40 F	*-F
66	1		*MOTOR, COOLING FAN, LH	Not Necessary	543.50 F	*-F
67	1		*HOSE, RADIATOR, NO.1	Not Necessary	42.60 F	*-F
68	1		*HOSE, RADIATOR, NO.2	Not Necessary	40.20 F	*-F
69	1		*HOSE, WATER BY-PASS, NO.2	Not Necessary	37.40 F	*-F
70	1		*HOSE, WATER BY-PASS, NO.3	Not Necessary	20.10 F	*-F
71	1		*HOSE, WATER BY-PASS, NO.4	Not Necessary	13.20 F	*-F
72	1		*HOSE, WATER BY-PASS, NO.1	Not Necessary	37.40 F	*-F
73	1		*HORN ASSY, HIGH	Not Necessary	112.80 F	*-F
74	1		*HORN ASSY, LOW	Not Necessary	112.80 F	*-F
75	1		*AIR CON CONDENSER ASSY	Not Necessary	1,317.70 F	*-F
76	1		*TUBE & ACCESSORY	Not Necessary	574.40 F	*-F
77	1		*HOSE SUB-ASSY, DISCHARGE	Not Necessary	337.10 F	*-F
78	1		*HOSE, HV WATER PUMP INLET	Not Necessary	37.90 F	*-F
79	1		*INVERTER WATER PUMP ASSY	Not Necessary	432.00 F	*-F
80	1		*HOSE, HV WATER PUMP OUTLET	Not Necessary	29.60 F	*-F
81	1		*HOSE, INVERTER RADIATOR INLET	Not Necessary	40.70 F	*-F
82	1		*INLET, AIR CLEANER, NO 3	Not Necessary	35.30 F	*-F
83	1		*INLET, AIR CLEANER, NO.1	Not Necessary	130.50 F	*-F
84	1		*AIR CLEANER ASSY	Not Necessary	956.20 F	*-F
85	1		*WIRE, ENGINE ROOM MAN	Not Necessary	6,138.00 F	*-F
86	1		*HOOD SUB-ASSY	Not Necessary	938.40 F	*-F
87	1		*HINGE ASSY, HOOD, RH	Not Necessary	57.00 F	*-F
88	1		*HINGE ASSY, HOOD, LH	Not Necessary	57.00 F	*-F
89	1		*INSULATOR, HOOD	Not Necessary	393.90 F	*-F
90	1		*INSULATOR, HOOD CLIP	Not Necessary	2.30 F	*-F
91	1		*WIPER GARNISH LOUVER SUB-ASSY	Not Necessary	666.90 F	*-F
92	1		*UNIT HEADLAMP, LH	Not Necessary	2,558.90 F	*-F
93	1		*EMBLEM, SIDE PANEL (HYBRID)	Not Necessary	52.90 F	*-F
94	1		*COMPUTER SUB-ASSY, HEADLAMP, LH NO.1	Not Necessary	486.40 F	*-F
95	1		*UNIT, HEADLAMP, RH	Not Necessary	2,558.90 F	*-F
96	1		*EMBLEM, SIDE PANEL (HYBRID)	Not Necessary	52.90 F	*-F
97	1		*COMPUTER SUB-ASSY, HEADLAMP, RH NO.1	Not Necessary	486.40 F	*-F
98	1		*STOPPER, RR BUMPER, RH & LH	Not Necessary	4.30 F	*-F
99	1		*SEAL, RR BUMPER, RH	Not Necessary	85.20 F	*-F
100	1		*SEAL, RR BUMPER, LH	Not Necessary	85.20 F	*-F
101	1		*FILLER, RR BUMPER, RH	Not Necessary	119.90 F	*-F
102	1		*LENS & BODY ASSY, RR BUMPER RH	Not Necessary	486.80 F	*-F
103	1		*LENS & BODY ASSY, RR BUMPER, LH	Not Necessary	486.80 F	*-F
104	1		*LENS & BODY, REAR COMBINATION LAMP, RH	Not Necessary	438.10 F	*-F
105	1		*LENS & BODY, REAR COMBINATION LAMP, LH	Not Necessary	438.10 F	*-F
106	1		*RETAINER, RR BUMPER, RH	Not Necessary	112.70 F	*-F
107	1		*RETAINER, RR BUMPER, LH	Not Necessary	111.50 F	*-F

Report was unsubmitted during this print-out.

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
108	1		*END PANEL SUB-ASSY, BODY LOWER BACK	Not Necessary	629.80 F	*- F
109	1		*COVER, REAR FLOOR UNDER, RH	Not Necessary	169.50 F	*- F
110	1		*COVER, REAR FLOOR UNDER, LH	Not Necessary	234.30 F	*- F
111	1		*COVER, REAR FLOOR UNDER CENTER	Not Necessary	222.60 F	*- F
112	1		*TAIL GATE PANEL SUB-ASSY, BACK DOOR	Not Necessary	929.60 F	*- F
113	1		*COVER, FR BUMPER (DISC 25%)	Deformed	495.50 F	*371.63 F
114	1		*FENDER SUB-ASSY, FR, LH	Repair	933.10 F	*- F
115	1		*FENDER SUB-ASSY, FR, RH	Repair	933.10 F	*- F
116	1		*RETAINER, OUTSIDE, RH & LH	Not Necessary	3.30 F	*- F
Total Parts (\$\$)					39,618.60	6,174.49

F=Franchise part.

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	PANEL BEATING & BODYWORK.	New	2,535.00	1,000.00
2	SPRAY PAINT.	New	3,348.00	900.00
3	TO CHECK WIRING AND SYSTEM FUNCTION.	New	80.00	30.00
4	TO APPLY RUST-PROOFING AFFECTED AREA.	New	200.00	40.00
5	TO CHECK & RESET SYSTEM FUNCTION.	New	350.00	0.00
6	TO REMOVE & REFIX FAN ENGINE & RADIATOR ASSY & INNER COOLER & AIR CON CONDENSER.	New	120.00	0.00
7	TO REMOVE AND REFIT WIRE HARDESS.	New	250.00	0.00
8	TO TEST AND REFIX REVERSE SENSOR SYSTEM.	New	120.00	0.00
9	TO REMOVE AND INSTALL LUGGAGE COMPARTMENT TRIM TO FACILITATE REPAIR.	New	120.00	40.00
10	TO INSPECT RR LIGHTING, MECHANISM & WATER TEST RR LIGHTING FOR LEAKAGE.	New	120.00	0.00
11	TO TOP UP A/C GAS.	New	120.00	0.00
12	TO CONDUCT RADIATOR PRESSURE CHECK.	New	120.00	0.00
13	TO REPLACE SUNDRY PARTS.	New	100.00	0.00
14	TO WASH AND VACUUM.	New	60.00	0.00
Gross Labour Cost (S\$)			7,643.00	2,010.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >