

ASS. REC. BY: Meinien REP: CS/SM019002639/Utd3 ⁿ²
Special Instruction:
From (Person): Ginoh pau loong of SMO Date/Time: 13/2/19 @ 9.01am
Estimated Cost: Bill to:

OD / TP / VS / TP RES / OD RES / EVA / INV / MVT / CS
To Inspect Vehicle No: SV31U Insured: SLU 2711 R
at Workshop m/s: Centre Line Car Tel: 6846 8203
of 2 Kaki Bkt Ave 2 #02-23
Policy No: D18MTPV01018425 Claim No: EMTD1900746
Sum Insured: Excess:
Make of Veh: D.O.A. 04/02/2019
(Client's Record)

CA / REV / REP. / REV 24 HRS ^{imp}
Date/Time: 10:32am @ 13/2/19 Person Contacted: Mr. Heng H.O.D. Endorsement:
Vehicle: IN / OUT

Date/Time	Action/Instruction (✓) Estimate
	<u>SV31U-X</u>
	<u>SLU 2711 R - CS/SM019002639/Utd3</u>
<u>14/2/19 @ 7:08pm</u>	<u>revert pending estimate.</u>

(08/11/13) wef

REF:

ASS. REC. BY: *Matus***ASSIGNMENT**

From: _____ Date: _____

Estimated Cost: _____

OD / TP / WS / TP RES / OD RES / EVA / INV / MVTo Inspect Vehicle No: *SV 314*
at Workshop m/s *Centreline*
of _____

Insured: _____

Policy No. _____

Claims No. _____

Sum Insured: _____ Excess: _____

(Client's Record)

Make of Veh: _____

(Policy Condition)

Remark: The veh had commenced its
repair at the time of inspection.

N/S	O/S

Bal. or Market Value: _____

IDAC Accident Rpt: _____ Consistent? : Yes or No

GIA / PR Seen: _____ Consistent? : Yes or No

Est. Repairs: *5* days Res.: Yes or NoLum Sum: *22* % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Date: _____ Person Contacted: _____

Vehicle: IN / OUT

Veh No: *SV 314*Yr Regn: *8117*Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make: *Tarpt herring* c.c. *1998*Colour: *white*

A/C: Insured / Std / NI / NA

Sp. Reading: *13066*

T/Radio: Insured / Std / NI / NA

Eng/No: _____

C/No: *JTEKB 36H/X0J000173*

Gen. Cond: Good / Fair / Poor / Burnt

Steering: Inorder / Jammed / Leaked / Burnt or

Brake: Inorder / Jammed / Leaked / Burnt or

Modi: Nil / S/Rim / STD A/Rim or

Tyre Size: F: *235/55R18*

R: _____

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

Front

Rear

R/Bal. *7* mmR/Bal. *7* mmL/Bal. *7* mmL/Bal. *7* mmD.O.A. *4/2/19*D.O.I. *13/2/19*

Survey held at _____

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time Action / Instruction

*Direct LTA 71131**26/2/19 2/5 + 3500 confirmed with AMH node.
(Red: 3140.66, 47016)*

RECEIVED 26 FEB 2019

Date/Time, File Pass to?

☐ : Preli. ReportDays Of Repair: *5**26/2 Typist*☒ : Final Report

Resurvey No. of Trip: _____

Date/Time, File Return to?

Survey Fee:

Transportation:

2)

Add Fee: ☐ : Site Insp (\$

) __S + RS __SI

☐ : Interview (\$

) Photos

☐ : Tech. Invs (\$

) Others

☐ : Weekend (\$

)

Report Format :

Lump Sum / I.B.I: (\$ *3500*)

TOTAL

250
*10**260*

...CLAIM SUBFOLDER...(New Assignment)

CLAIM SUBFOLDER TRACKING

Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'd	Status
Main	07 Feb 2019		13 Feb 2019 09:01 Assign				New Assignment Cancel Case

Main	Reference	Claim Details	Documents	Show All
------	-----------	---------------	-----------	--------------------------

CLAIM SUBFOLDER DETAILS [Created by insurer]

Insured:	HOE YIWEN, ID: S6848132A		
Main Claimant:	TAN BEE LIAN, ID: S6816843J		
Vehicle Reg. No.:	SV31U	Date of Loss:	04/02/2019 08:00 - :59
Claim Type:	TP / CMTD1900746	Policy/Cover Note No.:	D18MTPV01018425 (Comprehensive)
Vehicle Reg. No. (Insured):	SLU2711R	Policy No. (Claimant):	
		Excess:	
Repairer:	Centre Line Car Spray Painting (HQ) 2 KAKI BUKIT AVNEUE 2, #02-23 KAKI BUKIT AUTOHUB, 417921 Kaki Bukit - Tel: 68468203		
Handling Insurer:	Sompo Insurance Singapore Pte. Ltd. (HQ) - Tel: 6461 6555 ... [Handled by GNOH PAU LOONG - 63295217]		
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Final Rpt due 22/02/2019]		
Adj Asg. Remarks:	WS: MR. HENG JU LENG / 96256931		

ASSOCIATED MAIL RECEIVED [View All](#) [Compose Case Mail](#)

There are no mail for this case.

ALL ASSOCIATED TASKS [View All](#) [Search Tasks](#) [Create New Task](#) [Complete](#)

Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

View Sent Message

This mail is associated with :

***SV31U (CMTD1900746)**
[SLU2711R]

TP
TAN BEE LIAN
Feb 4 2019 8:00AM
[HOE YIWEN]
Centre Line Car Spray Painting

[Resend](#) [View Recipients](#) [Print Message](#) [Delete Message](#) [Forward](#)

From LKK Auto Consultants Pte Ltd (LKK_HQ), sent on 14/02/2019 17:08 PM.
To pauloong.gnoh@sompo.com.sg
Subject SV31U (CMTD1900746) [SLU2711R]

Dear Sir/Madam,

Please be informed that we have inspected the vehicle SV31U on 13/2/2019
We are pending estimate from repairer.

Best Regards,
Denise Tay | Case Handler
LKK Auto Consultants Pte Ltd

DOCUMENTS SUMMARY

There are no documents.

> Back to OneMotoring

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars	
Owner ID Type:	Singapore NRIC
Owner ID:	6843J
Vehicle Details	
Vehicle No.:	SV31U
Vehicle to be Exported:	No
Intended Deregistration Date:	14 Feb 2019
Vehicle Make:	TOYOTA
Vehicle Model:	HARRIER G GRADE
Primary Colour:	White
Manufacturing Year:	2017
Engine No.:	8ARZ085540
Chassis No.:	JTEKB3GHX0J000173
Maximum Power Output:	170.0 kW (227 bhp)
Open Market Value:	\$33,308.00
Original Registration Date:	02 Aug 2017
First Registration Date:	02 Aug 2017
Transfer Count:	0
Actual ARF Paid:	\$38,632.00
Intended PARF Rebate Details	
PARF Eligibility:	Yes
PARF Eligibility Expiry Date:	01 Aug 2027
PARF Rebate Amount:	\$28,974.00
Intended COE Rebate Details	
COE Expiry Date:	01 Aug 2027
COE Category:	B - Car above 1600cc or 97kW (130bhp)
COE Period(Years):	10
QP Paid:	\$49,802.00
COE Rebate Amount:	\$42,157.00
Total Rebate Amount:	\$71,131.00

The information contained herein is correct as at 14 Feb 2019

OK

Centre Line Car Spray Painting

2 Kaki Bukit Avenue 2, #02-18/23, (Kaki Bukit Autohub), Singapore 417921

Telephone: 6846 8203 FAX: 6538 4108 Handphone: 9625 6931 (Ah JU)

not Allocated plate
4/5 # 3500
5 day.

Vehicle number: SV31U

Vehicle Made & Model: TOYOTA HARRIER

Qty	List Items	Amount \$
1	Rear bumper	991.10 ✓
1	Rear bumper reflector - RH	110.62 ✓
1	Rear bumper difusser	453.20 ✓
1	Rear bumper PDC sensor - RH	414.75 ✓
1	Rear bumper sponge	155.91 X
1	Rear bumper carrier	733.50 X
1	Rear bumper side bracket - RH	89.95 ✓
2	Rear bumper side retainers - L/R @ 55.13	110.25 ✓
10	Rear bumper clips @ 4.50	45.00 ✓
1	Rear end panel	727.20 ✓
1	Rear exhaust silencer	822.60 X
1	Rear fender - RH	1,015.90 X
1	Rear fender inner shield - RH	104.23 ✓
Sub-total		5,774.21
Less 25%		1,443.55
Total List		4,330.66

2-2991.8
2243.38

Labour charges

To check rear electrical wiring	50.00	30
To remove, refix rear interior trims to assist repair	120.00	80
To remove, refix rear exhaust	100.00	60
To respray undercoating	60.00	50
To respray painting and etc	900.00	880
Panel beating, cut, weld remove & replacing above parts	1,080.00	1050
Total Labour	2,310.00	

4393.38
3514.

ESTIMATE PARTS AND LABOUR GRAND TOTAL \$

6,640.66

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CS/SMO19002639/UTD3N2

Date: 28/02/2019

REFERENCE

Handling Insurer:	Sompo Insurance Singapore Pte. Ltd.	Policy No:	D18MTPV01018425
Claimant Vehicle No :	SV31U	Insured Vehicle No :	SLU2711R
Date of Loss:	04/02/2019	Nature of Claim:	TP
		Claim No:	CMTD1900746

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SV31U	Engine No:	8ARZ085540
Make & Model:	TOYOTA HARRIER, 2.0 G GRADE (A)	Chassis No:	JTEKB3GHX0J000173
Reg. Date:	02/08/2017 (Man. Year: 2017)	Odometer:	13066 km
Colour:	White		
Engine Capacity:	1998 cc		
Market Value/New Car Price:	N/A		
Sum Insured (\$\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	235/55R18	Rear Tyre Size:	235/55R18
Front Left Side:	Bridgestone 7 mm	Rear Left Side:	Bridgestone 7 mm
Front Right Side:	Bridgestone 7 mm	Rear Right Side:	Bridgestone 7 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS

	Repairer's	Adjuster's	Difference	Diff %
Parts	4,330.66	2,243.38	2,087.28	48.20
Miscellaneous Items	0.00	0.00	0.00	
Labour	2,310.00	2,150.00	160.00	6.93
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (\$\$)	6,640.66	4,393.38	2,247.28	33.84
Approved Total (Overridden) (\$\$)		3,500.00		
Nett Amount (\$\$)	6,640.66	3,500.00	3,140.66	47.29

INSPECTION

Date of Assignment:	13/02/2019	
Date Inspected:	13/02/2019	Inspected At:
		Centre Line Car Spray Painting (HQ) 2 KAKI BUKIT AVNEUE 2, #02-23 KAKI BUKIT AUTOHUB Singapore 417921
Estimated Period of Repair:	5.0 days	

Adjuster: MARCUS CHUA

Manager: DENISE TAY KWEE CHENG

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference

Part Source:	MRM-SG	Version: 1.0 (Last Synchronised: 28 Feb 2019)
Parts:	M1-SUV	TOYOTA HARRIER 2.0 G GRADE (A) (Catalogue:Merimen Singapore 1.0)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for SV31U)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*REAR BUMPER	Distorted	991.10 FL	*991.10 FL
2	1		*REAR BUMPER REFLECTOR-RH	Cracked	110.62 FL	*110.62 FL
3	1		*REAR BUMPER DIFUSSER	Distorted	453.20 FL	*453.20 FL
4	1		*REAR BUMPER PDC SENSOR-RH	Shorted	414.75 FL	*414.75 FL
5	1		*REAR BUMPER SPONGE	Not Necessary	155.91 FL	*- FL
6	1		*REAR BUMPER CARRIER	Repair	733.50 FL	*- FL
7	1		*REAR BUMPER SIDE BRACKET-RH	Cracked	89.95 FL	*89.95 FL
8	1		*REAR BUMPER SIDE RETAINERS-L/R	O/s Bent	110.25 FL	*55.13 FL
9	10		*REAR BUMPER CLIPS	Necessary	45.00 FL	*45.00 FL
10	1		*REAR END PANEL	Badly Dented	727.20 FL	*727.20 FL
11	1		*REAR EXHAUST SILENCER	Repair	822.60 FL	*- FL
12	1		*REAR FENDER-RH	Repair	1,015.90 FL	*- FL
13	1		*REAR FENDER INNER SHIELD-RH	Deformed	104.23 FL	*104.23 FL

F=Franchise part. L=ListItemDisc.

Sub Total (\$\$)	5,774.21	2,991.18
- List Item Discount on L Items 25.00/25.00% (\$\$)	1,443.55	747.80
Total Parts (\$\$)	4,330.66	2,243.38

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	TO CHECK REAR ELECTRICAL WIRING	New	50.00	30.00
2	TO REMOVE,REFIX REAR INTERIOR TRIMS TO ASSIST REPAIR	New	120.00	80.00
3	TO REMOVE,REFIX REAR EXHAUST	New	100.00	60.00
4	TO RESPRAY UNDERCOATING	New	60.00	50.00
5	TO RESPRAY PAINTING AND ETC	New	900.00	880.00
6	PANEL BEATING,CUT,WELD REMOVE & REPLACING ABOVE PARTS	New	1,080.00	1,050.00
Gross Labour Cost (\$\$)			2,310.00	2,150.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >