

ASS. REC. BY

REP CS/FCI/19002647/Dads

n2
Special Instruction

Sub Vehicle
CWS

Snyen
Sitham

ASSIGNMENT (Office)

From (Person)

FCI

Date/Time: 9.49am @ 13/2/19

Estimated Cost

Bill to:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No.

SHB 4346X

Insured:

SHB 36332

at Workshop n/s

chunni Motor

Tel:

65425119

of

Amk Auto point #01-05/06

Policy No.

Claim No:

D19000969MFSH

Sum Insured

Excess:

Make of Veh:
(Client's Record)

D.O.A

10/02/2019

CA / REV / REP. / REV 24 HRS ^{lup}

H.O.D. Endorsement:

Date/Time: 10.17am @ 13/2/19

Person Contacted:

Lynn

Vehicle IN / OUT


Date/Time	Action/Instruction (✓) Estimate
	SHB 4346 X - CS/FCI/18024869 / 11rd/3rd Don: 8/3/18
	SHB 36332 - CS/FCI/17001567 / Rlg/3rd Don: 15/1/17
15/07/19 @	llayan revised to sitham by email.

10B Jan 2023

AGENCY

From: _____ Date: _____
 Estimated Cost: _____
 ON / TP / AWS / TP RES / OD RES / VA / BV / MY
 Make of Vehicle: _____
 Model: _____
 Year: _____
 Insured: _____
 Policy No: _____
 Class: _____
 Sum Insured: _____ Excess: _____
 (Client's Record)
 Make of Veh: _____

(Policy Condition)
 Remark: The veh had commenced its repair at the time of inspection.



Est. or Market Value: _____
 IDAC Accident Report: _____ Consistent?: Yes or No
 GIA / PR Seen: _____ Consistent?: Yes or No
 Est. Repair: 10 days Res.: Yes or No
 Turn Sum: 20 % 3 Val.: Yes or No
 CA / REV / REP. / 24 HRS

Vehicle: IN / OUT

Date: _____ Person Contacted: _____

Date / Time: _____ Action / Instruction: _____

First Capital SHB 3833Z

19/03/19 Jinnu +/s 13000/- with 10 days of repair
 (Check of 741.36 + 35%)

RECEIVED 20 MAR 2019

Vehicle: SHB 4346 X Year: 2015 Jan
 Type: Car / M/Cycle / Bus / Van / Lorry / Prime Mover / Truck / Trailer or
 Make: Hyundai I40 CC: 1685
 Colour: Blue A/C: Insured / Std / Nil / NA
 Sp Reading: 506226 B/E: Insured / Std / Nil / NA
 Engine: D4DFU595972
 Chassis: KMHLB41UMFU065729
 Gen. Cond: Good / Fair / Poor / Burnt
 Steering: In order / Jammed / Leaked / Burnt or
 Brake: In order / Jammed / Leaked / Burnt or
 Mod: Nil / S/Rim / STD A/Rim or
 Tyre Size: F: 205/60R16
 R: - 11 -
 BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /
 TOYO / YOKO or Westlake
 Front: _____ Rear: _____
 R/Bal: S mm R/Bal: S mm
 L/Bal: S mm L/Bal: S mm
 D.O.A: 10/02/2019 D.O.I: 13/02/2019
 Survey held at Churni AMC
 Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or
 0/3 Rew
 The U/C / Chassis frame / Body Structure affected due to collision.

Date/Time: File Pass by: : Prel. Report
 : Final Report
 Date/Time: File Return to?

Days Of Repair: 10

Resurvey No. of Trip: 2

Survey Fee: _____
Transportation: _____

10x15 = 150

170 + 150
50
50 + 50
142
612

Add Fee: Site Insp. (₹)
 Interview (₹)
 Team Inv. (₹)
 Weekend (₹)

Report Format: 7P

Lump Sum / I.B. / 13000

580
OSP
20/3/19



Auto
Consultants
Pte Ltd

51 UBI AVE 1, #01-25 PAYA UBI INDUSTRIAL PARK, SINGAPORE 408933 TEL : (065) 62563561 FAX : (065) 62564315

Your Ref: D19000969MFSH
Our Ref: CS/FCI19002647/Dqd3

Date: 15 February 2019

The Motor Claims Department
First Capital Insurance Ltd

Dear Sir/Madam,


INITIAL INSPECTION REPORT OF VEHICLE NO. SHB 4346X.

Please be informed that we had conducted the inspection of the abovementioned vehicle on 13/02/2019 at the premises of M/s CHUNNI MOTOR. and have the following to report:-

Workshop Estimate Amount	: <u>S\$ 20,141.36</u> .
Revised Estimate Amount	: <u>S\$ 16,444.88</u> .
"Check" Items Amount	: <u>S\$ -</u> .
Market Value	: <u>S\$ -</u> .
LTA Reimbursement Value	: <u>S\$ -</u> .
Nett Value	: <u>S\$ -</u> .

Description of Damage:

The vehicle sustained damages at the o/s rear portion.



Yours faithfully

Bryan Ang Tani
Motor Surveyor / Investigator

MOTOR SURVEY ASSIGNMENT

Date 11-02-2019 Our Ref No. D19000969MFSH

Accident Date 10-02-2019 Claim Type. Third Party

Insured Vehicle SHB3633Z Third Party Vehicle. SHB4346X

Survey Location AMK AUTOPOINT, SOON HOCK MOTOR, #01-05/06

Contact Person. LYNN OR IRENE - 65421726

Contact No. 65427162/ 65425119 Fax No. 65426039

Survey Type WITHOUT PREJUDICE:

Appointed Surveyor LKK AUTO CONSULTANTS PTE LTD

Contact Person NA Fax No. 68416315

Contact Number. NA

FOR DIRECT SETTLEMENT

Please submit to us the Tax Invoice together with letter of claim for Rental OR Loss of use (based on NIMA Benchmark rates) together with your survey report.

THIRD PARTY SURVEY REQUEST

Cc : Workshop CHUNNI MOTOR WORK PTE LTD Attention. NIL

Cc : TP Solicitor NA TP Solicitor Fax No. NA

Officer Incharge SITHARA

IMPORTANT NOTE

Kindly submit the survey report via CWS within 14 days for survey assignment and 7 days for re-inspection.
This is a computer generated letter, no signature required.

Shiau Chan (LKKAuto)

From: Shiau Chan (LKKAuto)
Sent: Friday, 15 February 2019 11:25 AM
To: 'CWS Motor Claims'; assignments
Cc: 'Sithara'; SUR
Subject: RE: SURVEY ASSESSMENT - D19000969MFSH/1
Attachments: CSFCI19002647Dqd3.pdf

Dear Sithara,

Enclosed herewith preliminary advice of SHB 4346X.

Best Regards,

Shiau Chan (Ms) | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email: siewsc@lkkauto.com | fax: 6256-4315
Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Admin-D (LKKAuto)
Sent: Wednesday, 13 February 2019 10:46 AM
To: 'CWS Motor Claims' <cwsmotorclaims@msfirstcapital.com.sg>; assignments <assignments@lkkauto.com>
Cc: 'Sithara' <Sithara@msfirstcapital.com.sg>; SUR <sur@lkkauto.com>
Subject: RE: SURVEY ASSESSMENT - D19000969MFSH/1

Dear Sir/Mdm,

Thank you for the assignment.



BEST REGARDS,

G.Nivitha | Admin

LKK Auto Consultants Pte Ltd

Phone: 6841-1972 | email: assignments@lkkauto.com | fax: 6256-4315
Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)



From: CWS Motor Claims [<mailto:cwsmotorclaims@msfirstcapital.com.sg>]
Sent: Wednesday, 13 February 2019 9:49 AM
To: ASSIGNMENTS@LKKAUTO.COM

REPAIR ESTIMATE*

VEHICLE NO : SHB 4346X

DATE : 11.02.2019

MAKE :

TEL : 6542 5119

MODEL : HYUNDAI i40

FAX : 6542 6039

PCI

Qty	Parts Description/ Labour	Type	Unit Price	Amount	
	Rear Bumper distorted mainly crack			\$ 553.00	✓
	Rear Bumper Clip 10 pcs Nec			\$ 22.00	✓
	Rear Fender With Housing (RH) Distorted			\$ 4,736.80	✓
	Rear Fender Inner Lining (RH) Nec			\$ 169.30	X
	Rear Windscreen Moulding Nec			\$ 28.30	✓
	Rear Door (RH) Distorted			\$ 2,201.10	✓
	Front Door (RH) Distorted			\$ 2,256.40	✓
	Door Centre Pillar Outer (RH) Distorted			\$ 2,527.80	✓
	Rear Tyre Rim (RH) & distorted			\$ 325.30	✓
	Rear Wheel Hup-Cap (RH) B+			\$ 107.10	✓
	Rear Wheelbearing ING & Hub & Drum			\$ 362.00	✓
	Rear Trailing Arm (RH) & distorted			\$ 192.00	✓
	Rear Assist (RH) & distorted			\$ 145.70	✓
	Rear Shock Absorber (RH) & distorted			\$ 276.30	✓
	Rear Shock Absorber Mounting (RH) Nec			\$ 81.30	X
	Rear Crossmember & distorted			\$ 1,021.50	✓
	Stabilizer Bar & distorted			\$ 199.60	✓
	Stabilizer Link & distorted			\$ 85.90	✓
	Rear Upper Arm (RH) & distorted			\$ 335.75	✓
	Rear Lower Arm (RH) & distorted			\$ 353.80	✓
	Rear Knuckle Arm (RH) & distorted			\$ 545.60	✓
			16275.95		
			13020.76		
				\$ 16,526.55	
				\$ 3,305.31	
				\$ 13,221.24	
	Rear Bumper Advertisement Logo Nec			\$ 50.00	Nett ✓
	Rear Bumper Rubber Mat Nec			\$ 50.00	Nett ✓
	Rear Fender Advertisement Logo (LH/RH) Nec		\$ 100.00	\$ 200.00	Nett ✓
	Rear Windscreen Sealant Nec			\$ 46.00	Nett ✓
	Rear Door Advertisement Logo (RH) Nec			\$ 100.00	Nett ✓
	Rear Door Comfortdelgro & Apps Sticker (RH) Nec			\$ 80.00	Nett ✓
	Front Door Coloured Comfort Logo (RH) Nec			\$ 75.00	Nett ✓
	Front Door Advertisement Logo (RH) Nec		701.00	\$ 100.00	Nett ✓
	Rear Tyre (RH) s/c			\$ 216.00	Nett X
				\$ 917.00	

SHB 4346X

Qty	Parts Description/ Labour	Type	Unit Price	Amount
	Labour Charge			
	Panel Beating			\$ 2,000.00 800/-
	Spray Painting Charge			\$ 1,500.00 900/-
	Wiring Charge			\$ 50.00 30/-
	Tuff Kote			\$ 100.00 40/-
	Towing Charge			\$ 50.00 44
	Remove/Refix Cushion & Upholstery Rear			\$ 150.00 80/-
	Remove/Refix Rear Windscreen Glass			\$ 120.00 80/-
	Remove/Refix Reverse Sensor			\$ 120.00 40/-
	Transfer of Door	\$	120.00	\$ 240.00 120/-
	Remove/Refix Undercarriage (RR)			\$ 200.00 150/-
	Rear Wheel Alignment			\$ 120.00 60/-
	Re-set Rear ABS System			\$ 200.00
	Re-set Frt & Rear Power Window System	\$	200.00	\$ 400.00 } 180/-
	Diagnostic & Resetting To Erase Fault Code			\$ 480.00
			2450.00	
	TOTAL LABOUR			\$ 5,730.00
	ESTIMATE TOTAL			\$ 19,868.24
	13/02/2019 @ 1330hrs L/KK Auto L/Sure 10 days. nyan LKK Auto	supp	16171.76 273.12 16444.88 L/S 13000/-	

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer:
Signature:
Date:

20141.36

This is an initial estimate based on a visual inspection of the above vehicle. The final repair quantum will be prepared after the vehicle is surveyed by a motor Surveyor appointed by the insurance company.

CHUNNI MOTOR WORK PTE LTD

REPAIR ESTIMATE*

VEHICLE NO : SHB 4346X (Supplementary)

DATE : 13.02.2019

MAKE :

TEL : 6542 5119

MODEL : HYUNDAI i40

FAX : 6542 6039

Qty	Parts Description/ Labour	Type	Unit Price	Amount
	Rocker Panel Outer Garnish, RH <i>namoty broken</i>			\$ 341.40 ✓
	SUB TOTAL			\$ 341.40
	LESS 20%			\$ 68.28
	DISCOUNTED TOTAL			\$ 273.12
<p>13/02/2019</p> <p><i>(Signature)</i></p> <p>2 KK Auto</p> <p><i>(Signature)</i></p>				

This is an initial estimate based on a visual inspection of the above vehicle. The final repair quantum will be prepared after the vehicle is surveyed by a motor Surveyor appointed by the insurance company.

NAME
ADDRESS

Home Tel.:

VIN:

Registration: SHB 4346 X

Technician:

Mileage: 506226

Time Printed 13.2.19 2:25 PM

HYUNDAI I40

Front : Left

Actual	BEFORE	Specified Range
-0°40'		-3°00' 3°00'
3°45'		-0°19' 5°41'
0°49'		-1°30' 1°30'
25°28'		
24°48'		

Camber
Caster
Toe
SAI
Included Angle
Turning Angle Diff.

Front : Right

Actual	BEFORE	Specified Range
-0°24'		-3°00' 3°00'
4°07'		-0°19' 5°41'
-0°49'		-1°30' 1°30'
8°15'		
7°51'		

Front

Cross Camber
Cross Caster
Cross SAI
Total Toe
Cross Turn Diff.

Actual	BEFORE	Specified Range
-0°17'		-3°00' 3°00'
-0°22'		-3°00' 3°00'
17°13'		-3°00' 3°00'
0°00'		-3°00' 3°00'

Rear : Left

Actual	BEFORE	Specified Range
-0°08'		-3°30' 2°30'
0°19'		-1°30' 1°30'

Camber
Toe

Rear : Right

Actual	BEFORE	Specified Range
3°57'		-3°30' 2°30'
2°22'		-1°30' 1°30'

Rear

Cross Camber
Total Toe
Thrust Angle

Actual	BEFORE	Specified Range
-4°05'		-3°00' 3°00'
2°42'		-3°00' 3°00'
-1°01'		-3°00' 3°00'



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile			
MS FIRST CAPITAL INSURANCE LTD		Ref : CS/FCI19002647/Dqd3n2	
36 ROBINSON ROAD #16-01 CITY HOUSESINGAPORE 068877		Date : 20-03-2019	
		Code : FCI2	
1. Policy Particulars :- THIRD PARTY CLAIM			
	Insured Veh.	SHB 3633Z	Veh. Inspected
	Policy No.		SHB 4346X
	Claim No.	D19000969MFSH	Coverage (\$)
	Assign From	SITHARA	0.00
			Excess (\$)
			0.00
			Assign Date
			13/02/2019
2. Vehicle Particulars & Condition			
	Make & Model	HYUNDAI I40	c.c
	Engine No.	HIDDEN	1685
	Chassis No.	KMHLB41UMFU065729	Year of Reg.
	Odometer	506226	2015
	Brakes	IN ORDER	Colour
	General	GOOD	BLUE
			Steering
			IN ORDER
			Modification
			NIL
3. Conditions of Tyres			
		Size	Make
	R/H Front Tyre	205/60 R16	Balance
	L/H Front Tyre	205/60 R16	WEST LAKE
	R/H Rear Tyre	205/60 R16	5 mm
	L/H Rear Tyre	205/60 R16	WEST LAKE
			5 mm
4. Description of Damages			
THE VEHICLE SUSTAINED DAMAGES AT THE O/S REAR PORTION.			
DAMAGES SEE DETAILS.			
5. General Information			
	Accident Date	10/02/2019	Inspection Date
	Survey held at	CHUNNI MOTOR WORK PTE LTD	
		BLK 10 ANG MO KIO IND. PARK 2A,	
		#03-19 AMK AUTOPOINT	
		SINGAPORE 568047.	
5a. Remarks			
A)DAMAGES CONSISTENT TO ACCIDENT REPORT.			
B)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS.			
C)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.			
5b. Estimate Days of Repair			
ESTIMATED NORMAL PERIOD FOR REPAIR:		10 Working Days	



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 2

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SHB 4346X

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
REPLACEMENT OF PARTS				
1	REAR BUMPER	DISTORTED / MOUNTING CRACKED	553.00	553.00
10	REAR BUMPER CLIP	NECESSARY	22.00	22.00
1	REAR FENDER WITH HOUSING (RH)	DENTED	4,736.80	4,736.80
1	REAR FENDER INNER LINING (RH)	NOT NECESSARY	169.30	-
1	REAR WINDSCREEN MOULDING	NECESSARY	28.30	28.30
1	REAR DOOR (RH)	DENTED	2,201.10	2,201.10
1	FRONT DOOR (RH)	DENTED	2,256.40	2,256.40
1	DOOR CENTRE PILLAR OUTER (RH)	DENTED	2,527.80	2,527.80
1	REAR TYRE RIM (RH)	DISTORTED	325.30	325.30
1	REAR WHEEL HUP-CAP (RH)	BENT	107.10	107.10
1	REAR WHEELBEARING ING & HUB	DAMAGED	362.00	362.00
1	REAR TRAILING ARM (RH)	DISTORTED	192.00	192.00
1	REAR ASSIST (RH)	DISTORTED	145.70	145.70
1	REAR SHOCK ABSORBER (RH)	DISTORTED	276.30	276.30
1	REAR SHOCK ABSORBER MOUNTING (RH)	NOT NECESSARY	81.30	-
1	REAR CROSSMEMBER	DISTORTED	1,021.50	1,021.50
1	STABILIZER BAR	DISTORTED	199.60	199.60
1	STABILIZER LINK	DISTORTED	85.90	85.90
1	REAR UPPER ARM (RH)	DISTORTED	335.75	335.75
1	REAR LOWER ARM (RH)	DISTORTED	353.80	353.80
1	REAR KNUCKLE ARM (RH)	DISTORTED	545.60	545.60
1	ROCKER PANEL OUTER GARNISH,RH (ADDITIONAL)	MOUNTING BROKEN	341.40	341.40
	LESS 20% DISCOUNT		-3,373.59	-3,323.47
			13,494.36	13,293.88
SPECIAL NETT ITEMS				
1	REAR BUMPER ADVERTISEMENT LOGO (SN)	NECESSARY	50.00	50.00
1	REAR BUMPER RUBBER MAT (SN)	NECESSARY	50.00	50.00
2	REAR FENDER ADVERTISEMENT LOGO (LH/RH) @\$100.00 (SN)	NECESSARY	200.00	200.00

Report Ref No. CS/FCI19002647/Dqd3n2



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:2 of 2

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
1	REAR WINDSCREEN SEALANT (SN)	NECESSARY	46.00	46.00
1	REAR DOOR ADVERTISEMENT LOGO (RH)(SN)	NECESSARY	100.00	100.00
1	REAR DOOR COMFORTDELGRO & APPS STICKER (RH) (SN)	NECESSARY	80.00	80.00
1	FRONT DOOR COLOURED COMFORT LOGO (RH)(SN)	NECESSARY	75.00	75.00
1	FRONT DOOR ADVERTISEMENT LOGO (RH)(SN)	NECESSARY	100.00	100.00
1	REAR TYRE (RH)(SN)	SERVICEABLE	216.00	-
			917.00	701.00
	LABOUR			
	PANEL BEATING.		2,000.00	800.00
	SPRAY PAINTING CHARGE.		1,500.00	900.00
	WIRING CHARGE.	NOT NECESSARY	50.00	-
	TUFF KOTE.		100.00	40.00
	TOWING CHARGE.	NOT NECESSARY	50.00	-
	REMOVE/REFIX CUSHION & UPHOLSTERY REAR.		150.00	80.00
	REMOVE/REFIX REAR WINDSCREEN GLASS.		120.00	80.00
	REMOVE/REFIX REVERSE SENSOR.		120.00	40.00
	TRANSFER OF DOOR.		240.00	120.00
	REMOVE/REFIX UNDERCARRIAGE (RR).		200.00	150.00
	REAR WHEEL ALIGNMENT.		120.00	60.00
	DIAGNOSTIC & RESETTING TO ERASE FAULT CODE. }		480.00	180.00
	RE-SET REAR ABS SYSTEM. }		200.00	-
	RE-SET FRT & REAR POWER WINDOW SYSTEM. }		400.00	-
			5,730.00	2,450.00
	GRAND TOTAL		20,141.36	16,444.88
	RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION)			13,000.00

Report Ref No. CS/FC19002647/Dqd3n2

ANG BRYAN TANI

Automotive Assessor / Investigator

ADRIAN LING WAI PING

B.Eng,AMSOE,AMIRTE,AMSAE-A,M.MATAI

Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.