

2/20/2002

ASS. REC. BY:

REF:

es/FCI19002657/Aqd3n2

Special Instruction:

Surveyor:

Adrian

ASSIGNMENT (Office)

CWS

From (Person):

May chua

of

FCI

Date/Time:

5:56pm @ 12/2/19

Estimated Cost:

Bill to:

OD ☒ TP WS / TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No:

SMC5682D

Insured:

SH62004

at Workshop m/s

Hua Meng

Tel:

67465519

of

11caki Bkt Ave 6 # 01-61/34

Policy No:

Claim No:

D19000933MFSH

Sum Insured:

Excess:

Make of Vch:

D.O.A.

4/2/19

(Client's Record)

CA / REV / REP. / REV 24 HRS

up

H.O.D. Endorsement:

Date/Time:

12:51pm @ 13/2/19

Person Contacted:

june

Vehicle ☒ IN / OUT

Date/Time

Action/Instruction (✓) Estimate

SMC5682D - NA/AIG19002244/R3

D.O.A: 4/2/19

SH62004 - NA/AIG19002214/13

D.O.A: 4/2/19

14/2/19 @ 4:23pm Informed May chua, we are pending estimate from repairer.

19/4/19 @ 2:24pm revised to May chua by email.

L9 \$13000, 13 days (Red \$13482.92, 51%).

ASS. REC. BY:

REF:

Adrian

ASSIGNMENT

From: _____ Date: _____

Estimated Cost: _____

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No: _____

at Workshop m/s _____

of _____

Insured: _____

Policy No. _____

Claims No. _____

Sum Insured: _____ Excess: _____

(Client's Record)

Make of Veh: _____

(Policy Condition)

Remark: The veh had commenced its
repair at the time of inspection.

N/S	O/S

Bal. or Market Value: _____

IDAC Accident Rpt: _____ Consistent? : Yes or No

GIA / PR Seen: _____ Consistent? : Yes or No

Est. Repairs: 13 days Res.: Yes or No

Lum Sum: _____ % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Vehicle: IN / OUT

Date: _____ Person Contacted: _____

Veh No: SMC5682D Yr Regn: 2018, JulyType: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make: Kia Cerato K3 c.c. 1591Colour: White A/C: Insured / Std / Nil / NASp. Reading: 6470 T/Radio: Insured / Std / Nil / NA

Eng/No: _____

C/No: KNAFJ411MJS767918Gen. Cond: Good / Fair / Poor / BurntSteering: Inorder / Jammed / Leaked / Burnt orBrake: Inorder / Jammed / Leaked / Burnt orModi: Nil / SRim / STD A/Rim orTyre Size: F: 205/55R16R: 205/55R16BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /
TOYO / YOKO or

Front

Rear

R/Bal. 06 mm R/Bal. 06 mmL/Bal. 06 mm L/Bal. 06 mmD.O.A. 13/02/19 D.O.I. 13/02/19Survey held at Hue MaryDes. of Damages: Fit / Rear / O/S / N/S / UIC / Rooftop or

The UIC / Chassis frame / Body Structure affected due to collision.

Date / Time Action / Instruction

TP 1st Lp

MV:

PV:

Nett:

RECEIVED 29 APR 2019

Date/Time, File Pass to?

Date/Time, File Return to?

1) 29/4 17:15

2)

3)

4)

5)

6)

Prel. Report:

Final Report:

Part Prices Check:

IN

OUT

Survey Fee:

Date: 17/15/25

Basic & Add.

S + RS, SI

Photos

Others

TOTAL

170 + 255050184709580



Auto.
Consultants
Pte Ltd

51 UBI AVE 1, #01-25 PAYA UBI INDUSTRIAL PARK, SINGAPORE 408933 TEL : (065) 62563561 FAX : (065) 62564315

Your Ref: D19000933MFSH

Date: 29 April 2019

Our Ref: CS/FCI19002657/Aqd3

The Motor Claims Department
MS First Capital Insurance Ltd

Dear Sir/Madam,


INITIAL INSPECTION REPORT OF VEHICLE NO. SMC 5682D .

Please be informed that we had conducted the inspection of the abovementioned vehicle on 04/02/2019 at the premises of M/s HUA MENG. and have the following to report:-

Workshop Estimate Amount	: S\$ 26,482.92 .
Revised Estimate Amount	: S\$ 13,000.00 (Lump Sum) .
"Check" Items Amount	: S\$ - .
Market Value	: S\$ - .
LTA Reimbursement Value	: S\$ - .
Nett Value	: S\$ - .

Description of Damage:

The vehicle sustained damages at the front & rear portion.



Yours faithfully

ADRIAN LING WAI PING
B.Eng, AMSOE, AMIRTE, AMSAE-A, M.MATAI
Licensed Appraiser

MOTOR SURVEY ASSIGNMENT

Date	09-02-2019	Our Ref No. D19000933MFSH
Accident Date	04-02-2019	Claim Type. Third Party
Insured Vehicle	SH6200H	Third Party Vehicle. SMC5682D
Survey Location	AUTOBAY@KAKIBUKIT 1 KAKI BUKIT AVENUE 6BLK C #01-61/01-34	
Contact Person.	JUNE	
Contact No.	67478064/ 0	Fax No. 67434896
Survey Type	WITHOUT PREJUDICE: WE ADMIT LIABILITY QUANTUM TO BE AGREED:	
Appointed Surveyor	LKK AUTO CONSULTANTS PTE LTD	
Contact Person	NA	Fax No. 68416315
Contact Number.	NA	

FOR DIRECT SETTLEMENT

Please submit to us the Tax Invoice together with letter of claim for Rental OR Loss of use (based on NIMA Benchmark rates) together with your survey report.

THIRD PARTY SURVEY REQUEST

Cc : Workshop	HUA MENG SPRAY PAINTING WORKSHOP	Attention. NIL
Cc : TP Solicitor	NA	TP Solicitor Fax No. NA
Officer Incharge	MAY CHUA	

IMPORTANT NOTE

Kindly submit the survey report via CWS within 14 days for survey assignment and 7 days for re-inspection.
This is a computer generated letter, no signature required.

Shiau Chan (LKKAUTO)

From: Shiau Chan (LKKAUTO)
Sent: Monday, 29 April 2019 2:24 PM
To: 'CWS Motor Claims'; assignments
Cc: 'May Chua Hui Chin'; SUR
Subject: RE: SURVEY ASSESSMENT - D19000933MFSH/1
Attachments: CSFCI19002657Aqd3.pdf

Dear May,

Enclosed herewith preliminary advice of SMC 5682D.

Best Regards,

Shiau Chan (Ms) | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email: siewsc@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Shiau Chan (LKKAUTO)
Sent: Thursday, 14 February 2019 4:23 PM
To: 'CWS Motor Claims' <cwsmotorclaims@msfirstcapital.com.sg>; assignments <assignments@lkkauto.com>
Cc: 'May Chua Hui Chin' <maychua@msfirstcapital.com.sg>; SUR <sur@lkkauto.com>
Subject: RE: SURVEY ASSESSMENT - D19000933MFSH/1

Dear May,

Please be informed that we have inspected the vehicle SMC 5682D on 13/02/2019.

We are pending for estimate from repairer.

Best Regards,

Shiau Chan (Ms) | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email: siewsc@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Admin-D (LKKAUTO)
Sent: Wednesday, 13 February 2019 12:54 PM
To: 'CWS Motor Claims' <cwsmotorclaims@msfirstcapital.com.sg>; assignments <assignments@lkkauto.com>
Cc: 'May Chua Hui Chin' <maychua@msfirstcapital.com.sg>; SUR <sur@lkkauto.com>
Subject: RE: SURVEY ASSESSMENT - D19000933MFSH/1

Dear Sir/Mdm,

Thank you for the assignment.



BEST REGARDS,

Shiau Chan (LKKAuto)

From: Shiau Chan (LKKAuto)
Sent: Thursday, 14 February 2019 4:23 PM
To: 'CWS Motor Claims'; assignments
Cc: 'May Chua Hui Chin'; SUR
Subject: RE: SURVEY ASSESSMENT - D19000933MFSH/1

Dear May,

Please be informed that we have inspected the vehicle SMC 5682D on 13/02/2019.

We are pending for estimate from repairer.

Best Regards,

Shiau Chan (Ms) | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email: siewsc@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Admin-D (LKKAuto)
Sent: Wednesday, 13 February 2019 12:54 PM
To: 'CWS Motor Claims' <cwsmotorclaims@msfirstcapital.com.sg>; assignments <assignments@lkkauto.com>
Cc: 'May Chua Hui Chin' <maychua@msfirstcapital.com.sg>; SUR <sur@lkkauto.com>
Subject: RE: SURVEY ASSESSMENT - D19000933MFSH/1

Dear Sir/Mdm,

Thank you for the assignment.



BEST REGARDS,

G.Nivitha | Admin

LKK Auto Consultants Pte Ltd

Phone: 6841-1972 | email: assignments@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)



From: CWS Motor Claims [<mailto:cwsmotorclaims@msfirstcapital.com.sg>]
Sent: Tuesday, 12 February 2019 5:56 PM
To: ASSIGNMENTS@LKKAUTO.COM

HUA MENG SPRAY PAINTING WORKSHOP

1, Kaki Bukit Avenue 6, Blk C #01-61 / 01-34, Singapore 417883

Autobay @ Kaki Bukit

Tel: 6747 8064, 6746 5519 / 9666 9680 Fax: 6743 4896

ESTIMATE

KNAFJ411MJS 767918

TAN WEI LIN

BLK 119C RIVERVALE DRIVE

#12-79344

S 543119

TP 1st Cap.
Xiao Chan.

Date

:01.03.2019

Vehicle no

:SMC 5682 D

Make/Model

:KIA CERATO

Accident date

:04.02.2019

No	DESCRIPTION	Qty	Amount (\$)
<u>List Items</u>			
1	Rear boot lid <i>Dented</i>	1	\$ 949.3 ✓
2	Rear boot lid upper lock <i>Dented</i>	1	\$ 68.2 ✓
3	Rear boot lid lower lock <i>new</i>	1	\$ 134.2 +
4	Rear boot lid hinges @ \$74.80 <i>new</i>	2	\$ 149.6 +
5	Rear boot lid KIA emblem <i>new</i>	1	\$ 41.8 ✓
6	Rear boot lid CERATO emblem <i>new</i>	1	\$ 46.2 ✓
7	Rear boot lid K3 emblem <i>new</i>	1	\$ 30.8 ✓
8	Rear boot lid reflector @ \$710.00 <i>new</i>	2	\$ 1420 X
9	Rear insulation <i>new</i>	1	\$ 101.2 X
10	Rear boot lid weather strip <i>new</i>	1	\$ 132 ✓
11	Rear lamp @ \$866.80 <i>crushed</i>	2	\$ 1733.6 1360
12	Rear lamp housing @ \$182.60 <i>repair</i>	2	\$ 365.2 X
13	Rear end panel <i>Distorted</i>	1	\$ 357.5 ✓
14	Rear end panel inner top garnish <i>Dented</i>	1	\$ 61.4 ✓
15	Rear bumper <i>Dented</i>	1	\$ 734.8 ✓
16	Rear bumper lower lip <i>Dented</i>	1	\$ 383.9 ✓
17	Rear bumper reflector @ \$107.80 <i>crushed</i>	2	\$ 215.6 ✓
18	Rear bumper reinforcement <i>crushed</i>	1	\$ 390.5 313
19	Rear bumper bracket @ \$182.60 <i>Bent</i>	2	\$ 365.2 ✓
20	Rear bumper side holder @ \$36.30 <i>new</i>	2	\$ 72.6 ✓
21	Rear bumper clips (1set) <i>new</i>	1	\$ 85 30
22	Rear exhaust pipe <i>Bent</i>	1	\$ 825 ✓
23	Rear exhaust pipe mounting <i>new</i>	1	\$ 41.8 X
24	Rear centre exhaust pipe <i>new</i>	1	\$ 825 X
25	Rear spare tyre top board <i>torn</i>	1	\$ 385 ✓
26	Rear spare tyre well <i>Distorted</i>	1	\$ 662.2 ✓
27	Rear spare tyre well insulation @ \$294.80 <i>new</i>	3	\$ 884.4 200(SN)
28	Rear fender inner trim @ \$189.20 <i>Dented</i>	2	\$ 378.4 ✓
29	Rear number plate lamp @ \$52.80 <i>new</i>	2	\$ 105.6 X
30	Rear RH door <i>Repair</i>	1	\$ 1013.1 X
31	Rear RH door inner lock <i>new</i>	1	\$ 278.3 ✓
32	Rear fender inner shield @ \$165.00 <i>torn</i>	2	\$ 330 ✓ 165
33	Rear spare tyre screw <i>new</i>	1	\$ 35.2 ✓
34	Front bumper <i>Dented</i>	1	\$ 756.8 ✓
35	Front bumper side holder @ \$35.20 <i>new</i>	2	\$ 70.4 ✓
			13695

HUA MENG SPRAY PAINTING WORKSHOP

1, Kaki Bukit Avenue 6, Blk C #01-61 / 01-34, Singapore 417883

Autobay @ Kaki Bukit

Tel: 6747 8064, 6746 5519 / 9666 9680 Fax: 6743 4896

ESTIMATE

TAN WEI LIN

BLK 119C RIVERVALE DRIVE

#12-79344

S 543119

Date :01.03.2019

Vehicle no :SMC 5682 D

Make/Model :KIA CERATO

Accident date :04.02.2019

No	DESCRIPTION	Qty	Amount (\$S)
36	Front bumper lower centre grille <i>crushed</i>	1	\$ 71.5 ✓
37	Front bumper fog lamp cover @ \$104.50 <i>NE new</i>	2	\$ 209 X
38	Front bumper reinforcement <i>Bent</i>	1	\$ 545.6 495.
39	Front bumper bracket @ \$46.20 <i>NE new</i>	2	\$ 92.4 X
40	Front bumper clips (1set) <i>NE</i>	1	\$ 70 30.
41	Front KIA emblem <i>NE</i>	1	\$ 41.8 ✓
42	Front grille <i>cut</i>	1	\$ 360.8 ✓
43	Front number plate garnish <i>crushed</i>	1	\$ 46.2 ✓
44	Front bumper top rubber <i>NE new</i>	1	\$ 46.2 X
45	Front head lamp @ \$1675.30 <i>crushed</i>	2 <i>S.N. 200.</i>	\$ 3350.6 ✓
46	Front bonnet <i>NE</i>	1	\$ 1656 X
47	Front support panel <i>NE</i>	1	\$ 742.5 X
48	Front support panel top garnish <i>crushed</i>	1	\$ 90.2 ✓
49	Tools Tray. <i>crushed</i>	202 ✓	\$ 21017.8
50	Rear Bumper side underscores <i>to be</i>	68 ✓	
51	Rear Exhaust Heat Shield. <i>crushed</i>	115 ✓	
52	Front Bumper Sponge <i>crushed</i>	156 ✓	
			Less 10% Disc
			Total
			\$ 18916.02

Special Nett Items

1	Rear camera <i>NE new</i>	1	\$ 800 X
2	Rear bumper sensor (1set) <i>damaged</i>	1	\$ 380 200.
3	Front number plate <i>Bent</i>	1	\$ 50 30
4	Front number plate holder <i>Behind</i>	1	\$ 50 30
			Total
			\$ 1280

Labour Cost

1	To supply rear end panel inner sealant	\$ 200 60
2	Remove & reinstall air con fill in gas	\$ 150 X
3	Remove & reinstall reverse sensor	\$ 150 50
4	Remove & reinstall exhaust pipe	\$ 200 80
5	Remove & reinstall boot lid inner garnish	\$ 200 60
6	Remove, replace & repair consistent to the accident	\$ 2800 1900
7	Respray painting of the following:	\$ 1800 1300.
8	Tuff kote	\$ 150 60
9	Remove & reinstall petrol tank	\$ 150 80
		Total
		\$ 5800

Acknowledged by Repairer

Signature:

Date:

Grand Total

\$ 25996.02

total: 16320.06

4/5: 13K 13Days.

13K



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
MS FIRST CAPITAL INSURANCE LTD		Ref : CS/FCI19002657/Aqd3n2		
36 ROBINSON ROAD #16-01 CITY HOUSESINGAPORE 068877		Date : 07-05-2019		
		Code : FCI2		
1. Policy Particulars :- THIRD PARTY CLAIM				
Insured Veh.	SH 6200H	Veh. Inspected	SMC 5682D	
Policy No.		Coverage (\$)	0.00	
Claim No.	D19000933MFSH	Excess (\$)	0.00	
Assign From	MAY CHUA	Assign Date	12/02/2019	
2. Vehicle Particulars & Condition				
Make & Model	KIA CERATO K3	c.c	1591	
Engine No.	HIDDEN	Year of Reg.	2018	
Chassis No.	KNAFJ411MJ5767918	Colour	WHITE	
Odometer	6470	Steering	IN ORDER	
Brakes	IN ORDER	Modification	SPORTS RIM	
General	GOOD			
3. Conditions of Tyres				
	Size	Make	Balance	
R/H Front Tyre	205/55 R16	BRIDGESTONE	6 mm	
L/H Front Tyre	205/55 R16	BRIDGESTONE	6 mm	
R/H Rear Tyre	205/55 R16	BRIDGESTONE	6 mm	
L/H Rear Tyre	205/55 R16	BRIDGESTONE	6 mm	
4. Description of Damages				
THE VEHICLE SUSTAINED DAMAGES AT THE FRONT AND REAR PORTION. DAMAGES SEE DETAILS.				
5. General Information				
Accident Date	04/02/2019	Inspection Date	13/02/2019	
Survey held at	HUA MENG SPRAY PAINTING WKSP 1 KAKI BUKIT AVE 6 #01-61 AUTOBAY SINGAPORE 417883			
5a. Remarks				
A) DAMAGES CONSISTENT TO ACCIDENT REPORT. B) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS. C) IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.				
5b. Estimate Days of Repair				
ESTIMATED NORMAL PERIOD FOR REPAIR:		13 Working Days		



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 3

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SMC 5682D

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
REPLACEMENT OF PARTS				
1	REAR BOOT LID	DENTED	949.30	949.30
1	REAR BOOT LID UPPER LOCK	DAMAGED	68.20	68.20
1	REAR BOOT LID LOWER LOCK	NOT NECESSARY	134.20	-
2	REAR BOOT LID HINGES @\$74.80	NOT NECESSARY	149.60	-
1	REAR BOOT LID KIA EMBLEM	NECESSARY	41.80	41.80
1	REAR BOOT LID CERATO EMBLEM	NECESSARY	46.20	46.20
1	REAR BOOT LID K3 EMBLEM	NECESSARY	30.80	30.80
2	REAR BOOT LID REFLECTOR @\$710.00	NOT NECESSARY	1,420.00	-
1	REAR INSULATION	NOT NECESSARY	101.20	-
1	REAR BOOT LID WEATHER STRIP	CUT	132.00	132.00
2	REAR LAMP @\$866.80	CRACKED	1,733.60	1,360.00
2	REAR LAMP HOUSING @\$182.60	TO REPAIR SEE LABOUR	365.20	-
1	REAR END PANEL	DISTORTED	357.50	357.50
1	REAR END PANEL INNER TOP GARNISH	DEFORMED	61.40	61.40
1	REAR BUMPER	DEFORMED	734.80	734.80
1	REAR BUMPER LOWER LIP	DEFORMED	383.90	383.90
2	REAR BUMPER REFLECTOR @\$107.80	CRACKED	215.60	215.60
1	REAR BUMPER REINFORCEMENT	CRACKED	390.50	313.00
2	REAR BUMPER BRACKET @\$182.60	BENT	365.20	365.20
2	REAR BUMPER SIDE HOLDER @\$36.30	NECESSARY	72.60	72.60
1	SET REAR BUMPER CLIPS	NECESSARY	85.00	30.00
1	REAR EXHAUST PIPE	BENT	825.00	825.00
1	REAR EXHAUST PIPE MOUNTING	NOT NECESSARY	41.80	-
1	REAR CENTRE EXHAUST PIPE	NOT NECESSARY	825.00	-
1	REAR SPARE TYRE TOP BOARD	TORN	385.00	385.00
1	REAR SPARE TYRE WELL	DISTORTED	662.20	662.20
2	REAR FENDER INNER TRIM @\$189.20	DEFORMED	378.40	378.40
2	REAR NUMBER PLATE LAMP @\$52.80	NOT NECESSARY	105.60	-
1	REAR RH DOOR	TO REPAIR SEE LABOUR	1,013.10	-

Report Ref No. CS/FCI19002657/Aqd3n2



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.: 2 of 3

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
1	REAR RH DOOR INNER LOCK	NOT NECESSARY	278.30	-
2	REAR FENDER INNER SHIELD @\$165.00	TORN	330.00	330.00
1	REAR SPARE TYRE SCREW	DAMAGED	35.20	35.20
1	FRONT BUMPER	DEFORMED	756.80	756.80
2	FRONT BUMPER SIDE HOLDER @\$35.20	NECESSARY	70.40	70.40
1	FRONT BUMPER LOWER CENTRE GRILLE	CRACKED	71.50	71.50
2	FRONT BUMPER FOG LAMP COVER @\$104.50	NOT NECESSARY	209.00	-
1	FRONT BUMPER REINFORCEMENT	BENT	545.60	495.00
2	FRONT BUMPER BRACKET @\$46.20	NOT NECESSARY	92.40	-
1	SET FRONT BUMPER CLIPS	NECESSARY	70.00	30.00
1	FRONT KIA EMBLEM	NECESSARY	41.80	41.80
1	FRONT GRILLE	CUT	360.80	360.80
1	FRONT NUMBER PLATE GARNISH	CRACKED	46.20	46.20
1	FRONT BUMPER TOP RUBBER	NOT NECESSARY	46.20	-
2	FRONT HEAD LAMP @\$1675.30	CRACKED	3,350.60	3,350.60
1	FRONT BONNET	NOT NECESSARY	1,656.00	-
1	FRONT SUPPORT PANEL	NOT NECESSARY	742.50	-
1	FRONT SUPPORT PANEL TOP GARNISH	CRACKED	90.20	90.20
1	TOOLS TRAY	CRACKED	202.00	202.00
1	REAR BUMPER SIDE UNDERCOVER	TORN	68.00	68.00
1	REAR EXHAUST HEAT SHIELD	CRUMPLED	115.00	115.00
1	FRONT BUMPER SPONGE	CRACKED	156.00	156.00
	LESS 10% DISCOUNT		-2,140.92	-1,363.24
			19,268.28	12,269.16
3	REAR SPARE TYRE WELL INSULATION @\$294.80 (SN)	NECESSARY	884.40	200.00
	LESS 10% DISCOUNT		-88.44	-
			795.96	200.00
	SPECIAL NETT ITEMS			
1	REAR CAMERA (SN)	NOT NECESSARY	800.00	-
1	SET REAR BUMPER SENSOR (SN)	DAMAGED	380.00	200.00
1	FRONT BUMPER PLATE (SN)	BENT	50.00	30.00

Report Ref No. CS/FCI19002657/Aqd3n2



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:3 of 3

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
1	FRONT BUMPER PLATE HOLDER (SN)	DEFORMED	50.00	30.00
			1,280.00	260.00
	LABOUR			
	TO SUPPLY REAR END PANEL INNER SEALANT.		200.00	60.00
	REMOVE & REINSTALL AIR CON FILL IN GAS.	NOT NECESSARY	150.00	-
	REMOVE & REINSTALL REVERSE SENSOR.		150.00	50.00
	REMOVE & REINSTALL EXHAUST PIPE.		200.00	80.00
	REMOVE & REINSTALL BOOT LID INNER GARNISH.		200.00	60.00
	REMOVE, REPLACE & REPAIR CONSISTENT TO THE ACCIDENT. INCLUSIVE OF THE REPAIR OF REAR LAMP HOUSING AND REAR RH DOOR.		2,800.00	1,900.00
	RESPRAY PAINTING.		1,800.00	1,300.00
	TUFF KOTE.		150.00	60.00
	REMOVE & REINSTALL PETROL TANK.		150.00	80.00
			5,800.00	3,590.00
GRAND TOTAL			27,144.24	16,319.16
RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION)				13,000.00

Report Ref No. CS/FCI19002657/Aqd3n2

ADRIAN LING WAI PING

B.Eng,AMSOE,AMIRTE,AMSAE-A,M.MATAI

Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.