



Case Details

Case Reference Number : TAX/02/19/2032
 Type of Repair : Accident Repair
 Vehicle Registration Number : SHB823L

Company Type : SMRT Taxis Pte Ltd
 Estimation ID : EST-5631-ID
 Assigned By : Taxi Claims Manager Team

Insurance Company Name : MSIG Insurance (S) Pte Ltd
 Accident Date and Time : 05/02/2019 04:33 AM
 Vehicle Age(In Months) : 16

Documents / Photographs

[View Documents / Photographs](#)

Total Documents: 0

Estimation Details

Spare Part's Cost Detail

BOM Type	Costing Type	Portion	Material Number	SMRT Recommendation					Final Price(\$)	Repair/ Replace	Surveyor Approval			Remarks
				Part Name	Qty	List Price Per Unit(\$)	List Price(\$)	Dis(%)			Surveyor Quantity	Surveyor Final Price(\$)	Repair/Replace	
One Time Key In	Main			PANEL SUB-ASSY, FRONT DOOR RH	1	1,249.60	1,249.60	30.00	874.72	Replace	1	0.00	Replace ▾	BUC
One Time Key In	Main			STICKER DECAL SMRT (DOOR)	1	60.00	60.00	0.00	60.00	Replace	1	60.00	Replace ▾	NEC
One Time Key In	Main			MOULDING ASSY, BODY ROCKER PANEL, RH	1	576.00	576.00	30.00	403.20	Replace	1	0.00	Replace ▾	NEC
One Time Key In	Main			MIRROR ASSY, OUTER REAR VIEW, RH	1	1,373.50	1,373.50	10.00	1,236.15	Replace	0	0	Not Give ▾	
One Time Key In	Main			COVER, OUTER MIRROR, RH	1	89.50	89.50	30.00	62.65	Replace	1	0	Repair ▾	
One Time Key In	Main			MIRROR OUTER GLASS, RH	1	215.20	215.20	30.00	150.64	Replace	0	0	Not Give ▾	
One Time Key In	Main			LAMP ASSY, SIDE MIRROR TURN SIGNAL, RH	1	162.20	162.20	10.00	145.98	Replace	0	0	Not Give ▾	

Total Spare Part Cost 4,897.77

Surveyor Total 180.00

Lump Sum Discount (%) 0.00

Lump Sum Dis (%) 0

Final Spare Part Cost 4,897.77

Final Sur Total 180.00

SMRT Recommendation											Surveyor Approval			
BOM Type	Costing Type	Portion	Material Number	Part Name	Qty	List Price Per Unit(\$)	List Price(\$)	Dis(%)	Final Price(\$)	Repair/ Replace	Surveyor Quantity	Surveyor Final Price(\$)	Repair/Replace	Remarks
One Time Key In	Main			PANEL SUB-ASSY, REAR DOOR , RH	1	1,243.90	1,243.90	30.00	870.73	Replace	1	0.00	Replace ▾	BUC
One Time Key In	Main			PIXEL STICKER	2	60.00	120.00	0.00	120.00	Replace	2	120.00	Replace ▾	NEC
One Time Key In	Main			PANEL SUB-ASSY, FENDER REAR RH	1	824.80	824.80	30.00	577.36	Replace	1	0	Repair ▾	
One Time Key In	Main			COVER, RR BUMPER ASSY	1	423.90	423.90	30.00	296.73	Replace	0	0	Check ▾	
One Time Key In	Main			PAD, RR BUMPER, RH & LH , 1	1	3.80	3.80	30.00	2.66	Replace	0	0	Not Give ▾	
One Time Key In	Main			PAD, RR BUMPER, RH & LH , 2	1	3.80	3.80	30.00	2.66	Replace	0	0	Not Give ▾	
One Time Key In	Main			PAD, RR BUMPER, RH & LH , 3	1	3.80	3.80	30.00	2.66	Replace	0	0	Not Give ▾	
One Time Key In	Main			SEAL, RR BUMPER ARM, RH & LH	1	11.00	11.00	30.00	7.70	Replace	0	0	Not Give ▾	
One Time Key In	Main			FILLER, RR BUMPER , RH	1	119.90	119.90	30.00	83.93	Replace	0	0	Check ▾	

Total Spare Part Cost 4,897.77

Surveyor Total 180.00

Lump Sum Discount (%) 0.00

Lump Sum Dis (%) 0

Final Spare Part Cost 4,897.77

Final Sur Total 180.00

Labour's Cost Detail

S.No.	Costing Type	Job Scope	SMRT Recommendation(\$)	Surveyor Adjustment(\$)	Remarks
1	Main	TO REPAIR RH PORTION	845.00	600	
Total:			845.00	600.00	

Spray Cost Detail

S.No.	Costing Type	Job Scope	SMRT Recommendation(\$)	Surveyor Adjustment(\$)	Remarks
Total:			1,674.00	550.00	

S.No.	Costing Type	Job Scope	SMRT Recommendation(\$)	Surveyor Adjustment(\$)	Remarks
1	Main	TO RESPRAY FRONT DOOR RH	378.00	200	
2	Main	TO RESPRAY ROCKER PANEL MOULDING	180.00	100	
3	Main	TO RESPRAY VIEW MIRROR	180.00	50	
4	Main	TO RESPRAY REAR DOOR RH	378.00	200	
5	Main	TO REPSRAY REAR BUMPER	378.00	0	
6	Main	TO RESPRAY FILLER RR BUMPER RH	180.00	0	
Total:			1,674.00	550.00	

Other Cost Detail

S.No.	Costing Type	Job Scope	SMRT Recommendation(\$)	Surveyor Adjustment(\$)	Remarks
1	Main	TO CHECK WIRING AND SYSTEM FUNCTION	80.00	20	
2	Main	TO APPLY RUST-PROOFING ON AFFECTED AREA	100.00	30	
3	Main	TO TRANSFER DOOR MECHANISM	240.00	100	
4	Main	TO REMOVE AND REFIX WING MIRROR	120.00	0	
5	Main	TO WASH AND VACUUM	60.00	0	
6	Main	TO REPLACE SUNDRY PARTS	100.00	0	
Total:			700.00	150.00	

Summary

	Estimator Assesment(\$)	Surveyor Assesment(\$)
Total Spare Part Detail	4,897.77	180.00
Total Labour Cost	845.00	600.00
Total Spray Painting	1,674.00	550.00
Other	700.00	150.00
Overall Total	8,116.77	1,480.00

	Estimator Assesment(\$)	Surveyor Assesment(\$)
Lump Sum Repair Option		
Lump Sum Total	0.00	1,480.00
Surveyor Approved Amount		1,480.00
No of Repair Days*	5	4
Remarks		P/P REPAIR, PHOTO BEFORE PAINT.
Surveyor Name		Hwee jie
Signature		
Survey Date	11/02/2019	

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
Signature:
Date: