

CC31MSG19 00 2602/SS0307
E

REF:

MSG

File

ASSIGNMENT

From: _____ Date: _____
Estimated Cost: _____
OD ☒ TP WS / TP RES / OD RES / EVA / INV / MV
To Inspect Vehicle No: _____
at Workshop n/s: _____
of: _____
Insured: **SLK 2846m**
Policy No: _____
Claims No: _____
Sum Insured: _____ Excess: _____
(Client's Record)
Make of Veh: _____
(Policy Condition)
Remark: The veh had commenced its
repair at the time of inspection.
Bal. or Market Value: _____
IDAC Accident Rpt: _____ Consistent? : Yes or No
GIA / PR Seen: _____ Consistent? : Yes or No
Est Repairs: _____ days Res.: Yes or No
Lum Sum: _____ % 3 Val: Yes or No
CA / REV / REP. / 24 HRS
Date: _____ Person Contacted: _____
Vehicle: IN / OUT

N/S	O/S

Veh No: **SHB 823L** Yr Regn: **10 Oct 2017**
Type: M.Car / M.Cycle / Bus / Van / Lorry ☒ Prime Mover /
Truck / Trailer or
Make: **Toyota Prius** C.C: **1798**
Colour: **maroon** A/C: Insured / Std / NI / NA
Sp. Reading: _____ T/Radio: Insured / Std / NI / NA
Eng/No: _____
C/No: **JTDKB3FU003572392**
Gen. Cond: ☒ Good / Fair / Poor / Burnt
Steering: ☒ In order / Jammed / Leaked / Burnt or
Brake: ☒ In order / Jammed / Leaked / Burnt or
Modi: Nil / ☒ S/Rim / STD A/Rim or
Tyre Size: F: **195/65 R 15**
R: _____
BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /
TOYO / YOKO or **Westlake**
Front: _____ Rear: _____
R/Bal. **6** mm R/Bal. **2** mm
L/Bal. **6** mm L/Bal. **6** mm
D.O.A. **5/2/19** D.O.I. **11/2/19**
Survey held at **Sumit**
Des. of Damages: Frt / Rear / ☒ D/S / N/S / U/C / Rooftop or
The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time Action / Instruction
SHB 823L - CC31 TML 13000377 / 7/1/19 **Dur: 26/12/12** **02/19/2032**
SLK 2846M-X **SLK 2846m**

13/2/19 Email GIA to Yi Qian
26/3/19 Finalize Confir \$5064.80, 5 days
C & 4, 666.12 Red - 48%

RECEIVED 28 AUG 2019

Date/Time, File Pass to?

28/08/19

1) **Typist**
Date/Time, File Return to?

☐

Preli. Report

☒

Final Report

Days Of Repair: **5**

Resurvey No. of Trip: **1**

Survey Fee:

Transportation

3 + R5 - SI

Photos

Others

TOTAL

Report Format

Lump Sum (I.B): (\$ **5,064.80** p/p)

Add Fee:

☐

Site Insp (\$

☐

Interview (\$

☐

Tech. Invs (\$

☐

Weekend (\$

200
11
211

RE: SHB823L

Yeo Poh Suan (Auto Svcs/ARC/AR & SC/Taxis) <YeoPohsuan@smrt.com.sg>

Tue 27/8/2019 9:24 AM

To: Steve Chen (LKK Auto) <SteveChen@lkkauto.com>

Cc: SUR <sur@lkkauto.com>; CS A Team <cs-a@lkkauto.com>

Hi,

Amount confirmed as per your recommendation, thanks.

Regards

Poh Suan

-----Original Message-----

From: Steve Chen (LKK Auto) [<mailto:SteveChen@lkkauto.com>]

Sent: Monday, 26 August 2019 6:32 PM

To: Yeo Poh Suan (Auto Svcs/ARC/AR & SC/Taxis)

Subject: SHB823L

Dear Poh Suan,

We confirm the finalize \$5064.80 (P/P, before GST). 5 repair days.

Thanks

Best Regards,

Steve Chen| Assistant Automotive Assessor

LKK Auto Consultants

Phone: 6256 3561 | Email: SteveChen@lkkauto.com | fax: 6256-4315 Blk 51, Paya Ubi Industrial Park,
Ubi Avenue 1, #02-25 | S(408933)

-----Original Message-----

From: Yeo Poh Suan (Auto Svcs/ARC/AR & SC/Taxis) [<mailto:YeoPohsuan@smrt.com.sg>]

Sent: Monday, August 26, 2019 10:48 AM

To: Steve Chen (LKK Auto)

Cc: SUR; CS A Team

Subject: SHB823L

Hi Steve,

Attached herewith the repair estimate of SHB 823L having Case No: TAX/02/19/2032.

There is no change to the approved amount of \$5,064.80 @ 5 working days under part by part repair.

Cost of Repair invoice will be generated as approved.

Please finalize with me within 7 working day, thanks.

Thanks & Regards
Poh Suan

-----Original Message-----

From: Yeo Poh Suan (Auto Svcs/ARC/AR & SC/Taxis)

Sent: Thursday, 22 August 2019 2:31 PM

To: Yeo Poh Suan (Auto Svcs/ARC/AR & SC/Taxis)

Subject: Scan Data from FX-D421D6

Veron Chen (LKKAuto)

From: Veron Chen (LKKAuto)
Sent: Wednesday, 13 February 2019 5:04 PM
To: Low Yi Qian
Cc: SUR; Accounts (LKKAuto); KKLau
Subject: DIRECT SURVEY INSPECTION ON WORKSHOP - SMRT AUTOMOTIVE SERVICES PTE LTD, DOA: 5/2/2019, SHB 823L (TP VEHICLE), SLK 2846M (OI VEHICLE)
Attachments: GIA.pdf; MARK EST.pdf

Dear Yi Qian,

Please be informed that we had inspected the vehicle SHB 823L at M/s: SMRT AUTOMOTIVE SERVICES PTE LTD, 60 WOODLANDS INDUSTRIAL PARK E4 SINGAPORE 757705 on 11/2/2019

Enclosed herewith a copy of TP's GIA report and estimated cost of repair .

Meanwhile, kindly provide us the claim reference number for our necessary action.

Best Regards,

Veron Chen | Case Handler **on behalf of Shirley**

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email :sur@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. **Any false reporting may be referred to the Police for investigation.**
6. This report will be forwarded by the Insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT

Date Of Report	09/02/2019 09:16
Date Of Accident	05/02/2019 12:35
Exact Location Of Accident	TAMPINES AVE 10
Country/State of Loss	SINGAPORE

DETAILS OF OWN VEHICLE

Vehicle Registration Number	SHB823L
Insured/Policyholder	
Name Of Registered Owner	SMRT TAXIS PTE LTD
Co Reg No	198905369K
Email Address	NOEMAIL
Mobile Phone No	
Alternative Phone No	OFFICE-80000000

Vehicle Particulars

Manufacturer	TOYOTA
Model	PRIUS TAXI-1.8 (A)
Exact Purpose for which vehicle was being used at time of accident	HIRE AND REWARD
Are you claiming under your own insurance policy for repair to your vehicle?	NO
If No, Please state action to be taken	THIRD PARTY
Vehicle Category	TAXI

Insurance Company

Name of Insurance Company	MS FIRST CAPITAL INSURANCE LTD
Type Of Coverage	THIRD PARTY FIRE AND/OR THEFT
Fleet Policy	YES
Policy Number	D-18090213MFSH
Cover Note Number	

Driver

Name of Driver	POH AH CHYE
NRIC No	S1716245D
Date Of Birth	21/03/1965
Occupation	OUTDOOR
Date Of Driving Pass	19/07/1985
Driving Experience	33 YEARS AND 6 MONTHS
Gender	FEMALE
Mobile Number	(LOCAL) +65-80000000
Fax Number	
Contact Number	
Email Address	NOEMAIL

Address	11
Postcode	
Was driver an employee of the Insured's Company	NO
If No, Relationship of the Driver with the Insured	OTHER - RELIEF
Vehicle Registration Number of Driver's Own Vehicle	-
	-
Insurance Company of Driver's Own Vehicle	-
	-
	-

General Information of the Accident

Type Of Accident	SIDE SWIPE
Weather Conditions	CLEAR
Road Surface	DRY

Other Information

Was any foreign vehicle involved in this accident?	NO
Number of vehicles (including own vehicle) involved in the accident	2
Was any body injured in the Accident?	NO
Was any injured conveyed to hospital by ambulance?	NO
Was any other material or property damaged?	YES
I have been approached by unknown person(s) soliciting/offering accident claims assistance.	NO
Number of Passengers (Including Driver)	6
Passenger 1	NAME: : UNKNOWN GENDER: : MALE
Passenger 2	NAME: : UNKNOWN GENDER: : FEMALE
Passenger 3	NAME: : UNKNOWN GENDER: : MALE
Passenger 4	NAME: : UNKNOWN GENDER: : FEMALE
Passenger 5	NAME: : UNKNOWN GENDER: : MALE

Details of Police Action

Was the accident reported to the police?	NO
If Yes, Please state which Police Station	
Was notice of intended Prosecution given?	NO
If Yes, against whom?	

Circumstances of Accident

I WAS DRIVING ALONG TAMPINES AVE 10 ON 2ND LANE. I AM IN MY OWN LANE . SUDDENLY A PRIVATE CAR SLK2846M COLLIDED INTO MY RIGHT HAND SIDE OF MY TAXI. WE GOT OUT FROM OUR VEHICLES. DRIVER OF SLK2846M ASKED ME IF I NEED TO DO POLICE REPORT AND IF ANYONE IN MY TAXI IS INJURED. I TOLD HIM I CANNOT DO PRIVATE SETTLEMENT AS I HAVE 5 PAXS IN MY TAXI. WE EXCHANGE PARTICULARS & TOOK PHOTOS OF OUR VEHICLE NUMBER.

Attachment(s)


Are accident photos available for attachment?	YES
Was there any video captured by Car Camera?	NO
Was there any audio recorded?	NO

DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number	SLK2846M
Vehicle Make/Model/Colour	
Details Of Properties	
Vehicle Category	PRIVATE CAR
Name of Driver	LIM SHER EE DENNIS
NRIC/Passport Number	
Contact Number	
Address	
Postcode	
Insurance Company Name	
Nature Of Damage	
No. Of Passenger (Including Driver)	

SKETCH PLAN

Tampines Ave 10



DESCRIBE CIRCUMSTANCES OF THE ACCIDENT

This image shows a single sheet of white paper with horizontal blue or grey ruling lines. The lines are evenly spaced and run across the width of the page. There is no handwriting or other markings on the paper.

DECLARATION-

I/We declare the foregoing particulars are true in every respect.



Policyholder's Signature

Date & Time:

Driver's Signature

(If driver is not the policyholder)

Date & Time: 7/2/19 10.00 am

Reporting Centre Personnel's Signature

Name: Selens

NRIC/FIN No.:

SKETCH PLAN

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. The report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgment of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.


8. **Consent under the Personal Data Protection Act (PDPA)**

I understand, acknowledge, agree and consent that:

- (a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this [form] and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the Insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of :
 - (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
 - (ii) investigating the accident and/or my claims;
 - (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
 - (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
 - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims.(collectively the "Purposes")
- (b) all insurer(s) who have insured vehicle(s) involved in this accident and the Insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
- (c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third party service providers or agents(including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.
- (d) my Personal Information will also be collected and used to compile claims history for the purpose of fraud detection, investigation and management in present and all future claims.
- (e) the information so collected under (d) above may be shared / disclosed:
 - (i) to all insurers and/or any other third parties that assist in evaluating, investigating, controlling or managing fraud, regulators, law enforcement and government agencies as reasonably required for the purposes stated, or
 - (ii) for complying with requirements under any regulations, laws or court orders.

Policyholder's Signature
Date & Time:

Driver's Signature
(If driver is not the policyholder)
Date & Time:



Reporting Centre Personnel's Signature
Name:
NRIC/FIN No.:

Case Details

Case Reference Number : TAX/02/19/2032
Type of Repair : Accident Repair
Vehicle Registration Number : SHB823L

Company Type : SMRT Taxis Pte Ltd
Estimation ID : EST-5631-ID
Assigned By : Taxi Claims Manager Team

Insurance Company Name : MSIG Insurance (S) Pte Ltd
Accident Date and Time : 05/02/2019 04:33 AM
Vehicle Age(In Months) : 16

Documents / Photographs

[View Documents / Photographs](#)

Total Documents: 0

Estimation Details

Spare Part's Cost Detail

SMRT Recommendation										Surveyor Approval				
BOM Type	Costing Type	Portion	Material Number	Part Name	Qty	List Price Per Unit(\$)	List Price(\$)	Dis(%)	Final Price(\$)	Repair/ Replace	Surveyor Quantity	Surveyor Final Price(\$)	Repair/Replace	Remarks
One Time Key In	Main			PANEL SUB-ASSY, FRONT DOOR RH	1	1,249.60	1,249.60	30.00	874.72	Replace	1	0.00	Replace ▾	BUC
One Time Key In	Main			STICKER DECAL SMRT (DOOR)	1	60.00	60.00	0.00	60.00	Replace	1	60.00	Replace ▾	NEC
One Time Key In	Main			MOULDING ASSY, BODY ROCKER PANEL, RH	1	576.00	576.00	30.00	403.20	Replace	1	0.00	Replace ▾	NEC
One Time Key In	Main			MIRROR ASSY, OUTER REAR VIEW, RH	1	1,373.50	1,373.50	10.00	1,236.15	Replace	0	0	Not Give ▾	X N/A
One Time Key In	Main			COVER, OUTER MIRROR, RH	1	89.50	89.50	30.00	62.65	Replace	1	0	Repair ▾	X R
One Time Key In	Main			MIRROR OUTER GLASS, RH	1	215.20	215.20	30.00	150.64	Replace	0	0	Not Give ▾	X N/A
One Time Key In	Main			LAMP ASSY, SIDE MIRROR TURN SIGNAL, RH	1	162.20	162.20	10.00	145.98	Replace	0	0	Not Give ▾	X N/A
Total Spare Part Cost									4,897.77	Surveyor Total 180.00				
Lump Sum Discount (%)									0.00	Lump Sum Dis (%) 0				
Final Spare Part Cost									4,897.77	Final Sur Total 180.00				

SMRT Recommendation											Surveyor Approval			
BOM Type	Costing Type	Portion	Material Number	Part Name	Qty	List Price Per Unit(\$)	List Price(\$)	Dis(%)	Final Price(\$)	Repair/ Replace	Surveyor Quantity	Surveyor Final Price(\$)	Repair/Replace	Remarks
One Time Key In	Main			PANEL SUB-ASSY, REAR DOOR , RH	1	1,243.90	1,243.90	30.00	870.73	Replace	1	0.00	Replace	✓ BUC
One Time Key In	Main			PIXEL STICKER	2	60.00	120.00	0.00	120.00	Replace	2	120.00	Replace	✓ NEC
One Time Key In	Main			PANEL SUB-ASSY, FENDER REAR RH	1	824.80	824.80	30.00	577.36	Replace	1	0	Repair	✓ X R
One Time Key In	Main			COVER, RR BUMPER ASSY	1	423.90	423.90	30.00	296.73	Replace	0	0	Check	✓ X N/A
One Time Key In	Main			PAD, RR BUMPER, RH & LH , 1	1	3.80	3.80	30.00	2.66	Replace	0	0	Not Give	✓ X N/A
One Time Key In	Main			PAD, RR BUMPER, RH & LH , 2	1	3.80	3.80	30.00	2.66	Replace	0	0	Not Give	✓ X N/A
One Time Key In	Main			PAD, RR BUMPER, RH & LH , 3	1	3.80	3.80	30.00	2.66	Replace	0	0	Not Give	✓ X N/A
One Time Key In	Main			SEAL, RR BUMPER ARM, RH & LH	1	11.00	11.00	30.00	7.70	Replace	0	0	Not Give	✓ X N/A
One Time Key In	Main			FILLER, RR BUMPER , RH	1	119.90	119.90	30.00	83.93	Replace	0	0	Check	✓ X N/A
Total Spare Part Cost									4,897.77	Surveyor Total 180.00				
Lump Sum Discount (%)									0.00	Lump Sum Dis (%) 0				
Final Spare Part Cost									4,897.77	Final Sur Total 180.00				

Labour's Cost Detail

S.No.	Costing Type	Job Scope	SMRT Recommendation(\$)	Surveyor Adjustment(\$)	Remarks
1	Main	TO REPAIR RH PORTION	845.00	600	
Total:			845.00	600.00	

Spray Cost Detail

S.No.	Costing Type	Job Scope	SMRT Recommendation(\$)	Surveyor Adjustment(\$)	Remarks
Total:			1,674.00	550.00	

S.No.	Costing Type	Job Scope	SMRT Recommendation(\$)	Surveyor Adjustment(\$)	Remarks
1	Main	TO RESPRAY FRONT DOOR RH	378.00	200	
2	Main	TO RESPRAY ROCKER PANEL MOULDING	180.00	100	
3	Main	TO RESPRAY VIEW MIRROR	180.00	50	
4	Main	TO RESPRAY REAR DOOR RH	378.00	200	
5	Main	TO REPSRAY REAR BUMPER	378.00	0	
6	Main	TO RESPRAY FILLER RR BUMPER RH	180.00	0	
Total:			1,674.00	550.00	

2052

750

Other Cost Detail

S.No.	Costing Type	Job Scope	SMRT Recommendation(\$)	Surveyor Adjustment(\$)	Remarks
1	Main	TO CHECK WIRING AND SYSTEM FUNCTION	80.00	20	
2	Main	TO APPLY RUST-PROOFING ON AFFECTED AREA	100.00	30	
3	Main	TO TRANSFER DOOR MECHANISM	240.00	100	
4	Main	TO REMOVE AND REFIX WING MIRROR	120.00	0	
5	Main	TO WASH AND VACUUM	60.00	0	
6	Main	TO REPLACE SUNDRY PARTS	100.00	0	
Total:			700.00	150.00	

Summary

11651.40

	Estimator Assesment(\$)	Surveyor Assesment(\$)
Total Spare Part Detail	4,897.77	180.00
Total Labour Cost	845.00	600.00
Total Spray Painting	1,674.00	550.00
Other	700.00	150.00
Overall Total	8,116.77	1,480.00

9730.92

Estimator Assesment(\$)

Surveyor Assesment(\$)

Lump Sum Repair Option

Lump Sum Total

0.00

1,480.00

Surveyor Approved Amount

1,480.00

No of Repair Days*

5

4

Remarks

P/P REPAIR, PHOTO BEFORE PAINT.

Surveyor Name

Hwee jie

Signature




Save

Clear

Survey Date

11/02/2019



REQUEST FOR SUPPLEMENT PARTS

Contractor:			
Accident Case Number	TAX 021910032	Date of Collection	1 1
Vehicle No	SHB 823 L	Date of Request	12/02/2019
Vehicle Model	TOYOTA PRIUS 4	Number of Days to Extend (if any)	X 1

S/N	Part Number	Part Description	Quantity	Unit Price
		SIDE MIRROR RH	1pc	1375.50
		TO SPRAY REAR FENDER RH		\$ 378.00

\$1236.15 A
\$200

<<Please submit photographs for damaged parts>>

13/2/19

(Name)

(Position)

I solemnly and sincerely declare that:- Supplementary Parts are used for replacement for the aforesaid vehicle.

Signature of person making this declaration
(to be signed in front of an authorised witness)

I acknowledge that this declaration is true and correct, and I make it with the understanding and belief that a person who makes a false declaration is liable to the damages of perjury.

SMRT SMT

Acknowledged By	ARCE Executive / Supervisor / SA	
Approval By	Surveyor / In-house Staff	
Parts Ordering	SMRT Store / Contractor Supply / Form 22 / WOC	Form 22 / PO / WOC / Reservation / Number
Photo Submitted	YES / NO	Date of submission



SMRT Accident Vehicle Repair Estimates

SMRT Automotive Services Pte Ltd
60 Woodlands Industrial Park E4, Singapore 757705
FAX Number 63685592
Estimator Telephone Number 68852023
Accident Reporting Number 68562072

Date Generated : 22/09/2019


User ID : PehSuan

Section A - Accident Details

Registration Number	SHB823L
Case Reference Number	TAX/02/19/2032
Registration Date	10/10/2017
Company Type	SMRT Taxis Pte Ltd
Make	TOYOTA
Model	PRIUS4
Name of Driver	POH AH CHYE
Type of Accident	Head To Side
Accident Date and Time	5/2/2019 12:33 PM
Accident Reported Date and Time	7/2/2019 5:19 PM
Is Surveyor Required?	Yes
Survey by	
Vehicle is Towed Back?	No
Towed Back Date and Time	
Replacement Vehicle issued?	No
Job Card Number	24100018
Special Instruction to ARC, if any	BP/MSIG
Prepared Date and Time	8/2/2019 3:35 PM
Chassis Number	
Mileage	
Work Shop	
Repair Completion Date and Time	

Section B - Summary of Repair Estimates

Summary of Repair Estimates

	Quotation from ARC	Adjusted by Surveyor, if applicable
Total Labour Cost	\$845.00	\$600.00
Total Spray Cost	\$2,052.00	\$750.00
Total Spare Part Cost	\$6,133.92	\$3,564.80
Total Other Cost	\$700.00	\$150.00
TOTAL COST	\$9,730.92	\$5,064.80 (P/P)
Lump Sum Total	\$0.00	\$0.00
Number of Repair Days	5.0	5.0
Prepared / Adjusted By	Kim Ming Chin	Hwee Jie (LKK) / MSIG
ARC / Surveyor Sign Off Date	08/02/2019 4:29 PM	11/02/2019 1:18 PM
Signature		
Remarks	P/P REPAIR, PHOTO BEFORE PAINT.	

Section C - Quotation and Accident Invoice Details

Quotation Number	QN-1908-0145	Invoice Number	
Quotation Date	13.08.2019	Invoice Date	
Invoice Amount		Prepared Date	

Section D - Details of Repair Estimates

Part 1 - Labour Works

Job Scope	Quotation from AR	Adjusted by Surveyor, if applicable
TO REPAIR RH PORTION	\$845.00	\$600.00
Total Labour	\$845.00	\$600.00

Part 2 - Spray Painting & Panel Beating Related Works

Job Scope	Quotation from ARC	Adjusted by Surveyor, if applicable
TO RESPRAY FRONT DOOR RH	\$378.00	\$200.00
TO RESPRAY ROCKER PANEL MOULDING	\$180.00	\$100.00
TO RESPRAY VIEW MIRROR	\$180.00	\$50.00
TO RESPRAY REAR DOOR RH	\$378.00	\$200.00
TO RESPRAY REAR BUMPER	\$378.00	\$0.00
TO RESPRAY FILLER RR BUMPER RH	\$180.00	\$0.00
TO RESPRAY REAR FENDER RH	\$378.00	\$200.00
Total Spray Painting & Panel Beating	\$2,052.00	\$750.00

Part 3 - Other Costs - Accident and Accident Repair Related Expense

Job Scope	Quotation from ARC	Adjusted by Surveyor, if applicable
TO CHECK WIRING AND SYSTEM FUNCTION	\$80.00	\$20.00
TO APPLY RUST-PROOFING ON AFFECTED AREA	\$100.00	\$30.00
TO TRANSFER DOOR MECHANISM	\$240.00	\$100.00
TO REMOVE AND REFIX WING MIRROR	\$120.00	\$0.00
TO WASH AND VACUUM	\$60.00	\$0.00
TO REPLACE SUNDRY PARTS	\$100.00	\$0.00
Total Other Costs	\$700.00	\$150.00

Part 4 - Spare Parts / Material Usage

Part Number	Portion	Stock Number	Part Name	Quantity	List Price (\$)	Discount (%)	Final Price (\$)	Estimator Approved	Surveyor Approved
		67001471 52	PANEL SUB-ASSY, FRONT DOOR RH	1.00	\$1,249.60	30.00	\$874.72	Replace	Replace
			STICKER DECAL SMRT (DOOR)	1.00	\$60.00	0.00	\$60.00	Replace	Replace
		75850479 10	MOULDING ASSY, BODY ROCKER PANEL, RH	1.00	\$576.00	30.00	\$403.20	Replace	Replace
		87910474 50	MIRROR ASSY, OUTER REAR VIEW, RH	0.00	\$1,373.50	0.00	\$0.00	Replace	Not Given
		87915470 70A1	COVER, OUTER MIRROR, RH	1.00	\$89.50	100.00	\$0.00	Replace	Repair
		81730470 10	LAMP ASSY, SIDE MIRROR TURN SIGNAL, RH	0.00	\$162.20	0.00	\$0.00	Replace	Not Given
		67003472 10	PANEL SUB-ASSY, REAR DOOR, RH	1.00	\$1,243.90	30.00	\$870.73	Replace	Replace
			PIXEL STICKER	2.00	\$60.00	0.00	\$120.00	Replace	Replace
		61501471 50	PANEL SUB-ASSY, FENDER REAR RH	1.00	\$624.80	100.00	\$0.00	Replace	Repair



SMRT Accident Vehicle Repair Estimates

SMRT Automotive Services Pte Ltd
60 Woodlands Industrial Park EA, Singapore 757705
FAX Number: 63685592
Estimator Telephone Number: 88662623
Accident Reporting Number: 68082672

Date Generated : 22/08/2019

User ID : PehSuan

	52159479 13	COVER, RR BUMPER ASSY	0.00	\$423.90	0.00	\$0.00	Replace	Check
	52462470 30	PAD, RR BUMPER, RH & LH, 1	0.00	\$3.80	0.00	\$0.00	Replace	Not Given
	52462470 20	PAD, RR BUMPER, RH & LH, 2	0.00	\$3.80	0.00	\$0.00	Replace	Not Given
	52462470 10	PAD, RR BUMPER, RH & LH, 3	0.00	\$3.80	0.00	\$0.00	Replace	Not Given
	52191470 30	SEAL, RR BUMPER ARM, RH & LH	0.00	\$11.00	0.00	\$0.00	Replace	Not Given
	52565479 00	FILLER, RR BUMPER, RH	0.00	\$119.90	0.00	\$0.00	Replace	Check
Total				\$6,205.70		\$2,328.65		

Added Spare Parts / Material Usage After Surveyor Signed off

Part Number	Portion	Stock Number	Part Name	Quantity	List Price \$	Discount (%)	Final Price (\$)	ARC Check	Surveyor Check
		87910474 50	MIRROR ASSY, OUTER REAR VIEW, RH	1.00	\$1,373.50	10.00	\$1,236.15	Replace	Replace
Total					1,588.70		1,236.15		

3564.80
+ 600.00
+ 900.00

5064.80

A SC5

...CLAIM SUBFOLDER...(Pending for Survey Report)

CLAIM SUBFOLDER TRACKING









































Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'd	Status
Main	08 Feb 2019		15 Feb 2019 13:26 Edit Adj Rpt	S\$5,064.80 Edit Estimates	S\$5,064.80 View Rpt		Pending for Survey Report Cancel Case

Main	Reference	Claim Details	Documents	Show All
------	-----------	---------------	-----------	----------

CLAIM SUBFOLDER DETAILS		[Created by insurer]							
Insured:	LIM SHER EE, DENNIS (LIN SHIYI), ID: S7906570F, Tel: +6596506519, Email: dennis.s.e.lim@gmail.com								
Main Claimant:	SMRT TAXIS PTE LTD, Co. Reg. No.: 198905369K								
Vehicle Reg. No.:	SHB823L	Date of Loss:	05/02/2019 12:00 - :59 [15 Months and 26 Days From LTA Reg Date (Man Yr)]						
Claim Type:	TP / 584314	Policy/Cover Note No.:	29113291 (Comprehensive) Coverage: 12/01/2019 - 11/01/2020						
Vehicle Reg. No. (Insured):	SLK2846M	Policy No. (Claimant):							
		Excess:							
Repairer:	SMRT Automotive Services Pte Ltd (Woodlands) 60 Woodlands Industrial Park E4, 757705 Woodlands - Tel: 68662628								
Handling Insurer:	MSIG Insurance (Singapore) Pte. Ltd. (HQ) - Tel: +65 6827 7888 ... [Handled by Pauline Tham - 6594 2545]								
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Handled by CHEN TSUE YEE] ... [Imm.Advice due 16/02/2019]								
Driver/Custodian (Insured):	LIM SHER EE, DENNIS (LIN SHIYI) (39 / Male) , NRIC: S7906570F, Tel: +6596506519 Email: dennis.s.e.lim@gmail.com								
Adj Asg. Remarks:	Direct survey on 11/2/2019.								
ASSOCIATED MAIL RECEIVED View All Compose Case Mail									
There are no mail for this case.									
ALL ASSOCIATED TASKS View All Search Tasks Create New Task Complete									
Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

Claim Documents

*SHB823L (584314)
[SLK2846M]
TP
SMRT TAXIS PTE LTD
Feb 5 2019 12:00PM
[LIM SHER EE, DENNIS (LIN SHIYI)]
SMRT Automotive Services Pte Ltd

Upload Documents		Upload Photos	Compose New Letter	View View in Browser	
Assessment Reports				1 per page	<input checked="" type="checkbox"/>
No	Finalized On	MSIG Insurance (Singapore) Pte. Ltd. (HQ)	Thumbnail	Print	
1	15/02/19 13:23	Accident Statement From: SC - Reg. No: SLK2846M, Claimant: LIM SHER EE, DENNIS (LIN SHIYI)	 Load HTM		
Photos/Images				3 per page	<input checked="" type="checkbox"/>
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print	
1	18/02/19 09:53	General View	 Load JPG		<input checked="" type="checkbox"/>
2	18/02/19 09:53	General View	 Load JPG		<input checked="" type="checkbox"/>
3	18/02/19 09:53	General View	 Load JPG		<input checked="" type="checkbox"/>
4	18/02/19 09:53	General View	 Load JPG		<input checked="" type="checkbox"/>
5	18/02/19 09:53	General View	 Load JPG		<input checked="" type="checkbox"/>
6	18/02/19 09:53	General View	 Load JPG		<input checked="" type="checkbox"/>
7	18/02/19 09:53	General View	 Load JPG		<input checked="" type="checkbox"/>
8	18/02/19 09:53	General View	 Load JPG		<input checked="" type="checkbox"/>
9	18/02/19 09:53	General View	 Load JPG		<input checked="" type="checkbox"/>
10	18/02/19 09:53	General View	 Load JPG		<input checked="" type="checkbox"/>
11	18/02/19 09:53	General View	 Load JPG		<input checked="" type="checkbox"/>
12	18/02/19 09:53	General View	 Load JPG		<input checked="" type="checkbox"/>
13	18/02/19 09:53	General View	 Load JPG		<input checked="" type="checkbox"/>
14	18/02/19 09:53	General View	 Load JPG		<input checked="" type="checkbox"/>
15	18/02/19 09:53	General View	 Load JPG		<input checked="" type="checkbox"/>
16	18/02/19 09:53	General View	 Load JPG		<input checked="" type="checkbox"/>
17	18/02/19 09:53	General View	 Load JPG		<input checked="" type="checkbox"/>
18	18/02/19 09:53	General View	 Load JPG		<input checked="" type="checkbox"/>
19	18/02/19 09:53	General View	 Load JPG		<input checked="" type="checkbox"/>
20	18/02/19 09:53	General View	 Load JPG		<input checked="" type="checkbox"/>
21	18/02/19 09:53	General View	 Load JPG		<input checked="" type="checkbox"/>
22	18/02/19 09:53	General View	 Load JPG		<input checked="" type="checkbox"/>
23	18/02/19 09:53	General View	 Load JPG		<input checked="" type="checkbox"/>
24	18/02/19 09:53	General View	 Load JPG		<input checked="" type="checkbox"/>
25	18/02/19 09:53	General View	 Load JPG		<input checked="" type="checkbox"/>
26	18/02/19 09:53	General View	 Load JPG		<input checked="" type="checkbox"/>
27	18/02/19 09:53	General View	 Load JPG		<input checked="" type="checkbox"/>
28	18/02/19 09:53	General View	 Load JPG		<input checked="" type="checkbox"/>
29	18/02/19 09:53	General View	 Load JPG		<input checked="" type="checkbox"/>
30	18/02/19 09:53	General View	 Load JPG		<input checked="" type="checkbox"/>
31	18/02/19 09:53	General View	 Load JPG		<input checked="" type="checkbox"/>
32	18/02/19 09:53	General View	 Load JPG		<input checked="" type="checkbox"/>
33	18/02/19 09:53	General View	 Load JPG		<input checked="" type="checkbox"/>
34	18/02/19 09:53	General View	 Load JPG		<input checked="" type="checkbox"/>
35	18/02/19 09:53	Dismantled Parts	 Load JPG		<input checked="" type="checkbox"/>
36	18/02/19 09:53	Dismantled Parts	 Load JPG		<input checked="" type="checkbox"/>
37	18/02/19 09:53	Dismantled Parts	 Load JPG		<input checked="" type="checkbox"/>
38	18/02/19 09:53	Dismantled Parts	 Load JPG		<input checked="" type="checkbox"/>
39	18/02/19 09:53	Dismantled Parts	 Load JPG		<input checked="" type="checkbox"/>

Assessment Reports				1 per page	<input checked="" type="checkbox"/>
No	Finalized On	MSIG Insurance (Singapore) Pte. Ltd. (HQ)		Thumbnail	Print
40	18/02/19 09:53	Dismantled Parts		Load JPG	<input checked="" type="checkbox"/>
41	18/02/19 09:53	Replacement Part Photo		Load JPG	<input checked="" type="checkbox"/>
42	18/02/19 09:53	Replacement Part Photo		Load JPG	<input checked="" type="checkbox"/>
43	18/02/19 09:53	Replacement Part Photo		Load JPG	<input checked="" type="checkbox"/>
44	18/02/19 09:53	Replacement Part Photo		Load JPG	<input checked="" type="checkbox"/>
45	18/02/19 09:53	Replacement Part Photo		Load JPG	<input checked="" type="checkbox"/>
46	18/02/19 09:53	Replacement Part Photo		Load JPG	<input checked="" type="checkbox"/>
47	18/02/19 09:53	Replacement Part Photo		Load JPG	<input checked="" type="checkbox"/>
Documentation				1 per page	<input checked="" type="checkbox"/>
No	Finalized On	MSIG Insurance (Singapore) Pte. Ltd. (HQ)		Thumbnail	Print
1	15/02/19 13:25	SHB823L e-file report		Load PDF	
2	15/02/19 13:26	MARK EST		Load PDF	
3	15/02/19 13:28	Direct survey done		Load PDF	
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)		Thumbnail	Print
1	20/09/19 10:15	Supplementary		Load PDF	

Documents Checklist

DOCUMENTS CHECKLIST		Reset	Save	Print
There are no document checklists configured.				
Our Checklist Remarks - LKK Auto Consultants Pte Ltd (HQ) <div style="border: 1px solid black; height: 40px; margin-top: 5px;"></div>				
Show Remarks To: <input type="checkbox"/> Handling Insurer <small>Note: Remarks are private unless you show it to other parties.</small>				

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CC3/MSG19002662/ESD3E2

Date: 20/09/2019

REFERENCE

Handling Insurer: MSIG Insurance (Singapore) Pte. Ltd.

Policy No: 29113291

Claimant SHB823L

Insured Vehicle No : SLK2846M

Vehicle No : SHB823L

Date of Loss: 05/02/2019

Nature of Claim: TP

Claim No: 584314

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: SHB823L

Make & Model: TOYOTA PRIUS, 1.8 HYBRID CVT (A)

Engine No: 2ZRS095011

Reg. Date: 10/10/2017 (Man. Year: 2017)

Chassis No: JTDKB3FU003572392

Colour: Maroon

Odometer: 0 km

Engine Capacity: 1798 cc

Market Value/New Car Price: N/A

Sum Insured (S\$): Market Value/New Car Price

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable):

Yes

Footbrake (Serviceable):

Yes

Handbrake (Serviceable):

Yes

Engine Modification:

No

Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 195/65 R15

Rear Tyre Size: 195/65 R15

Front Left Side: West Lake 6 mm

Rear Left Side: West Lake 6 mm

Front Right Side: West Lake 6 mm

Rear Right Side: West Lake 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	7,854.40	3,564.80	4,289.60	54.61
Miscellaneous Items	0.00	0.00	0.00	
Labour	3,597.00	1,500.00	2,097.00	58.30
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Nett Amount (S\$)	11,451.40	5,064.80	6,386.60	55.77

INSPECTION

Date of Assignment: 15/02/2019

Date Inspected: 11/02/2019 Inspected At:

SMRT Automotive Services Pte Ltd
(Woodlands)
60 Woodlands Industrial Park E4
Singapore 757705

Estimated Period of Repair: 5.0 days

Adjuster: CHEN TSUE YEE

Manager: Hiew May Fung

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference		
Part Source:	MRM-SG	Version: 1.0 (Last Synchronised: 20 Sep 2019)
Parts:	144	TOYOTA PRIUS 1.8 HYBRID CVT (A) (Catalogue:Merimen Singapore 1.0)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for SHB823L)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*PANEL SUB-ASSY, FRONT DOOR RH (DISC 30%)	Buckled	1,249.60 F	*874.72 F
2	1		*MOULDING ASSY, BODY ROCKER PANEL, RH (DISC 30%)	Necessary	576.00 F	*403.20 F
3	1		*PANEL SUB-ASSY, REAR DOOR, RH (DISC 30%)	Buckled	1,243.90 F	*870.73 F
4	1		*STICKER DECAL SMRT (DOOR) (SN)	Necessary	60.00 F	*60.00 F
5	2		*PIXEL STICKER (SN)	Necessary	120.00 F	*120.00 F
6	1		*MIRROR ASSY, OUTER REAR VIEW, RH	Not Necessary	1,373.50 F	*- F
7	1		*MIRROR OUTER GLASS, RH	Not Necessary	215.20 F	*- F
8	1		*LAMP ASSY, SIDE MIRROR TURN SIGNAL, RH	Not Necessary	162.20 F	*- F
9	1		*COVER, RR BUMPER ASSY	Not Necessary	423.90 F	*- F
10	2		*PAD, RR BUMPER, RH & LH, 1	Not Necessary	3.80 F	*- F
11	2		*PAD, RR BUMPER, RH & LH, 2	Not Necessary	3.80 F	*- F
12	2		*PAD, RR BUMPER, RH & LH, 3	Not Necessary	3.80 F	*- F
13	2		*SEAL, RR BUMPER ARM, RH & LH	Not Necessary	11.00 F	*- F
14	1		*FILLER, RR BUMPER, RH	Not Necessary	119.90 F	*- F
15	1		*COVER, OUTER MIRROR, RH	Repair	89.50 F	*- F
16	1		*PANEL SUB-ASSY, FENDER REAR RH	Repair	824.80 F	*- F
17	1		*MIRROR ASSY, OUTER REAR VIEW, RH (DISC 10%)	Scratched	1,373.50 F	*1,236.15 F
					Total Parts (\$\$)	7,854.40 3,564.80

F=Franchise part.

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	SPRAY PAINT	New	2,052.00	750.00
2	TO CHECK WIRING AND SYSTEM FUNCTION	New	80.00	20.00
3	TO APPLY RUST-PROOFING ON AFFECTED AREA	New	100.00	30.00
4	TO TRANSFER DOOR MECHANISM	New	240.00	100.00
5	TO REMOVE AND REFIX WING MIRROR	New	120.00	0.00
6	TO WASH AND VACUUM	New	60.00	0.00
7	TO REPLACE SUNDRY PARTS	New	100.00	0.00
8	PANEL BEATING	New	845.00	600.00
Gross Labour Cost (S\$)			3,597.00	1,500.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >