

**KAH MOTOR CO. SDN. BHD.**

(A Member of the Oriental Holdings Berhad)

Service and Body Repair

Tel: +65 6841 3838

Website: www.honda.com.sg

For 24-hours Roadside Assistance, Call 98203838

QUOTATION

GST Reg No.: M200050223

Company Ref. No.: S60FC1380G

Customer : INDIA INTERNATIONAL INSURANCE
64 CECIL STREET
#04-00 & #05-00 IOB BUILDING
SINGAPORE 049711

Registration No : SLH6346D

Chassis No : JHMRC1890GC207015

Model : ODYSSEY2.4 EXV-S 16YM NAVI-RES

Owner's Name : ELSIE TONG PAIK KOON

Ins Policy No. :

Date of Accident : 8/2/2019

Document No. : SQT19000754 **Page** 1

Date : 16. Feb 2019

Customer No. : WZI007

Svc Advisor :

Engine No : K24W72013079

Date | Time : 16. Feb 2019 2:01:53 PM

Surveyor Name :

Survey Date :

Authorisation Date :

Item	Description	Qty	Unit Price	Disc %	Amount	0% GST Amount	Amount incld GST
	TP DIRECT SETTLEMENT (J/NO:) OWNER:ELSIE TONG PAIK KOON OWNER INSURER:LIBERTY INSURANCE ACC DATE:08/02/2019 SURVEYED BY: DATE: REF NO: TP INSURER:III TP VEH:SHD 4753 T						
04715-T6A-900ZZ	FACERR.BUMPER <i>DE</i>	1	568.30	25	426.22	29.84	456.06
33505-SLJ-013	REFLECTOR ASSYR.RR. <i>X</i>	1	45.40	25	34.05	2.38	36.43
33555-SLJ-013	REFLECTOR ASSYL.RR. <i>?</i>	1	45.40	25	34.05	2.38	36.43
71512-T6A-921ZE	SPOILER ASSYR.RR.SIDE <i>X</i>	1	114.10	25	85.57	5.99	91.56
71517-T6A-921ZE	SPOILER ASSYL.RR.SIDE <i>X</i>	1	114.10	25	85.57	5.99	91.56
71593-T6A-003	SPACERR.RR.BUMPER SIDE <i>m</i>	1	19.10	25	14.32	1.00	15.32
71598-T6A-003	SPACERL.RR.BUMPER SIDE <i>m</i>	1	19.10	25	14.32	1.00	15.32
91505-TM8-003	CLIP,BUMPER <i>m</i>	8	2.30	25	13.80	0.97	14.77
68100-T6A-Q10ZZ	TAILGATE COMP <i>HA</i>	1	1070.80	25	803.10	56.22	859.32
74440-T6A-003	WEATHERSTRIPTAILGATE <i>X</i>	1	117.40	25	88.05	6.16	94.21
74800-TF0-J02	LOCKTAILGATE <i>X</i>	1	185.40	25	139.05	9.73	148.78
74810-T4N-H01	SWITCH ASSYTAILGATE OPENER <i>X</i>	1	105.30	25	78.97	5.53	84.50
75701-T6A-000	EMBLEMH <i>m</i>	1	26.30	25	19.72	1.38	21.10
66100-T6A-Q00ZZ	PANEL COMP,REAR <i>repair</i>	1	460.80	25	345.60	24.19	369.79
73214-T6A-003	MOLDINGRR.WINDSHIELD SIDE <i>m</i>	2	18.00	25	27.00	1.89	28.89
73215-T6A-003	MOLDINGR.RR.WINDSHIELD CORNER <i>m</i>	1	16.90	25	12.67	0.89	13.56
73216-T6A-003	MOLDINGL.RR.WINDSHIELD CORNER <i>m</i>	1	16.90	25	12.67	0.89	13.56
73221-SR4-000	SPACERRR.W/SHIELD <i>m</i>	4	3.90	25	11.70	0.82	12.52
73225-TM8-000	RUBBER A WINDSHIELD DAM <i>m</i>	1	3.70	25	2.77	0.19	2.96
73226-SZW-000	DAMPERSTD 5X5 <i>m</i>	2	8.50	25	12.75	0.89	13.64
76711-T6A-003	CAPPIVOT <i>m</i>	1	4.80	25	3.60	0.25	3.85

**KAH MOTOR CO. SDN. BHD.**

(A Member of the Oriental Holdings Berhad)

Service and Body Repair

Tel: +65 6841 3838

Website: www.honda.com.sg

For 24-hours Roadside Assistance, Call 98203838

QUOTATION

GST Reg No.: M200050223

Company Ref. No.: S60FC1380G

Customer : INDIA INTERNATIONAL INSURANCE
64 CECIL STREET
#04-00 & #05-00 IOB BUILDING
SINGAPORE 049711

Registration No : SLH6346D

Chassis No : JHMRC1890GC207015

Model : ODYSSEY2.4 EXV-S 16YM NAVI-RES

Owner's Name : ELSIE TONG PAIK KOON

Ins Policy No. :

Date of Accident : 8/2/2019

Document No. : SQT19000754

Date : 16. Feb 2019

Customer No. : WZI007

Svc Advisor :

Engine No : K24W72013079

Date | Time : 16. Feb 2019 2:01:53 PM

Surveyor Name :

Survey Date :

Authorisation Date :

Page 2

Item	Description	Qty	Unit Price	Disc %	Amount	0% GST Amount	Amount incld GST
BO-WS-SEALANT	WINDSCREEN SEALANT (N) <i>✓</i>	2	60.00		120.00	8.40	128.40
Sum Item					<u>2385.55</u>	<u>166.98</u>	<u>2,552.53</u>
BOSUN	SUNDRIES	1	100.00 <i>30</i>		100.00	7.00	107.00
BOJSE	BODY JOINT SEALANT FOR TAILGATE	1	150.00 <i>120</i>		150.00	10.50	160.50
BOJSE	BODY JOINT SEALANT FOR END PANEL	1	150.00 <i>X</i>		150.00	10.50	160.50
BML02I	INSPECT RR LIGHTING MECHANISMS. PERFORM WATER	1	380.00 <i>280</i>		380.00	26.60	406.60
BA02R	REMOVE & RENEW REVERSE SENSORS-4 PCS (N)	1	380.00 <i>✓</i>		380.00	26.60	406.60
BOMISC1	REMOVE & RE-INSTALL REAR VIEW CAMERA (N)	1	450.00 <i>✓</i>		450.00	31.50	481.50
BOMISC1	RESET & CALLIBRATE SMART ENTRY SYSTEM (N)	1	450.00 <i>✓</i>		450.00	31.50	481.50
BG02R	REPLACE RR. WINDSCREEN.(N)	1	560.00 <i>✓</i>		560.00	39.20	599.20
BODAMKIT	WINDSCREEN DAM KIT.	1	200.00 <i>150</i>		200.00	14.00	214.00
BMI03D	REMOVE & INSTALL REAR COMPARTMENT LININGS	1	800.00 <i>560</i>		800.00	56.00	856.00
BKRP02M	CUT OFF & RENEW RR PANEL. RENEW ALL DAMAGE PARTS	1	6000.00 <i>1680</i>		6000.00	420.00	6420.00
BP06R	SPRAY PAINTING ON REPAIRED OR REPLACED AREAS. (6P)	1	3500.00 <i>1350</i>		3500.00	245.00	3745.00
Sum Labor					<u>13120.00</u>	<u>918.40</u>	<u>14,038.40</u>

Survey By

Date & Time

Excess

Status

Signature

*Ram - Hp 90010068**18/02/19 @ 12:40**5 days**for**Reps by paint*

Total Amount 15,505.55 1,085.38 16,590.93

Total (Inclusive of GST) 16,590.93

Printed on 16/2/2019 2:17:04 PM

This is a computer generated invoice. No signature is required.

Part prices are subjected to change without notice.

The above estimated cost of repair do not include any unforeseen damages.

GST Amount is calculated from individual line(s)