



LIU'S BROTHER AUTO ENGINEERING WORKSHOP

No. 1 Kaki Bukit Avenue 6 #01-01 Auto Bay @ Kaki Bukit Singapore 417883

ROB No: 53291793J . Tel: 6741-1730 / 731 . Fax: 6744-5746. Email: liusbro@gmail.com

Invoice/Ref No: YN5941G19018

Estimate

Customer			
Name: AXA Insurance Singapore Pte Ltd	Date: 26-01-19		
Address: Motor Claims Department	Vehicle No: YN5941G		
8 Shenton Way #27-01	Model/Make: Mitsubishi		
AXA Tower Singapore 068811	Canter FEB21ER3SDEB (CBU)		

Item No.	Descriptions Of Parts	Original Quotation / Estimation	Revised Quotation / Cost Of Repair
1	Front Rh Corner Panel <i>CU7</i>	\$ 474.60	
2	Signal Lamp <i>CNA</i>	\$ 313.60	
3	Head Lamp <i>CNA</i>	\$ 672.70	
4	Side Lamp <i>3AS</i>	\$ 235.20	
5	<i>ful</i> Bumper Side <i>o/s 2.5</i>	\$ 340.70	
6	<i>ful</i> Bumper <i>ful 1010-30</i>	\$ 1,117.20	
7	<i>ful</i> "Corporate" Advertisement & Artwork <i>o/s 1010-30</i>	\$ 300.00	
8	To check all wiring & electrical component for proper function Labor for Panel Beating, Cut, Weld, Straighten & Replacing Parts Etc To putty & spray painting & including touch up paint on accident affected area	\$ 60.00 \$ 600.00 \$ 600.00	

Total Parts & Labour of estimate for damaged vehicle \$ 4,714.00

Total amount in Lump Sum Basis for repaired vehicle

SDLS: One Thousand Four Hundred Only



M/s Liu's Brother Auto Engrg Wks

not allocated
labor
mercus 14/2/19
d/s \$ 2650
Wharfedale. Atteridge
Helen

P-3047.1
502
P-1523.55
S.N- 280.00
labor - 870.00
2673.55

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
Signature: