

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORTChina Taiping Insurance (Singapore) Pte. Ltd.
3 Anson Road, #16-00 Springleaf Tower
Singapore 079909**Our File No:** CS/CTI19002744/T1VD3S2
Date: 20/06/2019REFERENCEInsured/Claimant: SNG CHEN YANG PATRICK (SUN ZHENGYANG PATRICK) Policy No: DMPCSN1901751900
Date of Loss: 27/01/2019 Nature of Claim: OD Claim No: SNM19D200502DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SLJ2808D	Engine No:	1ZZ313601
Make & Model:	LOTUS ELISE, 1.6 (M)	Chassis No:	SCCYC11149HN30153
Reg. Date:	09/01/2009 (Man. Year: 2008)	Odometer:	58106 km
Colour:	Yellow		
Engine Capacity:	1794 cc		
Market Value/New Car Price:	S\$105,000.00		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Good	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:	

CONDITION OF TYRES

Front Tyre Size:	175/55R16	Rear Tyre Size:	225/45R17
Front Left Side:	Yokohama 6 mm	Rear Left Side:	Yokohama 6 mm
Front Right Side:	Yokohama 6 mm	Rear Right Side:	Yokohama 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	48,808.00	46,298.00	2,510.00	5.14
Miscellaneous Items	0.00	0.00	0.00	
Labour	13,680.00	11,820.00	1,860.00	13.60
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	62,488.00	58,118.00	4,370.00	6.99
- Excess (S\$)	4,000.00	4,000.00	0.00	0.00
(S\$)	58,488.00	54,118.00	4,370.00	7.47
+ GST 7.00/7.00% (S\$)	4,094.16	3,788.26	305.90	7.47
Nett Amount (S\$)	62,582.16	57,906.26	4,675.90	7.47

INSPECTION

Date of Assignment:	27/02/2019		
Date Inspected:	14/02/2019	Inspected At:	24 LENG KEE ROAD Repairer: EUROSPTS AUTO PTE LTD
Estimated Period of Repair:	0.0 days		

Adjuster: MOHD TAUFIKH BIN HAMID**Manager:** VERON CHEN*NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.*

SPECIAL REMARKS

Due to extensive damage on the chassis under the category of the section 2 of the road traffic act on THE MOTOR VEHICLES (CONSTRUCTION AND USE) (AMENDMENT NO.2) RULES 1989, that: no vehicle shall fitted with replacement chassis or any body part where the chassis is an integral part of the vehicle. and therefore recommend it to be written off as "Total Loss".

EXCLUDE CHECK ITEMS S\$2,510.00 NETT)

TOTAL LOSS ASPECT

Market Value :	\$105,000.00
OMV :	\$38,516.00
PARF Rebate (1) :	\$0
Quota Premium Paid :	\$31,335.00
COE Rebate (2) :	\$31,014.00
Total Rebate (1) + (2) = :	\$31,014.00

The total amount incurred will be Market Value \$105,000.00 minus Total Rebate \$31,014.00 = \$73,986.00 before excess.

The total repair cost will be above \$90,000/-

REPAIR DETAILS

Reference

Part Source:	(Last Synchronised: 11 Mar 2019)	
Parts:	N/A	LOTUS ELISE 1.6 (M) (Model not available in database)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	LKK Auto Consultants Pte Ltd/SLJ2808D/20/06/2019 11:21	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*FRONT BODY CLAMSHELL	Cracked	33,904.00 F	*33,904.00 F
2	1		*BRACKET, CENTRE FRONT CLAMMSHELL	*Check	222.00 F	*- F
3	1		*FASTENER SPIRENUT, M5	Necessary	45.00 F	*45.00 F
4	1		*BRACKET, SIDES FRONT CLAMMSHELL (PAIR)	*Check	228.00 F	*- F
5	1		*BRACKET SHIM FOR FRONT CLAM SHELL 0.5MM	*Check	44.00 F	*- F
6	1		*BRACKET SHIM FOR FRONT CLAM SHELL 1.0MM	*Check	44.00 F	*- F
7	1		*BRACKET, FRONT LINER PANEL MOUNTING (PAIR)	*Check	192.00 F	*- F
8	1		*POP RIVET, FASTENER	Necessary	32.00 F	*32.00 F
9	1		*MOUNTING, FRONT TOWING STRUT	Bent	420.00 F	*420.00 F
10	1		*CENTER FRONT GRILLE	Missing	333.00 F	*333.00 F
11	1		*LH FRONT GRILLE	*Check	316.00 F	*- F
12	1		*RH FRONT GRILLE	Deformed	316.00 F	*316.00 F
13	1		*CLIPS FOR CENTER GRILLE	Necessary	72.00 F	*72.00 F
14	1		*CLIPS FOR CLAMSHELL	Necessary	168.00 F	*168.00 F
15	1		*FASTENER GRILLER SPIGOTS	Necessary	72.00 F	*72.00 F
16	1		*SCREWS FOR OUTER GRILLE	Necessary	36.00 F	*36.00 F
17	1		*CLIPS FOR OUTER GRILLES	Necessary	72.00 F	*72.00 F
18	1		*SEALERS FOR GRILLES	Necessary	144.00 F	*144.00 F
19	1		*FRONT LOGO - LOTUS	Necessary	610.00 F	*610.00 F
20	1		*FRONT CRASH STRUCTURE ASSEMBLY	Cracked	8,490.00 F	*8,490.00 F
21	1		*FRONT UNDERSHIELD PANEL	Bent	930.00 F	*930.00 F
22	1		*SPIRENUTS FOR UNDERSHIELD	Necessary	54.00 F	*54.00 F
23	1		*ALLOY PLATE LH	*Check	84.00 F	*- F
24	1		*ALLOY PLATE RH	*Check	102.00 F	*- F
25	1		*POP RIVET FOR PLATES	*Check	72.00 F	*- F
26	1		*WASHER FOR PLATES	*Check	48.00 F	*- F
27	1		*SIDE IMPACT FOAM LH	*Check	300.00 F	*- F
28	1		*SIDE IMPACT FOAM RH	*Check	342.00 F	*- F
29	1		*BRACKETS FOR FOAMS	*Check	360.00 F	*- F
30	1		*POP RIVETS FOR BRACKETS	*Check	96.00 F	*- F
31	1		*GRILLES FOR CRASH STRUCTURE	*Check	60.00 F	*- F
32	1		*BETASEAL FOR CRASH STRUTURE	Necessary	600.00 F	*600.00 F

F=Franchise part.

Total Parts (\$\$)	48,808.00	46,298.00
---------------------------	------------------	------------------

LKK Auto Consultants Pte Ltd/SLJ2808D/20/06/2019 11:21. Not valid without Reference section.
--

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	DISMANTLE, RE FITTING AND REPAIR.	New	7,680.00	6,720.00
2	RESPRAY FOR FRONT BODY CLAMSHELL.	New	4,500.00	4,000.00
3	SEALERS FOR BODY ATTACHMENT.	New	1,200.00	800.00
4	AIRCON GAS REMOVE AND REFILL.	New	300.00	300.00
Gross Labour Cost (\$\$)			13,680.00	11,820.00

LKK Auto Consultants Pte Ltd/SLJ2808D/20/06/2019 11:21. Not valid without Reference section.

< END OF ESTIMATES >