

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

To: MSIG Insurance (Singapore) Pte. Ltd.
4 Shenton Way
#21-01 SGX Centre 2
Singapore 068807

From: LKK Auto Consultants Pte Ltd
51 Ubi Ave 1 #01-25
Paya Ubi Industrial Park
Singapore 408933

Attn: Christina Wong

Date: 15 Feb 2019

Preliminary Advice

Insured Vehicle No	: GBF8703Y	Accident Date	: 04/02/2019
TP Vehicle No	: SGF6719G	Assignment Date	: 13/02/2019
Make	: TOYOTA COROLLA	Est. Duration of Repair	: 5.00
Date of Inspection	: 13/02/2019		
Inspection At	: MY CAR CONSULTANT - UBI (HQ) 53 PAYA UBI INDUSTRIAL PARK, #01-33 SINGAPORE 408934		

Point of Impact / General Description of Damages

The vehicle sustained impact / damages rear portion and parts claimed are consistent to the accident.

Repairer's Estimate (Gross)	:S\$	11,017.00
Revised Amount	:S\$	4,508.50
Check Items (Estimated)	:S\$	0.00
Total	:S\$	4,508.50

Lump Sum Repair	:S\$	
-----------------	------	--

Total Loss Consideration

New for Old Value	:S\$	
Pre-Accident Value	:S\$	
COE / PARF Rebate	:S\$	
Salvage Value	:S\$	
Margin for Repair	:S\$	

Remarks

- () The vehicle is economical/not economical for repair.
- (X) The above survey was conducted on a 'without prejudice' basis.