

2/01/2002

ASS. REC. BY:

REF:

CS/INC19002767/71sd302

Special Instruction:

Surveyor:

Taufelch

ASSIGNMENT (Office)

From (Person):

Daniel Koh

of

INC

Date/Time:

14/2/1999 9:30am

Estimated Cost:

Bill to:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No:

GBC 1437C

Insured:

SM @ 4036E

at Workshop m/s

BP Auto

Tel:

62660555

of

48th Green Rd East #01-121

Policy No:

Claim No:

MT-1030397-002

Sum Insured:

Excess:

Make of Veh:

(Client's Record)

D.O.A.

30/1/19

CA / REV / REP. / REV 24 HRS

1up

H.O.D. Endorsement:

Date/Time:

12:17pm 14/2/1999

Person Contacted:

Ivonne

Vehicle IN/OUT

Date/Time

Action/Instruction

(✓)

Estimate

Tanfich

REF:

INC

LoE 2021 June

20/1 June

From: _____ Date: _____
Estimated Cost: _____
OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To inspect Vehicle No: _____

at Workshop m/s _____

of _____

Insured _____

Policy No: _____

Claims No: _____

Sum Insured: _____

Excess: _____

(Client's Record)

Make of Veh: _____

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.

N/S	O/S

Bal. or Market Value: _____

925K

IDAC Accident Report: _____ Consistent? : Yes or No

GIA / PR Seen: _____ Consistent? : Yes or No

Est. Repairs: _____ days Res.: Yes or No

Lum Sum: _____ % 3 Val: Yes or No

CA / REV / REP. / 24 HRS :

Date: _____

Person Contacted: _____

Vehicle: IN / OUT

Winn

Veh No: _____

GR614370

Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make: _____

Toyota Dyna

CC 2982

Colour: _____

blue

A/C Insured / Std / NI / NA

Sp. Reading _____

352324

T/Radio: Insured / Std / NI / NA

Eng/No: _____

C/No: _____

JTFAT35900K24548

Gen. Cond: Good / Fair / Poor / Burnt

Steering: Inorder / Jammed / Leaked / Burnt or

Brake: Inorder / Jammed / Leaked / Burnt or

Modi: (N) / S/Rim / STD A/Rim or

Tyre Size: _____

F: _____

195/R15

R: _____

155/R12

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

Front

Rear

R/Bal. _____

5

mm

R/Bal. _____

3/5

mm

L/Bal. _____

5

mm

L/Bal. _____

5/5

mm

D.O.A. _____

D.O.I. _____

14/2/19

0112pm

Survey held at _____

BP Auto

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

Frt O/S

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time Action / Instruction

29/8

4/54 16,000, 1.0 days

confirm with Winn

C\$26,105.49 Red - 62%?

Tanfich

pls see my remarks.

29/8/2019

Date/Time File Pass to?

29/08/19

1)

Typist

Date/Time File Return to?

☐

: Preli. Report

☒

: Final Report

Days Of Repair: _____

10

Resurvey No. of Trip: _____

2

Survey Fee: _____

Transportation _____

1) 1st Rpt. \$

2) 2nd Rpt. \$

3) 3rd Rpt. \$

4) 4th Rpt. \$

Total

Add Fee: _____

☐

Site Insp. (\$

☐

Interview (\$

☐

Each Trip (\$

☐

Workload (\$

Report Format :

Lump Sum / LB R/S 16,000/- HS

290

290

Nivitha (LKK Auto)

From: Daniel Koh <daniel.koh@income.com.sg>
Sent: Thursday, 14 February 2019 9:26 AM
To: 'assignments@lkkauto.com'
Cc: Teng Ken Leong; Thio Tse Kiat
Subject: FW: TP CASES FARMED OUT TO LKK ON 14/2/2019

Dear Veron / Nivitha,

Please assist to survey the vehicles as per Mr Teng's instruction :-

S/NO	THIRD PARTY	OUR INSURED	WORKSHOP / CONTACT	DOA / REF / OFFICER
1	GBC1437C	SMG4036E	BP AUTO / 62660555	30-1-2019 / MT-1030397-002 / Fiona Shen
2	SLQ4070P	SJP1689D	WORLD AUTO / Ainee 63621776	12-2-2019 / MT-1031899-001 / Fiona Shen

Please contact workshops.

Please ack.

Thank You

Daniel Koh
Senior Admin Assistant, Motor Insurance
T +65 6430 7901
www.income.com.sg



Disclaimer

This e-mail contains privileged or confidential information which is intended only for the use of the

recipient(s) named above. If you have received this message in error, please notify the sender immediately and delete all copies of it. Thank you.

[> Back to OneMotoring](#)**Enquire PARF/COE Rebate for Registered Vehicle****Vehicle Owner Particulars**

Owner ID Type: Company

Owner ID: 5967R

Vehicle Details

Vehicle No.: GBC1437C

Vehicle to be Exported: No

Intended
Deregistration Date: 15 Feb 2019

Vehicle Make: TOYOTA

Vehicle Model: DYNA 150 MANUAL
3SEATER

Primary Colour: Silver

Manufacturing Year: 2011

Engine No.: 1KD2097985

Chassis No.: JTFAT35Y00K201548

Maximum Power

Output: -

Open Market Value: \$24,970.00

Original Registration
Date: 23 Jun 2011

First Registration Date: 23 Jun 2011

Transfer Count: 0

Actual ARF Paid: \$1,249.00

Intended PARF Rebate Details

PARF Eligibility: No

PARF Eligibility Expiry
Date: -

PARF Rebate Amount: \$0.00

Intended COE Rebate Details

COE Expiry Date: 22 Jun 2021

COE Category: C - Goods Vehicle &
Bus

COE Period(Years): 10

QP Paid: \$22,989.00

COE Rebate Amount: \$5,408.00

Total Rebate Amount: \$5,408.00

The information contained herein is correct as at 15 Feb 2019

OK

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. **Any false reporting may be referred to the Police for investigation.**
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT

Date Of Report	01/02/2019 11:28
Date Of Accident	30/01/2019 17:35
Exact Location Of Accident	JURONG GATE WAY RD
Country/State of Loss	SINGAPORE

DETAILS OF OWN VEHICLE

Vehicle Registration Number	GBC1437C
Insured/Policyholder	
Name Of Registered Owner	APEX SEALING TECHNOLOGIES PTE LTD
Co Reg No	200905967R
Email Address	NOEMAIL
Mobile Phone No	(LOCAL) +65-93708559
Alternative Phone No	OFFICE-93708559

Vehicle Particulars

Manufacturer	TOYOTA
Model	DYNA 150-3.0 D (M)
Exact Purpose for which vehicle was being used at time of accident	
Are you claiming under your own insurance policy for repair to your vehicle?	NO
If No, Please state action to be taken	THIRD PARTY
Vehicle Category	COMMERCIAL VEHICLE

Insurance Company

Name of Insurance Company	ERGO INSURANCE PTE. LTD.
Type Of Coverage	COMPREHENSIVE
Fleet Policy	NO
Policy Number	DMCV18S005316
Cover Note Number	

Driver

Name of Driver	LIU XIAO GUANG
Passport No/FIN	G8332623P
Date Of Birth	10/05/1977
Occupation	OUTDOOR
Date Of Driving Pass	11/05/2009
Driving Experience	9 YEARS AND 8 MONTHS
Gender	MALE
Mobile Number	(LOCAL) +65-93708559
Fax Number	
Contact Number	OFFICE-93708559
E Mail Address	NOEMAIL

Address 648 JURONG WEST #02-08

Postcode

Was driver an employee of the Insured's Company YES

If No, Relationship of the Driver with the Insured

Vehicle Registration Number of Driver's Own Vehicle -

Insurance Company of Driver's Own Vehicle -

General Information of the Accident

Type Of Accident COLLISION - HEAD ON COLLISION

Weather Conditions CLEAR

Road Surface DRY

Other Information

Was any foreign vehicle involved in this accident? NO

Number of vehicles (including own vehicle) involved in the accident 1

Was any body injured in the Accident? NO

Was any injured conveyed to hospital by ambulance? NO

Was any other material or property damaged? YES

I have been approached by unknown person(s) soliciting/offering accident claims assistance. NO

Number of Passengers (Including Driver) 1

Details of Police Action

Was the accident reported to the police? YES

If Yes, Please state which Police Station

Police Station Name JURONG NPP

Police Station Address ROAD: 158 YUNG LOH ROAD #01-58 , POSTCODE: 610158 , COUNTRY: SINGAPORE

Police Station Contact TEL NO: - FAX NO:

Was notice of intended Prosecution given? NO

If Yes, against whom?

Circumstances of Accident

REFER TO POLICE REPORT

Attachment(s)

Are accident photos available for attachment? YES

Was there any video captured by Car Camera? NO

Was there any audio recorded? NO

DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number SMG4036E

Vehicle Make/Model/Colour

Details Of Properties

Vehicle Category PRIVATE CAR

Name of Driver

NRIC/Passport Number

Contact Number

Address

Postcode

Insurance Company Name

Nature Of Damage

No. Of Passenger (Including Driver)

DESCRIBE CIRCUMSTANCES OF THE ACCIDENT

DECLARATION

Reporting Centre Personnel's Signature
Name:
NRIC/FIN No.:

SKETCH PLAN

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. The report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgment of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.
8. Consent under the Personal Data Protection Act (PDPA)

I understand, acknowledge, agree and consent that:

- (a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this [form] and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the Insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of:
 - (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
 - (ii) investigating the accident and/or my claims;
 - (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
 - (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
 - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims.(collectively the "Purposes")
- (b) all insurer(s) who have insured vehicle(s) involved in this accident and the Insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
- (c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third party service providers or agents(including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.
- (d) my Personal Information will also be collected and used to compile claims history for the purpose of fraud detection, investigation and management in present and all future claims.
- (e) the information so collected under (d) above may be shared / disclosed:
 - (i) to all insurers and/or any other third parties that assist in evaluating, investigating, controlling or managing fraud, regulators, law enforcement and government agencies as reasonably required for the purposes stated, or
 - (ii) for complying with requirements under any regulations, laws or court orders.

Policyholder's Signature
Date & Time:



Driver's Signature
(If driver is not the policyholder)
Date & Time:

Reporting Centre Personnel's Signature
Name:
NRIC/FIN No.:



**SINGAPORE
POLICE FORCE**



T/20190130/2161

Police Station Of Origin:
Jurong West N.P.C
700 Corporation Road SINGAPORE 649818
Tel No: 1800-2689999

1 of 3

Report No. T/20190130/2161

REPORT OF A TRAFFIC ACCIDENT

Date/Time Report Made: 30/01/2019 20:22	Vide Report No.: D/20190130/0092	Station Diary No.: 200
--	-------------------------------------	---------------------------

Informant's Particulars			
Name of Informant: LIU XIAOGUANG		Address: APT BLK 648 jurong west #02-08 SINGAPORE	
ID Type / ID No.: FIN NO / G8332623P		Contact No.: Home/Office: Mobile: 93708559	
Nationality: CHINESE		Email:	
Sex: Male	Age: 41	Date of Birth: 10/05/1977	Type of Informant: Driver
Race: Chinese		Language: Mandarin	Institution / School Name:
Occupation: Van driver		Driving Licence Information: Class: 3	Date of Expiry:

General Information of the Accident				
Type of Accident:	Non-Injury Attended by Police	Drink Drive: No	Date/Time of Accident: 30/01/2019 17:35	Type of Location: X-Junction
Location: Along Road 1 JURONG GATEWAY ROAD JURONG EAST STREET 21 JUNCTION				
Weather: Clear		Road Surface: Dry	Road Speed Limit:	
Traffic Flow: Two Way		Traffic Control: Traffic Light - Working	Traffic Volume:	
Type of Collision: Between Moving Vehicles - Head To Side			Anyone conveyed by ambulance: No	

Details of Vehicle Involved						
Vehicle No.	Type	Make	Model	Color	Condition	No of Passenger
GBC1437C	Lorry					0
SMG4036E	Car					0

Details of Person Involved	
Any Pedestrian Involved: No	
No. of Pedestrians Injured: NIL	Use of Pedestrian Crossing: NA



**SINGAPORE
POLICE FORCE**



T/20190130/2161

Police Station Of Origin:
Jurong West N.P.C
700 Corporation Road SINGAPORE 649818
Tel No: 1800-2689999

2 of 3

Report No. T/20190130/2161

CONTINUATION OF REPORT

Driver			
Name	LIU XIAO GUANG	ID No.	G8332623P
Related Vehicle	GBC1437C (Lorry)	Contact No.	93708559
Hospital/Clinic	NIL	Class of Driving Licence & Expiry Date	Class: 3 Date of Expiry: NIL
Date Treatment	NIL	Date Discharge	NIL
No. of Days granted Medical Leave	NIL	Degree of Injury	NIL
Driver			
Name	TAN HUI PIN	ID No.	S1557135G
Related Vehicle	SMG4036E (Car)	Contact No.	NIL
Hospital/Clinic	NIL	Class of Driving Licence & Expiry Date	Class: NIL Date of Expiry: NIL
Date Treatment	NIL	Date Discharge	NIL
No. of Days granted Medical Leave	NIL	Degree of Injury	NIL

Brief Details.

On 30.1.2019 at about 1735hrs, I am driving along the middle lane of the said road and the traffic light was green at the traffic junction. After I have crossed the junction, a car suddenly collided into the front right side of my lorry when making an U turn at the said junction from the opposite direction. The impact caused my lorry to move toward the inner lane but I managed to stop my lorry. However, the said car crashed into the road divider and railings after the collision. However, nobody was injured but I called Police immediately. The female driver called her male friend to the scene and passed her ID to him before leaving the accident scene when Traffic Police has yet to arrive. I managed to take her particulars from the said male person and told Traffic Police of the incident. The right front side of my lorry was badly damaged and I am lodging the report for insurance. The lorry belongs to my company APEX SEALING TECHNOLOGIES PTE LTD.



**SINGAPORE
POLICE FORCE**



T/20190130/2161

Police Station Of Origin:
Jurong West N.P.C
700 Corporation Road SINGAPORE 649818
Tel No: 1800-2689999

3 of 3


Report No. T/20190130/2161

CONTINUATION OF REPORT

Sketch Plan

Informant is not able to provide sketch plan

IMPORTANT: Please attach a copy of your vehicle's Insurance Certificate to this report. If you don't have the certificate with you now, please fax a copy to 65474885 stating the report number as reference.

Signature Of Officer Recording The Report: J / SI LIM YEN FANG	Signature Of Informant: 
Signature Of Interpreter: Not applicable	Date/Time: 30/01/2019 20:22
Officer In Charge Of Case: TP / GIT / SI MOHAMMAD SHAHRIL BIN ABDULLAH Contact No.: 65476083	Classification Of Case:
Authentication Stamp NP168	

BP Auto
(UEN No. 53378133K)
1 Soon Lee Street, #04-45
Pioneer Centre, S (627605)
Tel: 6262 4438 Fax : 6484 1111

TO : NTUC Income Insurance ATTENTION : MOTOR CLAIMS DEPARTMENT ESTIMATE REPORT : OWNER PARTICULAR NAME : ADDRESS : TEL. NO. : OWNER INSURANCE : ERGO POLICY NO. : DMCV18S005316 PERSON INCHARGE : 6266 0555	DATE : 13-Feb-19 JOB TYPE : T/P CLAIMS VEHICLE DETAILS VEHICLE NO. : GBC1437C MODEL / MAKE : TOYOTA DYNA CHASSIS NO. : JTFAT35Y00K201548 ACCIDENT DETAIL DATE : 30-Jan-19 TIME : 17:35 hrs
--	---

QUOTATION SUMMARY

PAGE 01

CLAIMS DETAIL : PARTS LIST

S/N	DESCRIPTION	QTY	UNIT LIST PRICE	TOTAL LIST PRICE
1	FRONT DOOR RH <i>bt</i>	1	\$ 1,218.90	\$ 1,218.90
2	FRONT DOOR RH GLASS OUTER MOULDING <i>de</i>	1	\$ 168.60	\$ 168.60
3	FRONT DOOR RH OUTER LOCK HANDLE <i>de</i>	1	\$ 128.60	\$ 128.60
4	FRONT DOOR OUTER KEY LOCK <i>x nn</i>	1	\$ 294.80	\$ 294.80
5	FRONT DOOR HINGES <i>bt</i>	2	\$ 78.90	\$ 157.80
6	FRONT DOOR WIRE HARNESS <i>x nn</i>	1	\$ 1,893.70	\$ 1,893.70
7	FRONT DOOR INNER TRIM BOARD <i>de</i>	1	\$ 942.60	\$ 942.60
8	FRONT DOOR INNER LOCK HANDLE <i>x nn</i>	1	\$ 109.70	\$ 109.70
9	FRONT DOOR SPEAKER <i>de</i>	1	\$ 454.10	\$ 454.10
10	FRONT DOOR POWER WINDOW MOTOR <i>bt</i> <i>photo</i>	1	\$ 596.30	\$ 596.30
11	FRONT DOOR POWER WINDOW REGULATOR <i>bt</i> <i>photo</i>	1	\$ 436.60	\$ 436.60
12	FRONT DOOR POWER WINDOW CHANNEL <i>de</i>	1	\$ 124.10	\$ 124.10
13	FRONT DOOR POWER WINDOW MAIN CONTROL SWITCH <i>x nn</i>	1	\$ 392.80	\$ 392.80
14	FRONT DOOR LOWER RUBBER SEAL <i>de</i>	1	\$ 164.40	\$ 164.40
15	FRONT DOOR WEATHERSTRIP <i>nn</i>	1	\$ 278.40	\$ 278.40
16	FRONT DOOR CHECKER <i>x nn</i>	1	\$ 121.30	\$ 121.30
17	FRONT DOOR LOCK STROKER <i>x nn</i>	1	\$ 42.10	\$ 42.10
18	FRONT DOOR MECHANISM LOCK <i>bt</i>	1	\$ 399.50	\$ 399.50
19	FRONT DOOR PILLAR PANEL 'OUTER' <i>bt</i>	1	\$ 1,944.30	\$ 1,944.30
20	FRONT DOOR PILLAR PANEL 'INTER' <i>Rr</i>	1	\$ 1,894.20	\$ 1,894.20
21	FRONT DOOR PILLAR PANEL SUPPORT FRAME <i>Rr</i>	1	\$ 979.30	\$ 979.30
22	FRONT DOOR PILLAR WATER STRIP <i>ad</i>	1	\$ 227.20	\$ 227.20
23	FRONT DOOR SWITCH <i>x nn</i>	1	\$ 28.60	\$ 28.60
24	FRONT SIDE MIRROR RH <i>x nn</i>	1	\$ 156.70	\$ 156.70
25	FRONT DOOR OUTER GARNISH VERTICAL <i>x nn</i>	1	\$ 58.10	\$ 58.10
26	FRONT DOOR STEP PANEL <i>bt</i>	1	\$ 148.20	\$ 148.20
27	FRONT DOOR STEP PANEL GARNISH <i>nn</i>	1	\$ 291.80	\$ 291.80

768140

QUOTATION SUMMARY

PAGE 02

CLAIMS DETAIL : PARTS LIST

S/N	DESCRIPTION	QTY	UNIT LIST PRICE	TOTAL LIST PRICE
28	FRONT WINDACREEN GLASS <i>am</i>	1	\$ 1,247.40	\$ 1,247.40
29	FRONT WINDSCREEN GLASS RUBBER MOULDING <i>ne</i>	1	\$ 276.30	\$ 276.30
30	FRONT WINDSCREEN GLASS INNER GARNISH RH <i>? Xun</i>	1	\$ 269.30	\$ 269.30
31	FRONT PANEL <i>bt</i>	1	\$ 895.90	\$ 895.90
32	FRONT PANEL APRON GARNISH "CENTRE" <i>cut</i>	1	\$ 291.90	\$ 291.90
33	FRONT PANEL APRON GARNISH LH / RH <i>bt</i>	2	\$ 101.20	\$ 202.40
34	FRONT PANEL DYNA EMBLEM <i>ne</i>	1	\$ 58.30	\$ 58.30
35	FRONT CORNER SIDE PANEL RH <i>bt</i>	1	\$ 233.90	\$ 233.90
36	FRONT GRILLE <i>cut</i>	1	\$ 429.80	\$ 429.80
37	FRONT GRILLE EMBLEM <i>ve</i>	1	\$ 54.70	\$ 54.70
38	FRONT GRILLE BRACKET <i>? X un</i>	1	\$ 109.20	\$ 109.20
39	FRONT WIPER PANEL <i>Ry</i>	1	\$ 479.60	\$ 479.60
40	FRONT WIPER PANEL CORNER SIDE GARNISH LH / RH <i>Ry</i>	2	\$ 386.90	\$ 773.80
41	HEADLAMP RH <i>am</i>	1	\$ 328.95	\$ 328.95
42	HEADLAMP LOWER RUBBER SEAL RH <i>ne</i>	1	\$ 47.20	\$ 47.20
43	HEAD LAMP CLIPS RH <i>ne</i>	1	\$ 9.80	\$ 9.80
44	HEADLAMP INNER PANEL RH <i>bt</i>	1	\$ 261.00	\$ 261.00
45	HEADLAMP LH <i>X un</i>	1	\$ 328.95	\$ 328.95
46	HEAD LAMP LOWER RUBBER SEAL LH <i>X un</i>	1	\$ 47.20	\$ 47.20
47	HEADLAMP CLIPS LH <i>X un</i>	1	\$ 9.80	\$ 9.80
48	FRONT BUMPER <i>bt</i>	1	\$ 356.90	\$ 356.90
49	FRONT BUMPER BRACKET LH / RH <i>bt</i>	2	\$ 193.20	\$ 386.40
50	FRONT DASHBOARD <i>? de</i>	1	\$ 1,689.10	\$ 1,689.10
51	FRONT DASHBOARD INNER SUPPORT FRAME <i>? bt</i>	1	\$ 894.50	\$ 894.50
52	FRONT WHEEL HOUSE PANEL RH <i>? bt</i>	1	\$ 538.90	\$ 538.90
53	FRONT WHEEL HOUSE PANEL TOP GARNISH RH <i>? de</i>	1	\$ 356.00	\$ 356.00
54	FRONT WHEEL HOUSE ARCH RUBBER SEAL RH <i>de</i>	1	\$ 21.30	\$ 21.30
55	FRONT MUDGUARD RH <i>X un</i>	1	\$ 258.90	\$ 258.90
56	FRONT MUDGUARD MUFLAP RH <i>X un</i>	1	\$ 181.40	\$ 181.40
57	FRONT CABIN BACK GUARD PANEL <i>Ry</i>	1	\$ 1,437.80	\$ 1,437.80
58	FRONT CABIN BACK SIDE CORNER PANEL RH <i>bt</i>	1	\$ 1,944.30	\$ 1,944.30
59	FRONT CABIN BACK SIDE CORNER PANEL D4D EMBLEM <i>ne</i>	1	\$ 78.80	\$ 78.80
60	FRONT CABIN FLOOR PANEL <i>Ry bt</i>	1	\$ 589.70	\$ 589.70
61	FRONT CABIN FLOOR PANEL TOP MAT <i>Ry</i>	1	\$ 697.90	\$ 697.90
62	FRONT CABIN HANDLE LOCK <i>? bt</i>	1	\$ 312.40	\$ 312.40
63	FRONT CABIN MECHANISM LOCK LH / RH <i>? bt</i>	2	\$ 223.40	\$ 446.80
64	FRONT CABIN HINGES LH / RH <i>? bt</i>	2	\$ 397.90	\$ 795.80
65	FRONT CABIN HINGES BRACKET LH / RH <i>? bt</i>	2	\$ 187.20	\$ 374.40
66	FRONT CABIN HINGES RUBBER SEAL LH / RH <i>Xun</i>	2	\$ 72.80	\$ 145.60
67	FRONT CABIN HINGES SHAFT ASSY <i>? bt</i>	1	\$ 458.70	\$ 458.70
68	FRONT CABIN HINGES CROSS BRACKET <i>? bt</i>	1	\$ 279.40	\$ 279.40
69	FRONT CABIN RUBBER GUIDE MOUNTING LH / RH <i>? bt</i>	2	\$ 123.40	\$ 246.80
70	RADIATOR <i>? X un</i>	1	\$ 1,422.10	\$ 1,422.10
71	RADIATOR FAN BLADE <i>? Xun</i>	1	\$ 217.60	\$ 217.60
72	RADIATOR FAN COWLING <i>? Xun</i>	1	\$ 329.40	\$ 329.40
73	RADIATOR FAN CLUTCH COIL <i>? X un</i>	1	\$ 457.90	\$ 457.90
74	FRONT POWER STEERING BOX <i>X un</i>	1	\$ 3,869.40	\$ 3,869.40

2721.45

13223.65

QUOTATION SUMMARY

PAGE 03

CLAIMS DETAIL : PARTS LIST

S/N	DESCRIPTION	QTY	UNIT LIST PRICE	TOTAL LIST PRICE
75	FRONT POWER STEERING BOX INTERMEDIATE SHAFT <i>Xnn</i>	1	\$ 1,794.60	\$ 1,794.60
76	ENGINE MOUNTING LH/RH <i>? Xnn</i>	2	\$ 241.70	\$ 483.40
77	GEAR BOX MOUNTING <i>? Xnn</i>	1	\$ 189.25	\$ 189.25
78	FRONT SUSPENSION SHOCK ABSORBER RH <i>x nn</i>	1	\$ 359.60	\$ 359.60
79	FRONT SUSPENSION KNUCKLE ARM RH <i>x nn</i>	1	\$ 294.10	\$ 294.10
80	FRONT SUSPENSION KNUCKLE ARM BEARING RH <i>x nn</i>	1	\$ 189.20	\$ 189.20
81	FRONT SUSPENSION STEERING TIE ROD <i>x nn</i>	1	\$ 194.20	\$ 194.20
21694.75 <i>20905.05</i>				TOTAL PRICE \$ 42,300.65
16271.06 <i>16271.06</i>				LESS -25% \$ (10,575.16)
				SUB TOTAL PRICE \$ 31,725.49

CLAIMS DETAIL : S/N LIST

S/N	DESCRIPTION	QTY	UNIT S/NETT	TOTAL S/NETT
1	FRONT DOOR COMPANY DETAIL STICKER <i>nr</i>	1	\$ 180.00	\$ <i>50</i> 180.00
2	FRONT DOOR INNER TRIM BOARD CLIPS SET <i>nr</i>	1	\$ 60.00	\$ <i>30</i> 60.00
3	FRONT DOOR STEP PANEL GARNISH CLIPS SET <i>nr</i>	1	\$ 30.00	\$ <i>10</i> 30.00
4	FRONT WINDSCREEN GLASS ERP BRACKET <i>nr</i>	1	\$ 50.00	\$ <i>20</i> 50.00
6	FRONT PANEL SEALANT <i>nr</i>	1	\$ 80.00	\$ <i>40</i> 80.00
7	FRONT PANEL APRON GARNISH CLIPS SET <i>x nn</i>	1	\$ 80.00	\$ 80.00
8	FRONT GRILLE CLIPS SET <i>x nn</i>	1	\$ 90.00	\$ 90.00
9	HEADLAMP BULB RH <i>? Xnn</i>	1	\$ 40.00	\$ 40.00
10	HEADLAMP SIGNAL BULB RH <i>? Xnn</i>	1	\$ 15.00	\$ 15.00
11	HEADLAMP SMALL BULB RH <i>? Xnn</i>	1	\$ 10.00	\$ 10.00
12	FRONT NUMBER PLATE <i>bt</i>	1	\$ 15.00	\$ <i>✓</i> 15.00
13	FRONT WHEEL HOUSE PANEL TOP GARNISH CLIPS SET <i>nr</i>	1	\$ 40.00	\$ <i>10 10</i> 40.00
14	FRONT WHEEL HOUSE PANEL SEALANT RH <i>nr</i>	1	\$ 80.00	\$ <i>40</i> 80.00
15	FRONT CABIN FLOOR PANEL INSULATOR MAT <i>x nn</i>	1	\$ 380.00	\$ 380.00
16	FRONT CABIN FLOOR PANEL SEALANT <i>x nn</i>	1	\$ 150.00	\$ 150.00
17	FRONT CABIN BACK GUARD PANEL SEALANT <i>x nn</i>	1	\$ 180.00	\$ 180.00
18	RADIATOR COOLANT <i>? Xnn</i>	1	\$ 80.00	\$ 80.00
19	FRONT 16' STEEL RIM <i>ry</i>	1	\$ 380.00	\$ 380.00

TOTAL

\$ 1,940.00

215

215

CLAIMS DETAIL : LABOUR CHARGES AND SPRAY PAINTING

TO DISMANTLE & REPLACED WITH PANEL BEATING ALL THE ACCIDENT PORTION	\$ 3,000.00	1500	
TO SPRAY PAINTING ALL THE ACCIDENT PORTION & POLISHING AFFECTED AREA	\$ 2,600.00	1400	
TO APPLY ANTI-RUST & TUFF KOTE	\$ 120.00	50	
TO PERFORM LIGHTING & WIRING CHECK	\$ 120.00	20	
TO DISMANTLE & REINSTALL FRONT DOOR INNER COMPONENT MECHANISM RH TO FACILITATE REPAIR WITH CHECKING	\$ 250.00	60	
TO CALIBRATE CHASSIS & CAR BODY BACK TO MANUFACTURING SPECIFICATION	\$ 380.00	? Xnn	
TO DISMANTLE & REINSTALL FRONT WINDSCREEN PERFORM WITH WATER LEAK TEST	\$ 150.00	120	
TO DISMANTLE & REINSTALL INTERIOR CARPET WITH OTHER ATTACHMENT PARTS COMPONENT TO FACILITATE REPAIR	\$ 280.00	80	
TO PERFORM CONDUCT WATER LEAKAGE TEST OF ACCIDENT PORTION	\$ 80.00	40	
TO DISMANTLE & REPLACED FRONT UNDER CARRIAGE COMPONENT RH TO PERFORM FACILITATE REPAIRS	\$ 280.00	150 Xnn	plnt.
TO DISMANTLE & REPLACED FRONT DASHBOARD, EVAPORATOR UNIT, WIRE HARNESS SET, RADIO COMPONENT WITH OTHER ATTACHMENT PARTS	\$ 800.00	200	plnt.
TO DISMANTLE & REINSTALL ENGINE & GEARBOX COMPONENT TO FACILITATE REPAIR	\$ 380.00	200 ? ⁿⁿ X	plnt.

TOTAL

\$ 8,440.00

9480

3480

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

ESTIMATE REPORT

TOTAL PARTS COST	:	\$	33,665.49
TOTAL LABOUR COST	:	\$	8,440.00
TOTAL REPAIR COST	:	\$	<u>42,105.49</u>

APPROVED DETAILS

EXCESS :
 NO. OF REPAIR DAYS :
 RE-SURVEY :
 P / P OR L / S :

DATE / TIME OF SURVEY :
 SURVEYED BY / FROM :
 CONTACT NUMBER :
 FAX NUMBER :
 EMAIL ADDRESS :

[Signature]
 20/2/10

Tanpin 97495747 / 87418434

sur@khaato.com

lunysun

Repay after repair

Check repair limit

10 days.

16271.06

215

3480

19966.06

115\$ 16,000 * 10 days

19966.06

\$16,000



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

DAMAGE ASSESSMENT REPORT

NTUC INCOME INSURANCE CO-OPERATIVE LTD Ref: CS/INC19002767/T1sd3e2

73 BRAS BASAH ROAD

Date: 04-09-2019

#05-01 NTUC TRADE UNION HOUSESINGAPORE
189556



ATTN : FIONA SHEN

Code: INC

1. Policy Particulars :- THIRD PARTY CLAIM

Insured Veh.	SMG 4036E	Veh. Inspected	GBC 1437C
Policy No.		Coverage (\$)	0.00
Claim No.	MT-1030397-002	Excess (\$)	0.00
Assign From	DANIEL KOH	Assign Date	14/02/2019

2. Vehicle Particulars & Condition

Make & Model	TOYOTA DYNA	c.c	2982
Engine No.	HIDDEN	Year of Reg.	2011
Chassis No.	JTFAT35Y00K201548	Colour	SILVER
Odometer	352324 KM	Steering	IN ORDER
Brakes	IN ORDER	Modification	NIL
General	GOOD		

3. Conditions of Tyres

	Size	Make	Balance
R/H Front Tyre	195 R15	BRIDGESTONE	5 mm
L/H Front Tyre	195 R15	BRIDGESTONE	5 mm
R/H Rear Tyre	155 R12 (D)	BRIDGESTONE	5/5 mm
L/H Rear Tyre	155 R12 (D)	BRIDGESTONE	5/5 mm

4. Description of Damages

THE VEHICLE SUSTAINED DAMAGES AT THE FRONT O/S PORTION. DAMAGES SEE DETAILS.

5. General Information

Accident Date	30/01/2019	Inspect Date / Time	14/02/2019 (01:12 PM)
Survey held at	BP AUTO-48 TOH GUAN RD EAST#01-121		
Repairer	-		

5a. Remarks

A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.
--

5b. Estimate Days of Repair

ESTIMATED NORMAL PERIOD FOR REPAIR:	10 Working Days
-------------------------------------	-----------------

**LKK Auto Consultants Pte Ltd**

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 5

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. GBC 1437C

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	<u>REPLACEMENT OF PARTS</u>			
1	FRONT DOOR RH	BENT	1,218.90	1,218.90
1	FRONT DOOR RH GLASS OUTER MOULDING	DEFORMED	168.60	168.60
1	FRONT DOOR RH OUTER LOCK HANDLE	DISTORTED	128.60	128.60
1	FRONT DOOR OUTER KEY LOCK	NOT NECESSARY	294.80	-
2	FRONT DOOR HINGES @\$78.90	BENT	157.80	157.80
1	FRONT DOOR WIRE HARNESS	NOT NECESSARY	1,893.70	-
1	FRONT DOOR INNER TRIM BOARD	DEFORMED	942.60	942.60
1	FRONT DOOR INNER LOCK HANDLE	NOT NECESSARY	109.70	-
1	FRONT DOOR SPEAKER	DEFORMED	454.10	454.10
1	FRONT DOOR POWER WINDOW MOTOR	BENT	596.30	596.30
1	FRONT DOOR POWER WINDOW REGULATOR	BENT	436.60	436.60
1	FRONT DOOR POWER WINDOW CHANNEL	DEFORMED	124.10	124.10
1	FRONT DOOR POWER WINDOW MAIN CONTROL SWITCH	NOT NECESSARY	392.80	-
1	FRONT DOOR LOWER RUBBER SEAL	DEFORMED	164.40	164.40
1	FRONT DOOR WEATHERSTRIP	NECESSARY	278.40	278.40
1	FRONT DOOR CHECKER	NOT NECESSARY	121.30	-
1	FRONT DOOR LOCK STRIKER	NOT NECESSARY	42.10	-
1	FRONT DOOR MECHANISM LOCK	BENT	399.50	399.50
1	FRONT DOOR PILLAR PANEL 'OUTER'	BENT	1,944.30	1,944.30
1	FRONT DOOR PILLAR PANEL 'INTER'	TO REPAIR SEE LABOUR	1,894.20	-
1	FRONT DOOR PILLAR PANEL SUPPORT FRAME	TO REPAIR SEE LABOUR	979.30	-
1	FRONT DOOR PILLAR WATER STRIP	CUT	227.20	227.20
1	FRONT DOOR SWITCH	NOT NECESSARY	28.60	-
1	FRONT SIDE MIRROR RH	NOT NECESSARY	156.70	-
1	FRONT DOOR OUTER GARNISH VERTICAL	NOT NECESSARY	58.10	-
1	FRONT DOOR STEP PANEL	BENT	148.20	148.20
1	FRONT DOOR STEP PANEL GARNISH	CRACKED	291.80	291.80
1	FRONT WINDSCREEN GLASS	CRACKED	1,247.40	1,247.40
1	FRONT WINDSCREEN GLASS RUBBER MOULDING	NECESSARY	276.30	276.30

Report Ref No. CS/INC19002767/T1sd3e2



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:2 of 5

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
1	FRONT WINDSCREEN GLASS INNER GARNISH RH	NOT NECESSARY	269.30	-
1	FRONT PANEL	BENT	895.90	895.90
1	FRONT PANEL APRON GARNISH "CENTRE"	CUT	291.90	291.90
2	FRONT PANEL APRON GARNISH LH / RH @\$101.20	N/S NOT NECESSARY / O/S BENT	202.40	101.20
1	FRONT PANEL DYNA EMBLEM	NECESSARY	58.30	58.30
1	FRONT CORNER SIDE PANEL RH	BENT	233.90	233.90
1	FRONT GRILLE	CUT	429.80	429.80
1	FRONT GRILLE EMBLEM	NECESSARY	54.70	54.70
1	FRONT GRILLE BRACKET	NOT NECESSARY	109.20	-
1	FRONT WIPER PANEL	TO REPAIR SEE LABOUR	479.60	-
2	FRONT WIPER PANEL CORNER SIDE GARNISH LH / RH @\$386.90	TO REPAIR SEE LABOUR	773.80	-
1	HEADLAMP RH	CRACKED	328.95	328.95
1	HEADLAMP LOWER RUBBER SEAL RH	NECESSARY	47.20	47.20
1	HEAD LAMP CLIPS RH	NECESSARY	9.80	9.80
1	HEADLAMP INNER PANEL RH	BENT	261.00	261.00
1	HEADLAMP LH	NOT NECESSARY	328.95	-
1	HEAD LAMP LOWER RUBBER SEAL LH	NOT NECESSARY	47.20	-
1	HEADLAMP CLIPS LH	NOT NECESSARY	9.80	-
1	FRONT BUMPER	BENT	356.90	356.90
2	FRONT BUMPER BRACKET LH / RH @\$193.20	N/S NOT NECESSARY / O/S BENT	386.40	193.20
1	FRONT DASHBOARD	DEFORMED	1,689.10	1,689.10
1	FRONT DASHBOARD INNER SUPPORT FRAME	BENT	894.50	894.50
1	FRONT WHEEL HOUSE PANEL RH	BENT	538.90	538.90
1	FRONT WHEEL HOUSE PANEL TOP GARNISH RH	DEFORMED	356.00	356.00
1	FRONT WHEEL HOUSE ARCH RUBBER SEAL RH	DEFORMED	21.30	21.30
1	FRONT MUDGUARD RH	NOT NECESSARY	258.90	-
1	FRONT MUDGUARD MUDFLAP RH	NOT NECESSARY	181.40	-
1	FRONT CABIN BACK GUARD PANEL	TO REPAIR SEE LABOUR	1,437.80	-

Report Ref No. CS/INC19002767/T1sd3e2



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:3 of 5

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
1	FRONT CABIN BACK SIDE CORNER PANEL RH	BENT	1,944.30	1,944.30
1	FRONT CABIN BACK SIDE CORNER PANEL D4D EMBLEM	NECESSARY	78.80	78.80
1	FRONT CABIN FLOOR PANEL	BENT	589.70	589.70
1	FRONT CABIN FLOOR PANEL TOP MAT	TORN	697.90	200.00
1	FRONT CABIN HANDLE LOCK	BENT	312.40	312.40
2	FRONT CABIN MECHANISM LOCK LH / RH @\$223.40	BENT	446.80	446.80
2	FRONT CABIN HINGES LH / RH @\$397.90	BENT	795.80	795.80
2	FRONT CABIN HINGES BRACKET LH / RH @\$187.20	BENT	374.40	374.40
2	FRONT CABIN HINGES RUBBER SEAL LH / RH @\$72.80	NOT NECESSARY	145.60	-
1	FRONT CABIN HINGES SHAFT ASSY	BENT	458.70	458.70
1	FRONT CABIN HINGES CROSS BRACKET	BENT	279.40	279.40
2	FRONT CABIN RUBBER GUIDE MOUNTING LH / RH @\$123.40	BENT	246.80	246.80
1	RADIATOR	NOT NECESSARY	1,422.10	-
1	RADIATOR FAN BLADE	NOT NECESSARY	217.60	-
1	RADIATOR FAN COWLING	NOT NECESSARY	329.40	-
1	RADIATOR FAN CLUTCH COIL	NOT NECESSARY	457.90	-
1	FRONT POWER STEERING BOX	NOT NECESSARY	3,869.40	-
1	FRONT POWER STEERING BOX INTERMEDIATE SHAFT	NOT NECESSARY	1,794.60	-
2	ENGINE MOUNTING LH / RH @\$241.70	NOT NECESSARY	483.40	-
1	GEAR BOX MOUNTING	NOT NECESSARY	189.25	-
1	FRONT SUSPENSION SHOCK ABSORBER RH	NOT NECESSARY	359.60	-
1	FRONT SUSPENSION KNUCKLE ARM RH	NOT NECESSARY	294.10	-
1	FRONT SUSPENSION KNUCKLE ARM BEARING RH	NOT NECESSARY	189.20	-
1	FRONT SUSPENSION STEERING TIE ROD	NOT NECESSARY	194.20	-
	LESS 25% DISCOUNT		-10,575.16	-5,423.69
			31,725.49	16,271.06
	SPECIAL NETT ITEMS			
1	FRONT DOOR COMPANY DETAIL STICKER (SN)	NECESSARY	180.00	50.00
1	SET FRONT DOOR INNER TRIM BOARD CLIPS (SN)	NECESSARY	60.00	30.00
1	SET FRONT DOOR STEP PANEL GARNISH CLIPS (SN)	NECESSARY	30.00	10.00
1	FRONT WINDSCREEN GLASS ERP BRACKET (SN)	NECESSARY	50.00	20.00
1	FRONT PANEL SEALANT (SN)	NECESSARY	80.00	40.00

Report Ref No. CS/INC19002767/T1sd3e2



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:4 of 5

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
1	SET FRONT PANEL APRON GARNISH CLIPS (SN)	NOT NECESSARY	80.00	-
1	SET FRONT GRILLE CLIPS (SN)	NOT NECESSARY	90.00	-
1	HEADLAMP BULB RH (SN)	NOT NECESSARY	40.00	-
1	HEADLAMP SIGNAL BULB RH (SN)	NOT NECESSARY	15.00	-
1	HEADLAMP SMALL BULB RH (SN)	NOT NECESSARY	10.00	-
1	FRONT NUMBER PLATE (SN)	BENT	15.00	15.00
1	SET FRONT WHEEL HOUSE PANEL TOP GARNISH CLIPS (SN)	NECESSARY	40.00	10.00
1	FRONT WHEEL HOUSE PANEL SEALANT RH (SN)	NECESSARY	80.00	40.00
1	FRONT CABIN FLOOR PANEL INSULATOR MAT (SN)	NOT NECESSARY	380.00	-
1	FRONT CABIN FLOOR PANEL SEALANT (SN)	NOT NECESSARY	150.00	-
1	FRONT CABIN BACK GUARD PANEL SEALANT (SN)	NOT NECESSARY	180.00	-
1	RADIATOR COOLANT (SN)	NOT NECESSARY	80.00	-
1	FRONT 16" STEEL RIM (SN)	TO REPAIR SEE LABOUR	380.00	-
			1,940.00	215.00
	LABOUR			
	TO DISMANTLE & REPLACED WITH PANEL BEATING ALL THE ACCIDENT PORTION. INCLUSIVE OF THE REPAIR OF FRONT DOOR PILLAR PANEL 'INTER', FRONT DOOR PILLAR PANEL SUPPORT FRAME, FRONT WIPER PANEL, FRONT WIPER PANEL CORNER SIDE GARNISH LH / RH, FRONT CABIN BACK GUARD PANEL AND FRONT 16" STEEL RIM.		3,000.00	1,500.00
	TO SPRAY PAINTING ALL THE ACCIDENT PORTION & POLISHING AFFECTED AREA.		2,600.00	1,400.00
	TO APPLY ANTI-RUST & TUFF KOTE.		120.00	50.00
	TO PERFORM LIGHTING & WIRING CHECK.		120.00	30.00
	TO DISMANTLE & REINSTALL FRONT DOOR INNER COMPONENT MECHANISM RH TO FACILITATE REPAIR WITH CHECKING.		250.00	60.00
	TO CALIBRATE CHASSIS & CAR BODY BACK TO MANUFACTURING SPECIFICATION.	NOT NECESSARY	380.00	-
	TO DISMANTLE & REINSTALL FRONT WINDSCREEN PERFORM WITH WATER LEAK TEST.		150.00	120.00
	TO DISMANTLE & REINSTALL INTERIOR CARPET WITH OTHER ATTACHMENT PARTS COMPONENT TO FACILITATE REPAIR.		280.00	80.00

Report Ref No. CS/INC19002767/T1sd3e2



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:5 of 5

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	TO PERFORM CONDUCT WATER LEAKAGE TEST OF ACCIDENT PORTION.		80.00	40.00
	TO DISMANTLE & REPLACED FRONT UNDER CARRIAGE COMPONENT RH TO PERFORM FACILITATE REPAIRS.	NOT NECESSARY	280.00	-
	TO DISMANTLE & REPLACED FRONT DASHBOARD, EVAPORATOR UNIT, WIRE HARNESS SET, RADIO COMPONENT WITH OTHER ATTACHMENT PARTS.		800.00	200.00
	TO DISMANTLE & REINSTALL ENGINE & GEARBOX COMPONENT TO FACILITATE REPAIR.	NOT NECESSARY	380.00	-
			8,440.00	3,480.00
GRAND TOTAL			42,105.49	19,966.06

RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION) (CONFIRMED)				16,000.00
--	--	--	--	-----------

Report Ref No. CS/INC19002767/T1sd3e2

MOHAMAD TAUFIKH

M.MATAI, AMSAE-A

Automotive Assessor

K.K.LAU CPT(RET)

BEng(Hons),B.Bus,MBA,PEng,PE,
MInstAEA,MASME,MIRTE

REGD Auto Consultant-SAE, Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.