

REF CS/FCI 19002772/A1d3n4

SURV. 107

Adm'n

ASSIGNMENT (Office)

WS

From (Person)

Eileen Lee

of

FCI

Date/Time

2:47pm @ 14/2/2019

Estimated Cost:

Bill to:

OD (P) WS/TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No:

SGK 6870A

Insured

SHA 13384

at Workshop n/s:

MCS Garage

Tel:

92700917

of

10 kaki Bkt Rd 2# 03-25

Policy No:

Claim No:

D19001026MFSH

Sum Insured:

Excess:

Make of Veh:

D.O.A.

8/2/2019

(Client's Record)

CA / REV / REP. / REV 24 HRS

lap

H.O.D. Endorsement:

Date/Time:

9:50am @ 14/2/19

Person Contacted:

Kendrick

Vehicle

IN/OUT

Date/Time

Action/Instruction (✓) Estimate

152-

Revert pending estimate

Finalized Lump Sum \$18001- , 3 days (Red: 3701.60; 67%)

ASS. REC. BY:

REF:

Adrian

ASSIGNMENT

From: _____ Date: _____

Estimated Cost: _____

OD / TP / WS / TP RES / OD RES / EVA / INV / MY

To Inspect Vehicle No: _____

at Workshop m/s _____

of _____

Insured: _____

Policy No. _____


Claims No. _____

Sum Insured: _____ Excess: _____

(Client's Record)

Make of Veh: _____

(Policy Condition)

Remark: The veh had commenced its
repair at the time of inspection.

Bal. or Market Value: _____

IDAC Accident Rpt: _____ Consistent?: Yes or No

GIA / PR Seen: _____ Consistent?: Yes or No

Est. Repairs: 3 days Res.: Yes or No

Lum Sum: _____ % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Date: _____ Person Contacted: _____

Vehicle: IN / OUT

Veh No: SGK6870A Yr Regn: 2006 / AugustType: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make: Mit Lances c.c. 1584Colour: Blue A/C: Insured / Std / NI / NASp. Reading: 375348 T/Radio: Insured / Std / NI / NA

Eng/No: _____

C/No: 7MYSXCS3A64007530Gen. Cond: Good / Fair / Poor / BurntSteering: Inorder / Jammed / Leaked / Burnt orBrake: Inorder / Jammed / Leaked / Burnt orModi: Nil / S/Rim / STD A/Rim orTyre Size: F: 205/50R15R: 205/50R15

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

Front

Rear

R/Bal. 06 mm R/Bal. 06 mmL/Bal. 06 mm L/Bal. 06 mmD.O.A. _____ D.O.I. 14/02/19Survey held at MCS GarageDes. of Damages: Frt / Rear O/S / NIS / UIC / Rooftop or

The UIC / Chassis frame / Body Structure affected due to collision.

Date / Time Action / Instruction

TP 1st Cop.COE Expiry: 31/07/21Market Value - 16000MV: 16K*CTA: 12.193PV: 12.2KNett Value: 3807Nett: 3.8K

RECEIVED 08 MAY 2019

Date/Time, File Pass to?

Date/Time, File Return to?

1) 8/5 Typist

2) _____

3) _____

4) _____

5) _____

6) _____

Prel. Report: _____

Final Report: _____

Part Prices Check:

IN

OUT

Survey Fee:

Date:

Basic & Add.

S + RS, SI

Photos

Others

TOTAL

140505018258

MOTOR SURVEY ASSIGNMENT

Date	12-02-2019	Our Ref No.	D19001026MFSH
Accident Date	08-02-2019	Claim Type.	Third Party
Insured Vehicle	SHA1338U	Third Party Vehicle.	SGK6870A
Survey Location	10 KAKI BUKIT ROAD 2 #03-25 FIRST EAST CENTRE		
Contact Person.	MR KENDRICK		
Contact No.	82857623/ 92700917	Fax No.	0
Survey Type	WITHOUT PREJUDICE:		
Appointed Surveyor	LKK AUTO CONSULTANTS PTE LTD		
Contact Person	NA	Fax No.	68416315
Contact Number.	NA		

FOR DIRECT SETTLEMENT

Please submit to us the Tax Invoice together with letter of claim for Rental OR Loss of use (based on NIMA Benchmark rates) together with your survey report.

THIRD PARTY SURVEY REQUEST

Cc : Workshop	MCS GARAGE	Attention.	NIL
Cc : TP Solicitor	VISION LAW LLC	TP Solicitor Fax No.	NA
Officer Incharge	EILEEN LEE		

IMPORTANT NOTE

Kindly submit the survey report via CWS within 14 days for survey assignment and 7 days for re-inspection.
This is a computer generated letter, no signature required.

Denise Tay (LKKAuto)

From: Denise Tay (LKKAuto)
Sent: Friday, 15 February 2019 5:04 PM
To: Admin-D (LKKAuto); 'CWS Motor Claims'; assignments
Cc: 'Eileen Lee'; SUR
Subject: RE: SURVEY ASSESSMENT - D19001026MFSH/1

Dear Sir/Madam,

Please be informed that we have inspected the vehicle SGK 6870A on 14/02/2019
We are pending estimate from repairer.

Best Regards,

Denise Tay | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email: denisetay@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Admin-D (LKKAuto)
Sent: Thursday, 14 February 2019 9:52 AM
To: 'CWS Motor Claims' <cwsmotorclaims@msfirstcapital.com.sg>; assignments <assignments@lkkauto.com>
Cc: 'Eileen Lee' <EileenLee@msfirstcapital.com.sg>; SUR <sur@lkkauto.com>
Subject: RE: SURVEY ASSESSMENT - D19001026MFSH/1

Dear Sir/Mdm,

Thank you for the assignment.



BEST REGARDS,

G.Nivitha | Admin

LKK Auto Consultants Pte Ltd

Phone: 6841-1972 | email: assignments@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)



Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Particulars	
Owner ID Type:	Singapore NRIC
Owner ID:	4273H
Vehicle Details	
Vehicle No.:	SGK6870A
Vehicle Type Exported:	Yes
Intended Re-registration Date:	14 Feb 2019
Vehicle Make:	MITSUBISHI
Vehicle Model:	LANCER 1.6 M
Primary Colour:	Red
Manufacture Year:	2006
Engine No.:	4G18HK0255
Chassis No.:	JMYSNCS3A6U007530
Maximum Gross Output:	79.0 kW (105 bhp)
Open Market Value:	\$11,503.00
Original Registration Date:	22 Aug 2006
First Registration Date:	22 Aug 2006
Transfer Count:	2
Actual Amount Paid:	\$12,654.00
Intended Rebate Details	
PARF Eligibility:	Forfeited
PARF Eligibility Expiry Date:	-
PARF Rebate Amount:	\$0.00
Intended COE Details	
COE Expiry Date:	31 Jul 2021
COE Category:	A - Car (1600cc & below)
COE Permit Type:	5
PQP Paid:	\$24,760.00
COE Rebate Amount:	\$12,193.00
Total Rebate Amount:	\$12,193.00
Message	

Please note that the 5-year COE for this vehicle cannot be further renewed. The vehicle must be de-registered upon COE expiry or when the vehicle reaches its statutory lifespan (if applicable) whichever is earlier.

The information contained herein is correct as at 14 Feb 2019

OK

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged parts during resurvey
- Parts prices are on a "Without Prejudice" basis
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Vehicle number: SGK6870A

Acknowledged by Repairer

Signature:

Qty List Items

MCS Garage

10 Kaki Bukit Road 2 #03-25, First East Centre Singapore 471868

Tel: 9270 0917 / 6538 4322

Vehicle Made & Model: MITSUBISHI LANCER

TP 1st Cap.
Denise.

Qty	List Items	Amount \$
1	Front door - RH <i>Dented.</i>	895.00 ✓
1	Front door glass outer moulding	126.00 x
1	Front door glass run channel	158.00 +
1	Front door glass regulator	260.00 x
1	Front door glass regulator motor	365.00 +
1	Front door w/strip	142.00 +
1	Front door insulation	122.00 x
1	Front door checker	89.00 x
2	Front door hinges @ 65	130.00 +
1	Front door outer handle	192.00 x
1	Side sill panel - RH <i>Rypr</i>	645.00 x
Sub-total		3,124.00
Less 10%		312.40
Total List		2,811.60

895
805.50

Special Nett Items

1 set	Front door black tape <i>new</i>	120.00 60
1 set	Front door sun visor <i>new</i>	300.00 60
1 set	Side sill panel skirt <i>new</i>	550.00 ✓
Total Special Nett		970.00

670

Labour charges

To check front electrical wiring	40.00 30
To respray undercoating	80.00 +
To respray painting and etc	800.00 400
Panel beating, cut, weld remove & replacing above parts	800.00 350
Total Labour	1,720.00

780

ESTIMATE PARTS AND LABOUR GRAND TOTAL \$

5,501.60

1.8/c

total: 2255.50
h/s 1.8/c
03 Dm/s.



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
MS FIRST CAPITAL INSURANCE LTD			Ref : CS/FCI19002772/Atd3n2	
36 ROBINSON ROAD #16-01 CITY HOUSESINGAPORE 068877			Date : 09-05-2019	
			Code : FCI2	
1. Policy Particulars :- THIRD PARTY CLAIM				
Insured Veh.	SHA 1338U	Veh. Inspected	SGK 6870A	
Policy No.		Coverage (\$)	0.00	
Claim No.	D19001026MFSH	Excess (\$)	0.00	
Assign From	EILEEN LEE	Assign Date	14/02/2019	
2. Vehicle Particulars & Condition				
Make & Model	MITSUBISHI LANCER	c.c	1584	
Engine No.	HIDDEN	Year of Reg.	2006	
Chassis No.	JMYSNCS3A6U007530	Colour	BLUE	
Odometer	375348	Steering	IN ORDER	
Brakes	IN ORDER	Modification	SPORTS RIM	
General	GOOD			
3. Conditions of Tyres				
	Size	Make	Balance	
R/H Front Tyre	205/50 R15	YOKOHAMA	6 mm	
L/H Front Tyre	205/50 R15	YOKOHAMA	6 mm	
R/H Rear Tyre	205/50 R15	YOKOHAMA	6 mm	
L/H Rear Tyre	205/50 R15	YOKOHAMA	6 mm	
4. Description of Damages				
THE VEHICLE SUSTAINED DAMAGES AT THE O/S BODY. DAMAGES SEE DETAILS.				
5. General Information				
Accident Date	08/02/2019	Inspection Date	14/02/2019	
Survey held at	MCS GARAGE 10 KAKI BUKIT ROAD 2 #03-25 FIRST EAST CENTRE SINGAPORE 417868			
5a. Remarks				
A)DAMAGES CONSISTENT TO ACCIDENT REPORT. B)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. C)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.				
5b. Estimate Days of Repair				
ESTIMATED NORMAL PERIOD FOR REPAIR:		3 Working Days		



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 2

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SGK 6870A

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
REPLACEMENT OF PARTS				
1	FRONT DOOR-RH	DENTED	895.00	895.00
1	FRONT DOOR GLASS OUTER MOULDING	NOT NECESSARY	126.00	-
1	FRONT DOOR GLASS RUN CHANNEL	NOT NECESSARY	158.00	-
1	FRONT DOOR GLASS REGULATOR	NOT NECESSARY	260.00	-
1	FRONT DOOR GLASS REGULATOR MOTOR	NOT NECESSARY	365.00	-
1	FRONT DOOR W/STRIP	NOT NECESSARY	142.00	-
1	FRONT DOOR INSULATION	NOT NECESSARY	122.00	-
1	FRONT DOOR CHECKER	NOT NECESSARY	89.00	-
2	FRONT DOOR HINGES @\$65.00	NOT NECESSARY	130.00	-
1	FRONT DOOR OUTER HANDLE	NOT NECESSARY	192.00	-
1	SIDE SILL PANEL-RH	TO REPAIR SEE LABOUR	645.00	-
	LESS 10% DISCOUNT		-312.40	-89.50
			2,811.60	805.50
SPECIAL NETT ITEMS				
1	SET FRONT DOOR BLACK TAPE (SN)	NECESSARY	120.00	60.00
1	SET FRONT DOOR SUN VISOR (SN)	NECESSARY	300.00	60.00
1	SET SIDE SILL PANEL SKIRT (SN)	DEFORMED	550.00	550.00
			970.00	670.00
LABOUR				
	TO CHECK FRONT ELECTRICAL WIRING.		40.00	30.00
	TO RESPRAY UNDERCOATING.	NOT NECESSARY	80.00	-
	TO RESPRAY PAINTING AND ETC.		800.00	400.00
	PANEL BEATING,CUT,WELD REMOVE & REPLACING ABOVE PARTS.INCLUSIVE OF THE REPAIR OF SIDE SILL PANEL-RH.		800.00	350.00
			1,720.00	780.00
GRAND TOTAL			5,501.60	2,255.50
RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION)				1,800.00

Report Ref No. CS/FCI19002772/Atd3n2



Report Ref No. CS/FCI19002772/Atd3n2

MARKET VALUE: \$16,000.00 (EST)-LTA REIMBURSEMENT VALUE: \$12,193.00=NETT VALUE: \$3,807.00

A handwritten signature in black ink, appearing to read 'A.L.P.' or similar.

ADRIAN LING WAI PING

B.Eng,AMSOE,AMIRTE,AMSAE-A,M.MATAI

Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.