

2/10/2012

ASS. REC. BY:

REF:

es/FCI19002787/Updset

Special Instruction:

Supervisor:
CWS

Maxell

ASSIGNMENT (Office)

From (Person):

May chuan

of

FCI

Date/Time:

11-06am @ 14/2/19

Estimated Cost:

Bill to:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No:

SLJ 1176A

Insured:

SHA 4370E

at Workshop m/s

Kah Motor

Tel:

81006303

of

15 ubi Road 4

Policy No:

Claim No:

D19001043MFSH

Sum Insured:

Excess:

Make of Veh:

(Client's Record)

D.O.A.

8/2/2019

15/2/19 @ 9:30am

H.O.D. Endorsement:

CA / REV / REP. / REV 24 HRS (up)

Date/Time:

12:01pm @ 14/2/19

Person Contacted:

Mr. Jim

Vehicle IN/OUT

Date/Time	Action/Instruction (✓) Estimate
19/2/19 @ 3:12pm	revised to May chuan by email.

REF: FCI

STATEMENT

Date: 15/2/19

Estimated Cost

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To inspect Vehicle No: SLJ 1176A

at Workshop no: Kah Motor

of: 15 ubi Rd 4

Insured

Policy No

Claims No

Sum Insured

(Client's Record)

Make of Veh: 9.30cm

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.

Bal. or Market Value: 64

IDAC Accident Rpt. Consistent? : Yes or No

GIA / PR Seen. Consistent? : Yes or No

Est. Repairs: 8 days Res.: Yes or No

Lum Sum: 13.1 % 3 Val: Yes or No

CA / REV / REP. / 24 HRS (OS)

Date: Person Contacted: Vehicle IN / OUT

Veh No: SLJ 1176A

Type: M/Car / M/Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or CA /

Make: Honda Jazz

Colour: Red

Sp. Reading: 31303

Eng No: JHM GK 5810H X200 872

Gen. Cond: Good / Fair / Poor / Burnt

Steering: In order / Jammed / Leaked / Burnt or

Brake: In order / Jammed / Leaked / Burnt or

Modi: Nil / S/Rim / STD A/Rim or

Tyre Size: F: 185/55R16

R:

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

Front: R/Bal: 7 mm L/Bal: 7 mm

Rear: R/Bal: 7 mm L/Bal: 7 mm

D.O.A. 8/2/19

Survey held at

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooltop or

Rear 8

The U/C / Chassis frame / Body Structure affected due to collision



Date/Time: 25/2/19

Action/Instruction: LTA 50492

CONFIRMED fine by 12893.41 with MATHAN

check @ 4904.86 + 37 (e)

RECEIVED 25 FEB 2019

Date/Time: File Pass to? 15/2/19

Date/Time: File Return to?

: Preli. Report

: Final Report

Days Of Repair: 8

Resurvey No. of Trip: 1

Add Fee:

Site Insp (\$)

Interview (\$)

Techn Invs (\$)

Weekend (\$)

Survey Fee: 170+75

Transportation: 50

5x15=75

123

26/2/19

1168

Report Format: TP

Lump Sum / L.B.E: 10593.41

MOTOR SURVEY ASSIGNMENT

Date 12-02-2019 **Our Ref No.** D19001043MFSH

Accident Date 08-02-2019 **Claim Type.** Third Party

Insured Vehicle SHA4370E **Third Party Vehicle.** SLJ1176A

Survey Location 15 UBI ROAD 4
Contact Person. LIM CHOU SIONG

Contact No. 68465671/ 81006303 **Fax No.** 67480770

Survey Type WITHOUT PREJUDICE: WE ADMIT LIABILITY QUANTUM TO BE AGREED:

Appointed Surveyor LKK AUTO CONSULTANTS PTE LTD

Contact Person NA **Fax No.** 68416315

Contact Number. NA

FOR DIRECT SETTLEMENT

Please submit to us the Tax Invoice together with letter of claim for Rental OR Loss of use (based on NIMA Benchmark rates) together with your survey report.

THIRD PARTY SURVEY REQUEST

Cc : Workshop KAH MOTOR CO SDN **Attention.** NIL
BHD

Cc : TP Solicitor NA **TP Solicitor Fax No.** NA

Officer Incharge MAY CHUA

IMPORTANT NOTE

Kindly submit the survey report via CWS within 14 days for survey assignment and 7 days for re-inspection.
This is a computer generated letter, no signature required.

Shiau Chan (LKKAuto)

From: Shiau Chan (LKKAuto)
Sent: Tuesday, 19 February 2019 3:12 PM
To: 'CWS Motor Claims'; assignments
Cc: 'May Chua Hui Chin'; SUR
Subject: RE: SURVEY ASSESSMENT - D19001043MFSH/1
Attachments: CSFC19002787Uqd3.pdf

Dear May,

Enclosed herewith preliminary advice of SLJ 1176A.

Best Regards,

Shiau Chan (Ms) | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email: siewsc@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Admin-D (LKKAuto)
Sent: Thursday, 14 February 2019 12:05 PM
To: 'CWS Motor Claims' <cwsmotorclaims@msfirstcapital.com.sg>; assignments <assignments@lkkauto.com>
Cc: 'May Chua Hui Chin' <maychua@msfirstcapital.com.sg>; SUR <sur@lkkauto.com>
Subject: RE: SURVEY ASSESSMENT - D19001043MFSH/1

Dear Sir/Mdm,

Thank you for the assignment.

Please be informed vehicle not in the workshop, repairer will arrange.



BEST REGARDS,

G.Nivitha | Admin

LKK Auto Consultants Pte Ltd

Phone: 6841-1972 | email: assignments@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)



From: CWS Motor Claims [<mailto:cwsmotorclaims@msfirstcapital.com.sg>]
Sent: Thursday, 14 February 2019 11:06 AM



Auto
Consultants
Pte Ltd

51 UBI AVE 1, #01-25 PAYA UBI INDUSTRIAL PARK, SINGAPORE 408933 TEL : (065) 62563561 FAX : (065) 62564315

Your Ref: D19001043MFSH

Date: 19 February 2019

Our Ref: CS/FCI19002787/Uqd3

The Motor Claims Department
First Capital Insurance Ltd

Dear Sir/Madam,


INITIAL INSPECTION REPORT OF VEHICLE NO. SLJ 1176A .

Please be informed that we had conducted the inspection of the abovementioned vehicle on 15/02/2019 at the premises of M/s KAH MOTOR. and have the following to report:-

Workshop Estimate Amount	: <u>S\$ 15,489.25</u> .
Revised Estimate Amount	: <u>S\$ 10,579.39</u> .
"Check" Items Amount	: <u>S\$ 566.76</u> .
Market Value	: <u>S\$ -</u> .
LTA Reimbursement Value	: <u>S\$ -</u> .
Nett Value	: <u>S\$ -</u> .

Description of Damage:

The vehicle sustained damages at the rear portion & rooftop. The chassis frame affected due to collision.



Yours faithfully

CHUA KANG SENG
Licensed Appraiser

> **Back to OneMotoring**

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars	
Owner ID Type:	Singapore NRIC
Owner ID:	1410E
Vehicle Details	
Vehicle No.:	SLJ1176A
Vehicle to be Exported:	No
Intended Deregistration Date:	15 Feb 2019
Vehicle Make:	HONDA
Vehicle Model:	JAZZ 1.5 VTIR CVT ABS D/AIRBAG 2WD
Primary Colour:	Red
Manufacturing Year:	2016
Engine No.:	L15B31190620
Chassis No.:	JHMGK5850HX200872
Maximum Power Output:	96.0 kW (128 bhp)
Open Market Value:	\$17,647.00
Original Registration Date:	29 Nov 2016
First Registration Date:	29 Nov 2016
Transfer Count:	0
Actual ARF Paid:	\$12,647.00
Intended PARF Rebate Details	
PARF Eligibility:	Yes
PARF Eligibility Expiry Date:	28 Nov 2026
PARF Rebate Amount:	\$9,485.00
Intended COE Rebate Details	
COE Expiry Date:	28 Nov 2026
COE Category:	A - Car up to 1600cc & 97kW (130bhp)
COE Period(Years):	10
QP Paid:	\$52,668.00
COE Rebate Amount:	\$41,007.00
Total Rebate Amount:	\$50,492.00

The information contained herein is correct as at 15 Feb 2019

OK



jazz Price Range Depreciation 2016 Vehicle Type

Home » Used Cars » Car (S) Pte Ltd » Honda Jazz 1.5A RS

Resources

- Car Buying
- Car Selling
- Car Ownership
- Car Aftermarket
- On The Move
- Lifestyle

Car Tyres

Honda Jazz 1.5A RS

Overview Financial Insurance Accessories Similar Research Photos Map



Add to Shortlist Add to Compare Add a Note Report Error More Actions Share

Car Details

Price	\$64,800	
Depreciation	\$7,590 /yr	?
	View models with similar depreciation	
Reg Date	01-Nov-2016	
	(7yrs 8mths 16days COE left)	
Manufactured	2016	?
Mileage	-	
Transmission	Auto	
Engine Cap	1,498 cc	
Road Tax	\$684 /yr	?
Power	96.0 kW (128 bhp)	
	View specs of the Honda Jazz (2014-2017)	
Curb Weight	1,046 kg	?
Features	129 BHP 1.5L 4 Cylinder Inline 16 Valve DOHC I-VTEC Engine, Earth Dream CVT With Paddle Shifters, Cruise/Traction Controls, Keyless Start/Stop Button	
Accessories	16" Rims, LED DRL/Headlights, Factory Touch Screen Audio, Bluetooth/USB Port, Reverse Camera, Auto Climate Control, Solar Film, Sport Pedals, Etc.	
Description	Fully Serviced At Honda Kah Motors. Low Mileage. 5 Years Warranty. Excellent Condition Interior And Exterior. Upgraded Auto Hazard Light And Auto Door Lock. Spacious Hatchback Packed With Lots Of Features, Fuel Efficient And Trouble Free Car. Powerful, Reliable And Responsive Engine. View To Believe, Flexible Finance Package Available.	
COE	\$51,507	?



Seller Information

Company Car (S) » deale » 62 ve
Address 39 Woc 04

Compare

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. **Any false reporting may be referred to the Police for investigation.**
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT

Date Of Report	09/02/2019 15:27
Date Of Accident	08/02/2019 19:50
Exact Location Of Accident	HOUGANG AVE 2 FILTER LANE INTO HOUGANG AVE 8
Country/State of Loss	SINGAPORE

DETAILS OF OWN VEHICLE

Vehicle Registration Number	SLJ1176A
Insured/Policyholder	
Name Of Registered Owner	LOW HAN SONG CLARENCE
NRIC No	S8621410E
Email Address	CLARENCE_LOWHS@HOTMAIL.COM
Mobile Phone No	(LOCAL) +65-98586063
Alternative Phone No	OFFICE-NOPHONE
Vehicle Particulars	
Manufacturer	HONDA
Model	JAZZ-1.5 VTIR CVT (A)
Exact Purpose for which vehicle was being used at time of accident	COMMERCIAL
Are you claiming under your own insurance policy for repair to your vehicle?	NO
If No, Please state action to be taken	THIRD PARTY
Vehicle Category	PRIVATE HIRE
Insurance Company	
Name of Insurance Company	NTUC INCOME INSURANCE CO-OPERATIVE LTD
Type Of Coverage	COMPREHENSIVE
Fleet Policy	NO
Policy Number	5100594022
Cover Note Number	
Driver	
Name of Driver	LOW HAN SONG CLARENCE
NRIC No	S8621410E
Date Of Birth	31/07/1986
Occupation	INDOOR
Date Of Driving Pass	17/07/2006
Driving Experience	12 YEARS AND 6 MONTHS
Gender	MALE
Mobile Number	(LOCAL) +65-98586063
Fax Number	
Contact Number	OFFICE-NOPHONE
EMail Address	CLARENCE_LOWHS@HOTMAIL.COM

Address BLK 458 #20-1590
ANG MO KIO AVENUE 10

Postcode 560458

Was driver an employee of the Insured's Company NO

If No, Relationship of the Driver with the Insured OWNER

Vehicle Registration Number of Driver's Own Vehicle -
-
-

Insurance Company of Driver's Own Vehicle -
-
-

General Information of the Accident

Type Of Accident COLLISION - HEAD TO REAR

Weather Conditions CLEAR

Road Surface DRY

Other Information

Was any foreign vehicle involved in this accident? NO

Number of vehicles (including own vehicle) involved in the accident 2

Was any body injured in the Accident? YES

Was any injured conveyed to hospital by ambulance? YES

Was any other material or property damaged? YES

I have been approached by unknown person(s) soliciting/offering accident claims assistance. NO

Number of Passengers (Including Driver) 2

Passenger 1 NAME: : SURESH S/O LETCHMANAN
GENDER: : MALE

Details of Police Action

Was the accident reported to the police? YES

If Yes, Please state which Police Station

POLICE STATION NAME [OTHER] ANG MO KIO SOUTH N.P.C

Was notice of intended Prosecution given? NO

If Yes, against whom?

Circumstances of Accident

REFER TO SKETCH PLAN AND POLICE REPORT

Attachment(s)

Are accident photos available for attachment? YES

Was there any video captured by Car Camera? YES

Remarks/ Reasons: EMAIL TO MOTORVIDEO@INCOME.COM.SG

Was there any audio recorded? NO

DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number SHA4370E

Vehicle Make/Model/Colour

Details Of Properties

Vehicle Category TAXI

Name of Driver JOSEPH TOH TIO BACK

NRIC/Passport Number S0500810G

Contact Number 96839386

Address

Postcode

Insurance Company Name

Nature Of Damage

No. Of Passenger (Including Driver)

DETAILS OF INJURED PERSON 1

Name SURESH S/O LETCHMANAN

Approximate Age

Injuries Sustain

Injured person in which vehicle? SLJ1176A

Were seat belts worn?

Was this injured conveyed to hospital by ambulance? YES

Address

Postcode



Police Station Of Origin:
Ang Mo Kio South N.P.C
81 Ang Mo Kio Avenue 3 SINGAPORE
569929
Tel No: 1800-4519999

CONTINUATION OF REPORT

Details of Vehicle Insurance				
Vehicle No.	Insurance Company	Insurance No	Effective	Expiry Date
SLJ1176A	NTUC Income Insurance Co-Operative Limited	5100594022	10/05/2018	28/05/2019

Details of Person Involved				
Any Pedestrian Involved: No				
No. of Pedestrians Injured: NIL			Use of Pedestrian Crossing: NA	
Driver				
Name	JOSEPH TOH TIO BACK		ID No.	S0500810G
Related Vehicle	SHA4370E (Car)		Contact No.	96839386
Hospital/Clinic	NIL		Class of Driving Licence & Expiry Date	Class: NIL Date of Expiry: NIL
Date Treatment	NIL		Date Discharge	NIL
No. of Days granted Medical Leave	NIL		Degree of Injury	NIL
Driver				
Name	LOW HAN SONG, CLARENCE		ID No.	S8621410E
Related Vehicle	SLJ1176A (Car)		Contact No.	98586063
Hospital/Clinic	NIL		Class of Driving Licence & Expiry Date	Class: 2B,3 Date of Expiry: NIL
Date Treatment	NIL		Date Discharge	NIL
No. of Days granted Medical Leave	NIL		Degree of Injury	NIL
Passenger				
Name	SURESH S/O LETCHMANAN		ID No.	S9244802I
Related Vehicle	SLJ1176A (Car)		Contact No.	96173787
Hospital/Clinic	NIL		Class of Driving Licence & Expiry Date	Class: NIL Date of Expiry: NIL
Date Treatment	NIL		Date Discharge	NIL
No. of Days granted Medical Leave	NIL		Degree of Injury	NIL



**SINGAPORE
POLICE FORCE**



T/20190208/2149

Police Station Of Origin:
Ang Mo Kio South N.P.C
81 Ang Mo Kio Avenue 3 SINGAPORE
569929
Tel No: 1800-4519999

3 of 4

Report No. T/20190208/2149

CONTINUATION OF REPORT

Brief Details.

On 08/02/2019 at about 1950hrs, I was driving one passenger along Hougang Avenue 2 was approaching the junction of Hougang Avenue 8. At the T-junction, I filtered left into the filter lane. As there was a cyclist about to cross the zebra crossing, I slowed down and stopped. Out of a sudden, I felt an impact from the back. Luckily the cyclist had managed to cross the zebra crossing and I did not hit the cyclist.

After the accident, I discovered that one taxi (SHA4370E) had hit on the rear of my vehicle. He moved forward and stopped his taxi at the side. My passenger complained of pain and he called for ambulance. Whilst waiting for the ambulance, all of us exchanged our contact and particulars and I had also called up my NTUC insurance. At the material time, I did not know how bad the injury of my passenger is and the said taxi driver left first. When ambulance and traffic police came and took over, it was discovered that the passenger has to be conveyed. Traffic Police then called the taxi driver to come and he returned about 8 plus.

I have in-built vehicle camera for both front and back view. The footage is captured and I will forward the video to the traffic officer.



**SINGAPORE
POLICE FORCE**



T/20190208/2149

Police Station Of Origin:
Ang Mo Kio South N.P.C
81 Ang Mo Kio Avenue 3 SINGAPORE
569929
Tel No: 1800-4519999

4 of 4

Report No. T/20190208/2149

CONTINUATION OF REPORT


Sketch Plan

Informant is not able to provide sketch plan

IMPORTANT: Please attach a copy of your vehicle's Insurance Certificate to this report. If you don't have the certificate with you now, please fax a copy to 65474885 stating the report number as reference.

Signature Of Officer Recording The Report: F / Staff Sgt MUHAMMAD HERMI BIN HAMIDON	Signature Of Informant: 
Signature Of Interpreter: Not applicable	Date/Time: 08/02/2019 22:20
Officer In Charge Of Case: TP / GIT / Sr Staff Sgt NOR FAIZAL BIN YAHYA Contact No.: 65476202	Classification Of Case:

Authentication Stamp
NP168



Certificate of Insurance

MOTOR VEHICLES (THIRD PARTY RISKS AND COMPENSATION) ACT (CHAPTER 189)
MOTOR VEHICLES (THIRD PARTY RISKS AND COMPENSATION) RULES, 1960
ROAD TRANSPORT ACT, 1987 (MALAYSIA)
MOTOR VEHICLES (THIRD PARTY RISKS) RULES, 1959 (MALAYSIA)

Certificate Number : 5100594022

Cover : Preferred Workshop Plan

- | | |
|--|--------------------------|
| 1. Index mark and Registration Number of Vehicle | : SLJ1176A |
| Chassis Number | : JHMGK5850HX200872 |
| 2. Name of Policyholder | : LOW HAN SONG, CLARENCE |
| 3. Effective Date of Insurance | : 10 May 2018 |
| 4. Expiry Date of Insurance | : 09 May 2019 |
| 5. Persons or Classes of Persons entitled to drive# | |
| (a) The Policyholder. | |
| (b) Any other person who is driving on the Policyholder's order or with his/her permission.
Provided that the person driving is permitted in accordance with the licensing or other laws or regulations to drive the Motor Vehicle or has been so permitted and is not disqualified by order of a Court of Law or by reason of any enactment or regulation in that behalf from driving the Motor Vehicle. | |
| 6. Limitations as to Use# | |
| (a) Use for social domestic and pleasure purposes and in connection with the Policyholder's or Hirer's business. | |
| (b) Use for the carriage of passengers or goods in connection with the Policyholder's or Hirer's business. | |

This Policy does not cover

- (a) Use for racing, pace-making, reliability trial or speed-testing.
- (b) Use whilst drawing a trailer except the towing of any one disabled mechanically propelled vehicle.

Limitations rendered inoperative by Section 8 of the Motor Vehicle (Third Party Risks and Compensation) Act (Chapter 189) and Section 95 of the Road Transport Act, 1987 (Malaysia), are not to be included under these headings.

EXCESS (SECTION 1)	: S\$2,000
EXCESS (SECTION 2)	: S\$2,000
WINDSCREEN EXCESS	: S\$100
INSURE WITH COE	: YES
HIRE PURCHASE COMPANY	: OCBC BANK LTD
SUM INSURED	: MARKET VALUE OF INSURED VEHICLE AT TIME OF LOSS

I/We hereby Certify that the Policy to which this Certificate relates is issued in accordance with the provisions of the Motor Vehicles (Third Party Risks and Compensation) Act (Chapter 189) and Part IV of the Road Transport Act, 1987 (Malaysia)

Agency : GRABCAR PTE. LTD. (00000601726)
Date of Issue : 08 May 2018 17:26 hrs

For NTUC INCOME INSURANCE CO-OPERATIVE LIMITED



Countersigned By:

Authorised Officer



Chief Executive



Name
LOW HAN SONG, CLARENCE

刘 汉 松

Race
CHINESE
Date of birth
31-07-1986
Country/Place of birth
SINGAPORE
Sex
M

REPUBLIC OF SINGAPORE DRIVING LICENCE

Licence Number: **S8621410E**
Name:
LOW HAN SONG, CLARENCE
Birth Date: **31 Jul 1986**
Issue Date: **17 Jul 2006**

001432596E

5643152



NRIC No. **S8621410E**



Date of issue
01-09-2016

Address
**APT BLK 458 ANG MO KIO AVENUE 10
#20-1590
SINGAPORE 560458**

YOU ARE LICENSED TO DRIVE VEHICLES IN THE FOLLOWING CLASS(ES)

Class 2B Motorcycles =< 200 CC
Class 3 Motor cars =< 3000 kg with =< 7 passengers, exclusive of the driver; and motor tractors/vehicles =< 2500 kg

PASS DATE

10 Apr 2008
17 Jul 2006

S8621410E


S / No. 9000070755

NP 428A





VOCATIONAL LICENCE
Licence No : S8621410E
Name : LOW HAN SONG, CLARENCE



Please visit www.lta.gov.sg to check the status of this vocational licence

This card is not transferable and is the property of the Land Transport Authority (LTA). It must be surrendered to LTA on request. If found, please return to LTA, 10 Sin Ming Drive, Singapore 575701.

Type	Description	Issue Date
13	PRIVATE HIRE CAR VL	04/05/2018





KAH MOTOR CO. SDN. BHD.
 (A Member of the Oriental Holdings Berhad)
 Service and Body Repair
 Tel: +65 6841 3838 Website: www.honda.com.sg
 For 24-hours Roadside Assistance, Call 98203838

*Kindly Help to arrange
 Surveyor to Survey this
 Vehicle thanks*

QUOTATION

GST Reg No.: M200050223
 Company Ref. No.: S60FC1380G

Customer : MS FIRST CAPITAL INSURANCE	Document No. : SQT19000697	Page 1
36 ROBINSON ROAD	Date : 12. Feb 2019	
#16-01 CITY HOUSE	Customer No. : WZF002	
SINGAPORE 068877	Svc Advisor : LIM CHOU SIONG	
Registration No : SLJ1176A	Engine No : L15B31190620	
Chassis No : JHMGK5850HX200872	Date Time : 12. Feb 2019 7:37:53 PM	
Model : JAZZ 1.5VTIR CVT 17YM	Surveyor Name :	
Owner's Name : LOW HAN SONG, CLARENCE	Survey Date :	
Ins Policy No. :	Authorisation Date :	
Date of Accident : 8/2/2019		

Item	Description	Qty	Unit Price	Disc %	Amount	0% GST Amount	Amount incld GST
	TP DIRECT SETTLEMENT (J/NO:) OWNER: LOW HAN SONG, CLARENCE OWNER INSURER: NTUC INCOME INS CO-OPERATIVE LTD ACC DATE: 08/2/2019 SURVEYED BY: DATE: REF NO: TP INSURER: MS FIRST CAPITAL INSURANCE LIMITED TP VEH: SHA4370E						
73127-TY0-000	RUBBER CWINDSHIELD DAMPER <i>rec</i>	1	11.40	25	8.55	0.60	9.15
73214-T5A-013	RUBBERWINDSHIELD DAMPER <i>rec</i>	2	6.50	25	9.75	0.68	10.43
73226-SZW-000	DAMPERSTD 5X5 <i>rec</i>	1	8.50	25	6.37	0.45	6.82
BO-WS-SEALANT	WINDSCREEN SEALANT (N) <i>rec</i>	2	60.00		120.00	8.40	128.40
68100-T5B-Z50ZZ	TAILGATE COMP <i>Body</i>	1	730.60	25	547.95	38.36	586.31
74440-T5A-003	WEATHERSTRIPTAILGATE <i>1/1</i>	1	92.30	25	69.22	4.85	74.07
74800-T5S-K61	LOCK ASSY, TAILGATE <i>no/Jan</i>	1	78.90	25	59.17	4.14	63.31
74813-T5A-003	STRIKER ASSYTAILGATE <i>1/1</i>	1	24.70	25	18.52	1.30	19.82
74899-T5R-A02	DAMPERTAILGATE DYNAMIC <i>1/1</i>	1	45.60	25	34.20	2.39	36.59
84440-T5A-J02ZA	LINING ASSYTAILGATE LOWER <i>1/1</i>	1	53.70	25	40.27	2.82	43.09
84441-T5A-003ZB	POCKETTAILGATE LINING PULL <i>1/1</i>	1	5.10	25	3.82	0.27	4.09
75722-T5L-T01	EMBLEMRR. <i>rec</i>	1	10.90	25	8.17	0.57	8.74
33500-T5A-J02	TAILLIGHT ASSY,R. <i>1/1</i>	1	223.90	25	167.92	11.75	179.67
33550-T5A-J02	TAILLIGHT ASSYL. <i>1/1</i>	1	223.90	25	167.92	11.75	179.67
34150-T5A-J01	LIGHT ASSYR.LID <i>1/1</i>	1	81.70	25	61.27	4.29	65.56
34155-T5A-J01	LIGHT ASSYL.LID <i>1/1</i>	1	81.70	25	61.27	4.29	65.56
34100-S60-013	LIGHT ASSYLICENCE <i>1/1</i>	2	34.10	25	51.15	3.58	54.73
74890-T5B-911	GARNISH ASSYRR.LICENSE <i>1/1</i>	1	200.60	25	150.45	10.53	160.98
BO-NUM-COMP-L	NUMBER PLATE WITH CASING-L(N) <i>but</i>	1	45.00		45.00	3.15	48.15
NMRS-4P-TM3040L	4PCS ACT RR.SENSOR <i>shovel</i>	1	320.00		320.00	22.40	342.40



QUOTATION

KAH MOTOR CO. SDN. BHD.
(A Member of the Oriental Holdings Berhad)

GST Reg No.: M200050223
Company Ref. No.: S60FC1380G

Service and Body Repair

Tel: +65 6841 3838

Website: www.honda.com.sg

For 24-hours Roadside Assistance, Call 98203838

Customer : MS FIRST CAPITAL INSURANCE
36 ROBINSON ROAD
#16-01 CITY HOUSE
SINGAPORE 068877

Registration No : SLJ1176A
Chassis No : JHMGK5850HX200872
Model : JAZZ 1.5VTIR CVT 17YM
Owner's Name : LOW HAN SONG, CLARENCE
Ins Policy No. :
Date of Accident : 8/2/2019

Document No. : SQT19000697 Page 2
Date : 12. Feb 2019
Customer No. : WZF002
Svc Advisor : LIM CHOU SIONG
Engine No : L15B31190620
Date | Time : 12. Feb 2019 7:37:53 PM
Surveyor Name :
Survey Date :
Authorisation Date :

Item	Description	Qty	Unit Price	Disc %	Amount	0% GST Amount	Amount incld GST
04715-T5B-000ZZ	FACERR.BUMPER <i>Dis</i>	1	502.50	25	376.87 ✓	26.38	403.25
71502-T5A-000	GARNISHR.RR.BUMPER <i>u</i>	1	14.30	25	10.72 X	0.75	11.47
71507-T5A-000	GARNISHL.RR.BUMPER <i>cu</i>	1	14.30	25	10.72 ✓	0.75	11.47
71593-T5A-000	SPACERR.RR.BUMPER <i>cut</i>	1	11.50	25	8.62 ✓	0.60	9.22
71598-T5A-000	SPACERL.RR.BUMPER <i>cut</i>	1	11.50	25	8.62 ✓	0.60	9.22
91505-TM8-003	CLIP,BUMPER <i>neu</i>	5	2.30	25	8.62 ✓	0.60	9.22
04655-TAS-300ZZ	PANEL SET,RR.FLOOR <i>n</i>	1	683.30	25	512.47 X	35.87	548.34
65540-T5A-310ZZ	STIFFENER COMP,R.RR. <i>2</i>	1	88.60	25	66.45 X	4.65	71.10
65590-T5A-310ZZ	STIFFENER COMP,L.RR. <i>2</i>	1	88.60	25	66.45 X	4.65	71.10
72841-SH3-315	OILSHEET <i>11</i>	1	40.70	25	30.52 X	2.14	32.66
63720-T5A-900ZZ	GUTTER COMP,L.RR.PILLAR LOWER <i>n</i>	1	88.60	25	66.45 X	4.65	71.10
66100-TAR-T10ZZ	PANEL COMPRR. <i>30/50</i>	1	320.40	25	240.30 ✓	16.82	257.12
84601-TAR-Z03ZA	LINING ASSYR.TRUNK <i>11</i>	1	169.00	25	126.75 X	8.87	135.62
84640-T5A-003ZA	LINING ASSYRR.PANEL <i>TW</i>	1	60.80	25	45.60 ✓	3.19	48.79
84651-TAR-Z03ZA	LINING ASSYL.TRUNK <i>11</i>	1	169.00	25	126.75 X	8.87	135.62
84521-T5A-901ZA	LID ASSYSPARE TIRE <i>11</i>	1	189.80	25	142.35 X	9.96	152.31
84550-T5S-M10	BOX ASSYCARGO FLOOR <i>To. n</i>	1	107.00	25	80.25 ✓	5.62	85.87
38387-TZ5-A01	ANTENNA ASSYL.F. <i>neu</i>	1	59.30	25	44.47 ✓	3.11	47.58
74940-TZ5-A01	BUZZER ASSYSMART <i>neu</i>	1	60.40	25	45.30 ✓	3.17	48.47
Sum Item					3969.25	277.82	4,247.07
BOSUN	SUNDRIES <i>neu</i>	1	50.00	20	50.00 ✓	3.50	53.50
BML02I	INSPECT RR LIGHTING MECHANISMS. PERFORM WATER	1	100.00		100.00 ✓	7.00	107.00
BOBC	BODY UNDERSIDE COATING (N)	1	100.00		100.00 ✓	7.00	107.00
BA02R	REMOVE & RENEW REVERSE SENSORS-4 PCS (N)	1	130.00		130.00 ✓	9.10	139.10
BP00R	APPLY BODY UNDERSIDE COATING (N).	1	250.00	180	250.00 ✓	17.50	267.50
BKOT00R	REMOVE & RENEW RR FLOOR INSULATOR.(N)	1	250.00	11	250.00 X	17.50	267.50
BMF00D	REMOVE & INSTALL FUEL TANK FUEL PIPES.(N)	1	250.00	11	250.00 X	17.50	267.50
BG02D	REMOVE & INSTALL RR. WINDSCREEN.(N)	1	300.00		300.00 ✓	21.00	321.00

Printed on 13/2/2019 9:55:11 AM

This is a computer generated invoice. No signature is required.

Part prices are subjected to change without notice.

The above estimated cost of repair do not include any unforeseen damages.

GST Amount is calculated from individual line(s)



QUOTATION

KAH MOTOR CO. SDN. BHD.

(A Member of the Oriental Holdings Berhad)

Service and Body Repair

Tel: +65 6841 3838

Website: www.honda.com.sg

For 24-hours Roadside Assistance, Call 98203838

GST Reg No.: M200050223

Company Ref. No.: S60FC1380G

Customer : MS FIRST CAPITAL INSURANCE
 36 ROBINSON ROAD
 #16-01 CITY HOUSE
 SINGAPORE 068877

Registration No : SLJ1176A

Chassis No : JHMGK5850HX200872

Model : JAZZ 1.5VTIR CVT 17YM

Owner's Name : LOW HAN SONG, CLARENCE

Ins Policy No. :

Date of Accident : 8/2/2019

Document No. : SQT19000697 Page 3

Date : 12. Feb 2019

Customer No. : WZF002

Svc Advisor : LIM CHOU SIONG

Engine No : L15B31190620

Date | Time : 12. Feb 2019 7:37:53 PM

Surveyor Name :

Survey Date :

Authorisation Date :

Item	Description	Qty	Unit Price	Disc %	Amount	0% GST Amount	Amount incld GST
BOMISC1	REMOVE, INSTALL AND RESET REAR VIEW CAMERA. (N)	1	320.00		320.00	22.40	342.40
BOMISC1	RESET SMART ENTRY SYSTEM AND REMOVE NECESSARY	1	320.00		320.00	22.40	342.40
BMI02D	REMOVE & INSTALL REAR COMPARTMENT LININGS, RR1		350.00	250	350.00	24.50	374.50
BKTG02R	REMOVE & TRANSFER ITEMS TO NEW TAILGATE. ADJUST &	1	380.00	300	380.00	26.60	406.60
BMI01D	REMOVE & INSTALL ROOF LINING GARNISHES SEATS	1	560.00	11	560.00	39.20	599.20
BKRP02B	CUT OFF & RENEW RR FLOOR PANEL, RR PANEL, BOTH RR	1	4500.00	3080	4500.00	315.00	4815.00
BP06R	SPRAY PAINTING ON ROOF PANEL, TAILGATE, RR BUMPER,	1	3500.00	3000	3500.00	245.00	3745.00
BOJSE	BODY JOINT SEALANT.	2	80.00	80	160.00	11.20	171.20
Sum Labor					11520.00	806.40	12,326.40

Survey By Marcus Lim

Date & Time 15/2/19

Excess _____

Status not admit

Signature the ph. repair party

C S Lim
81006303 (HP)

Total Amount 15,489.25 1,084.22 16,573.47

Total (Inclusive of GST) **16,573.47**

John

By signing this invoice, you hereby acknowledge that you have received the goods and services as described in this invoice and that you are satisfied with the quality of the work done.

It is understood that the repair work is done on a "without prejudice" basis and the repairer is not liable for any damage to the vehicle or its contents that may occur during or after the repair work.

The repairer is not responsible for any damage to the vehicle or its contents that may occur during or after the repair work.

The repairer is not responsible for any damage to the vehicle or its contents that may occur during or after the repair work.

The repairer is not responsible for any damage to the vehicle or its contents that may occur during or after the repair work.

Acknowledged by Repairer

Signature: _____

Date: _____

Printed on 13/2/2019 9:55:11 AM

This is a computer generated invoice. No signature is required.

Part prices are subjected to change without notice.

The above estimated cost of repair do not include any unforeseen damages.

GST Amount is calculated from individual line(s)

15503.27

**KAH MOTOR CO. SDN. BHD.**

(A Member of the Oriental Holdings Berhad)

370 Ubi Road 3 Singapore 408651. Tel: +65 6841 3883 Fax: +65 6741 5022

255 Alexandra Road Singapore 159937. Tel: +65 6471 5458 Fax: +65 6471 5460

SERVICE PRE-INVOICE

Page 1/3

25/2/2019

Attn: Marcus (L.K.K.)

GST Reg No.: M200050223
Company Ref. No.: S60FC1380G

8 days.

Customer:	WZF002 / MS FIRST CAPITAL	Document No:	SVO19010086
Chassis No:	JHMGK5850HX200872	Printed By:	CSLIM
License No:	SLJ1176A	Order Date:	15. February 2019
Mileage:	31303	Order Time:	12:53:56 PM
Engine No:	L15B31190620	Service Advisor:	LIM CHOU SIONG

ITEM	DESCRIPTION	QTY	UNIT PRICE	DISC %	AMOUNT	7% GST Amount	Incld GST
	TP DIRECT SETTLEMENT (J/NO: 72171) OWNER: LOW HAN SONG, CLARENCE OWNER INSURER: NTUC INCOME INS CO-OPERATIVE LTD ACC DATE: 08/2/2019 SURVEYED BY: MARCUS (L.K.K.) DATE: 15/02/2019 @ 09:30AM REF NO: TP INSURER: MS FIRST CAPITAL INSURANCE LIMITED TP VEH: SHA4370E						
73127-TY0-000	RUBBER CWINDOW SHIELD DAMPER	1	11.40	25	8.55	0.60	9.15
73214-T5A-013	RUBBER WINDOW SHIELD DAMPER	2	6.50	25	9.75	0.68	10.43
73226-SZW-000	DAMPER STD 5X5	1	8.50	25	6.37	0.45	6.82
BO-WS-SEALANT	WINDSCREEN SEALANT (N)	2	60.00		120.00	8.40	128.40
68100-T5B-Z50ZZ	TAILGATE COMP	1	730.60	25	547.95	38.36	586.31
74440-T5A-003	WEATHER STRIP TAILGATE	1	92.30	25	69.22	4.85	74.07
74800-T5S-K61	LOCK ASSY, TAILGATE	1	78.90	25	59.17	4.14	63.31
75722-T5L-T01	EMBLEM RR.	1	10.90	25	8.17	0.57	8.74
33500-T5A-J02	TAILLIGHT ASSY, R.	1	223.90	25	167.92	11.75	179.67
33550-T5A-J02	TAILLIGHT ASSYL.	1	223.90	25	167.92	11.75	179.67
BO-NUM-COMP-L	NUMBER PLATE WITH CASING-L(N)	1	45.00		45.00	3.15	48.15
NMRS-4P-TM3040L	4PCS ACT RR.SENSOR	1	320.00		320.00	22.40	342.40
04715-T5B-000ZZ	FACERR.BUMPER	1	502.50	25	376.87	26.38	403.25
71507-T5A-000	GARNISH L.RR.BUMPER	1	14.30	25	10.72	0.75	11.47
71593-T5A-000	SPACERR.RR.BUMPER	1	11.50	25	8.62	0.60	9.22
71598-T5A-000	SPACER L.RR.BUMPER	1	11.50	25	8.62	0.60	9.22
91505-TM8-003	CLIP, BUMPER	5	2.30	25	8.62	0.60	9.22
66100-TAR-T10ZZ	PANEL COMPRR.	1	320.40	25	240.30	16.82	257.12
84640-T5A-003ZA	LINING ASSY RR.PANEL	1	60.80	25	45.60	3.19	48.79
84550-T5S-M10	BOX ASSY CARGO FLOOR	1	107.00	25	80.25	5.62	85.87
38387-TZ5-A01	ANTENNA ASSYL.F.	1	59.30	25	44.47	3.11	47.58
74940-TZ5-A01	BUZZER ASSY SMART	1	60.40	25	45.30	3.17	48.47
38389-T5R-A01	COVER.LFR.ANTENNA	1	18.70	25	14.02	0.98	15.00
	SUM PARTS:				2,413.41	168.92	2,582.33
BOSUN	0760 SUNDRIES	1	20.00		20.00	1.40	21.40
BML02I	0760 INSPECT RR LIGHTING MECHANISMS. PERFORM WATER TEST.(N)	1	100.00		100.00	7.00	107.00
BOBC	0760 BODY UNDERSIDE COATING (N)	1	100.00		100.00	7.00	107.00
BA02R	0760 REMOVE & RENEW REVERSE SENSORS-4 PCS (N)	1	130.00		130.00	9.10	139.10
BP00R	0959 APPLY BODY UNDERSIDE COATING (N).	1	180.00		180.00	12.60	192.60
BG02D	0760 REMOVE & INSTALL RR. WINDSCREEN. (N)	1	300.00		300.00	21.00	321.00



SERVICE PRE-INVOICE

KAH MOTOR CO. SDN. BHD.

(A Member of the Oriental Holdings Berhad)

370 Ubi Road 3 Singapore 408651. Tel: +65 6841 3883 Fax: +65 6741 5022

255 Alexandra Road Singapore 159937. Tel: +65 6471 5458 Fax: +65 6471 5460

GST Reg No.: M200050223
Company Ref. No.: S60FC1380G

Customer:	WZF002 / MS FIRST CAPITAL	Document No:	SVO19010086			
Chassis No:	JHMGK5850HX200872	Printed By:	CSLIM			
License No:	SLJ1176A	Order Date:	15. February 2019			
Mileage:	31303	Order Time:	12:53:56 PM			
Engine No:	L15B31190620	Service Advisor:	LIM CHOU SIONG			
BOMISC1	0760 REMOVE, INSTALL AND RESET REAR VIEW CAMERA.(N)	1	320.00	320.00	22.40	342.40
BOMISC1	0760 RESET SMART ENTRY SYSTEM AND REMOVE NECESSARY COMPONENT.(N)	1	320.00	320.00	22.40	342.40
BMI02D	0760 REMOVE & INSTALL REAR COMPARTMENT LININGS, RR SEATS, TRUNK LININGS, GARNISHES & ETC.(N)	1	250.00	250.00	17.50	267.50
BKTG02R	0760 REMOVE & TRANSFER ITEMS TO NEW TAILGATE. ADJUST & ALIGN TAILGATE.(N)	1	300.00	300.00	21.00	321.00
BKRP02B	0760 CUT OFF & RENEW RR PANEL, BOTH RR STIFFENER, REPAIR FLOOR PANEL, RR CHASSIS & RENEW DAMAGE PART	1	3,080.00	3,080.00	215.60	3,295.60
BP06R	0959 SPRAY PAINTING ON TAILGATE, RR BUMPER, RR PANEL, FLOOR PANEL, RR R FENDER & RR L FENDER	1	3,000.00	3,000.00	210.00	3,210.00
BOJSE	0760 BODY JOINT SEALANT.	1	80.00	80.00	5.60	85.60
SUM LABOUR:				8,180.00	572.60	8,752.60
TOTAL SGD				10,593.41	741.52	11,334.93
Total Payable (SGD)						11,334.93

GST Amount is calculated from individual line(s)



QUOTATION

KAH MOTOR CO. SDN. BHD.
 (A Member of the Oriental Holdings Berhad)
 Service and Body Repair
 Tel: +65 6841 3838 Website: www.honda.com.sg
 For 24-hours Roadside Assistance, Call 98203838

GST Reg No.: M200050223
 Company Ref. No.: S60FC1380G

Customer	: MS FIRST CAPITAL INSURANCE 36 ROBINSON ROAD #16-01 CITY HOUSE SINGAPORE 068877	Document No.	: SQT19000879	Page	1
Registration No	: SLJ1176A	Date	: 24. Feb 2019	Customer No.	: WZF002
Chassis No	: JHMGK5850HX200872	Svc Advisor	: LIM CHOU SIONG	Engine No	: L15B31190620
Model	: JAZZ 1.5VTIR CVT 17YM	Date Time	: 24. Feb 2019 5:32:03 PM	Surveyor Name	: MARCUS (L.K.K.)
Owner's Name	: LOW HAN SONG, CLARENCE	Survey Date	: 15/2/2019	Authorisation Date	: 14/2/2019
Ins Policy No.	:				
Date of Accident	: 8/2/2019				

Item	Description	Qty	Unit Price	Disc %	Amount	0% GST Amount	Amount Incl GST
	TP DIRECT SETTLEMENT (J/NO: 72171) OWNER: LOW HAN SONG, CLARENCE OWNER INSURER: NTUC INCOME INS CO-OPERATIVE LTD ACC DATE: 8/2/2019 SURVEYED BY: MARCUS (L.K.K.) DATE: 15/02/2019 @ 09:30AM REF NO: TP INSURER: MS FIRST CAPITAL INSURANCE LIMITED TP VEH: SHA4370E SUPPLEMENTARY LABOUR & PARTS						
38389-T5R-A01	COVER.L.FR.ANTENNA <i>ADD</i>	1 <i>Car</i>	18.70	25	14.02	0.98	15.00
				Sum Item	14.02	0.98	15.00

Survey By	_____						
Date & Time	_____				Total Amount	14.02	0.98
Excess	_____				Total (Inclusive of GST)		15.00
Status	_____						
Signature	_____						

Printed on 24/2/2019 5:37:05 PM
 This is a computer generated invoice. No signature is required.
 Part prices are subjected to change without notice.
 The above estimated cost of repair do not include any unforeseen damages.
 GST Amount is calculated from individual line(s)



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile			
MS FIRST CAPITAL INSURANCE LTD		Ref : CS/FCI19002787/Uqd3e2	
36 ROBINSON ROAD #16-01 CITY HOUSESINGAPORE 068877		Date : 27-02-2019	
		Code : FCI2	
1. Policy Particulars :- THIRD PARTY CLAIM			
Insured Veh.	SHA 4370E	Veh. Inspected	SLJ 1176A
Policy No.		Coverage (\$)	0.00
Claim No.	D19001043MFSH	Excess (\$)	0.00
Assign From	MAY CHUA	Assign Date	14/02/2019
2. Vehicle Particulars & Condition			
Make & Model	HONDA JAZZ (A)	c.c	1498
Engine No.	HIDDEN	Year of Reg.	2016
Chassis No.	JHMGK5850HX200872	Colour	RED
Odometer	31303	Steering	IN ORDER
Brakes	IN ORDER	Modification	SPORTS RIM
General	GOOD		
3. Conditions of Tyres			
	Size	Make	Balance
R/H Front Tyre	185/55 R16	YOKOHAMA	7 mm
L/H Front Tyre	185/55 R16	YOKOHAMA	7 mm
R/H Rear Tyre	185/55 R16	YOKOHAMA	7 mm
L/H Rear Tyre	185/55 R16	YOKOHAMA	7 mm
4. Description of Damages			
THE VEHICLE SUSTAINED DAMAGES AT THE REAR AND ROOFTOP PORTION.THE CHASSIS FRAME AFFECTED DUE TO COLLISION. DAMAGES SEE DETAILS.			
5. General Information			
Accident Date	08/02/2019	Inspection Date	15/02/2019
Survey held at	KAH MOTOR CO SDN BERHAD 15 UBI ROAD 4 SINGAPORE 408610		
5a. Remarks			
A)DAMAGES CONSISTENT TO ACCIDENT REPORT. B)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. C)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.			
5b. Estimate Days of Repair			
ESTIMATED NORMAL PERIOD FOR REPAIR:		8 Working Days	



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 3

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SLJ 1176A

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	REPLACEMENT OF PARTS			
1	RUBBER CWINDSHIELD DAMPER (SN)	NECESSARY	8.55	8.55
2	RUBBERWINDSHIELD DAMPER (SN)	NECESSARY	9.75	9.75
1	DAMPERSTD 5X5 (SN)	NECESSARY	6.37	6.37
2	WINDSCREEN SEALANT (SN)	NECESSARY	120.00	120.00
1	TAILGATE COMP (SN)	BADLY DENTED	547.95	547.95
1	WEATHERSTRIPTAILGATE (SN)	TWISTED	69.22	69.22
1	LOCK ASSY, TAILGATE (SN)	DENTED / JAMMED	59.17	59.17
1	STRIKER ASSYTAILGATE (SN)	NOT NECESSARY	18.52	-
1	DAMPER TAILGATE DYNAMIC (SN)	NOT NECESSARY	34.20	-
1	LINING ASSYTAILGATE LOWER (SN)	NOT NECESSARY	40.27	-
1	POCKETTAILGATE LINING PULL (SN)	NOT NECESSARY	3.82	-
1	EMBLEMRR. (SN)	NECESSARY	8.17	8.17
1	TAILLIGHT ASSY, R. (SN)	CUT	167.92	167.92
1	TAILLIGHT ASSYL. (SN)	CUT	167.92	167.92
1	LIGHT ASSYR.LID (SN)	NOT NECESSARY	61.27	-
1	LIGHT ASSYL.LID (SN)	NOT NECESSARY	61.27	-
2	LIGHT ASSYLICENCE (SN)	NOT NECESSARY	51.15	-
1	GARNISH ASSYRR.LICENCE (SN)	NOT NECESSARY	150.45	-
1	NUMBER PLATE WITH CASING (SN)	BENT	45.00	45.00
4	ACT RR.SENSOR (SN)	SHORTED	320.00	320.00
1	FACERR.BUMPER (SN)	DISTORTED	376.87	376.87
1	GARNISHR.RR.BUMPER (SN)	NOT NECESSARY	10.72	-
1	GARNISHL.RR.BUMPER (SN)	CUT	10.72	10.72
1	SPACERR.RR.BUMPER (SN)	BENT	8.62	8.62
1	SPACERL.RR.BUMPER (SN)	BENT	8.62	8.62
5	CLIP, BUMPER (SN)	NECESSARY	8.62	8.62
1	PANEL SET, RR.FLOOR (SN)	TO REPAIR SEE LABOUR	512.47	-
1	STIFFENER COMP,R.RR (SN)	TO REPAIR SEE LABOUR	66.45	-
1	STIFFENER COMP,L.RR (SN)	TO REPAIR SEE LABOUR	66.45	-

Report Ref No. CS/FCI19002787/Uqd3e2



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:2 of 3

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
1	OILSHEET (SN)	NOT NECESSARY	30.52	-
1	GUTTER COMP, L.RR.PILLAR LOWER (SN)	TO REPAIR SEE LABOUR	66.45	-
1	PANEL COMPRR. (SN)	BADLY DENTED	240.30	240.30
1	LINING ASSYR. TRUNK (SN)	NOT NECESSARY	126.75	-
1	LINING ASSYRR.PANEL (SN)	TWISTED	45.60	45.60
1	LINING ASSYL.TRUNK (SN)	NOT NECESSARY	126.75	-
1	LID ASSYSPARE TIRE (SN)	NOT NECESSARY	142.35	-
1	BOX ASSYCARGO FLOOR (SN)	TORN	80.25	80.25
1	ANTENNA ASSYL.F (SN)	CRACKED	44.47	44.47
1	BUZZER ASSYSMART (SN)	CRACKED	45.30	45.30
1	SUNDRIES (SN)	NECESSARY	50.00	20.00
1	COVER.L.FR.ANTENNA (SN) (ADDITIONAL)	CRACKED	14.02	14.02
			4,033.27	2,433.41
	<u>LABOUR</u>			
	INSPECT RR LIGHTING MECHANISMS. PERFORM WATER.		100.00	100.00
	BODY UNDERSIDE COATING.		100.00	100.00
	REMOVE & RENEW REVERSE SENSORS - 4PCS.		130.00	130.00
	APPLY BODY UNDERSIDE COATING.		250.00	180.00
	REMOVE & RENEW RR FLOOR INSULATOR.	NOT NECESSARY	250.00	-
	REMOVE & INSTALL FUEL TANK FUEL PIPES.	NOT NECESSARY	250.00	-
	REMOVE & INSTALL RR.WINDSCREEN.		300.00	300.00
	REMOVE, INSTALL AND RESET REAR VIEW CAMERA.		320.00	320.00
	RESET SMART ENTRY SYSTEM AND REMOVE NECESSARY.		320.00	320.00
	REMOVE & INSTALL REAR COMPARTMENT LININGS, RR.		350.00	250.00
	REMOVE & TRANSFER ITEMS TO NEW TAILGATE. ADJUST &		380.00	300.00
	REMOVE & INSTALL ROOF LINING GARNISHES SEATS.	NOT NECESSARY	560.00	-
	CUT OFF & RENEW RR FLOOR PANEL, RR PANEL BOTH RR. INCLUSIVE OF THE REPAIR OF PANEL SET, RR.FLOOR, STIFFENER COMP,R.RR, STIFFENER COMP,L.RR AND GUTTER COMP, L.RR.PILLAR LOWER.		4,500.00	3,080.00

Report Ref No. CS/FCI19002787/Uqd3e2



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:3 of 3

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	SPRAY PAINTING ON ROOF PANEL, TAILGATE, RR BUMPER.		3,500.00	3,000.00
	BODY JOINT SEALANT.		160.00	80.00
			11,470.00	8,160.00
	GRAND TOTAL		15,503.27	10,593.41
RECOMMENDED COST OF REPAIRS				10,593.41

Report Ref No. CS/FCI19002787/Uqd3e2

CHUA KANG SENG

Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.