



CYCLE & CARRIAGE-FULCO MOTOR DEALER PTE LTD EUNOS LINK SERVICE CENTRE



CYCLE & CARRIAGE

330 Ubi Road 3 Singapore 408650 Tel: 67461000 Fax: 64875857

91792566

ESTIMATE

Invoice Name & Address	Owner Name & Vehicle Info	
CHINA TAIPING INSURANCE (SINGAPORE) 3 Anson Road #16-00 Springleaf Tower Singapore 079909 Attn: Claims Dept. Contact No 63896111 3 days	Cust No/Name	LCV06765/Mr Wong Zhi Wai (huang Zhiwei)
	Reg No/Reg Date	SME6393X / 10/10/2018
	Date In/Mileage	31/01/2019/ 0
	Chassis No	KNAF3416MK5015977
	Engine No	G4FGJH703624
	Make/Model	KIA/CER1.6ASXG335
	Colour/Trim	4SS / WK

Account No	Terms	Date/Time Printed	CSE	Operator	WIP No				
F0000018	Credit	14/02/2019/ 08:17	DS	303 / Renemer	18324				
Description of Goods / Services					Qty	Unit Price	Disc%	Amount	
S	MIPNT88088	DIAGNOSTIC / SCANNING							250.00
S	MIPNT88088	TO CHECK LIGHTING/WIRING SYSTEM ON REAR ACCIDENT AFFECTED AREAS							801 100.00
S	MIPNT88088	TO REPLACE REAR BUMPER, REINFORCEMENT, ETC. STRAIGHTEN, REFORM, ALIGN ON REAR ACCIDENT AFFECTED AREAS							600 1200.00
S	MIPNT88088	TO REMOVE & RE-INSTALL ALL CARPETS & TRIMMINGS TO GIVE WAY ACCESS FOR REPAIR							300 1200.00
S	MIPNT98088	SPRAY PAINTING ON REAR ACCIDENT AFFECTED AREAS							420 1260.00
M	KS 86611 M6 010	COVER - REAR BUMPER			1.00	688.00	10.00	619.20	
M	KS 86612 M6 010	COVER - REAR BUMPER			1.00	197.00	10.00	177.30	
M	KS 86651 M6 000	LH, UPR BRACKET ASSY-			1.00	25.00	10.00	22.50	
M	KS 86652 M6 000	RH, UPR BRACKET-ASSY			1.00	31.00	10.00	27.90	
M	KS 86661 M6 010	LH, COVER-RR BUMPER F			1.00	19.00	10.00	17.10	
M	KS 92305 M6 000	LH, LAMP ASSY-SIDE T/			1.00	181.00	10.00	162.90	
M	KS 86631 M6 200	BEAM - REAR BUMPER			1.00	318.00	10.00	286.20	
M	KS 86633 M6 200	LH, BRACKET-RR BEAM U			1.00	9.00	10.00	8.10	
M	KS 86634 M6 200	RH, BRACKET-RR BEAM U			1.00	9.00	10.00	8.10	
M	KS 86636 M6 200	CTR, BRACKET-RR BEAM			1.00	6.00	10.00	5.40	
M	KS 86637 M6 200	LWR, BRACKET-RR BEAM			1.00	6.00	10.00	5.40	
M	KS 95420 S6 200	ANTENNA ASSY-SMARTKE			1.00	46.00	10.00	41.40	
M	KS 99310 M6 100K LG	ULTRASONIC SENSOR AS			1.00	163.00	10.00	146.70	
M	KS 06032 50 037A	CLIP- BUMPER			10.00	2.00	10.00	18.00	
Z	NOTES								
ACCIDENT ON 30/01/2019 ALONG T-JUNCTION, NEW LOYANG LINK TOWARDS OLD TAMPINES ROAD / OWNER CLAIMING THIRD PARTY REQUIRED REPLACEMENT CAR									
TP #: SDW841X TP INS: CHINA TAIPING									

Confirmed by: <u>[Signature]</u> Received by: <u>[Signature]</u> • To resurvey before/after spray painting • To display damaged part(s) during resurvey • Parts prices are subject to confirmation • Third party survey is on a "Without Prejudice" basis • No illegal modification(s) is allowed • Supplementary item(s) must be resurveyed and Authorized Signatory and company stamp	Parts 1,546.20 Labour 0.00 Standard Menu 0.00 Specialist Job 4,010.00 Others (Lub, etc) 0.00 Sundry 0.00 Total (w/o GST) 5,556.20
--	--

Validity of this estimate is 14 days from date of quote. This is a computer generated document, no signature is required. Estimated costs quoted are excluding GST. We would mention that the above estimate is based on our initial inspection and does not include any additional parts or labour which may be required after repair work has commenced. Occasionally worn or damaged parts are discovered after work has started and needed for repairs or replacement. However, should this occur, we would advise you. Please be informed that a deposit of 50% of the above estimate is payable before commencement of the work. Payment for this may be made in cash, credit card or cheque. You must also agree to pay full amount for renewal of the windscreen in the event of inadvertent breakage in the course of renewing the rubber seal or other repair requiring the removal of the windscreen.