

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CC3/AIG19002845/KEA3Q2

Date: 05/05/2020

REFERENCE

Handling Insurer: AIG Asia Pacific Insurance Pte. Ltd. Policy No: 2100284824-07

Claimant
Vehicle No : SHD5404U **Insured Vehicle No :** GX6196U

Date of Loss: 12/02/2019 Nature of Claim: TP Claim No: 4802691909SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SHD5404U	Engine No:	2ZR2B98981
Make & Model:	TOYOTA PRIUS, 1.8 (A)	Chassis No:	JTDKB3FU503079145
Reg. Date:	25/01/2019 (Man. Year: 2018)	Odometer:	4395 km
Colour:	Metallic Pearl White/Red		
Engine Capacity:	1798 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	195/60 R15	Rear Tyre Size:	195/60 R15
Front Left Side:	Yokohama 9 mm	Rear Left Side:	Yokohama 9 mm
Front Right Side:	Yokohama 9 mm	Rear Right Side:	Yokohama 9 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	9,480.48	419.92	9,060.56	95.57
Miscellaneous Items	0.00	0.00	0.00	
Labour	10,400.00	740.00	9,660.00	92.88
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Gross Total (S\$)	19,880.48	1,159.92	18,720.56	94.17
+ GST 7.00/7.00% (S\$)	1,391.63	81.19	1,310.44	94.17
Nett Amount (S\$)	21,272.11	1,241.11	20,031.00	94.17
+ Loss of Use (6.0 x S\$50.00/day) (S\$)		300.00		
+ Car Rental (6.0 x S\$113.40/day) (S\$)		680.40		
		(S\$) 2,221.51		
Liabile Amount (50.00%) (S\$)		1,110.76		
+ Doc/Search Fee (S\$)		7.49		
Nett Liability (S\$)		1,118.25		
Global Sum Settlement (S\$)		1,120.00		

INSPECTION

Date of Assignment: 14/02/2019

Date Inspected: 14/02/2019 Inspected At: Trans-cab Auto Services Pte Ltd
No 2 Ang Mo Kio Street 63
Singapore 569111

Estimated Period of Repair: 3.0 days

Adjuster: KENNETH KONG

Manager: Asher Sng Rong Yi

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*FRONT BUMPER	Bent	499.90 FL	*499.90 FL
2	1		*BRACKET ,FRONT BUMPER EXTENSION MOUNTING	Serviceable	101.20 FL	*- FL
3	1		*REINFORCEMENT ,FRONT BUMPER	Repair	696.40 FL	*- FL
4	1		*ABSORBER ,FRONT BUMPER ,LOWER	Serviceable	130.20 FL	*- FL
5	1		*ABSORBER ,FRONT BUMPER ENERGY	Serviceable	78.10 FL	*- FL
6	1		*FRONT BUMPER SIDE RETAINER RH	Serviceable	78.00 FL	*- FL
7	1		*FRONT BUMPER SIDE RETAINER LH	Serviceable	78.00 FL	*- FL
8	1		*FRONT BUMPER SUPPORT	Serviceable	81.70 FL	*- FL
9	1		*EXTENSION ,FRONT BUMPER ,RH	Serviceable	117.80 FL	*- FL
10	1		*EXTENSION ,FRONT BUMPER ,LH	Serviceable	117.80 FL	*- FL
11	1		*FRONT LED LAMP (LOWER) RH	Serviceable	907.75 FL	*- FL
12	1		*FRONT LED LAMP (LOWER) LH	Serviceable	907.75 FL	*- FL
13	1		*FRONT HEADLAMP RH	Serviceable	2,909.04 FL	*- FL
14	1		*COMPUTER SUB-ASSY ,HEADLAMP ,RH NO.1	Serviceable	492.30 FL	*- FL
15	1		*MOTOR ,HEADLAMP LEVELING RH	Serviceable	413.10 FL	*- FL
16	1		*FRONT HEADLAMP LH	Serviceable	2,909.04 FL	*- FL
17	1		*COMPUTER SUB-ASSY ,HEADLAMP ,RH NO.1	Serviceable	492.30 FL	*- FL
18	1		*MOTOR ,HEADLAMP LEVELING ,RH	Serviceable	413.10 FL	*- FL
19	1		*FRONT BONNET	Repair	950.50 FL	*- FL
20	1		*FRONT NUMBER PLATE WITH MOULDING	Scratched /Dented	200.00 FS	*45.00 FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (S\$)	12,573.98	544.90
- List Item Discount on L Items 25.00/25.00% (S\$)	3,093.50	124.98
Total Parts (S\$)	9,480.48	419.92

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	PUTTY AND SPRAY PAINTING OF THE AFFECTED PORTION	New	4,200.00	440.00
2	PANEL BEATING ,KNOCKING AND STRAIGHTENING THE NECESSARY PORTION,REMOVE AND RENEWAL OF PARTS ,ADJUST AND REALIGN THE SAME.	New	4,200.00	300.00
3	TO RUST -PROOFING OF THE AFFECTED AREAS	New	170.00	0.00
4	TO TRANSFER OF FENDER FITTINGS ,ATTACHMENTS AND PERFORM WATER SEEPAGE TEST.	New	170.00	0.00
5	TO TRANSFER OF FRONT BUMPER FITTINGS ,ATTACHMENTS AND PERFORM WATER SEEPAGE TEST	New	170.00	0.00
6	TO TRANSFER OF FRONT WINDSCREEN FITTINGS AND CONDUCT WATER SEEPAGE TEST	New	170.00	0.00
7	TO CHECK STEERING GEOMETRY AND COMPUTER WHEEL ALIGNMENT	New	220.00	0.00
8	TO VACUUM ,REPLACE ,REFIX AND RECHARGE AIR CONDENSER	New	380.00	0.00
9	TO REPLACE ,REFIX AND TOP UP COOLANT FOR RADIATOR	New	170.00	0.00
10	TO VACUUM ,REPLACE ,REFIX AND RECHARGE AIR INTERCOOLER	New	170.00	0.00
11	TO DISMANTLE AND REFIT AIRCON ASSY AND ATTACHMENT ,VACUUM AND CHARGE-IN-GAS	New	380.00	0.00
			Gross Labour Cost (S\$)	740.00
			10,400.00	740.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >