

LKK Auto Consultants Pte Ltd

(Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CC4/AIG19002858/R1GA3Q2

Date: 18/01/2021

REFERENCE

Handling Insurer: AIG Asia Pacific Insurance Pte. Ltd. Policy No: 2100386308

Claimant
Vehicle No : PC9396T

Insured Vehicle No : SJZ2642D

Date of Loss: 01/02/2019

Nature of Claim: TP

Claim No: 1781912897SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: **PC9396T**

Make & Model: TOYOTA HIACE, 3.0 COMMUTER GL (A)

Engine No: 1KD2734679

Reg. Date: 23/11/2017 (Man. Year: 2017)

Chassis No: KDH2230033343

Colour: White

Odometer: 112824 km

Engine Capacity: 2982 cc

Market Value/New Car Price: N/A

Sum Insured (S\$): **Market Value/New Car Price**

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes

Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 215/70 R15C

Rear Tyre Size: 215/70 R15C

Front Left Side: Michelin 6 mm

Rear Left Side: Michelin 6 mm

Front Right Side: Michelin 6 mm

Rear Right Side: Michelin 6 mm

The above values represent the remaining tyre treads depth

| COST OF CLAIMS | Repairer's | Adjuster's | Difference | Diff % |
|---|-------------------|-------------------|-------------------|---------------|
| Parts | 5,767.41 | 2,689.16 | 3,078.25 | 53.37 |
| Miscellaneous Items | 0.00 | 0.00 | 0.00 | |
| Labour | 2,010.00 | 1,020.00 | 990.00 | 49.25 |
| Paintwork Labour | 0.00 | 0.00 | 0.00 | |
| Towing | 0.00 | 0.00 | 0.00 | |
| Calculated Gross Total (S\$) | 7,777.41 | 3,709.16 | 4,068.25 | 52.31 |
| Approved Total (Overridden) (S\$) | | 2,950.00 | | |
| (S\$) | 7,777.41 | 2,950.00 | 4,827.41 | 62.07 |
| + GST 7.00/7.00% (S\$) | 544.42 | 206.50 | 337.92 | 62.07 |
| Nett Amount (S\$) | 8,321.83 | 3,156.50 | 5,165.33 | 62.07 |
| + Loss of Use (6.0 x S\$90.00/day) (S\$) | | 540.00 | | |
| (S\$) | | 3,696.50 | | |
| Liabile Amount (50.00%) (S\$) | | 1,848.25 | | |
| + Doc/Search Fee (S\$) | | 29.00 | | |
| Nett Liability (S\$) | | 1,877.25 | | |

INSPECTION

Date of Assignment: 14/02/2019

Date Inspected: 02/05/2019 Inspected At:

Teamwork Garage Pte Ltd (HQ)
53 Ubi Ave 1 #01-24, Paya Ubi
Industrial Park
Singapore 408934

Estimated Period of Repair: 4.0 days

Adjuster: MOHD RASUL

Manager: Chong Pui Lin

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Recommended Parts

| No. | Qty | Part No. | Particulars | Condition | Repairer's | Amount |
|-----|-----|----------|---------------------------|---------------|-------------|--------------|
| 1 | 1 | | *FRONT BUMPER | Deformed | 799.34 FL | *799.34 FL |
| 2 | 1 | | *FRONT BUMPER BRACKET | Cracked | 211.20 FL | *211.20 FL |
| 3 | 1 | | *FRONT REINFORCEMENT | Bent | 563.97 FL | *563.97 FL |
| 4 | 1 | | *FRONT BUMPER RH RETAINER | Necessary | 98.60 FL | *98.60 FL |
| 5 | 1 | | *FRONT RH HEADLAMP | Scratched | 1,090.30 FL | *1,090.30 FL |
| 6 | 1 | | *FRONT RH CORNER PANEL | Serviceable | 101.30 FL | *- FL |
| 7 | 1 | | *FRONT RH FOG LAMP | Serviceable | 468.10 FL | *- FL |
| 8 | 1 | | *FRONT RH FOG LAMP COVER | Cut | 168.00 FL | *168.00 FL |
| 9 | 1 | | *FRONT GRILLE | Scratched | 410.80 FL | *410.80 FL |
| 10 | 1 | | *FRONT SUPPORT PANEL | Serviceable | 680.50 FL | *- FL |
| 11 | 1 | | *FRONT RH DOOR PANEL | Repair | 1,090.30 FL | *- FL |
| 12 | 1 | | *FRONT RH STEP GARNISH | Cut | 1,820.80 FL | *190.00 FL |
| 13 | 1 | | *SET FRONT BUMPER CLIP | Necessary | 40.00 FS | *40.00 FS |
| 14 | 1 | | *BOT BRAKE FUILD | Not Necessary | 50.00 FS | *- FS |
| 15 | 1 | | *BOT COOLANT | Not Necessary | 50.00 FS | *- FS |

F=Franchise part. S=SpcNett. L=ListItemDisc.

| | | |
|--|-----------------|-----------------|
| Sub Total (\$) | 7,643.21 | 3,572.21 |
| - List Item Discount on L Items 25.00/25.00% (\$) | 1,875.80 | 883.05 |
| Total Parts (\$) | 5,767.41 | 2,689.16 |

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

| No | Particulars | Lab.Type | Repairer's | Amount |
|---------------------------------|--|----------|-----------------|-----------------|
| <u>Labour Items</u> | | | | |
| 1 | CHECK FRONT LIGHTING AND WIRING SYSTEM | New | 60.00 | 30.00 |
| 2 | TRANSFER PARTS,ATTACHMENT FROM OLD FRONT DOOR TO N | New | 200.00 | 60.00 |
| 3 | PANEL BEATING ON AFFECTED AREAS | New | 800.00 | 400.00 |
| 4 | SPRAY PAINTING ON AFFECTED AREAS | New | 800.00 | 500.00 |
| 5 | APPLY ANTI RUST ON AFFECTED AREAS | New | 150.00 | 30.00 |
| Gross Labour Cost (\$\$) | | | 2,010.00 | 1,020.00 |

Report was unsubmitted during this print-out.

< END OF ESTIMATES >