



## LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 1

### ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SKA 1347H

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
<b><u>REPLACEMENT OF PARTS</u></b>				
1	RH FRONT DOOR (CONSISTENT)	DENTED	1,200.00	1,200.00
1	RH REAR DOOR (CONSISTENT)	TO REPAIR SEE LABOUR	1,140.00	-
1	RH DOOR CHROME STRIP FRT (CONSISTENT)	NECESSARY	271.00	271.00
1	RH DOOR CHROME STRIP REAR (CONSISTENT)	NECESSARY	271.00	271.00
	LESS 10% DISCOUNT		-	-174.20
			2,882.00	1,567.80
<b><u>SPECIAL NETT ITEMS</u></b>				
1	CLIPS /RETAINER STADS FOR 2 DOORS (CONSISTENT) (SN)	NECESSARY	80.00	30.00
			80.00	30.00
<b><u>LABOUR</u></b>				
	DISMANTLE /ASSEMBLY OF 2X DOORS INCLUDING UPHOLSTERY CABLES /WIRING & ETC.INCLUSIVE OF THE REPAIR OF RH REAR DOOR.		360.00	100.00
	PANEL BEATING ON ROCKER ARM SKIRTING.		200.00	200.00
	SPRAY PAINTING ON 2 DOORS (2X) SKIRTING.		800.00	600.00
			1,360.00	900.00
<b>GRAND TOTAL</b>			<b>4,322.00</b>	<b>2,497.80</b>
<b>RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION)</b>				<b>2,000.00</b>

Report Ref No. CC4/ASM19002871/Eps3q2

CHEN TSUE YEE

Automotive Assessor

HO LEONG CHUAN

Automotive Assessor

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or replying on this Report, in whole or in part, does so at his or her own risk.